

FAO The Court

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: Miss Poonam Patel: 15/01/2026


In accordance with your instructions received on 16/01/2026 requesting us to provide an independent accident damage report, we assessed the damage on 28/01/2026. Vehicle located at Image-based Assessment. Our findings are as detailed below:

Make	MERCEDES-BENZ	Registration	BU72MPO
Model	A 180 AMG LINE ED EX	Status	Repair
Category		Salvage Value	
Repair Cost	£8,003.75	Legal Status	Roadworthy
Engineer Value	£21,597.00	Impact Magnitude	Moderate



Impact Area





Our Ref: a.pch26190

Your Ref: 570147

Date: 28/01/2026

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the rear.

ENGINEER'S COMMENTS

UPDATED REPORT - Collect/Deliver has been added to the parts.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION


The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £8,025.00 would be reasonable on this occasion.

Vehicle Data

Retail Value	£21,597.00
Trade Value	£18,357.00
Engineer's Value	£21,597.00
Glass's Code	
VIN	W1K1770842J359479
Odometer	17258
Engine	1332
Fuel	Petrol
Extras	
Condition	Good
Unrelated Damage	



Our Ref: a.pch26190

Your Ref: 570147

Date: 28/01/2026

Main new parts required

Rear Bumper Cover
R/R Bumper Support
Rr Inner Bumper Part
R/R Bumper Damper
R/R Side Reflector
R/R Ctr Spacer Ring
R/R Out Spacer Ring
R/R Inn Spacer Ring
L/R Ctr Park Sensor
Rear No Plate Reinf
Rear Lock Striker
Rear Handle Control
Rear Badge
Rear Screen Bond Kit
Sundry Parts

L/R Bumper Support
Rear Bumper C-Member
L/R Bumper Damper
L/R Side Reflector
L/R Ctr Spacer Ring
L/R Out Spacer Ring
L/R Inn Spacer Ring
R/R Inn Parking Sens
Rear Number Plate
Bootlid/Tailgate
Boot/Tailgate Lock
Star Emblem
Clip Fastening
Rear Screen Supports

Additional operations

Paint Rear Bumper Cover Painting
Paint L/R Ctr Park Sensor Painting
Paint L/R Side Panel Painting Stage Ii
Paint Fuel Filler Flap Painting Stage Ii
Paint Outer Cleaning Carry Out
Paint Non Water Based Remove
Paint Additional Masking Tailgate Shut
Paint Additional Masking Tailgate
Paint Security Measures Before
Paint Add For Preparation Work
Assessment Fee
Vehicle Care Kit
Corrosion Mat
Collect/Deliver

Paint R/R Inn Parking Senspainting
Paint Bootlid/Tailgate Painting Stage I-M
Paint R/R Side Panel Painting Stage Ii
Paint Add Colour Sample 1
Paint Polish Vehicle
Paint Additional Mask Frt Screen
Paint Denib / Polish Paint
Blend Touch Up Bolts Surface Paint
Paint Preparation Work For Two Coat Painting
Paint Carry Out Colour Shade Determination
Epa Charge
Paint Consumable
First Calibration

Repair Cost Calculations

Hours	27.70
Hourly Rate	£103.06
Total Labour	£2,854.76
Parts	£2,081.13
Paint/Materials	£1,007.39
Specialist/Other	£726.51
Sub total	£6,669.79
Vat	£1,333.96
Total Estimated Cost	£8,003.75
























Our Ref: a.pch26190

Your Ref: 570147

Date: 28/01/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk



Our Ref: a.pch26190

Your Ref: 570147

Date: 28/01/2026

FAO The Court

Fee Note

BU72MPO.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £150.00

Sub Total: £150.00

VAT: £30.00

Total Due: £180.00

Payment

Please make cheques payable to Collision Engineers and quote reference a.pch26190.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10