

TEL: COLLISION ENGINEERS
01515590762 77-79 HOYLAKE ROAD
MORETON
WIRRAL, CH46 9PY

Assessment Number: NR002067
Version: VBR040CH/1

Full Report
Printed: 19/06/2026

Summary Information

Claim

Authorisation Status:	Interim	Date of Incident:	Not Known
Work Provider:	OTHER	Able to Authorise Repairs:	TBA
Claim Reference:		Repairs Authorised?	TBA
Policy Number:		VAT Portion Payable:	TBA
Other Reference:		Repairer:	
		Estimated Repair Time (Working Days):	

Vehicle Details

Vehicle

Manufacturer:	VOLKSWAGEN
Model:	TIGUAN R Line
Model Sheet Number:	6C3
Engine:	2.0 LTR 103 KW
Registration Number:	MT15MBO
VIN Number:	WVGZZZ5NZFW106766
Registration Month:	May
Registration Year:	2015
Odometer:	Not Known
Colour:	WHITE
Paint Code:	C9A
Build Date:	FROM 11/2014
Selection Type:	AudaVIN+
Fuel Type:	Diesel
Vehicle Imported:	No

Model Specs

LED NO PLATE LAMPS
FROM 11/2014
STOP-START SYSTEM
HANDS FREE CONV SYST
BLUE MOTION
R-LINE EXTERIOR
CLIMATRONIC
RADIO/NAVIG RNS 315
RAIN SENSOR
LIGHT/COMING HOME
SIDE WINDOW/RR SCRIN
SAFE SECURITY
AUTO DIPPING MIRROR
8 SPEAKER
RADIO RECEPT DIGITAL
XENON HEADLAMPS
FOG LAMPS
HEADLAMP WASHERS
PARK ASSISTENT
CLOTH TRIM
HEIGHT ADJ PASS SEAT
ROOF CONSOLE
ANTI-THEFT ALARM
FRONT SEAT DRAWER
FRONT LUMBAR SUPPORT
VARIABLE LOAD FLOOR
CLOSE RANGE LIGHTING
OIL LEVEL SENSOR
DETACHABLE TOWBAR
FRT SEAT FOLD TABLE
FRONT CENTRE ARMREST
FRT FOLDING BACKREST
2.0 LTR 103 KW
GEARBOX 6 SPEED
4MOTION (ALL WHEEL)
GEARBOX DIFF MQ 500

TEL: COLLISION ENGINEERS
01515590762 77-79 HOYLAKE ROAD
MORETON
WIRRAL, CH46 9PY

Assessment Number: NR002067
Version: VBR040CH/1

Full Report
Printed: 19/06/2026

DROWSINESS DETECTION
SPORTS SUSPENSION
MULTIMEDIA SYSTEM
TYRES 235/50 VR 18
WHEELS 8J X 18 ALLOY
SPACE SAVER SP-WHEEL
CHROME PACKAGE
REAR SPOILER
ROOF RAILS
SPORT BUMPER
PREPARE OFF VEHICLE
BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
Steering Rim Ply:
Brakes Pedal Travel:
Place of Inspection:
Pre-Accident Damage:



Severity of Impact:
Vehicle Status on Inspection:
Date of Inspection: 19/06/2026

Tyres Condition:
Tread Depth LHF:
Tread Depth LHR:

Tread Depth RHF:
Tread Depth RHR:

Damage Areas:

Direction of Impact:



TEL: COLLISION ENGINEERS
01515590762 77-79 HOYLAKE ROAD
MORETON
WIRRAL, CH46 9PY

Assessment Number: NR002067
Version: VBR040CH/1

Full Report
Printed: 19/06/2026

Addresses

No addresses entered.

Cost Summary

Total Labour	£1,415.76
Total Paint/Material	£664.74
Total Parts	£1,050.27
Additional Costs	£352.69
Grand Total Exc VAT:	£3,483.46
20 % VAT:	£696.69
Grand Total Inc VAT:	£4,180.15
Excess:	TBA

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price = £83.28/HR

Repair / Guide

Number	Description	Work Units
NO NUMBER	RENEW SPOILER BRACKET (ADD/WORK)	2.0
63 69 19 00	R + R REAR BUMPER COVER	7.0
63 69 65 02)	R + R REAR BUMPER PART COVER	5.0
	(FOR OUTER BODY)	
	(BUMPER COVER REMOVED)	
66 45 19 ZAX	R + R L/SIDE PANEL COVER	2.0
66 45 19 ZAX	R + R R/SIDE PANEL COVER	2.0
66 90 19 50	R + R TOW BAR	7.0
	(BUMPER COVER REMOVED)	
1000	REMOVE&REFIT BUMPER TO STAND	2.0*
2583	REPAIR REAR BUMPER	15.0*
1000	Specialist QC AND ROAD TEST	10.0*
1000	Specialist PRE REPAIR CLEAN	5.0*
1000	Specialist POST REPAIR CHECK	10.0*
1000	Specialist PRE REPAIR CHECK	10.0*
1000	Specialist WASH AND VACUUM	10.0*
1000	Specialist STANDARD SHUTDOWN	10.0*
1000	Specialist YARD CHARGE	10.0*
1000	Specialist OLDER VEHICLE ALLOW	10.0*
Total Work Units		117.0
Total Panel / Mechanical Labour		11.70 HRS
		£974.38

PAINT WORK

Time Basis 10 WU = 1 HR. Price = £83.28/HR

TEL: COLLISION ENGINEERS
01515590762 77-79 HOYLAKE ROAD
MORETON
WIRRAL, CH46 9PY

Assessment Number: NR002067
Version: VBR040CH/1

Full Report
Printed: 19/06/2026

Repair /Guide	Description	Work Units
Number		
2606	REAR BUMPER SPOILER NEW PART PAINT K1R	10.0
2583	REAR BUMPER REPAIR PAINT PLASTIC	13.0
1000	DENIB / POLISH Paint	3.0*
	PREPARATION FOR PRE-PAINTING	27.0
Total Work Units		53.0
Total Paintwork Labour		5.3 HRS. £441.38

MATERIAL COST - PAINT	COST
Total Paint Cost	£502.44
Sundry Paint Material	£0.00
Pre-Painting Sundry Materials	£162.30
Total Excluding Pearlescent Uplift	£664.74
Pearlescent Uplift @ 0.0%	£0.00
Total Paint And Material Cost	£664.74

PARTS

Price Valid: 01/06/2026

Guide No.	Description	Part Number	Bet.	Price
2593	REAR PANEL	5N0 807 482 B 2Z0	0%	£252.00
2594	REAR TRIM	5N0 807 397	0%	£93.80
2606	REAR BUMPER SPOILER	5N0 807 521 AF GRU	0%	£246.00
2608	SCREW	SEE GUIDE NO. 2627	0%	£1.15
2627	RR BUMPER CLAMP KIT	5N0 898 623 A	0%	£21.80
2800	TOW BAR		0%	£400.00 *
Sub Total				£1,014.75
Deduction from RRP (0.0 %)				£0.00
Sundry Parts (3.5 %)				£35.52
Total Parts				£1,050.27

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

TEL: COLLISION ENGINEERS
01515590762 77-79 HOYLAKE ROAD
MORETON
WIRRAL, CH46 9PY

Assessment Number: NR002067
Version: VBR040CH/1

Full Report
Printed: 19/06/2026

Description		Betterment	Price
ASSESSMENT FEE	Specialist	0%	£176.96
EPA CHARGE	Specialist	0%	£31.23
VEHICLE CARE KIT	Specialist	0%	£10.41
PAINT CONSUMABLE	Specialist	0%	£30.00
DELIVERY TO CLIENT	RETURNING VEH	0%	£78.07
PANEL SUNDRIES P/P	Specialist	0%	£26.02
Total Extras			£352.69

Calculation

19/06/2026

Labour

Total Panel/Mechanical	£974.38
Total Paintwork	£441.38

Total Labour

£1,415.76

Total Paint/Material Costs

£664.74

Total Parts

£1,050.27

Additional Costs

Cost of Specialist	£352.69
--------------------	----------------

Total Additional Costs

£352.69

Grand Total Excl VAT

£3,483.46

VAT @ 20 %

£696.69

Grand Total Incl VAT

£4,180.15

Excess

TBA

Assessment Notes

No assessment notes entered.