

Ms Cathryn Owen  
22 Wordsworth Road  
Newport  
Gwent  
NP  
Newport  
Gwent


Date: 02/06/2026  
Our Ref: 00036986/JEFFP  
Your Ref: EHR102191

**To the Court**  
**REPAIRABLE REPORT**

Dear Sirs,

Client: **Ms Cathryn Owen**

We refer to your instructions received on **26 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

|                    |                                              |             |                 |                                                                                     |                   |                   |                     |
|--------------------|----------------------------------------------|-------------|-----------------|-------------------------------------------------------------------------------------|-------------------|-------------------|---------------------|
| Vehicle:           | <b>VOLKSWAGEN TIGUAN R LINE TDI BLU</b>      |             | Colour:         | <b>White</b>                                                                        | Speedo:           | <b>100746</b>     | Miles               |
| Reg No:            | <b>MT15MBO</b>                               | Registered: | <b>May 2015</b> | Type:                                                                               | <b>Estate</b>     | Trans:            | <b>Manual</b>       |
| Vin No:            | <b>WVGZZZ5NZFW106766</b>                     |             | MOT Exp:        |                                                                                     | R/H/F Tyre        | <b>6</b>          | R/H/R Tyre <b>6</b> |
| Mods:              | <b>Not Seen</b>                              | Cond:       | <b>Good</b>     | R/H/F Belt                                                                          | <b>Not Tested</b> | R/H/R Belt        | <b>Not Tested</b>   |
| Audio:             | <b>Not Seen</b>                              | Manfd:      | <b>2015</b>     |  |                   | Spare Tyre        |                     |
| Brakes:            | <b>Not Known</b>                             | Tax Exp:    |                 |                                                                                     |                   | <b>Not Know</b>   |                     |
| Steering:          | <b>Not Known</b>                             | Fuel:       | <b>Diesel</b>   |                                                                                     |                   | Centre Belt       |                     |
| Extras:            | <b>Not Seen</b>                              | C.C.:       | <b>1968</b>     |                                                                                     |                   | <b>Not Tested</b> |                     |
| Air Bags Deployed: | <b>Not Known</b>                             | BHP:        | <b>138.</b>     | L/H/F Belt                                                                          | <b>Not Tested</b> | L/H/R Belt        | <b>Not Tested</b>   |
| Damage:            | <b>Moderate Collision/Impact Rear Bumper</b> |             | Incident:       | <b>18/05/2026</b>                                                                   | L/H/F Tyre        | <b>6</b>          | L/H/R Tyre <b>6</b> |

|                |                  |              |                          |                 |             |           |
|----------------|------------------|--------------|--------------------------|-----------------|-------------|-----------|
| Vehicle Value: | <b>£7,757.00</b> | Repair Cost: | <b>£3,368.09 inc VAT</b> | (43.42% of PAV) | Roadworthy: | <b>No</b> |
|----------------|------------------|--------------|--------------------------|-----------------|-------------|-----------|

**DESKTOP ASSESSMENT**

This report has been compiled from a desktop review of the information available relating to this claim.

**NATURE OF INCIDENT**

The vehicle has suffered moderate collision/impact damage to the rear bumper.

**VEHICLE HISTORY CHECK**

02/06/2026 - According to the Experian database; According to the Experian database; There is a plate change on record. See plate change details.

**REPAIR SCHEDULE**

**New parts required:-**Rear Panel, Rear Trim, Rear Bumper Spoiler, Rear Bumper Support, Sundry Parts

**Repairable parts:-**Rear Bumper

**Repaint only parts:-**Basecoat Clear, Rear Bumper Spoiler New Part Paint K1r, Rear Bumper Repair Paint Plastic, Machine Polish, Preparation For Pre-Painting

**Specialist/Sundry charges:-**Bs10125 Compliance, Panel Rep Sundries, Adas Methods, Tech Data + Methods, E.P.A. Charge, Car Care Kit

**Remove And Refit parts:-**Description, Renew Spoiler Bracket (Add/Work), Rear Crossmember, Rear Bumper



Cover, Rear Lower Bumper Spoiler, Renew Lower Rear Bumper Spoiler, Rear Number Plate, Final Inspect And Road Test

**Parts to check:-**L/R Inner Sensor, R/R Inner Sensor, Wash & Vac, Veh Diag Pre, Veh Diag Post, Est Pre Wash, Adas Exploration

### **COST OF REPAIRS**

The repairers, Ceejay Autoworx (Tel. 01633 421068), have compiled an estimate in the sum of £1,199.23 plus parts at manufacturer's list prices plus £622.60 for paint and materials plus £172.64 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 14.4 hours at a rate of £83.28 per hour. We have also agreed that the cost of paint and materials will be limited to £622.60. The cost of the necessary replacement parts will be approximately £812.27, the specialist/sundry charges will be £172.64, the VAT liability on this repair will amount to some £561.35 giving a total repair cost of £3,368.09 including VAT **subject to any undisclosed damage.**

### **PRE-INCIDENT CONDITION**

The vehicle is considered to be in good condition for its age and type.

### **PRE-INCIDENT VALUE**

According to the information available to us the vehicle was first registered in 15/05/2015. The corresponding Cazana Guide (model code: 8403) adjusted retail value for vehicles of this type and age in the May 2026 guide is £7,757.00 at 100746 Miles, trade value is £6,128.00 and mid value is £6,942.50. We place the pre-accident value of this particular vehicle at £7,757.00 bearing in mind the condition described herein.

### **OWNER'S CONTRIBUTION**

We do not consider that any betterment contribution is required on this occasion.

### **RESERVE**

We consider that a repair reserve of £3,375.00 would be reasonable on this occasion.

### **INSTRUCTIONS ISSUED**

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 2nd June 2026, on your behalf.

### **REPAIR DURATION**

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

### **ROADWORTHY STATE**

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to bumper parts adrift.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jeff Parr CAE AMIMI  
Exclusive Vehicle Assessors