

Exclusive Repair Network
St. George's House, 56 Peter Street
Manchester, M2 3NQ
Phone Number(s):0333 358 3532
Email Address:info@exclusive-assessors.co.uk

Invoice

Claim Reference: EHR102814

Created: 30/06/2026

Vehicle reg : MJ73 XTB

Calculation

30/06/2026

Labour	Total Panel/Mechanical	£1,615.63
	Total Paintwork	£1,360.80
Total Labour		£2,976.43
Total Paint/Materials Costs		£1,605.55
Total Parts		£801.20
Total Additional Costs		£642.36
Overall Discount		£0.00
Repair Grand Total Excl VAT		£6,025.54
Grand Total Excl VAT		£6,025.54
VAT		£1,205.11
Grand Total Incl VAT		£7,230.65
Total Due		£7,230.65

Repair Information

LABOUR

Time Basis 10 WU=1 HR.

Repair / Guide

Number	Description	Work Units
NO NUMBER	R + R L/WING TRIM	1.0
NO NUMBER	R + R R/WING TRIM	1.0
66 76 19 50	R + R LEFT REAR WHEELHOUSE SHELL	2.0
66 76 19 50	R + R RIGHT REAR WHEELHOUSE SHELL	2.0
53 55 65 00)	REMOVE AND REFIT L/SIDE PANEL PARTS	1.0
	(FOR OUTER PAINTING)	
	NOT INCLUDED: BUMPER COVER	
	AND REAR LAMPS REMOVE AND REFIT	
53 55 65 00)	REMOVE AND REFIT L/SIDE PANEL PARTS	1.0
	(FOR OUTER PAINTING)	
	NOT INCLUDED: BUMPER COVER,	

Exclusive Repair Network
St. George's House, 56 Peter Street
Manchester, M2 3NQ
Phone Number(s):0333 358 3532
Email Address:info@exclusive-assessors.co.uk

Claim Reference: EHR102814

Invoice
Created: 30/06/2026

	REAR LAMPS AND FUEL FLAP REMOVE AND REFIT		
66 50 55 07	RENEW TYPE BADGE		3.0
55 57 19 50	R + R TAILGATE HANDLE		1.0
70 92 19 00	R + R TAILGATE TRIM		2.0
94 31 20 00	R + R BOTH REAR LAMPS		2.0
63 69 19 50	R + R REAR BUMPER		3.0
63 69 55 52	RENEW REAR BUMPER COVER (REMOVED)		6.0
	INCLUDES: BUMPER SPOILER, LIGHT NUMBER PLATE, BOTH REAR REFLECTOR, NO PLATE BRACKET, PARK ASSIST SENSORS AND WIRING HARNESS REMOVE AND REFIT		
64 75 19 00	R + R L/SIDE WINDOW		11.0
64 75 19 00	R + R R/SIDE WINDOW		11.0
63 69 43 50	REAR BUMPER DRILL CAVITY (ASSEMBLY OPERATION) (3 DRILL HOLES)		3.0
55 37 19 00	R + R FUEL FLAP		2.0
44 05 20 00	R + R REAR WHEEL (WHEELS)		3.0
0737	REMOVE&REFIT AERIAL TELESCOPE		1.0
2938	REPAIR LOWER TAILGATE		60.0
1000	REPAIR PANEL REPAIR SYSTEM		10.0
2640	CHECK REAR BUMPER SUPPORT		
3282	CHECK R/R LAMP		
3572	CHECK R/R LAMP PANEL		
1000	CHECK ADAS IIR		5.0
1000	CHECK WASH AND VAC		10.0
1000	CHECK VEHICLE SHUTDOWN		10.0
1000	CHECK PRE CLEAN		5.0
1000	CHECK AND ROAD TEST		5.0
1000	CHECK AND QUALITY CONTROL		5.0
1000	PRE & POST SYSTEM DIAGNOSTICS		20.0
1000	CHECK ADAS ROADTEST		5.0
1000	CORR. PROT. EXT. TO 1ST PANEL		3.0
Total Work Units			194.0

PAINT WORK

Time Basis 10 WU=1 HR.

Repair / Guide

Number	Description	Work Units
2583	REAR BUMPER NEW PART PAINT K1R	15.0

Exclusive Repair Network
St. George's House, 56 Peter Street
Manchester, M2 3NQ
Phone Number(s):0333 358 3532
Email Address:info@exclusive-assessors.co.uk

Invoice

Claim Reference: EHR102814

Created: 30/06/2026

2938	LOWER TAILGATE REPAIR PAINTING <50%	14.8
2115	LEFT SILL PANEL CPL SURFACE PAINT	7.4
2116	RIGHT SILL PANEL CPLSURFACE PAINT	7.4
2263	L/OUT/UPP A-PILLAR SURFACE PAINT	6.0
2264	R/OUT/UPP A-PILLAR SURFACE PAINT	6.0
2367	L/OUTER ROOF FRAME SURFACE PAINT	7.2
2368	R/OUTER ROOF FRAME SURFACE PAINT	7.2
3481	L/R SIDE PANEL SURFACE PAINT	8.9
3482	R/R SIDE PANEL SURFACE PAINT	8.9
4080	FUEL FILLER FLAP SURFACE PAINT PLAST.	4.6
1000	MASK REAR SCREEN SURFACE PAINT	5.0
1000	MASK FRONT SCREEN X2SURFACE PAINT	10.0
1000	MASK ROOF APERTUREX2SURFACE PAINT	8.0
1000	DE NIB & POLISH SURFACE PAINT	12.0
	PREPARATION FOR PRE-PAINTING	35.0
Total Work Units		163.4

PARTS

Guide No.	Description	Part Number	Bet.	Price
2583	REAR BUMPER	6F0807421H GRU	0%	£330.00
2605	REAR BUMPER SPOILER	6F0807568J	0%	£74.44
2787	L/R SENSOR BRACKET	6F0919486	0%	£14.15
2788	R/R SENSOR BRACKET	6F0919486A	0%	£19.45
2789	RR CTR SENSOR BRKT	6F0919486B	0%	£22.00
2799	PRIMER	D 822150A1	0%	£2.08
3020	BADGE MODEL	6F0853687 3Q7	0%	£28.25
3815	CUTTING FILAMENT	357853999B	0%	£28.82
3861	L/S WINDOW BOND KIT	D 004660M4	0%	£88.40
3862	R/S WINDOW BOND KIT	D 004660M4	0%	£88.40
3866	CLEANING SOLUTION	D 00940104	0%	£13.86
3867	L/R S-WINDOW PRIMER	D 00920002	0%	£17.14
3868	R/R S-WINDOW PRIMER	D 00920002	0%	£17.14
3869	L/SIDE WDW ACTIVATOR	D 181802M1	0%	£14.99
3870	R/SIDE WDW ACTIVATOR	D 181802M1	0%	£14.99

Sub Total		£774.11
Deduction from RRP	(0.00 %)	£0.00
Sundry Parts	(3.5%)	£27.09
Total Parts		£801.20

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Exclusive Repair Network
St. George's House, 56 Peter Street
Manchester, M2 3NQ
Phone Number(s):0333 358 3532
Email Address:info@exclusive-assessors.co.uk

Invoice

Claim Reference: EHR102814

Created: 30/06/2026

EXTRAS

Description	Bet.	Price
Corrosion protection		£12.00
Bs10125 Compliance		£34.00
Glass Lifting Tape		£12.00
Aries Compliance		£21.00
Panel Sundries		£21.00
Adas Methods		£31.00
Wheel Alignment		£112.42
E.P.A. Charge		£31.23
Tech Data + Methods		£45.00
Car Care Kit		£10.41
Adas Reset		£312.30
Total Extras		£642.36
