




Date: 15/06/2026

Our Ref: 00034778

Claimant: Mr Thomas McGinley

Vehicle: FORD GALAXY ZETEC TDCI 6G

Registration: PX07ZSU

Qty	Description	Type	Labour	Paint	Litres	Mat Price	Anti-C	A/C Price	Price
1	Rear Bumper Lining Lower	New	1.00						£167.34
1	Left Rear Bumper Inner Side Distance-S	New							£44.84
1	Left R. Bumper Inner Distance-Sensor B	New							£6.87
1	Left Reflector	New							£9.75
1	Boot Lid/Tailgate Cover	Repair	1.00						
1	Tailgate Strip & Set-Up for Paint	R & R	2.30						
1	.Assessment Damage Appraisal Charge	Specialist							£176.96
1	.Environmental Charge	Specialist							£31.23
1	.Pre repair cleaning charge	Specialist	0.50						
1	.QC & Road Test	Specialist	1.00						
1	.Standard shutdown	Specialist	1.00						
1	.Sundries	Specialist							£20.00
1	.System Diagnostic Check (Post Repair)	Specialist	1.00						
1	.System Diagnostic Check (Pre Repair)	Specialist	1.00						
1	.Vehicle Care Kit	Specialist							£10.41
1	.Wash/Clean	Specialist	1.00						
1	De-nib	Specialist	0.30						
1	Panel repair sundries (including body fi	Specialist							£26.02
1	.Yard Charge	Specialist	1.00						
1	Tailgate Cover, Lower	Paint		0.50		£78.40			
1	Left Rear Bumper Distance-Sensor	Paint		0.10		£1.08			
1	Prep. synthetics (on vehicle without pre	Paint		0.70		£114.68			
1	Colour mixing (1)	Paint		0.30					
1	Sample colour creation (1)	Paint		0.30		£11.06			

New	Repair	Paint	R & R	Blend	Specialist	Check	Total Hours
1.00	1.00	1.90	2.30		6.80		13.00

Labour Rate	Labour Disc	Material Dis	Parts Dis	Labour	Materials	Parts	Other
£30.81	0.00%	0.00%	0.00%	£400.53	£205.22	£228.80	£264.62

Labour Discount	Materials Discount	Parts Discount	Other Discounts
£0.00	£0.00	£0.00	£0.00

Total Disc	£0.00
Nett	£1,099.17
Vat	£219.83
Gross	£1,319.00



Document produced
using the EVA system

www.CollisionEngineers.co.uk