

New inspection request for Collision Engineers (51030)

09 Jul 2024

AX Reference : **928287**
Inspection &
Report Due on : **11/07/2024**

Engineer Instructions

Verbal authority to be provided on the day of inspection. If this cannot be done for any reason, please contact the Credit Repair team on 01675 432266 or by email on CreditRepair_TeamInbox@ax-uk.com

Client Details

Name: **Mr Mustafa Yagoub**
VRM: **YS69NRU**
Vehicle: **TOYOTA PRIUS PLUS EXCEL TSS HEV**
Accident Date: **26 Jun 2024**
Postcode: **G20 9AH**
VAT Registered: **No**
Fault Insurer: **ADMIRAL INSURANCE**

Repair Notes: **Rear DS Wing/ Bumper Damaged - Dented/Scuffed.**
Accident Circumstances: **Our CL was in the Bus Lane, TP in RH lane, to change into Bus Lane, TP changed lanes and made impact on rear D.S Wing. TP refused to exchange details - Liability disputed.**

Bodyshop Details

Name: **Undentit Ltd**
Address: **15-17 Scotland Street**

Glasgow
Postcode: **G5 8NB**
Telephone: **07402749141**

Third Party Details

VRM: **SH19 HWN**
Make/Model: **RENAULT/TRAFFIC LL29 SPORT NAV DCI**