

Collision Engineers Ltd
77-79 Hoylake Road
Moreton
Wirral
CH49 6LH

Our Ref: JW/CS/14362/1

Date: 23 August 2022

Dear Sirs

Our Client: Mr James McNeil
Our Client's Vehicle: VOLKSWAGEN GOLF GTD
Registration: H8JTM
Date of Accident: 18 August 2022

ENGINEER NOTIFICATION

CLIENT DETAILS

Mr James McNeil
17 Nevis Road
Bearsden
Glasgow
G61 4EJ

Vehicle Details

Client's Vehicle:	VOLKSWAGEN	GOLF
	GTD	
Vehicle Registration:	H8JTM	
Accident Date:	18/08/2022	

Home Tel:
Work Tel:
Mobile: 07425257489

REPAIRER DETAILS

Hatties Auto Body Repairs
Unit 3E Monklands Industrial Estate
Kirkshaws Road
Coatbridge
ML5 4RP
Tel: 01236 898181
Fax:
Email: office@hattiesautobody.com
Engineer to Estimate: Unknown

We would be obliged if you could contact the repairing garage and/or the client as appropriate and agree figures with the repairer – **do not authorise repairs**. Please do not agree a contract repair in excess of 80% of the vehicle value. All contract repairs must be fully itemised.

Please confirm if the vehicle is un-roadworthy and/or illegal to drive.

Vehicle Status – Undriveable

Please could you check the damage for consistency with the following accident circumstances?

Our client was stationary in the left lane on Switchback Road at the entrance of the Canniesburn Toll Roundabout in Bearsden waiting to take the first exit. This section of Switchback Road has two lanes with the first lane being a left only and the second is to proceed ahead. Your insured, behind our client, has failed to stop and collided with the rear of our client's vehicle. Details were exchanged at the scene.

Damage Area – Rear: Heavy - Rear boot dented and will not open - Rear lights smashed - Rear end smashed in

TP Vehicle: LAND ROVER RANGE ROVER SP S TDV6 A

TP Registration: WF07 KFT

TP Representative Name: Esure

If you need any further information please contact us on 0800 093 0982 selecting option 2.

Yours faithfully

QDOS Assistance

QDOS Assistance