

Collision Engineers Ltd
77-79 Hoylake Road
Moreton
Wirral
CH49 6LH

Our Ref: CJH/RS/14363/1

Date: 22 August 2022

Dear Sirs

Our Client: Mr Martin Robertson
Our Client's Vehicle: FORD FIESTA ST-3 TURBO
Registration: ST65VNK
Date of Accident: 18 August 2022

ENGINEER NOTIFICATION

CLIENT DETAILS

Mr Martin Robertson
181 Greenloanings
Kirkcaldy
KY2 6NW

Vehicle Details

Client's Vehicle: FORD FIESTA ST-3
TURBO
Vehicle Registration: ST65VNK
Accident Date: 18/08/2022

Home Tel:
Work Tel:
Mobile: 07873703815

REPAIRER DETAILS

Scott Gibson
Unit 12 Smeaton Industrial Estate
Hayfield Road
Kirkcaldy
Fife
KY1 2HE
Tel: 07974 373610
Fax:
Email: scottgibsonbodyshop@outlook.com
Engineer to Estimate Unknown

We would be obliged if you could contact the repairing garage and/or the client as appropriate and agree figures with the repairer – **do not authorise repairs**. Please do not agree a contract repair in excess of 80% of the vehicle value. All contract repairs must be fully itemised.

Please confirm if the vehicle is un-roadworthy and/or illegal to drive.

Vehicle Status – Undriveable

Please could you check the damage for consistency with the following accident circumstances?

Our client was driving on Blairmore Road for approximately 2 minutes, heading towards Glamis Road. Your insured has proceeded to turn right out of the Kilmun Road junction, intending to join Blairmore Road, failing to stop and colliding with our client's correctly proceeding vehicle, causing damage to offside rear panel. Details exchanged at scene where your client admitted liability.

Damage Area – Rear Offside: Heavy
off side rear panel is dented just after door
bodyshop have advised also damage to suspension
TP Vehicle: AUDI A6 SE TDI
TP Registration: SK61EVD
TP Representative Name: Axa PLI Motor Claims

If you need any further information please contact us on 0800 093 0982 selecting option 2.

Yours faithfully

QDOS Assistance

QDOS Assistance