

QDOS Assistance
1st Floor, Barfield House
24-28 alderley Road
Wilmslow
Cheshire
SK9 1PL

Date: 08/04/2026
Our Ref: 00033800/MATTG
Your Ref: 44464/1


To the Court REPAIRABLE REPORT

Dear Sirs,

Client: **Mr Ben Peppiatt**

T/Party: **Miss Grace Lawson**

We refer to your instructions received on **07 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: SKODA FABIA COLOUR EDITION TSI		Colour: BLACK	Speedo:	Miles:
Reg No: KY69KJV	Registered: Sep 2019	Type: 5 Door Hatchback	Trans: Manual	
Vin No: TMBFP6NJ7LZ021907	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manfd: 2019			Spare Tyre
Brakes: Not Known	Tax Exp:			Not Know
Steering: Not Known	Fuel: Petrol			Centre Belt
Extras: Not Seen	C.C.: 999			Not Tested
Air Bags Deployed: Not Known	BHP: 93.9	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Damage: Moderate Collision/Impact RH Front Complete Vehicle	Incident: 02/04/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Vehicle Value: £9,037.00		Repair Cost: £3,541.02 inc VAT	(39.18% of PAV) Roadworthy: No	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand front complete vehicle.

ENGINEER'S COMMENTS

The engineer has inspected this vehicle from images supplied by the principal only, the repair costs have been based on the images received and therefore may not be accurate if further damage is found, condition details and service records have not been checked in relation to the pre-accident value.

The valuation for the purpose of this report has been calculated using an estimated mileage from the vehicles MOT history at the time of loss.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE



New parts required:-Front Bumper Cover, R/Headlamp Cpl, Panel Sundries, Car Care Kit, Glass Lifting Tape, Sundry Parts

Repaint only parts:-Front Bumper Cover New Part Paint K1r, De Nib & Polish. Per Panel, Preparation For Pre-Painting

Specialist/Sundry charges:-Bsi Compliance, Adas Methods, Geometry Check, Epa, Corrosion Protection Materials External

Blend only parts:-Bonnet Surface Paint, R/F Wing Surface Paint

Remove And Refit parts:-Description, Front Bumper Cover, Renew Front Bumper Cover, Right Headlamp, Renew R/F Headlamp (Removed), Adjust Headlamps, Right Front Wing, Corrosion Prote To 1St Panel

Parts to check:-R/F Fog Lamp, Adas Exploration, Qc & Road Test, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vacuum, Est Pre Wash

COST OF REPAIRS

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair using Audatex and we consider that a reasonable labour charge would be £1,254.59. The cost of the paint and materials would be £866.33, The cost of the replacement parts would be approximately £591.03, The specialist/sundry charges would be £238.90, and the VAT liability on the total would amount to some £590.17 giving a total repair cost of £3,541.02 including VAT **subject to undisclosed damage**. The labour charge is based on 13.1 hours at a rate of £95.77 per hour.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 19/09/2019. The corresponding Percayso Guide (model code: 3159992) adjusted retail value for vehicles of this type and age in the April 2026 guide is £9,037.00 at 50800 Miles, trade value is £8,133.00 and mid value is £8,585.00. We place the pre-accident value of this particular vehicle at £9,037.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £3,550.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We confirm that we have not authorised repairs on your behalf and our actions in this matter remain without prejudice.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to sharp edges, broken headlight. We understand that the vehicle is not currently being used by the owner.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. QDOS Assistance commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

 .

Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors



Clientvehicledamages-V1.jpeg



2_Clientandthirdpartyvehicles-V1.jpeg