

Our Ref: qdos221406

Your Ref: CJH/RS/14363/1

Date: 24/08/2022

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

REPAIRABLE REPORT

Dear Sirs



RE: Road traffic Accident: Martin Robertson: 18/08/2022

In accordance with your instructions received on 22/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 24/08/2022. Vehicle located at Image Based Assessment. Our findings are as detailed below:


Make	FORD	Registration	ST65VNK
Model	FIESTA ST-3 TURBO	Status	Repair
Category		Salvage Value	
Repair Cost	£6,277.46	Legal Status	Unroadworthy
Engineer Value	£10,680.00	Impact Magnitude	Moderate



Impact Area



Document produced
using the EVA system



Our Ref: qdos221406

Your Ref: CJH/RS/14363/1

Date: 24/08/2022

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand side.

ENGINEER'S COMMENTS

24/08/2022 - Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the offside.

VEHICLE HISTORY CHECK

24/08/2022 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £6,300.00 would be reasonable on this occasion.


Vehicle Data

Retail Value	£10,680.00
Trade Value	£9,300.00
Engineer's Value	£10,680.00
Glass's Code	JFNQ
VIN	WF0CXXGAKCFU30545
Odometer	45000
Engine	1596
Fuel	Petrol
Extras	
Condition	Good
Unrelated Damage	

Main new parts required

Right Front Door Window Outer Channel Strip
Right Rear Bumper Side Bracket
Right Rear Side Panel Bonding Kit
Right Side Glass Repair/Bonding Kit
Right Side Panel Liner

Right Sill Panel Cover (Plastic)
Right Rear Side Panel, Complete
Right Rear Side Panel Adhesive Foil
Right Side Panel Foam



Our Ref: qdos221406

Your Ref: CJH/RS/14363/1

Date: 24/08/2022

Repairs required

Right Front Door Shell
Right Rear Wheelarch with Inner Side Panel

Rear Bumper Lining

Additional operations

Jig set up, clamp and pull
Repair Method Research Allowance
System Diagnostic Check (Pre Repair)
Car Care Kit
De-Nib/Polish
Final Inspection & Road Test
Wash/Clean
Paint Right Front Door Outer Handle
Paint Right Rear Side Panel, Complete
Paint Rear Bumper k/e
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

Corrosion Protection Materials
System Diagnostic Check (Post Repair)
Alloy Wheel Refurbish
Check and adjust four wheel alignment
Environmental Charge
Tyre
Paint Right Front Door, Complete
Paint Right Sill Panel Protective Moulding
Paint Tailgate Rear Spoiler
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

Repair Cost Calculations

Hours	38.00
Hourly Rate	£62.50
Total Labour	£2,375.00
Parts	£1,316.28
Paint/Materials	£1,019.94
Specialist/Other	£520.00
Sub total	£5,231.22
Vat	£1,046.24
Total Estimated Cost	£6,277.46