

Our Ref: htu26011

Your Ref: YP15 OKF

Date: 16/02/2026

FAO The Court
C/O HTU Assessors Ltd
The Old Courthouse
18-22 St Peters Churchyard
Derby
DE1 1NN

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Ali Nasser Hashem Hassan : 06/02/2026

In accordance with your instructions received on 13/02/2026 requesting us to provide an independent accident damage report, we assessed the damage on 16/02/2026. Vehicle located at ITV Solutions, Cotton Brook Road, Derby, Derbyshire, DE23 8YJ. Our findings are as detailed below:


Make	SEAT	Registration	YP15OKF
Model	IBIZA FR TSI S-A	Status	T/Loss
Category	N	Salvage Value	£944.80
Repair Cost	£3,972.32	Legal Status	Unroadworthy
Engineer Value	£4,724.00	Impact Magnitude	Moderate



Impact Area



Document produced
using the EVA system



Our Ref: htu26011

Your Ref: YP15 OKF

Date: 16/02/2026

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the rear.

ENGINEER'S COMMENTS

20% has been deducted from the pre accident valuation due to the vehicle being a previous total loss.

Please note the vehicle is unroadworthy as the rear bumper trim is insecure and reg plate is damaged.

VEHICLE HISTORY CHECK

According to the Experian database; Category S total loss claim Structural Damage See the Condition details An entry exists on the MIAFTR register to this effect dated 13/03/2023, loss dated 03/03/2023

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £3,779.20 which represents the pre-accident engineer value of the vehicle of £4,724.00 less the value of the salvage of £944.80.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £944.80. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£5,906.00
Trade Value	£5,256.00
Engineer's Value	£4,724.00
Glass's Code	H7DG
VIN	VSSZZZ6JZFR118919
Odometer	67730
Engine	1197
Fuel	Petrol
Extras	
Condition	Good
Unrelated Damage	



Our Ref: htu26011

Your Ref: YP15 OKF

Date: 16/02/2026

Main new parts required

Rear Bumper Lining
Rear Bumper Reinforcement
Left Rear Bumper Outer Bracket
Left Rear Bumper Inner Bracket
Rear Bumper Repair Kit
Rear Bumper Lining Screw
B/Lid/Back Door/T/gate Type Designation
tailgate decal

Rear Bumper Spoiler
Rear Bumper Bracket
Right Rear Bumper Outer Bracket
Right Rear Bumper Inner Bracket
Rear Bumper Lining Clip
Rear bumper lining Nut
Right Side Emblem (Optional Equipment)


Repairs required

Tailgate

Additional operations

number plate holder
.Environmental Charge
.QC & Road Test
.Sundries
.System Diagnostic Check (Pre Repair)
.Wash/Clean
Check rear panel
Load / Unload vehicle to ramp
Older vehicle allowance
Second man lift
Paint Rear Bumper k/e
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

.Assessment Damage Appraisal Charge
.Pre repair cleaning charge
.Standard shutdown
.System Diagnostic Check (Post Repair)
.Vehicle Care Kit
check exhaust
Corrosion Protection
Number Plate
Polish
Paint Tailgate (with Window Frame)
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)



Our Ref: htu26011


Your Ref: YP15 OKF

Date: 16/02/2026

Repair Cost Calculations

Hours	19.50
Hourly Rate	£83.28
Total Labour	£1,623.96
Parts	£760.76
Paint/Materials	£625.32
Specialist/Other	£300.23
Sub total	£3,310.27
Vat	£662.05
Total Estimated Cost	£3,972.32






Our Ref: htU26011

Your Ref: YP15 OKF

Date: 16/02/2026






Our Ref: htu26011

Your Ref: YP15 OKF

Date: 16/02/2026






Our Ref: htu26011

Your Ref: YP15 OKF

Date: 16/02/2026






Our Ref: htu26011

Your Ref: YP15 OKF

Date: 16/02/2026






Our Ref: htu26011

Your Ref: YP15 OKF

Date: 16/02/2026






Our Ref: ht26011

Your Ref: YP15 OKF

Date: 16/02/2026






Our Ref: htu26011

Your Ref: YP15 OKF

Date: 16/02/2026






Our Ref: ht26011

Your Ref: YP15 OKF

Date: 16/02/2026







Our Ref: htu26011

Your Ref: YP15 OKF

Date: 16/02/2026





Our Ref: htu26011

Your Ref: YP15 OKF

Date: 16/02/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk