

Our Ref: qdos221401

Your Ref: JW//14218/1

Date: 24/08/2022

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

CONTRACT REPAIR REPORT

Dear Sirs


RE: Road traffic Accident: Dr Sarah Daley: 20/07/2022


In accordance with your instructions received on 24/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 24/08/2022. Vehicle located at Image based assessment. Our findings are as detailed below:

Make	VOLKSWAGEN	Registration	GD08ARZ
Model	EOS SPORT T FSI	Status	Repair
Category		Salvage Value	
Repair Cost	£2,858.89	Legal Status	Roadworthy
Engineer Value	£3,650.00	Impact Magnitude	Moderate



Impact Area





Our Ref: qdos221401

Your Ref: JW//14218/1

Date: 24/08/2022

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand front.

ENGINEER'S COMMENTS

Mileage calculated from MOT history

24/08/2022 - Vehicle is unroadworthy due to the damaged/insecure front bumper.

Repairs agreed on a contract basis and costs must not increase.

VEHICLE HISTORY CHECK

24/08/2022 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

CONTRACT REPAIR

To ensure no further repair costs are found we have agreed a contract repair figure with the repairers in the sum total of £2,858.89 which is inclusive of VAT but subject to the deduction of any applicable excess.

RESERVE

We consider that a repair reserve of £2,875.00 would be reasonable on this occasion.


Vehicle Data

Retail Value	£3,650.00
Trade Value	£2,220.00
Engineer's Value	£3,650.00
Glass's Code	7LJ9
VIN	WVWZZZ1FZ9V002955
Odometer	79500
Engine	1984
Fuel	Petrol
Extras	
Condition	Good
Unrelated Damage	

Main new parts required

Front Bumper
Front Bumper Beam

Os Headlamp
Sundries/clips/fixings



Our Ref: qdos221401

Your Ref: JW//14218/1

Date: 24/08/2022

Repairs required

Os Wing


Additional operations

epa Charges
Covid Clean
System Diagnostic Check (Pre Repair)
Energy Surcharge

car Care Kit
system Diagnostic Check (Post Repair)
methods Research
colour Blends

Repair Cost Calculations

Hours	15.12
Hourly Rate	£62.50
Total Labour	£945.00
Parts	£812.76
Paint/Materials	£371.65
Specialist/Other	£253.00
Sub total	£2,382.41
Vat	£476.48
Total Estimated Cost	£2,858.89




Vinnumbering V1.jpg



Clientsvehicleimage5jpeg-V1.jpeg



Clientsvehicleimage4jpeg-V1(1).jpeg




Clientsvehicleimage3jpeg-V1(1).jpeg



Clientsvehicleimage2jpeg-V1.jpeg



Clientsvehicleimage1jpeg-V1.jpeg



Our Ref: qdos221401

Your Ref: JW//14218/1

Date: 24/08/2022

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: qdos221401

Your Ref: JW//14218/1

Date: 24/08/2022

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

Fee Note

GD08ARZ.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference qdos221401.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10