

Our Ref: qdos24912

Your Ref: JMO//28590/1

Date: 28/06/2024

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

CONTRACT REPAIR REPORT

Dear Sirs


RE: Road traffic Accident: Mr David Guildford: 01/06/2024


In accordance with your instructions received on 28/06/2024 requesting us to provide an independent accident damage report, we assessed the damage on 28/06/2024. Vehicle located at Image Based Assessment. Our findings are as detailed below:

Make	JAGUAR	Registration	S500MSK
Model	XJ PORTFOLIO V8 AUT	Status	Repair
Category		Salvage Value	
Repair Cost	£7,798.91	Legal Status	Unroadworthy
Engineer Value	£10,000.00	Impact Magnitude	Moderate



Impact Area





Our Ref: qdos24912
Your Ref: JMO//28590/1

Date: 28/06/2024

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand front.

ENGINEER'S COMMENTS

Please note the mileage has been calculated from online MOT data.

Valuation is based on market research.

This is a contract repair, costs must not increase.

28/06/2024 - Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the nearside front.

02/07/2024 - UPDATED REPORT: - The vehicle owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £10,000.00

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION


The vehicle is considered to be in good condition for its age and type.

CONTRACT REPAIR

To ensure no further repair costs are found we have agreed a contract repair figure with the repairers in the sum total of £7,798.91 which is inclusive of VAT but subject to the deduction of any applicable excess.

Vehicle Data

Retail Value	
Trade Value	
Engineer's Value	£10,000.00
Glass's Code	
VIN	SAJAC16P8ALV07140
Odometer	93100
Engine	5000
Fuel	Petrol
Extras	
Condition	Good
Unrelated Damage	



Our Ref: qdos24912

Your Ref: JMO//28590/1

Date: 28/06/2024

Main new parts required

Front Bumper Lining
Front Bumper Repair kit
Front Bumper Lining Screw
Left LED Headlamp, Complete (with Indicator)
Left Front Wing Bracket (Front)
Left Front Wing Cover
Left Front Wing Foam
Left Front Wing Panel Nut
Front Panel, Upper
Left Front Wheel (Aluminium)

Left Front Bumper Side Support
Front Bumper Lining Clip
Front Bumper Lining Nut
Left Front Wing
Left Front Wing Repair Kit
Left Front Wing Liner
Left Front Wing Panel Screw
Bonnet Sealing Frame
Left Front Door Membrane


Additional operations

De-nib/ polish
Environmental Charge
NSF tyre
QC & Road Test
Standard shutdown
System Diagnostic Check (Pre Repair)
Wash/Clean
Paint Front Bumper
Paint Left Front Wing, Complete
Paint Bonnet
Paint Left Front Door, Complete
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)
Set-up time

Energy cost supplement
Estimate/Assessment Charge
PPE equipment
Research Methods
System Diagnostic Check (Post Repair)
Vehicle Care Kit
Wheel Alignment (4 wheel)
Paint Front Inner Panel, Upper, Complete
Paint Right Front Wing, Complete
Paint Left A-Post, Upper
Paint Left Front Door Outer Handle
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

Repair Cost Calculations

Hours	18.60
Hourly Rate	£80.00
Total Labour	£1,488.00
Parts	£3,579.77
Paint/Materials	£1,008.32
Specialist/Other	£423.00
Sub total	£6,499.09
Vat	£1,299.82
Total Estimated Cost	£7,798.91



Our Ref: qdos24912
Your Ref: JMO//28590/1

Date: 28/06/2024

