

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Mr Neil Hanna: 05/04/2026


In accordance with your instructions received on 07/04/2026 requesting us to provide an independent accident damage report, we assessed the damage on 07/04/2026. Vehicle located at Image Based Assessment. Our findings are as detailed below:

Make	FORD	Registration	YE600JZ
Model	FOCUS TITANIUM TDC	Status	T/Loss
Category	B	Salvage Value	£43.00
Repair Cost	£9,330.19	Legal Status	Unroadworthy
Engineer Value	£2,150.00	Impact Magnitude	Heavy



Impact Area





Our Ref: ap.qdos26931

Your Ref: SCL/JMO/44502/1

Date: 07/04/2026

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered heavy collision/impact damage to the right hand front.

ENGINEER'S COMMENTS

The mileage has been calculated from online MOT data.

The valuation is based on market research.

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the offside front.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.


SETTLEMENT

We consider that an equitable settlement would be £2,107.00 which represents the pre-accident engineer value of the vehicle of £2,150.00 less the value of the salvage of £43.00.

SALVAGE

We consider that this is Category B (break for spares only and in-line with the ABI salvage code of practice)

This vehicle is damaged beyond any form of economical repair, therefore in our Engineers professional opinion it should not be returned to the road and a certificate of destruction should be completed / issued We suggest that the sale of the salvage will realise in the order of £43.00. **We have not taken any action towards removal of the salvage at this time.**



Our Ref: ap.qdos26931

Your Ref: SCL/JMO/44502/1

Date: 07/04/2026


Vehicle Data

Retail Value	£2,150.00
Trade Value	
Engineer's Value	£2,150.00
Glass's Code	CBB9
VIN	WF0SXXGCD SAR45392
Odometer	102999
Engine	1560
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	

Main new parts required

Front Bumper Lining
 Front Bumper Reinforcement
 Front Bumper Moulding
 Front Bumper Air Guide
 Front Bumper Lower Air Guide
 Front Bumper Lining Screw
 Left Headlamp, Complete (with Indicator)
 Headlamp, Complete (w/Indicator, Both)
 Right Headlamp Inner Bracket
 Right Front Fog Lamp Ring/Trim
 Right Front Wing
 Right Front Wing Repair Kit
 Right Front Wing Liner
 Right Front Wing Panel Screw
 Front Grille
 Front Grille Moulding
 Bonnet Insulation
 Right Bonnet Buffer
 Bonnet Latch
 Right One Front Wing and Front Panel
 Right Flitch Support
 Right Front Door Trim Outer Seal
 Right Front Steering Knuckle
 Right Front Wheel (Aluminium)
 PDC outer

Front Bumper Impact Absorber/Filler
 Right Front Bumper Side Reinforcement
 Right Front Bumper Auxiliary Lamp Cover
 Right Front Bumper Air Guide
 Front Bumper Repair kit
 Front Bumper Lining Nut
 Right Headlamp, Complete (with Indicator)
 Right Headlamp Outer Bracket
 Right Front Fog Lamp, Complete
 Right Front Fog Lamp Bracket
 Right One Front Wing and Front Bumper
 Right Front Wing Corner Moulding
 Right Front Wing Liner, Front
 Right Front Wing Panel Nut
 Front Grille Seal
 Front Grille Badge
 Left Bonnet Buffer
 Bonnet Stay Support Bracket
 Front Panel Assembly
 Engine Guard Panel
 Right Front Door Outer Handle Seal
 Right Front Suspension Lower Arm
 Right Front Wheel Hub with Bearing
 Radiator
 PDC inner



Our Ref: ap.qdos26931

Your Ref: SCL/JMO/44502/1

Date: 07/04/2026

Additional operations

.Assessment Damage Appraisal Charge

.Pre repair cleaning charge

.Standard shutdown

.System Diagnostic Check (Post Repair)

.Vehicle Care Kit

Jig, clamp and pull

Paint Front Inner Panel, Complete

Paint Bonnet

Paint Right Flitch Panel

Paint Right Front Door Outer Handle

Paint Prep. synthetics (combined-operation work)

Paint Sample colour creation (1)

.Environmental Charge

.QC & Road Test

.Sundries

.System Diagnostic Check (Pre Repair)

.Wash/Clean

OSF tyre

Paint Right Front Wing, Complete

Paint Right A-Post, Upper

Paint Right Front Door, Complete


Paint Prep. metal (on vehicle without pre-painting)


Paint Colour mixing (1)

Repair Cost Calculations

Hours	26.00
Hourly Rate	£83.28
Total Labour	£2,165.28
Parts	£4,286.07
Paint/Materials	£985.21
Specialist/Other	£338.60
Sub total	£7,775.16
Vat	£1,555.03
Total Estimated Cost	£9,330.19







Our Ref: ap.qdos26931

Your Ref: SCL/JMO/44502/1

Date: 07/04/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

N O'Reilly - ATA VDA

engineers@collisionengineers.co.uk



Our Ref: ap.qdos26931

Your Ref: SCL/JMO/44502/1

Date: 07/04/2026

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

Fee Note

YE600JZ.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference ap.qdos26931.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10