

**Date:** 18/06/2025

FAO. The Court  
C/o Davison Flynn Duke  
Chester Street  
Birkenhead  
CH41 5DL

### REPAIRABLE REPORT

Dear Sirs


**RE: Road traffic Accident: Mike Jones: 03/06/2025**


In accordance with your instructions received on 16/06/2025 requesting us to provide an independent accident damage report, we assessed the damage on 17/06/2025. Vehicle located at SMC Ltd, Tarren Way South, Moreton, CH464TP. Our findings are as detailed below:

|                |                             |                  |                     |
|----------------|-----------------------------|------------------|---------------------|
| Make           | <b>CITROEN</b>              | Registration     | <b>BX17KKB</b>      |
| Model          | <b>RELAY 40 H-Y L4H2 EP</b> | Status           | <b>Repair</b>       |
| Category       |                             | Salvage Value    |                     |
| Repair Cost    | <b>£6,452.46</b>            | Legal Status     | <b>Unroadworthy</b> |
| Engineer Value | <b>£10,750.00</b>           | Impact Magnitude | <b>Moderate</b>     |



Impact Area





**Our Ref:** dfd25114

**Your Ref:** RJP/81271

**Date:** 18/06/2025

### **NATURE OF INCIDENT**

The minibus has suffered moderate collision/impact damage to the left hand front.

### **ENGINEER'S COMMENTS**

18/06/2025 - Please note the minibus is unroadworthy / unfit for purpose due to the damage sustained. We do not expect the minibus to comply with the local licensing authority regulations.

19/6/2025 - UPDATED REPORT: - The minibus owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £10750.00

### **VEHICLE HISTORY CHECK**

We confirm having checked this minibus on the Experian AutoCheck database and there is no record of any adverse history.

### **PRE-INCIDENT CONDITION**

The minibus is considered to be in good condition for its age and type.

### **RESERVE**

We consider that a repair reserve of £6,475.00 would be reasonable on this occasion.

## **Vehicle Data**

|                  |                          |
|------------------|--------------------------|
| Retail Value     |                          |
| Trade Value      |                          |
| Engineer's Value | <b>£10,750.00</b>        |
| Glass's Code     |                          |
| VIN              | <b>VF7YE2MFC12E38463</b> |
| Odometer         | <b>87096</b>             |
| Engine           | <b>1997</b>              |
| Fuel             | <b>Diesel</b>            |
| Extras           |                          |
| Condition        | <b>Good</b>              |
| Unrelated Damage |                          |

### **Main new parts required**

LH BMPR Rubber

LH support

LH Bumper Rad

LH Mudflap F

Low FR pan

LH Bumper RA

Front Half Frame

Hog Ring (10@2.46)

Arch Lip Protect

Bumper bracket

Front bumper

LH WIng prot


Front wing

Arch Protect

NSF headlamp

LH Front wing

RH Protector



**Our Ref:** dfd25114

**Your Ref:** RJP/81271

**Date:** 18/06/2025

Repairs required

Inner wing

Additional operations

Anti Protection  
Car Care Kit  
Diagnostic check  
Estimate/Assessment Charge  
4 Wheel Align Geo Sublet  
Pre repair cleaning charge (including sa  
Sundries  
Front bumper brackets LH  
Paint NSF Door  
Check Check NSF wheel and tyre  
Wax Oil  
Headlamp aim align  
Final check

Bead Sealers  
PPE equipment  
Energy cost supplement  
EPA Charge  
Methods Research  
Spotweld drill bits  
Valeting Charges  
Paint Inner wing  
Paint NSF A Post  
Clamp And Pull  
Road test  
Denib

## Repair Cost Calculations

|                      |                  |
|----------------------|------------------|
| Hours                | <b>23.00</b>     |
| Hourly Rate          | <b>£80.00</b>    |
| Total Labour         | <b>£1,840.00</b> |
| Parts                | <b>£2,394.45</b> |
| Paint/Materials      | <b>£343.60</b>   |
| Specialist/Other     | <b>£799.00</b>   |
| Sub total            | <b>£5,377.05</b> |
| Vat                  | <b>£1,075.41</b> |
| Total Estimated Cost | <b>£6,452.46</b> |








































**Our Ref:** dfd25114

**Your Ref:** RJP/81271

**Date:** 18/06/2025

### Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA  
engineers@collisionengineers.co.uk



**Our Ref:** dfd25114

**Your Ref:** RJP/81271

**Date:** 18/06/2025

FAO. The Court  
C/o Davison Flynn Duke  
Chester Street  
Birkenhead  
CH41 5DL

### Fee Note

BX17KKB.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

**Agreed Fee: £180.00**

**Sub Total: £180.00**

**VAT: £36.00**

**Total Due: £216.00**

### Payment

Please make cheques payable to Collision Engineers and quote reference dfd25114.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o Davison Flynn Duke confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10