

QDOS Assistance  
1st Floor, Barfield House  
24-28 alderley Road  
Wilmslow  
Cheshire  
SK9 1PL

Date: 13/05/2026  
Our Ref: 00036223/MATTG  
Your Ref: 45099

## To the Court REPAIRABLE REPORT

Dear Sirs,

Client: **Mrs Joanne Bailey**

We refer to your instructions received on **13 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

|                                                                            |                             |                                                                                      |                              |                       |
|----------------------------------------------------------------------------|-----------------------------|--------------------------------------------------------------------------------------|------------------------------|-----------------------|
| Vehicle: <b>SEAT LEON FR ETSI S-A</b>                                      |                             | Colour: <b>GREY</b>                                                                  | Speedo: <b>7521</b>          | Miles                 |
| Reg No: <b>PK74YUJ</b>                                                     | Registered: <b>Feb 2025</b> | Type: <b>5 Door Hatchback</b>                                                        | Trans: <b>Semi-Auto</b>      |                       |
| Vin No: <b>VSSZZZKL9SR037733</b>                                           | MOT Exp:                    | R/H/F Tyre <b>Not Kno</b>                                                            | R/H/R Tyre <b>Not Kno</b>    |                       |
| Mods: <b>Not Seen</b>                                                      | Cond: <b>Good</b>           | R/H/F Belt <b>Not Tested</b>                                                         | R/H/R Belt <b>Not Tested</b> |                       |
| Audio: <b>Not Seen</b>                                                     | Manfd: <b>2025</b>          |  |                              | Spare Tyre            |
| Brakes: <b>Not Known</b>                                                   | Tax Exp:                    |                                                                                      |                              | <b>Not Known</b>      |
| Steering: <b>Not Known</b>                                                 | Fuel:                       |                                                                                      |                              | Centre Belt           |
| Extras: <b>Not Seen</b>                                                    | C.C.: <b>1498</b>           |                                                                                      |                              | <b>Not Tested</b>     |
| Air Bags Deployed: <b>Not Known</b>                                        | BHP: <b>147.</b>            | L/H/F Belt <b>Not Tested</b>                                                         | L/H/R Belt <b>Not Tested</b> |                       |
| Damage: <b>Light to Moderate Collision/Impact LH Rear Complete Vehicle</b> | Incident: <b>01/05/2026</b> | L/H/F Tyre <b>Not Kno</b>                                                            | L/H/R Tyre <b>Not Kno</b>    |                       |
| Vehicle Value: <b>£20,814.00</b>                                           |                             | Repair Cost: <b>£2,804.71 inc VAT</b>                                                | (13.48% of PAV)              | Roadworthy: <b>No</b> |

### DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

### NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the left hand rear complete vehicle.

### ENGINEER'S COMMENTS

The engineer has inspected this vehicle from images supplied by the principal only, the repair costs have been based on the images received and therefore may not be accurate if further damage is found, condition details and service records have not been checked in relation to the pre-accident value.

### VEHICLE HISTORY CHECK

13/05/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

### REPAIR SCHEDULE

**New parts required:-**L/R Tyre, Panel Sundries, Car Care Kit, Glass Lifting Tape, Sundry Parts

**Repairable parts:-**Rear Cover Bumper, L/R Side Panel Rear



**Repaint only parts:-**Two Coat Metallic, Rear Cover Bumper Repair Paint Plastic, L/R Side Panel Rear Repair Painting <50%, De Nib & Polish. Per Panel, Preparation For Pre-Painting

**Specialist/Sundry charges:-**Bsi Compliance, Adas Methods, Geometry Check, Epa, Corrosion Protection Materials External

**Remove And Refit parts:-**Description, Rear Wheel, Left Rear Wheelhouse Shell, Rear Bumper Cover, Rear Reflectors, Tyres (Wheel Removed) R + R (Add/Work), Renew Left Rear Wheel/Tyre, Corrosion Prote To 1St Panel

**Parts to check:-**L/R Wheel, Adas Exploration, Qc & Road Test, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vacuum, Est Pre Wash

### **COST OF REPAIRS**

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair using Audatex and we consider that a reasonable labour charge would be £1,449.07. The cost of the paint and materials would be £595.43, The cost of the replacement parts would be approximately £53.86, The specialist/sundry charges would be £238.90, and the VAT liability on the total would amount to some £467.45 giving a total repair cost of £2,804.71 including VAT **subject to undisclosed damage**. The labour charge is based on 17.4 hours at a rate of £83.28 per hour.

### **PRE-INCIDENT CONDITION**

The vehicle is considered to be in good condition for its age and type.

### **PRE-INCIDENT VALUE**

According to the information available to us the vehicle was first registered in 22/02/2025. The corresponding Cazana Guide (model code: 6882077) adjusted retail value for vehicles of this type and age in the May 2026 guide is £20,814.00 at 7521 Miles, trade value is £18,108.00 and mid value is £19,461.00. We place the pre-accident value of this particular vehicle at £20,814.00 bearing in mind the condition described herein.

### **OWNER'S CONTRIBUTION**

We do not consider that any betterment contribution is required on this occasion.

### **RESERVE**

We consider that a repair reserve of £2,825.00 would be reasonable on this occasion.

### **INSTRUCTIONS ISSUED**

We confirm that we have not authorised repairs on your behalf and our actions in this matter remain without prejudice.

### **REPAIR DURATION**

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

### **ROADWORTHY STATE**

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. QDOS Assistance commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jeff Parr CAE AMIMI  
Exclusive Vehicle Assessors



2\_CLVreg45099jpeg-V1.jpeg



3\_CLVvin45099jpeg-V1.jpeg



4\_CLVnearside45099jpeg-V1.jpeg



5\_CLVoffside45099jpeg-V1.jpeg



6\_CLVdamage45099jpeg-V1.jpeg



7\_CLVdamage245099jpeg-V1.jpeg



8\_CLVnearside245099jpeg-V1.jpeg



9\_CLVfrontoffside45099jpeg-V1.jpeg



10\_CLVrearnearside45099jpeg-V1.jpeg



CLVdashboard45099jpeg-V1.jpeg