

Mr Amar Shazad
32 The Crescent
Slough
Berkshire
SL
SLOUGH
Berkshire

Date: 17/12/2025

Our Ref: 00026734/NOELB


Your Ref: EHR93453 \ FJNCC0004893

To the Court REPAIRABLE REPORT

Dear Sirs,

Client: **Mr Amar Shazad**

We refer to your instructions received on **10 December 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: MERCEDES SL 280 AUTO		Colour: BLUE	Speedo: 60294 Miles
Reg No: P815UTM	Registered: Apr 1997	Type: Convertible	Trans: Automatic
Vin No: WDB1290582F152177	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Above Average	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 1997		Spare Tyre
Brakes: Not Known	Tax Exp:		Not Know
Steering: Not Known	Fuel: Petrol		Centre Belt
Extras: Not Seen	C.C.: 2799		Not Tested
Air Bags Deployed: Not Known	BHP: 190	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light to Moderate Collision/Impact Front	Incident: 03/12/2025	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £8,796.00		Repair Cost: £2,811.22 inc VAT (31.96% of PAV)	Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the front.

ENGINEER'S COMMENTS

This vehicle has a previous CAT-S total loss, 20% reduction on PAV to reflect this.

VEHICLE HISTORY CHECK

17/12/2025 - According to the Experian database; there is a plate change on record See the plate change details. Category S total loss claim Structural Damage See the Condition details An entry exists on the MIAFTR register to this effect dated 28/10/2021, loss dated 12/06/2019

REPAIR SCHEDULE

New parts required:-Labour, E.P.A. Charge, Sundries

COST OF REPAIRS

The repairers, Autoworks Bodyshop Ltd (Tel. 01628 676 822), have compiled an estimate in the sum of £1,910.70 plus parts at manufacturer's list prices plus £415.98 for paint and materials. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 19.3 hours at a rate of £99.00 per hour. We also consider that the cost of paint and materials should be limited to £415.98. The cost of the necessary



replacement parts will be approximately £16.00, the VAT liability on this repair will amount to some £468.54 giving a total repair cost of £2,811.22 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in above average condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 23/04/1997. There are no guide values for vehicles of this age and type. We place the pre-accident value of this particular vehicle at £8,796.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £2,825.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 17th December 2025, on your behalf.

REPAIR DURATION

We consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.** We understand that the vehicle is still being used by the owner.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions (ACHL) commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Noel Barnes Dip VDA AQP
Exclusive Vehicle Assessors