

Mr David Monaghan
6 The Ridgeway
Ruislip
Middlesex
HA4 8QS

Date: 16/03/2026
 Our Ref: 00031890/JAKER
 Your Ref: EHR97955

To the Court
REPAIRABLE REPORT - Supplementary Report

Dear Sirs,
Client: **Mr David Monaghan**

We refer to your instructions received on **09 March 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: MERCEDES-BENZ GLA 200 AMG LINE P		Colour: GREY	Speedo: 84248 Miles	
Reg No: VX18NDJ	Registered: Mar 2018	Type: Estate	Trans: Automatic	
Vin No: WDC1569432J507216		MOT Exp: 	R/H/F Tyre Not Kno R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manfd: 2018			
Brakes: Not Known	Tax Exp: 			Spare Tyre Not Known
Steering: Not Known	Fuel: Petrol			Centre Belt Not Tested
Extras: Not Seen	C.C.: 1595			
Air Bags Deployed: Not Known	BHP: 154	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Damage: Moderate Collision/Impact Rear Bumper	Incident: 07/03/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Vehicle Value: £13,063.00		Repair Cost: £3,584.71 inc VAT (27.44% of PAV)	Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the rear bumper.

VEHICLE HISTORY CHECK

16/03/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Upper Bumper, Rr Bumper Protection, Lower Bumper Cover, Lower Bumper Brkt, Lwr Bumper Cvr Trim, Rear Bumper Cover, Rr Ctr Bumper Brkt, Nut, Screw, Nut, Nut, Screw, Nut, Blind Rivet, L/R Side Trim, R/R Side Trim, Car Care Kit

Repaint only parts:-Rear Upper Bumper Painting, Machine Polish 3 Per Panel, Preparation Work For Two Coat Painting

Specialist/Sundry charges:-Bs10125, Methods Research, Adas Methods, Sundry Part, Epa, ADAS Methods

Remove And Refit parts:-L/R Side Panel Trim, R/R Side Panel Trim, Rear Bumper, Dis + Ass Rear Bumper

(Removed), Addition To Dis + Ass Rear Bumper

Parts to check:-Check Rear Bumper C-Member, Check Pre Clean, Check Wash & Vac, Check Rt And Final Check, Check Prescan, Check Postscan, Check Adas Exploration

COST OF REPAIRS

An Audatex estimate has been obtained from Junction Road Motor Company, 6-8 Woodside Grove, North Finchley, London, N128QU (Tel. 020 8445 1242) in the sum of £688.50 labour plus parts at manufacturer's list prices plus £493.64 for paint and materials plus £174.38 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be low and we have agreed an amended labour figure of £739.50 The labour charge is based on 8.7 hours at a rate of £85.00 per hour. We have also agreed that the cost of paint and materials will be limited to £493.64. The cost of the necessary replacement parts will be approximately £1,572.10, the specialist/sundry charges will be £182.02, the VAT liability on this repair will amount to some £597.45 giving a total repair cost of £3,584.71 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 23/03/2018. There are no guide values for vehicles of this age and type. We place the pre-accident value of this particular vehicle at £13,063.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £3,600.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 16th March 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 2 to 3 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy.

The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jake Roberts CAE AMIMI
Exclusive Vehicle Assessors