

Mr Michael Connor
60 Bedford Farm Court
Crofton
Wakefield
WF
Crofton
WF4 1AN


Date: 10/04/2026
Our Ref: 00033859/JEFPF
Your Ref: EHR99584

To the Court REPAIRABLE REPORT

Dear Sirs,

Client: **Mr Michael Connor**

We refer to your instructions received on **07 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: VOLKSWAGEN TOUAREG V6 BLACK E		Colour: BLACK	Speedo: 51590 Miles
Reg No: MK71TYF	Registered: Sep 2021	Type: Estate	Trans: Automatic
Vin No: WVGZZZCRZND002832	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manfd: 2021		Spare Tyre
Brakes: Not Known	Tax Exp:		Not Known
Steering: Not Known	Fuel: Diesel		Centre Belt
Extras: Not Seen	C.C.: 2967		Not Tested
Air Bags Deployed: Not Known	BHP: 282	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light to Moderate Collision/Impact RH Rear Bumper	Incident: 06/04/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £36,941.00		Repair Cost: £2,175.80 inc VAT (5.89% of PAV)	Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the right hand rear bumper.

VEHICLE HISTORY CHECK

10/04/2026 - According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-Sundry Parts

Repairable parts:-Rear Cover Bumper

Repaint only parts:-Two Coat Pearl/Mica, Rear Cover Bumper Repair Paint Plastic, Rear Bumper Spoiler Repair Paint Plastic, Azt Uplift >15% Rear Bumper, Preparation For Pre-Painting

Specialist/Sundry charges:-Panel Sundries, Adas Methods, Tech Data + Methods, E.P.A. Charge, Aries Support, Car Care Kit

Blend only parts:-De Nib Surface Paint

Remove And Refit parts:-Description, Rear Bumper Cover, Remove And Refit Rear Lower Spoiler, Rear Bumper



Part Cover, Road Test And Quality Control

Parts to check:-Pre Clean, Wash And Vac, Veh Diag Pre, Veh Diag Post, Adas Exploration

COST OF REPAIRS

The repairers, JCT600 Accident Repair Bradford (Tel. 01274778600), have compiled an estimate in the sum of £1,215.89 plus £432.62 for paint and materials plus £164.66 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 14.6 hours at a rate of £83.28 per hour. We have also agreed that the cost of paint and materials will be limited to £432.62. No new parts are required and the specialist/sundry charges will be £164.66, the VAT liability on this repair will amount to some £362.63 giving a total repair cost of £2,175.80 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 16/09/2021. The corresponding Cazana Guide (model code: 6341407) adjusted retail value for vehicles of this type and age in the April 2026 guide is £36,941.00 at 51590 Miles, trade value is £32,877.00 and mid value is £34,909.00. We place the pre-accident value of this particular vehicle at £36,941.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £2,200.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 10th April 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy.

The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance. We understand that the vehicle is still being used by the owner.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors