

FAO - The Court
AA Motor Claims
PO Box 585
Tonbridge
Kent
TN99NQ

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Nigel Toms: 15/04/2026


In accordance with your instructions received on 17/04/2026 requesting us to provide an independent accident damage report, we assessed the damage on 20/04/2026. Vehicle located at Image based assessment. Our findings are as detailed below:

Make	LAND ROVER	Registration	AK09VRY
Model	RANGE ROVER SP HSE	Status	T/Loss
Category	N	Salvage Value	£770.60
Repair Cost	£4,189.48	Legal Status	Unroadworthy
Engineer Value	£3,853.00	Impact Magnitude	Moderate



Impact Area





Our Ref: aa26002

Your Ref: GDAA488948

Date: 20/04/2026

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand front.

ENGINEER'S COMMENTS

The mileage has been calculated from online MOT data.

Please note the vehicle is unroadworthy due to the broken offside front fog lamp.

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £3,082.40 which represents the pre-accident engineer value of the vehicle of £3,853.00 less the value of the salvage of £770.60.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £770.60. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£3,853.00
Trade Value	£1,772.00
Engineer's Value	£3,853.00
Glass's Code	7CKC
VIN	SALLSAA239A209699
Odometer	117467
Engine	3628
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	



Our Ref: aa26002

Your Ref: GDAA488948

Date: 20/04/2026

Main new parts required

Front Bumper
R/F Cover
R/F Fog Lamp
R/F Out U-Sonic Sens
Sundry Parts

Centre Bumper Insert
Front Air Int Grille
Right Lamp Holder
R/F Out Sensor Brkt

Additional operations

Check Right Headlamp Assy
Paint Front Bumper New Part Paint K1r
Blend L/F Wing Surface Paint
Paint Preparation For Pre-Painting

Paint Two Coat Metallic
Paint R/F Out U-Sonic Sensnew Part Paint K1r
Blend R/F Wing Surface Paint
Assessment Fee


Repair Cost Calculations

Hours	12.30
Hourly Rate	£80.00
Total Labour	£984.00
Parts	£1,610.05
Paint/Materials	£720.22
Specialist/Other	£176.96
Sub total	£3,491.23
Vat	£698.25
Total Estimated Cost	£4,189.48









Our Ref: aa26002

Your Ref: GDAA488948

Date: 20/04/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk