

Our Ref: htu26021

Your Ref: AL17JAT

Date: 19/05/2026

FAO The Court
C/O HTU Assessors Ltd
The Old Courthouse
18-22 St Peters Churchyard
Derby
DE1 1NN

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Waquas Ali: 16/05/2026

In accordance with your instructions received on 18/05/2026 requesting us to provide an independent accident damage report, we assessed the damage on 19/05/2026. Vehicle located at Image based assessment. Our findings are as detailed below:


Make	TOYOTA	Registration	AL17JAT
Model	AVENSIS BUSINESS E	Status	T/Loss
Category	N	Salvage Value	£370.90
Repair Cost	£3,891.90	Legal Status	Unroadworthy
Engineer Value	£3,709.00	Impact Magnitude	Moderate



Impact Area



Document produced
using the EVA system



Our Ref: ht26021

Your Ref: AL17JAT

Date: 19/05/2026

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand rear.

ENGINEER'S COMMENTS

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the offside. and the rear lamp is damaged/compromised. and the possible wheel, suspension and tyre damage.

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £3,338.10 which represents the pre-accident engineer value of the vehicle of £3,709.00 less the value of the salvage of £370.90.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £370.90. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£3,709.00
Trade Value	£2,744.00
Engineer's Value	£3,709.00
Glass's Code	8NH8
VIN	SB1ET76L50E019187
Odometer	212784
Engine	1995
Fuel	Diesel
Extras	
Condition	Good



Our Ref: htu26021

Your Ref: AL17JAT

Date: 19/05/2026

Main new parts required

Rear Bumper Lining
Rear Bumper Lining Clip
Right Rear Lamp LED Outer

Rear Bumper Repair Kit
Rear Bumper Lining Screw

Repairs required

Right Rear Side Panel


Additional operations

.Assessment Damage Appraisal Charge
.Pre repair cleaning charge
.Standard shutdown
.System Diagnostic Check (Post Repair)
.Vehicle Care Kit
check alloy wheel and tyre for damage
Load / Unload vehicle to ramp
Panel repair sundries (including body fi
Second man lift
Paint Rear Bumper
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)
Wheel Alignment (check)

.Environmental Charge
.QC & Road Test
.Sundries
.System Diagnostic Check (Pre Repair)
.Wash/Clean
Corrosion Protection
Miracle Pull
Polish
Paint Right Rear Side Panel, Complete
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)
Paint Mask Rear Quarter Glass

Repair Cost Calculations

Hours	18.80
Hourly Rate	£83.28
Total Labour	£1,565.66
Parts	£458.82
Paint/Materials	£826.12
Specialist/Other	£392.65
Sub total	£3,243.25
Vat	£648.65
Total Estimated Cost	£3,891.90




Our Ref: ht26021

Your Ref: AL17JAT

Date: 19/05/2026






Our Ref: ht26021

Your Ref: AL17JAT

Date: 19/05/2026






Our Ref: ht26021

Your Ref: AL17JAT

Date: 19/05/2026






Our Ref: ht26021

Your Ref: AL17JAT

Date: 19/05/2026






Our Ref: ht26021

Your Ref: AL17JAT

Date: 19/05/2026






Our Ref: htu26021

Your Ref: AL17JAT

Date: 19/05/2026





Our Ref: htu26021

Your Ref: AL17JAT

Date: 19/05/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk