

FAO The Court
C/O Auto Logistic Solutions Ltd
Caledonia House
1 Livsey Street
Rochdale
OL16 1SS

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Mrs Michelle Quinn: 18/05/2026


In accordance with your instructions received on 29/05/2026 requesting us to provide an independent accident damage report, we assessed the damage on 29/05/2026. Vehicle located at Image-based Assessment. Our findings are as detailed below:

Make	KIA	Registration	MJ71V NK
Model	CEED 2 ISG	Status	T/Loss
Category	S	Salvage Value	£1,076.90
Repair Cost	£10,168.30	Legal Status	Unroadworthy
Engineer Value	£10,769.00	Impact Magnitude	Moderate to Heavy



Impact Area





Our Ref: als26062

Your Ref: 159734

Date: 02/06/2026

NATURE OF INCIDENT

The vehicle has suffered moderate to heavy collision/impact damage to the left hand rear.

ENGINEER'S COMMENTS

Please note the vehicle is unroadworthy as the rear body has been compromised.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £9,692.10 which represents the pre-accident engineer value of the vehicle of £10,769.00 less the value of the salvage of £1,076.90.

SALVAGE

Under the current salvage categorisation matrix, **within the scope of our inspection**, we consider that this is Category S, (Structural damage) and can be sold as repairable salvage. Further information is available www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £1,076.90. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£10,769.00
Trade Value	£9,261.00
Engineer's Value	£10,769.00
Glass's Code	
VIN	U5YH2512LNL142738
Odometer	45633
Engine	998
Fuel	Petrol
Extras	
Condition	Good



Our Ref: als26062

Your Ref: 159734

Date: 02/06/2026

Main new parts required

Rear Bumper Lining
Rear Bumper Spoiler
Left Rear Bumper Side Protection Trim
Left Rear Bumper Lower Support
Rear Bumper Repair Kit
Rear Bumper Lining Screw
Left Outer Rear Lamp, Complete
Right Reflector
Left Rear Side Panel Bonding Kit
Left Side Panel Rear Mudguard
Right Side Glass Repair/Bonding Kit
Rear Panel
Boot Lid/Tailgate Cover
Left Boot Lid/Tailgate Hinge
Boot Lid/Back Door/Tailgate Badge
Right Side Emblem (Optional Equipment)
Left Rear Window Spacing Block/Sleeve
Left Rear Window Upper Spacing Block/Sleeve
Left Rear Window Lower Spacing Block/Sleeve
Tailgate/Boot Lid Trim Support Kit
Tailgate/Boot Lid Trim Screw

Left Rear Bumper Side Impact Absorber (Tube)
Rear Bumper Reinforcement
Left Rear Bumper Side Stoneguard
Left Rear Bumper Side Support Plate
Rear Bumper Lining Clip
Rear bumper lining Nut
Left Reflector
Left Rear Side Panel
Left D-Post
Left Side Glass Repair/Bonding Kit
Left Side Panel Liner
Tailgate
Boot Lid/Tailgate/Back Door Weatherstrip
Right Boot Lid/Tailgate Hinge
Left Side Type Designation
Rear Window Repair/Bonding Kit
Right Rear Window Spacing Block/Sleeve
Right Rear Window Upper Spacing Block/Sleeve
Right Rear Window Lower Spacing Block/Sleeve
Tailgate/Boot Lid Trim Clip

Repairs required

Left Rear Wheelarch with Inner Side Panel

Additional operations


.Assessment Damage Appraisal Charge
.Pre repair cleaning charge
.Standard shutdown
.System Diagnostic Check (Post Repair)
.Vehicle Care Kit
Boron Drill
Jig, clamp and pull
Panel Bonding Kit
Sill dressings
.Yard Charge
Paint Left Rear Door, Complete
Paint Left Rear Side Panel, Complete
Paint Left Fuel Filler Lid
Paint Tailgate Cover, Lower
Paint Rear Skirt, Centre e
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

.Environmental Charge
.QC & Road Test
.Sundries
.System Diagnostic Check (Pre Repair)
.Wash/Clean
De-nib
NSR tyre
Seam Sealant
Wheel Alignment (check)
Paint Left A-Post, Upper
Paint Left Roof Panel, Side
Paint Right Rear Side Panel, Complete
Paint Tailgate (with Window Frame)
Paint Rear Panel, Complete
Paint Rear Bumper k/e
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

Repair Cost Calculations

Hours	43.60
Hourly Rate	£83.28
Total Labour	£3,631.01
Parts	£2,382.06
Paint/Materials	£1,774.62
Specialist/Other	£685.89
Sub total	£8,473.58
Vat	£1,694.72
Total Estimated Cost	£10,168.30






Our Ref: als26062

Your Ref: 159734

Date: 02/06/2026






Our Ref: als26062

Your Ref: 159734

Date: 02/06/2026





Our Ref: als26062


Your Ref: 159734

Date: 02/06/2026










Our Ref: als26062

Your Ref: 159734

Date: 02/06/2026





Our Ref: als26062

Your Ref: 159734

Date: 02/06/2026





**COLLISION
ENGINEERS**


INDEPENDENT AUTOMOTIVE EXPERTS

Our Ref: als26062

Your Ref: 159734

Date: 02/06/2026





Our Ref: als26062

Your Ref: 159734

Date: 02/06/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk



Our Ref: als26062

Your Ref: 159734

Date: 02/06/2026

FAO The Court
C/O Auto Logistic Solutions Ltd
Caledonia House
1 Livsey Street
Rochdale
OL16 1SS

Fee Note

MJ71VNK.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference als26062.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/O Auto Logistic Solutions Ltd confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10