

Providing excellence and expertise in automotive and mechanical assessment for over 35 years

Somerset Bridge Group Ltd.
Floor 1,
2 St James Gate,
Newcastle Upon Tyne
NE1 4AD

Date: 01/10/2021

Our Ref: 00793523/AIA

Your Ref: BD575665 \ BDPC7290320574

TOTAL LOSS REPORT - Cat N

Dear Sirs,

Client/Insured: [REDACTED]

T/Party: **Mr Ar [REDACTED] Bhaia**

We refer to your instructions received on **28 September 2021** and we confirm that we have attended at **Mr [REDACTED] Bhaia, [REDACTED]** on **30 September 2021** and we are pleased to report our findings as follows;

Vehicle: AUDI Q7 S LINE TDI QUATTRO A	Colour: BLACK	Speedo: [REDACTED] Miles
Reg No: YT58DXG	Registered: Sep 2008	Type: 5 Door Estate
Vin No: [REDACTED]	MOT Exp: [REDACTED]	R/H/F Tyre 4
Mods: None	Cond: Below Average	R/H/R Tyre 4
Audio: Standard	Man'd: 2008	R/H/R Belt Fitted
Brakes: Satisfactory- static check	Tax Exp: Nov 2021	Spare Tyre
Steering: Satisfactory- static check	Fuel: Diesel	Centre Belt
Extras: None	C.C.: 2967	Fitted
Air Bags Deployed: Not Deployed	BHP: [REDACTED]	L/H/F Belt Fitted
Damage: Moderate Accidental Damage Front	Incident: 25/09/2021	L/H/R Belt Fitted
		L/H/F Tyre 4
		L/H/R Tyre 4

Vehicle Value: £5,800.00	Repair Cost: £10,185.97 inc VAT (175.62% of PAV)	Roadworthy: No
---------------------------------	---	-----------------------

REPAIR COSTS

Recovery £0.00	Labour £1,135.00	Materials £1,261.71
Other £132.00	Parts £5,959.60	VAT £1,697.66
	Total Net £8,488.31	Total Gross £10,185.97

NATURE OF INCIDENT

The vehicle has suffered moderate accidental damage to the front.

VEHICLE HISTORY CHECK

28/09/2021 - We confirm having checked this vehicle on the HPI database and there is no current record of any adverse history or finance.

REPAIR SCHEDULE

New parts required:-Front Bumper, Front Bumper Armature, Front Bumper Brackets, Front Bumper Pads, Front Bumper Mouldings, Front Spoiler, Grille Assembly, Grille Mouldings, Os Headlamp, Os Flasher, Ns Headlamp, Ns Flasher, Front Number Plate, Radiator, Radiator Cowling, Bonnet, Bonnet Lock, Bonnet Hinges, Bonnet Motif, Front Panel, Osf Wing, Coolant, Aux Radiator



Document produced
using the EVA system

Tel: 01484 864430 / 01484 865355

Email: mail@northern-assessors.co.uk | Web: www.northern-assessors.co.uk | Company Registration Number 7018936

Repairable parts:-OsF Door

Specialist/Sundry charges:-Epa, car Care Kit, System Diagnostic Check (Pre-Post Repair), Anti Corrosion Treatment

Blend only parts:-Nsf Wing

Parts to check:-Check And Report Upon Dismantling

COST OF REPAIRS

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair and we consider that a reasonable labour charge would be £1,135.00. The cost of the paint and materials would be £1,261.71, The cost of the replacement parts would be approximately £5,959.60, The specialist/sundry charges would be £132.00, and the VAT liability on the total would amount to some £1,697.66 giving a total repair cost of £10,185.97 including VAT **subject to undisclosed damage**. The labour charge is based on 22.7 hours at a rate of £50.00 per hour.

UNRELATED DAMAGE

We noted the following damage on the vehicle which does not appear to relate to the claim under review and we have therefore classed it as unrelated damage; rear bumper damaged, poor repairs to ns doors and various scratches and minor dents to the bodyside-£1330.

PRE-INCIDENT CONDITION

The vehicle was found to be in below average condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in Sep 2008. The corresponding Glass's Guide (model code: 7GN6) adjusted retail value for vehicles of this type and age in the September 2021 guide is £7,130.00 at 137271 Miles, trade value is £4,610.00 and mid value is £5,870.00. We place the pre-accident value of this particular vehicle at £5,800.00 bearing in mind the condition described herein. **We would emphasise that this figure is subject to consideration of the vehicle registration documents, purchase invoice and any relevant service records confirming the recorded mileage and vehicle details as contained in this report. Our valuation is also subject to the usual vehicle checks via H.P.I. And M.I.A.F.T.R.**

SETTLEMENT

Subject to all relevant claim validation enquiries, we consider that an equitable settlement would be £4,118.00 which represents the pre-accident engineer value of the vehicle of £5,800.00 less the value of the salvage of £1,682.00.

SALVAGE

We are not aware of any outstanding recovery charge nor have we been advised that any storage charges are accruing. Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. The salvage category has been applied by an appropriately qualified person; the unique identification number has been provided separately for use only by the instructing party. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £1,682.00. **We have not taken any action towards removal of the salvage at this time.**

ROADWORTHY STATE

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to sharp edges, lamps damaged and radiator leaking.

TEMPORARY REPAIRS

We suggest that it would not be practical to consider cost effective temporary repairs on this occasion to make this vehicle roadworthy.

At the time of our inspection owner was present.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

Yours faithfully





[REDACTED] A.M.I.M.I.
Northern Assessors



P1930766.jpg



P1930768.jpg



P1930759.jpg



P1930760.jpg



P1930761.jpg



P1930762.jpg



P1930763.jpg



P1930764.jpg



P1930765.jpg



P1930767.jpg



P1930780.jpg



P1930769.jpg



P1930770.jpg



P1930771.jpg



P1930772.jpg



P1930773.jpg



P1930774.jpg




P1930775.jpg



P1930776.jpg



P1930777.jpg



P1930778.jpg



P1930779.jpg



P1930786.jpg



P1930781.jpg



P1930782.jpg



P1930783.jpg



P1930784.jpg



P1930785.jpg