

Our Ref: qdos221405

Your Ref: CL//14384/1

Date: 24/08/2022

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: James Robinson: 20/08/2022

In accordance with your instructions received on 24/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 24/08/2022. Vehicle located at Image based assessment. Our findings are as detailed below:


Make	VAUXHALL	Registration	KY63GVC
Model	INSIGNIA DESIGN CD	Status	Repair
Category		Salvage Value	
Repair Cost	£2,255.76	Legal Status	Roadworthy
Engineer Value	£4,600.00	Impact Magnitude	Light to Moderate



Impact Area



Document produced
using the EVA system



Our Ref: qdos221405

Your Ref: CL//14384/1

Date: 24/08/2022

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the left hand rear.

ENGINEER'S COMMENTS

Mileage calculated from MOT history

VEHICLE HISTORY CHECK

24/08/2022 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £2,275.00 would be reasonable on this occasion.


Vehicle Data

Retail Value	£4,600.00
Trade Value	£2,730.00
Engineer's Value	£4,600.00
Glass's Code	MNNV
VIN	W0LGM6EL5E1060414
Odometer	105500
Engine	1956
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	

Main new parts required

Rear Bumper Lining
Rear Bumper Cover
Right Rear Bumper Outer Bracket
Rear Bumper Lining Clip
Rear bumper lining Nut

Rear Bumper Impact Absorber/Filler
Left Rear Bumper Outer Bracket
Rear Bumper Repair Kit
Rear Bumper Lining Screw



Our Ref: qdos221405

Your Ref: CL//14384/1

Date: 24/08/2022


Additional operations

Repair Method Research Allowance
System Diagnostic Check (Pre Repair)
De-Nib/Polish
Final Inspection & Road Test
Paint Left Rear Side Panel, Complete
Paint Rear Bumper k/e
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

System Diagnostic Check (Post Repair)
Car Care Kit
Environmental Charge
Wash/Clean
Paint Right Rear Side Panel, Complete
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

Repair Cost Calculations

Hours	7.20
Hourly Rate	£62.50
Total Labour	£450.00
Parts	£592.16
Paint/Materials	£727.64
Specialist/Other	£110.00
Sub total	£1,879.80
Vat	£375.96
Total Estimated Cost	£2,255.76



ClientVINjpeg-V1.jpeg