

FAO The Court
C/O Auto Logistic Solutions Ltd
Caledonia House
1 Livsey Street
Rochdale
OL16 1SS

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: John Brown-Hicks : 08/08/2025


In accordance with your instructions received on 18/08/2025 requesting us to provide an independent accident damage report, we assessed the damage on 19/08/2025. Vehicle located at Image Based Assessment. Our findings are as detailed below:

Make	VOLKSWAGEN	Registration	CE59GXP
Model	TOURAN SE TDI 105	Status	T/Loss
Category	B	Salvage Value	£50.00
Repair Cost	£15,190.51	Legal Status	Unroadworthy
Engineer Value	£2,100.00	Impact Magnitude	Moderate



Impact Area





Our Ref: als25101

Your Ref: 153116

Date: 19/08/2025

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand rear.

ENGINEER'S COMMENTS

The mileage has been calculated from online MOT data.

The valuation is based on market research.

19/08/2025 - Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the offside rear.

20/8/2025 - UPDATED REPORT: - The vehicle owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £2100.00

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT

We consider that an equitable settlement would be £2,050.00 which represents the pre-accident engineer value of the vehicle of £2,100.00 less the value of the salvage of £50.00.


SALVAGE

We consider that this is Category B (break for spares only and in-line with the ABI salvage code of practice)

This vehicle is damaged beyond any form of economical repair, therefore in our Engineers professional opinion it should not be returned to the road and a certificate of destruction should be completed / issued We suggest that the sale of the salvage will realise in the order of £50.00. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£2,100.00
Trade Value	
Engineer's Value	£2,100.00
Glass's Code	378F
VIN	WVGZZZ1TZA010525
Odometer	156000
Engine	1896
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	



Our Ref: als25101

Your Ref: 153116

Date: 19/08/2025

Main new parts required

Right Rear Door Shell
Right Rear Door Protective Moulding
Rear Bumper Lining
Rear Bumper Reinforcement
Left Rear Bumper Side Bracket
Rear Bumper Repair Kit
Left R. Bumper Inner Distance-Sensor Bracket
Left R. Bumper Outer Distance-Sensor Bracket
Rear Bumper Distance-Sensor ECU
Rear Bumper Lining Screw
Left Rear Lamp, Complete
Right Rear Side Panel
Right Rear Side Panel and Rear Panel
Right Rear Side Glass Primer
Right Rear Side Glass Activator
Right Rear Wheelarch with Inner Side Panel
Rear Panel
Tailgate
Left Boot Lid/Tailgate Hinge
Latch with Central Locking
Left Side Type Designation
Rear Window (Heated, Tinted)
Rear Window Repair/Bonding Kit
Rear Window Applicator
Rear Window Wiper Motor
Right Rear Door Trim Clip
Upper Tailgate/Back Door Trim
Tailgate/Boot Lid Trim Support Kit
Tailgate/Boot Lid Trim Screw

Right Rear Door Skin Bonding Kit
Right Rear Door Insulation
Rear Bumper Spoiler
Rear Bumper Bracket
Right Rear Bumper Side Bracket
Right Rear Bumper Outer Side Distance-Sensor
Right R. Bumper Inner Distance-Sensor Bracket
Right R. Bumper Outer Distance-Sensor Bracket
Rear Bumper Lining Clip
Rear bumper lining Nut
Right Rear Lamp, Complete
Right Rear Side Panel Bonding Kit
Right Side Glass Repair/Bonding Kit
Right Rear Side Glass Applicator
Right Rear Wheelarch, Inner
Right Side Panel Liner
Right Rear Lamp Panel
Boot Lid/Tailgate/Back Door Weatherstrip
Right Boot Lid/Tailgate Hinge
Boot Lid/Back Door/Tailgate Striker
Right Side Emblem (Engine Designation)
Rear Window Additional Cartridge
Rear Window Primer
Rear Window Activator
Right Rear Door Trim Support Kit
Right Rear Door Trim Screw
Lower Tailgate/Back Door Trim
Tailgate/Boot Lid Trim Clip

Additional operations

Assessment Damage Appraisal Charge
De-nib/ polish
Glass clean
Older vehicle allowance
Pre repair cleaning charge (including sa
Repair method research charge
Standard shutdown
System Diagnostic Check (Pre Repair)
Wash/Clean
Paint Right Rear Door, Complete
Paint Tailgate (with Window Frame)
Paint Right Rear Panel, Complete
Paint Right Rear Bumper Distance-Sensor
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)


Corrosion Protection
Energy cost supplement
Jig, clamp and pull
OSR tyre
QC & Road Test
Sill dressing (per side)
System Diagnostic Check (Post Repair)
Vehicle Care Kit
Paint Right Front Door, Complete
Paint Right Rear Side Panel, Complete
Paint Rear Panel, Complete
Paint Rear Bumper a-d
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

Repair Cost Calculations

Hours	60.30
Hourly Rate	£80.00
Total Labour	£4,824.00
Parts	£5,654.16
Paint/Materials	£1,675.60
Specialist/Other	£505.00
Sub total	£12,658.76
Vat	£2,531.75
Total Estimated Cost	£15,190.51







Our Ref: als25101

Your Ref: 153116

Date: 19/08/2025

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: als25101

Your Ref: 153116

Date: 19/08/2025

FAO The Court
C/O Auto Logistic Solutions Ltd
Caledonia House
1 Livsey Street
Rochdale
OL16 1SS

Fee Note

CE59GXP.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference als25101.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/O Auto Logistic Solutions Ltd confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10