

Our Ref: qdos252196

Your Ref: SCL/SBU/41065/1

Date: 21/11/2025

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Mrs Ciara Monaghan: 13/11/2025


In accordance with your instructions received on 20/11/2025 requesting us to provide an independent accident damage report, we assessed the damage on 21/11/2025. Vehicle located at Image Based Assessment. Our findings are as detailed below:

Make	MAZDA	Registration	EIG9713
Model	CX-3 SPORT NAV D	Status	T/Loss
Category	N	Salvage Value	£1,147.50
Repair Cost	£6,021.84	Legal Status	Unroadworthy
Engineer Value	£7,650.00	Impact Magnitude	Moderate



Impact Area





Our Ref: qdos252196

Your Ref: SCL/SBU/41065/1

Date: 21/11/2025

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand side.

ENGINEER'S COMMENTS

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the nearside.

2/12/2025 - UPDATED REPORT: - The vehicle owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £7,650.00

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £6,502.50 which represents the pre-accident engineer value of the vehicle of £7,650.00 less the value of the salvage of £1,147.50.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £1,147.50. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	
Trade Value	
Engineer's Value	£7,650.00
Glass's Code	
VIN	MMZDK6WS60W222005
Odometer	84656
Engine	1497
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	



Our Ref: qdos252196

Your Ref: SCL/SBU/41065/1

Date: 21/11/2025

Main new parts required

Front Wing (L)
Front Wing Insulation (L)
Front Wing Liner (L)
Front Wing Panel Screw (L)
Front Door Covering Sheet (Skin) (L)
Front Door Lower Hinge (L)
Front Door Outer Seal (L)
Front Door Rear Window Moulding (L)
Front Door Window Outer Channel Strip (L)
Rear Door Covering Sheet (Skin) (L)
Sill Panel Cover (Plastic) (L)
Sill Panel Cover (Plastic) Repair Kit (L)
Sill Panel Cover (Plastic) Screw (L)
Front Door Trim Clip (L)

Front Wing Repair Kit (L)
Front Wing W/arch Protective Moulding (L)
Front Wing Stone Protection (L)
Front Door Shell (L)
Front Door Upper Hinge (L)
Front Door Checkstrap (L)
Front Door Upper Window Moulding (L)
Front Door Lower Cover (L)
Front Door Lock (w/Central Locking) (L)
Rear Door Lower Cover (L)
Sill Panel Cover, Front (Plastic) (L)
Sill Panel Cover (Plastic) Clip (L)
Front Door Trim Support Kit (L)
Front Door Trim Screw (L)


Repairs required

Rear Door Shell (L)

Additional operations

ADAS methods Research Fee
De-nib/ polish
Environmental Charge
NSF tyre
Standard shutdown
System Diagnostic Check (Pre Repair)
Blend Front Bumper k/d-e
Blend Bonnet
Paint Front Door, Complete K (L)
Paint Rear Door, Complete K (L)
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

Assessment Damage Appraisal Charge
Energy cost supplement
Identify the presence of ADAS
QC & Road Test
System Diagnostic Check (Post Repair)
Wheel Alignment (4 wheel)
Paint Front Wing, Complete (L)
Blend A-Post, Upper (L)
Blend Front Door Outer Handle (L)
Blend Rear Door Outer Handle (L)
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)



Our Ref: qdos252196

Your Ref: SCL/SBU/41065/1

Date: 21/11/2025


Repair Cost Calculations

Hours	20.00
Hourly Rate	£80.00
Total Labour	£1,600.00
Parts	£1,446.88
Paint/Materials	£1,355.32
Specialist/Other	£616.00
Sub total	£5,018.20
Vat	£1,003.64
Total Estimated Cost	£6,021.84









Our Ref: qdos252196


Your Ref: SCL/SBU/41065/1

Date: 21/11/2025










Our Ref: qdos252196

Your Ref: SCL/SBU/41065/1

Date: 21/11/2025





Our Ref: qdos252196

Your Ref: SCL/SBU/41065/1

Date: 21/11/2025

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: qdos252196

Your Ref: SCL/SBU/41065/1

Date: 21/11/2025

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

Fee Note

EIG9713.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference qdos252196.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10