

**Our Ref:** ap.qdos26914

**Your Ref:** LR/44086/1

**Date:** 02/04/2026

FAO The Court  
C/o QDOS Assistance  
1st Floor, Barfield House  
24-28 Alderly Road  
SK91PL

### **TOTAL LOSS REPORT**

Dear Sirs


**RE: Road traffic Accident: Mr Jesno Joy: 17/03/2026**


In accordance with your instructions received on 01/04/2026 requesting us to provide an independent accident damage report, we assessed the damage on 02/04/2026. Vehicle located at Image Based Assessment. Our findings are as detailed below:

|                |                           |                  |                   |
|----------------|---------------------------|------------------|-------------------|
| Make           | <b>TOYOTA</b>             | Registration     | <b>WF10XAS</b>    |
| Model          | <b>AURIS TR VALVEMATI</b> | Status           | <b>T/Loss</b>     |
| Category       | <b>N</b>                  | Salvage Value    | <b>£116.41</b>    |
| Repair Cost    | <b>£2,639.99</b>          | Legal Status     | <b>Roadworthy</b> |
| Engineer Value | <b>£1,663.00</b>          | Impact Magnitude | <b>Moderate</b>   |



Impact Area





**Our Ref:** ap.qdos26914

**Your Ref:** LR/44086/1

**Date:** 02/04/2026

### **DESKTOP ASSESSMENT**

This report has been compiled from a desktop review of the information available relating to this claim.

### **NATURE OF INCIDENT**

The vehicle has suffered moderate collision/impact damage to the rear.

### **ENGINEER'S COMMENTS**

The mileage has been calculated from online MOT data.

20% has been deducted from the pre accident valuation due to the vehicle being a previous total loss.

### **VEHICLE HISTORY CHECK**

According to the Experian database; Category N total loss claim Non Structural Damage See the Condition details An entry exists on the MIAFTR register to this effect dated 26/09/2022, loss dated 06/09/2022

### **PRE-INCIDENT CONDITION**

The vehicle is considered to be in good condition for its age and type.

### **SETTLEMENT**


We consider that an equitable settlement would be £1,546.59 which represents the pre-accident engineer value of the vehicle of £1,663.00 less the value of the salvage of £116.41.

### **SALVAGE**

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at [www.abi.org.uk](http://www.abi.org.uk). We suggest that the sale of the salvage will realise in the order of £116.41. **We have not taken any action towards removal of the salvage at this time.**

## **Vehicle Data**

|                  |                          |
|------------------|--------------------------|
| Retail Value     | <b>£2,079.00</b>         |
| Trade Value      | <b>£200.00</b>           |
| Engineer's Value | <b>£1,663.00</b>         |
| Glass's Code     | <b>694G</b>              |
| VIN              | <b>SB1KE56E40E016526</b> |
| Odometer         | <b>155182</b>            |
| Engine           | <b>1598</b>              |
| Fuel             | <b>Petrol</b>            |
| Extras           |                          |
| Condition        | <b>Good</b>              |
| Unrelated Damage |                          |



**Our Ref:** ap.qdos26914

**Your Ref:** LR/44086/1

**Date:** 02/04/2026

#### Main new parts required

Rear Bumper Lining  
Left Rear Bumper Side Reinforcement  
Left Rear Bumper Inner Bracket  
Rear Bumper Repair Kit

Rear Bumper Reinforcement  
Right Rear Bumper Side Reinforcement  
Right Rear Bumper Inner Bracket  
Rear Bumper Lining Clip

#### Additional operations

Remove and Refit PDC sensors  
.Environmental Charge  
.QC & Road Test  
.System Diagnostic Check (Post Repair)  
.Vehicle Care Kit  
Collection / Delivery  
Older vehicle allowance  
Paint Prep. synthetics (on vehicle without pre-painting)  
Paint Sample colour creation (1)

.Assessment Damage Appraisal Charge  
.Pre repair cleaning charge  
.Standard shutdown  
.System Diagnostic Check (Pre Repair)  
.Wash/Clean  
Load / Unload vehicle to ramp  
Paint Rear Bumper  
Paint Colour mixing (1)


### Repair Cost Calculations

|                      |                  |
|----------------------|------------------|
| Hours                | <b>10.40</b>     |
| Hourly Rate          | <b>£83.28</b>    |
| Total Labour         | <b>£866.11</b>   |
| Parts                | <b>£418.36</b>   |
| Paint/Materials      | <b>£540.78</b>   |
| Specialist/Other     | <b>£374.74</b>   |
| Sub total            | <b>£2,199.99</b> |
| Vat                  | <b>£440.00</b>   |
| Total Estimated Cost | <b>£2,639.99</b> |

















**Our Ref:** ap.qdos26914

**Your Ref:** LR/44086/1

**Date:** 02/04/2026







**Our Ref:** ap.qdos26914

**Your Ref:** LR/44086/1

**Date:** 02/04/2026

### **Statement of Truth**

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

N O'Reilly - ATA VDA

engineers@collisionengineers.co.uk



**Our Ref:** ap.qdos26914

**Your Ref:** LR/44086/1

**Date:** 02/04/2026

FAO The Court  
C/o QDOS Assistance  
1st Floor, Barfield House  
24-28 Alderly Road  
SK91PL

### Fee Note

WF10XAS.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

**Agreed Fee: £100.00**

**Sub Total: £100.00**

**VAT: £20.00**

**Total Due: £120.00**

### Payment

Please make cheques payable to Collision Engineers and quote reference ap.qdos26914.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10