

Mr Lee Joyner
30 Sheaves Park
Bristol
Avon
BS10 6WG

Date: 14/04/2026
Our Ref: 00034113/DME
Your Ref: EHR99761

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mr Lee Joyner**

We refer to your instructions received on **10 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: MERCEDES-BENZ A 220 D AMG LINE A		Colour: Black	Speedo: 89395 Miles	
Reg No: HD21BVA	Registered: Jun 2021	Type: 4 Door Saloon	Trans: Automatic	
Vin No: W1K1771142J277050	MOT Exp: 	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Unknown	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manfd: 2021			
Brakes: Not Known	Tax Exp: 			Spare Tyre Not Known
Steering: Not Known	Fuel: Diesel			Centre Belt Not Tested
Extras: Not Seen	C.C.: 1950			
Air Bags Deployed: Not Known	BHP: 187.	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Damage: Moderate Collision/Impact Front	Incident: 09/04/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	

Vehicle Value: £14,008.00	Repair Cost: £5,044.49 inc VAT (36.01% of PAV)	Roadworthy: No
----------------------------------	---	-----------------------

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF DAMAGE

The vehicle has suffered moderate collision impact to the front.

ENGINEER'S COMMENTS

I can confirm repairs have been authorised via Audatex in accordance with your original instructions.

Authority sent via Audatex.

VEHICLE HISTORY CHECK

13/04/2026 - I confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Front Number Plate, Frt No Plate Reinf, Front Bumper, L/Grille Trim, R/Grille Trim, Star Emblem, Star Emblem, Rad Grille Cover, Sundries, Sundries



Repairable parts:-Repair Bonnet

Repaint only parts:-Front Bumper Painting, Bonnet Painting Stage Iii, Add Colour Sample 1, Outer Cleaning Carry Out, Polish Vehicle, Non Water Based Remove, Machine Polish, Security Measures Before, Preparation Work For Two Coat Painting, Add For Preparation Work, Carry Out Colour Shade Determination

Specialist/Sundry charges:-Energy Payment, Anti-Corrosion, Adas-Methods, Adas Reset, Methods Research, E.P.A. Charge, Car Care Kit

Remove And Refit parts:-Short Test, Front Bumper, Addition To Front Bumper, Dis + Ass Front Bumper, Addition To Dis + Ass Front Bumper, Addition To Front Bumper, Addition To Dis + Ass Front Bumper, Pre And Clean Car, Corrosion Protection To 1St Panel

Parts to check:-Check Wash & Vac, Check Road test-QC, Check Vehicle Diag Pre Check, Check Vehicle Diag Post Check, Check LIR-Adas

COST OF REPAIRS

An Audatex estimate has been obtained from Dentmagic Southwest Ltd, Dentmagic in Makro Lysander Rd, BS, CRIBBS CAUSEWAY, Bristol, BS10 7TZ (Tel. 0117 972 0333) in the sum of £1,638.65 labour plus parts at manufacturer's list prices plus £1,317.88 for paint and materials plus £547.55 for specialist/sundry charges. Having calculated the time involved in this repair I consider this to be reasonable and I have agreed with the repairers that there will be a reduction of £145.92 to £1,171.96 for paint and materials in their final account. The labour charge is based on 15.9 hours at a rate of £103.06 per hour. I have also agreed that the cost of paint and materials will be limited to £1,171.96. The cost of the necessary replacement parts will be approximately £915.58, the specialist/sundry charges will be £477.55, the VAT liability on this repair will amount to some £840.75 giving a total repair cost of £5,044.49 including VAT **subject to any undisclosed damage. I am pleased to confirm that I have achieved total gross savings in this matter of £259.10.**

OTHER DAMAGE

I noted the following damage on the vehicle:- None noted.

REPAIRER VAT STATUS

I am informed that the repairer is registered for VAT

PRE-INCIDENT VALUE

According to the information available to me the vehicle was first registered in 16/06/2021.

The corresponding CAP Guide (model code: 91358) adjusted retail value for vehicles of this type and age in the April 2026 guide is £14,008.00 at 89000 Miles, trade value is £11,992.00.

I place the pre-accident value of this particular vehicle at £14,008.00 bearing in mind the condition described herein.

RESERVE

I consider that a repair reserve of £5,050.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

I am pleased to confirm that I have authorised the repairers to proceed with the work via Audatex in accordance with your instructions, on the 14th April 2026, on your behalf.

REPAIR DURATION

I consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In my opinion this vehicle was not roadworthy at the time of my inspection as a result of the damage sustained due to Frontal damage.

For & on behalf of

TIM CLARKE

Tim Clarke IMI VDA Accreditation, C.A.E., M.I.M.I.
Exclusive Vehicle Assessors