


Mr Alexander Mcandrew
5 Corbett Place
Dunfermline
KY
DUNFERMLINE
KY11 4XX

Date: 26/10/2025
Our Ref: 00022761/JAKER
Your Ref: EHR90205

To the Court
REPAIRABLE REPORT - Supplementary Report

Dear Sirs,
Client: **Mr Alexander Mcandrew**

We refer to your instructions received on **16 October 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: MERCEDES-BENZ CLS350 D AMG LINE	Colour: GREY	Speedo: 82289	Miles
Reg No: V55MCA	Registered: Sep 2017	Type: Estate	Trans: Automatic
Vin No: WDD2189262A200933	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manfd: 2017		Spare Tyre
Brakes: Not Known	Tax Exp:		Not Known
Steering: Not Known	Fuel: Diesel		Centre Belt
Extras: Not Seen	C.C.: 2987		Not Tested
Air Bags Deployed: Not Known	BHP: 255	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light to Moderate Collision/Impact RH Front Bumper	Incident: 10/10/2025	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £16,180.00		Repair Cost: £1,578.00 inc VAT	(9.75% of PAV) Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the right hand front bumper.

VEHICLE HISTORY CHECK

26/10/2025 - According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

Repaint only parts:-Paint and mats

Specialist/Sundry charges:-Ceramic coat bumper

Remove And Refit parts:-Labout

COST OF REPAIRS

The repairers, Layla Mitchell Office Manager (Tel. 01383 830645), have compiled an estimate in the sum of £455.00 plus £250.00 for paint and materials plus £165.00 for specialist/sundry charges. Having calculated the time involved



in this repair we consider this to be low and we have agreed an amended labour figure of £650.00. The labour charge is based on 10 hours at a rate of £65.00 per hour. We have also agreed that the cost of paint and materials will be limited to £500.00. No new parts are required and the specialist/sundry charges will be £165.00, the VAT liability on this repair will amount to some £263.00 giving a total repair cost of £1,578.00 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 22/09/2017. There are no guide values for vehicles of this age and type. We place the pre-accident value of this particular vehicle at £16,180.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £1,600.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 26th October 2025, on your behalf.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions (ACHL) commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jake Roberts AMIMI VDA
Exclusive Vehicle Assessors