

Miss Nisha Mohite
8 Bolsover Close
Bedford
Bedfordshire
MK
Bedford
Bedfordshire

Date: 06/01/2026
Our Ref: 00027933/COHARE
Your Ref: EHR94642

To the Court REPAIRABLE REPORT

Dear Sirs,

Client: **Miss Nisha Mohite**

We refer to your instructions received on **31 December 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle:	TESLA MODEL 3 LONG RANGE RWD		Colour:	WHITE		Speedo:	16104	Miles
Reg No:	GL73MKD	Registered:	Dec 2023	Type:	4 Door Saloon	Trans:	Automatic	
Vin No:	LRW3F7ES0PC945776	MOT Exp:		R/H/F Tyre	Not Kno	R/H/R Tyre	Not Kno	
Mods:	Not Seen	Cond:	Excellent	R/H/F Belt	Not Tested	R/H/R Belt	Not Tested	
Audio:	Not Seen	Man'f'd:	2023					Spare Tyre
Brakes:	Not Known	Tax Exp:						Not Know
Steering:	Not Known	Fuel:	Electric					Centre Belt
Extras:	Not Seen	C.C.:	0					Not Tested
Air Bags Deployed:	Not Known	BHP:	279	L/H/F Belt	Not Tested	L/H/R Belt	Not Tested	
Damage:	Moderate Accidental Damage Front Bumper	Incident:	18/12/2025	L/H/F Tyre	Not Kno	L/H/R Tyre	Not Kno	
Vehicle Value:		£25,606.00		Repair Cost:	£5,505.10 inc VAT		(21.50% of PAV)	
				Roadworthy:	No			

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate accidental damage to the front bumper.

VEHICLE HISTORY CHECK

06/01/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Front Bumper, Frt Lwr Bumper Brkt, L/F Inn Sensor Brkt, R/F Inn Sensor Brkt, L/F Out Sensor Brkt, R/F Out Sensor Brkt, L/F Side Sensor Brkt, R/F Side Sensor Brkt, R/Bumper Bracket, R/Inn Bumper Bracket, Grille Badge, R/F Out Bumper Brkt, R/Screw M5 X 20, Lift Tape

Repaint only parts:-Front Bumper New Part Paint K1r, Frt Towing Eye Coversurface Paint Plast., Bonnet Surface Paint, L/F Wing Surface Paint, R/F Wing Surface Paint, Touch In Bolts Surface Paint, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Bsi 10125 Compliance, Manufacturer Appr, Assessment Charge, E.P.A. Charge,



Methods Research, Car Care Kit, Elect Vehicle Rechar, Drive Calibration, Active Web Fee, Energy Payment, Adas Methods, Sundry Part

Remove And Refit parts:-Vehicle Preparation Time, L/F Wing Side Camera Calibrate, R/F Wing Side Camera Calibrate, Front Bumper, Renew Front Bumper (Removed), Front Badge, Right Front Bumper Bracket, Front Axle Insulation Protect, Left Headlamp, Right Headlamp, Front Bumper Fittings, L/Repeater Lamp, R/Repeater Lamp, Front Bumper Bracket, Wash Vehicle, Standard Driving Test, Specialist Standard Veh Shutdow, Battery Disconnect 12V, Battery Reconnect 12V, Quality Check And Road Test, Specialist Pre- Repair Clean, Major Repair Valet, Specialist Adas Check

Parts to check:-Check Hybrid Risk Assess, Check Wash & Vac, Check Service Mode, Check Power Down & Reinsta

COST OF REPAIRS

The repairers, Werrens (Tel. 01234 331900), have compiled an estimate in the sum of £2,120.58 plus parts at manufacturer's list prices plus £1,333.23 for paint and materials plus £638.34 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 21.42 hours at a rate of £99.00 per hour. We have also agreed that the cost of paint and materials will be limited to £1,333.23. The cost of the necessary replacement parts will be approximately £495.43, the specialist/sundry charges will be £638.34, the VAT liability on this repair will amount to some £917.52 giving a total repair cost of £5,505.10 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in excellent condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 29/12/2023. The corresponding Glass's Guide (model code: 366793001) adjusted retail value for vehicles of this type and age in the December 2025 guide is £25,606.00 at 16104 Miles, trade value is £22,778.00 and mid value is £24,192.00. We place the pre-accident value of this particular vehicle at £25,606.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £5,525.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 6th January 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to SHARP EDGES ON THE BUMPER IN THE PADESTRIAN SAFTY AREA. We understand that the vehicle is still being used by the owner.

TEMPORARY REPAIRS

We suggest that it would not be practical to consider cost effective temporary repairs on this occasion to make this vehicle roadworthy.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions (ACHL) commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

A handwritten signature in black ink that reads "C O'Hare". The signature is written in a cursive, flowing style.

Chris O'Hare AMIMI IMI VDA
Exclusive Vehicle Assessors