

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Abi Umal: 17/04/2026


In accordance with your instructions received on 22/04/2026 requesting us to provide an independent accident damage report, we assessed the damage on 22/04/2026. Vehicle located at Image Based Assessment. Our findings are as detailed below:

Make	SKODA	Registration	BJ63YZS
Model	OCTAVIA SE TDI CR	Status	T/Loss
Category	N	Salvage Value	£128.10
Repair Cost	£2,294.54	Legal Status	Roadworthy
Engineer Value	£1,830.00	Impact Magnitude	Light



Impact Area





Our Ref: ap.qdos261068

Your Ref: SCL/44772/1

Date: 23/04/2026

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light collision/impact damage to the right hand rear.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT

We consider that an equitable settlement would be £1,701.90 which represents the pre-accident engineer value of the vehicle of £1,830.00 less the value of the salvage of £128.10.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £128.10. **We have not taken any action towards removal of the salvage at this time.**


Vehicle Data

Retail Value	£1,830.00
Trade Value	£1,208.00
Engineer's Value	£1,830.00
Glass's Code	4RXX
VIN	TMBBG7NE9E0056656
Odometer	283294
Engine	1598
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	

Main new parts required

Right rear tail light
91132101
JOINT

10549603
NUT



Our Ref: ap.qdos261068

Your Ref: SCL/44772/1

Date: 23/04/2026

Additional operations

Right rear tail light mounting kit
Paint Rear bumper Repaired (K3) Parts removed
Paint Fuel tank flap Surface (K2) Parts removed
Paint Right A-Pillar Upper zone A-Pillar Surface (II)
Specialist Car Care Kit
Sundry parts

VIN
Paint Rear right wing Surface (II)
Paint Right bodywork side Upper section (A) Surface
Paint Preparation paintwork
Parts
Paint Paint and Materials


Repair Cost Calculations

Hours	11.90
Hourly Rate	£83.30
Total Labour	£991.27
Parts	£130.85
Paint/Materials	£775.01
Specialist/Other	£14.99
Sub total	£1,912.12
Vat	£382.42
Total Estimated Cost	£2,294.54









Our Ref: ap.qdos261068

Your Ref: SCL/44772/1

Date: 23/04/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk



Our Ref: ap.qdos261068

Your Ref: SCL/44772/1

Date: 23/04/2026

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

Fee Note

BJ63YZS.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference ap.qdos261068.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10