

Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026

FAO The Court
C/O HTU Assessors Ltd
The Old Courthouse
18-22 St Peters Churchyard
Derby
DE1 1NN

TOTAL LOSS REPORT

Dear Sirs



RE: Road traffic Accident: Mohammed Adam Ibrahim: 21/12/2025


In accordance with your instructions received on 05/01/2026 requesting us to provide an independent accident damage report, we assessed the damage on 06/01/2026. Vehicle located at ITV Solutions, Cotton Brook Road, Derby, Derbyshire, DE23 8YJ. Our findings are as detailed below:

Make	FORD	Registration	BP15YLB
Model	TRANSIT CUSTOM 270	Status	T/Loss
Category	S	Salvage Value	£253.60
Repair Cost	£18,630.06	Legal Status	Unroadworthy
Engineer Value	£5,072.00	Impact Magnitude	Heavy



Impact Area





Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026

NATURE OF INCIDENT

The vehicle has suffered heavy collision/impact damage to the right hand rear, and moderate collision/impact to the right hand front.

ENGINEER'S COMMENTS

20% has been deducted from the pre accident valuation due to the vehicle being a previous total loss.

Please note the vehicle is unroadworthy as the rear body has been compromised.

vehicle value includes vat.

VEHICLE HISTORY CHECK

According to the Experian database; Category N total loss claim Non Structural Damage See the Condition details An entry exists on the MIAFTR register to this effect dated 16/12/2024, loss dated 26/11/2024

PRE-INCIDENT CONDITION


The vehicle is considered to be in good condition for its age and type.

SETTLEMENT

We consider that an equitable settlement would be £4,818.40 which represents the pre-accident engineer value of the vehicle of £5,072.00 less the value of the salvage of £253.60.

SALVAGE

Under the current salvage categorisation matrix, **within the scope of our inspection**, we consider that this is Category S, (Structural damage) and can be sold as repairable salvage. Further information is available www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £253.60 excluding VAT. **We have not taken any action towards removal of the salvage at this time.**



Our Ref: htu26001

Your Ref: BP15 YLB


Date: 07/01/2026

Vehicle Data

Retail Value	£5,284.00
Trade Value	£4,174.00
Engineer's Value	£5,072.00
Glass's Code	CLPK
VIN	WFOYXXTTGYFY89705
Odometer	130583
Engine	2198
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	

Main new parts required

Right Headlamp, Complete (with Indicator) Right Front Wing Repair Kit Front Grille Front Trim Rear Bumper, Centre Rear Bumper Reinforcement Right Rear Bumper Side Bracket Right Rear Side Panel Right Rear Side Panel Reinforcement Right Side Panel Cover Trim Lower Front Right Side Glass Repair/Bonding Kit Rear Panel Right Rear Panel Side Reinforcement Right Back Door Right Upper Back Door Hinge Right Back Door Checkstrap Boot Lid/Back Door/Tailgate Lwr Striker Right Handle Retainer/Plate Left Back Door Side Handle Inner Seal Boot Lid/Back Door/Tailgate Badge Right Back Door Sealing Compound Right Lower Tailgate/Back Door Trim	Right Front Wing Right Front Wing Panel Screw Right Bonnet Hinge Right Rear Bumper Corner Left Rear Bumper Side Bracket Right Rear Lamp, Complete Right Lower Side Panel Rear Extension Right Rear Side Panel Reinforcement rear Right Side Panel Air Vent Grille Right Side Panel Liner Rear Panel Reinforcement Right Back Panel Part Corner Panel Right Tailgate Plastic Cover Right Lower Back Door Hinge Right Side Latch with Central Locking Right Boot Lid/Back Door/Tailgate Outer Handle Right B/Lid/B.Dr/T/gate Outer Handle Cover Right Back Door Side Handle Inner Seal Right Boot Lid/Back Door/Tailgate Side Emblem Right Upper Tailgate/Back Door Trim
---	---



Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026

Additional operations

.Assessment Damage Appraisal Charge

.Sundries

.System Diagnostic Check (Pre Repair)

.Wash/Clean

.Standard shutdown

Paint Front Cover

Paint Right Front Door, Complete

Paint Right Rear Side Panel Protective Moulding,
Front

Paint Right Back Door, Complete (Glazed)

Paint Prep. metal (on vehicle without pre-painting)

Paint Colour mixing (1)

.QC & Road Test

.System Diagnostic Check (Post Repair)

.Vehicle Care Kit

Check tyre OSR

Wheel Alignment (check)

Paint Right Front Wing, Complete

Paint Right Rear Side Panel, Complete (Glazed)

Paint Left Back Door, Complete (Glazed)


Paint Rear Panel, Complete

Paint Prep. synthetics (combined-operation work)

Paint Sample colour creation (1)

Repair Cost Calculations

Hours	74.40
Hourly Rate	£83.28
Total Labour	£6,196.03
Parts	£6,515.71
Paint/Materials	£2,493.52
Specialist/Other	£319.79
Sub total	£15,525.05
Vat	£3,105.01
Total Estimated Cost	£18,630.06




Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: ht26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: ht26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026







Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026







Our Ref: ht26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: ht26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: ht26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: ht26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026






Our Ref: htu26001

Your Ref: BP15 YLB

Date: 07/01/2026





Our Ref: ht26001

Your Ref: BP15 YLB

Date: 07/01/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk