

Our Ref: htu26004

Your Ref: LB08FOA

Date: 20/01/2026

FAO The Court
C/O HTU Assessors Ltd
The Old Courthouse
18-22 St Peters Churchyard
Derby
DE1 1NN

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Id Said Hussein : 13/01/2026

In accordance with your instructions received on 19/01/2026 requesting us to provide an independent accident damage report, we assessed the damage on 20/01/2026. Vehicle located at ITV Solutions, Cotton Brook Road, Derby, Derbyshire, DE23 8YJ. Our findings are as detailed below:

Make	SUZUKI	Registration	LB08FOA
Model	SPLASH GLS+ AUTO	Status	T/Loss
Category	S	Salvage Value	£122.90
Repair Cost	£5,501.40	Legal Status	Unroadworthy
Engineer Value	£2,458.00	Impact Magnitude	Moderate




Impact Area



Document produced
using the EVA system

www.CollisionEngineers.co.uk



Our Ref: htu26004

Your Ref: LB08FOA

Date: 20/01/2026

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand side.

ENGINEER'S COMMENTS

20% has been deducted from the pre accident valuation due to the vehicle being a previous total loss.

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the offside.

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record See the plate change details. Category S total loss claim Structural Damage See the Condition details An entry exists on the MIAFTR register to this effect dated 28/10/2021, loss dated 07/09/2018

PRE-INCIDENT CONDITION


The vehicle is considered to be in good condition for its age and type.

SETTLEMENT

We consider that an equitable settlement would be £2,335.10 which represents the pre-accident engineer value of the vehicle of £2,458.00 less the value of the salvage of £122.90.

SALVAGE

Under the current salvage categorisation matrix, **within the scope of our inspection**, we consider that this is Category S, (Structural damage) and can be sold as repairable salvage. Further information is available www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £122.90. **We have not taken any action towards removal of the salvage at this time.**



Our Ref: htu26004

Your Ref: LB08FOA

Date: 20/01/2026

Vehicle Data

Retail Value	£3,072.00
Trade Value	£1,475.00
Engineer's Value	£2,458.00
Glass's Code	BJ3Q
VIN	TSMEXB32S00113100
Odometer	66655
Engine	1242
Fuel	Petrol
Extras	
Condition	Good
Unrelated Damage	

Main new parts required


Right Front Door Shell
Right Front Door Rear Adhesive Foil
Right Front Door Outer Handle
Right Front Door Trim Support Kit

Right Front Door Membrane
Right Front Door Electric Window Regulator
Right Sill Panel
Right Front Door Trim Clip

Repairs required

Right Rear Door Shell

Right Rear Side Panel



Our Ref: htu26004

Your Ref: LB08FOA

Date: 20/01/2026


Additional operations

.Assessment Damage Appraisal Charge
.Pre repair cleaning charge
.Standard shutdown
.System Diagnostic Check (Post Repair)
.Vehicle Care Kit
Boron Drill
Corrosion Protection
Corrosion Protection additional panel
Wheel Alignment (check)
Paint Right Front Door, Complete
Paint Right Rear Door, Complete
Paint Right Rear Side Panel, Complete
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

.Environmental Charge
.QC & Road Test
.Sundries
.System Diagnostic Check (Pre Repair)
.Wash/Clean
Check tyre OSF
Corrosion Protection additional panel
OSR tyre
Paint Right Front Wing, Complete
Paint Right Front Door Outer Handle
Paint Right Sill Panel, Outer
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

Repair Cost Calculations

Hours	28.30
Hourly Rate	£83.28
Total Labour	£2,356.82
Parts	£709.08
Paint/Materials	£964.52
Specialist/Other	£554.08
Sub total	£4,584.50
Vat	£916.90
Total Estimated Cost	£5,501.40




Our Ref: htu26004

Your Ref: LB08FOA

Date: 20/01/2026






Our Ref: htu26004

Your Ref: LB08FOA

Date: 20/01/2026






Our Ref: htU26004

Your Ref: LB08FOA

Date: 20/01/2026







Our Ref: htu26004

Your Ref: LB08FOA

Date: 20/01/2026






Our Ref: htu26004

Your Ref: LB08FOA

Date: 20/01/2026






Our Ref: htu26004

Your Ref: LB08FOA

Date: 20/01/2026






Our Ref: htu26004

Your Ref: LB08FOA

Date: 20/01/2026






Our Ref: htu26004

Your Ref: LB08FOA

Date: 20/01/2026






Our Ref: htu26004

Your Ref: LB08FOA

Date: 20/01/2026





Our Ref: htu26004

Your Ref: LB08FOA

Date: 20/01/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk