

Our Ref: oak25155

Your Ref: GHE/WHITEFORD/
S428279.00

Date: 15/05/2025

FAO The Court
C/o Oakwood Solicitors
1 West Regent Street
Glasgow
Scotland
G2 1RW

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Andrew Whiteford: 08/05/2025

In accordance with your instructions received on 09/05/2025 requesting us to provide an independent accident damage report, we assessed the damage on 15/05/2025. Vehicle located at A76 Recovery Ltd, Newton Terrace, Catrine, Mauchline, Ayrshire, KA5 6SA. Our findings are as detailed below:


Make	HONDA	Registration	MK16YLJ
Model	CR-V SR I-DTEC 4X2	Status	T/Loss
Category	N	Salvage Value	£1,212.50
Repair Cost	£14,334.36	Legal Status	Unroadworthy
Engineer Value	£12,125.00	Impact Magnitude	Heavy



Impact Area



Document produced
using the EVA system



Our Ref: oak25155

Your Ref: GHE/WHITEFORD/
S428279.00

Date: 15/05/2025

NATURE OF INCIDENT

The vehicle has suffered heavy collision/impact damage to the rear.

ENGINEER'S COMMENTS

15/05/2025 - Please note the vehicle is unroadworthy as the rear body has been compromised.

16/05/25 - UPDATED REPORT: - The vehicle owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £12,125.00

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £10,912.50 which represents the pre-accident engineer value of the vehicle of £12,125.00 less the value of the salvage of £1,212.50.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £1,212.50. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£10,760.00
Trade Value	£9,039.00
Engineer's Value	£12,125.00
Glass's Code	R9CH
VIN	SHSRE6700FU217314
Odometer	67973
Engine	1597
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	



Our Ref: oak25155

Your Ref: GHE/WHITEFORD/
S428279.00

Date: 15/05/2025

Main new parts required


Right Rear Door Covering Sheet (Skin)
Rear Bumper Cover
Right Rear Bumper Side Protection Trim
Right Rear Bumper Side Bracket
Right Rear Bumper Outer Side Distance-Sensor
Right Upper Rear Lamp
Right Side Rear Fog Lamp, Complete
Right Side Panel W/arch Protective Moulding
Right Side Glass Weatherstrip Front
Right Side Glass Repair/Bonding Kit
Tailgate
Boot Lid/Back Door/Tailgate Moulding
Right Rear Window Weatherstrip
Rear Window Repair/Bonding Kit
Tailgate/Boot Lid Trim Support Kit

Rear Bumper Lining
Rear Bumper Reinforcement
Left Rear Bumper Side Bracket
Rear Bumper Repair Kit
Right R. Bumper Inner Distance-Sensor Bracket
Right Lower Rear Lamp
Right Rear Side Panel
Left Side Glass Weatherstrip Front
Left Side Glass Repair/Bonding Kit
Rear Panel
Boot Lid/Tailgate Cover
Left Rear Window Weatherstrip
Rear Window Lower Weatherstrip
Rear Exhaust Silencer
Tailgate/Boot Lid Trim Clip

Additional operations

Assessment Damage Appraisal Charge
Clamp and Pull
Energy cost supplement
Identify the presence of ADAS
Panel Bonding Kit
Repair method research charge
Second man lift
Sundries
System Diagnostic Check (Pre Repair)
Wash/Clean
Paint Left A-Post, Upper
Paint Right Rear Door, Complete
Paint Right Rear Side Panel, Complete
Paint Tailgate Cover, Lower
Paint Rear Bumper k/e
Paint Rear Bumper Cover, Centre e
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

Boron Drill
De-nib/ polish
Environmental Charge
OSR tyre
QC & Road Test
Seam Sealant
Standard shutdown
System Diagnostic Check (Post Repair)
Vehicle Care Kit
Wheel Alignment (4 wheel)
Paint Right A-Post, Upper
Paint Left Rear Side Panel, Complete
Paint Tailgate (with Window Frame)
Paint Rear Panel, Complete
Paint Rear Bumper Reinforcement
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)



Our Ref: oak25155


Your Ref: GHE/WHITEFORD/
S428279.00

Date: 15/05/2025

Repair Cost Calculations

Hours	42.90
Hourly Rate	£80.00
Total Labour	£3,432.00
Parts	£5,596.12
Paint/Materials	£1,921.32
Specialist/Other	£995.86
Sub total	£11,945.30
Vat	£2,389.06
Total Estimated Cost	£14,334.36







Our Ref: oak25155

Your Ref: GHE/WHITEFORD/
S428279.00

Date: 15/05/2025






Our Ref: oak25155

Your Ref: GHE/WHITEFORD/
S428279.00

Date: 15/05/2025






Our Ref: oak25155

Your Ref: GHE/WHITEFORD/
S428279.00

Date: 15/05/2025





Our Ref: oak25155

Your Ref: GHE/WHITEFORD/
S428279.00

Date: 15/05/2025

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: oak25155

Your Ref: GHE/WHITEFORD/
S428279.00

Date: 15/05/2025

FAO The Court
C/o Oakwood Solicitors
1 West Regent Street
Glasgow
Scotland
G2 1RW

Fee Note

MK16YLJ.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £180.00

Sub Total: £180.00

VAT: £36.00

Total Due: £216.00

Payment

Please make cheques payable to Collision Engineers and quote reference oak25155.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o Oakwood Solicitors confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10