

Our Ref: qdos221388

Your Ref: RGM/14283/1

Date: 22/08/2022

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: Martin Bull: 14/08/2022

In accordance with your instructions received on 16/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 22/08/2022. Vehicle located at Image based assessment. Our findings are as detailed below:


Make	MERCEDES-BENZ	Registration	M6JBU
Model	E 220 AMG LINE ED PR	Status	Repair
Category		Salvage Value	
Repair Cost	£2,747.69	Legal Status	Roadworthy
Engineer Value	£31,230.00	Impact Magnitude	Light to Moderate



Impact Area



Document produced
using the EVA system



Our Ref: qdos221388
Your Ref: RGM/14283/1

Date: 22/08/2022

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the right hand side.

VEHICLE HISTORY CHECK

22/08/2022 - According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £2,750.00 would be reasonable on this occasion.

Vehicle Data

Retail Value	£31,230.00
Trade Value	£28,490.00
Engineer's Value	£31,230.00
Glass's Code	
VIN	W1K2130042A762882
Odometer	25460
Engine	1950
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	


Main new parts required

Right Front Door Window Outer Channel Strip
Right Rear Door Trim Support Kit

Right Rear Door Outer Window Channel Strip
Right Rear Door Trim Screw

Repairs required

Right Rear Door Shell



Our Ref: qdos221388
Your Ref: RGM/14283/1

Date: 22/08/2022

Additional operations

Corrosion Protection Materials
System Diagnostic Check (Post Repair)
Car Care Kit
Environmental Charge
Wash/Clean
Paint Right Front Door Outer Handle
Paint Right Rear Door Outer Handle
Paint Right Rear Side Panel, Complete
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)
Job Allowance

Repair Method Research Allowance
System Diagnostic Check (Pre Repair)
De-Nib/Polish
Final Inspection & Road Test
Paint Right Front Door, Complete
Paint Right Rear Door, Complete
Paint Right Roof Panel, Side
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)
Drop Rear Bumper Corner
Covid Clean

Repair Cost Calculations

Hours	17.60
Hourly Rate	£80.00
Total Labour	£1,408.00
Parts	£122.70
Paint/Materials	£579.04
Specialist/Other	£180.00
Sub total	£2,289.74
Vat	£457.95
Total Estimated Cost	£2,747.69