

Our Ref: dfd22084

Your Ref: RJP/KIRBY

Date: 23/08/2022

FAO. The Court
C/o Davison Flynn Duke
Chester Street
Birkenhead
CH41 5DL

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: Tracy Kirby: 09/08/2022

In accordance with your instructions received on 09/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 23/08/2022. Vehicle located at Car 2 Go, 220 Price Street, Birkenhead. Our findings are as detailed below:


Make	AUDI	Registration	T90PPE
Model	Q7 S LINE + TDI QUAT	Status	Repair
Category		Salvage Value	
Repair Cost	£7,452.06	Legal Status	Unroadworthy
Engineer Value	£15,390.00	Impact Magnitude	Moderate



Impact Area



Document produced
using the EVA system



Our Ref: dfd22084

Your Ref: RJP/KIRBY

Date: 23/08/2022

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand side.

ENGINEER'S COMMENTS

Please note the vehicle is unroadworthy due to the damaged nearside step.

VEHICLE HISTORY CHECK

23/08/2022 - According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £7,475.00 would be reasonable on this occasion.

Vehicle Data


Retail Value	£15,390.00
Trade Value	£11,940.00
Engineer's Value	£15,390.00
Glass's Code	PH3V
VIN	WAUZZZ4L8ED005241
Odometer	97271
Engine	2967
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	

Main new parts required

L/Wing Badge L/F Door Handle L/R Door L/R Door Insulation L/R Door Trim Front L/R Door Lower Cover L/R Door Insulation L/R Outer Sill Mldg L/R Bumper Guide L/R Extension Rear Sundry Parts	L/F Extension Rear L/F Door Cover L/R Outer Door Seal L/R Door Clamp Kit L/R Door Trim Rear L/R Door Prot Foil L/F Outer Sill Mldg L/Side Step L/R Extension Front Car Care Kit
---	--

Repairs required

Left Front Door L/R Side Panel	Rear Bumper
-----------------------------------	-------------



Our Ref: dfd22084

Your Ref: RJP/KIRBY

Date: 23/08/2022

Additional operations

Check And Clean Car
Check And Road Test
Paint L/R Door New Part Painting
Paint L/F Door Handle New Part Paint K1r
Paint L/R Door Lower Covernew Part Paint K1r
Paint L/R Extension Rear New Part Paint K1r
Paint Rear Bumper Repair Paint Plastic
Paint L/R Side Panel Repair Painting <50%
Paint Preparation For Pre-Painting
Epa Chrg
Covid Cleaning
4 Wheel Alignment Specialist

Check And Quality Control
Check Technical Info
Paint L/F Extension Rear New Part Paint K1r
Paint L/F Door Cover New Part Paint K1r
Paint L/R Extension Front New Part Paint K1r
Paint Left Front Door Repair Painting <50%
Paint Rear Bumper Spoiler Repair Paint Plastic
Blend L/F Wing Surface Paint
Estimate Fee
Bs10125 Compliance Specialist
Ecu Sweep/Resets
Corrosion Protection Materials External

Repair Cost Calculations

Hours	29.50
Hourly Rate	£65.00
Total Labour	£1,917.50
Parts	£2,597.77
Paint/Materials	£1,326.78
Specialist/Other	£368.00
Sub total	£6,210.05
Vat	£1,242.01
Total Estimated Cost	£7,452.06



08c22659-86d0-4ffb-86d3-f92a0523f8f4.jpg



9b72b928-cbf1-48d5-911f-791ac065ede4.jpg



13d37b9c-dcec-46fb-8931-07de8eae7bbf.jpg



31ee1cbb-7c8b-4b4f-a873-1eda85c4ff34.jpg



86a18ccc-ba06-4b8d-a557-df23a6213577.jpg



651ceaf9-f267-4209-ad0e-fa8e00a140f7.jpg



7371d1ad-e72a-49af-b2d5-39ba51104a3e.jpg



14284b94-0401-4b37-855f-b1b8e45c566c.jpg



060980f3-a8d4-4025-982e-efe7a8e5b84b
(1).jpg



b5c6530c-0a88-4064-
b4f8-09dfdde96de1.jpg



cd5fb75b-f6df-46df-841d-3a721ec6ad87.jpg



d59a69e5-0f39-4bb9-b7b0-08f71081e9f7.jpg



d4487dca-45bd-4fad-8710-15e7ece64667.jpg



d4487dca-45bd-4fad-8710-15e7ece64667-1.jpg



ed2c95a5-2d95-4819-8863-3dfc2acfc50a(1).jpg



f7e4df67-b2f2-4d3e-9ca3-1d5783739504.jpg



fc8a0170-d173-4ffa-9faf-7d955219d7af.jpg



fc5966e9-1054-4e27-85a4-550332b9cfde.jpg



2a43c7a8-eff6-4a5d-b77b-e4cb6aa7fad9.jpg



03b21ed8-9654-400e-afcb-24976e56fb36.jpg



3fa903af-db9f-4d60-bc27-695ef3b60e85.jpg




4b32f4c4-0fda-4d2d-9e24-dcc4916488c7.jpg



7a3bb751-af60-4d94-93f2-e3ae61df9639.jpg



a1b9f046-3687-4fe6-bf3e-3dbe6300358e.jpg



Our Ref: dfd22084

Your Ref: RJP/KIRBY

Date: 23/08/2022

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: dfd22084

Your Ref: RJP/KIRBY

Date: 23/08/2022

FAO. The Court
C/o Davison Flynn Duke
Chester Street
Birkenhead
CH41 5DL

Fee Note

T90PPE.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £150.00

Sub Total: £150.00

VAT: £30.00

Total Due: £180.00

Payment

Please make cheques payable to Collision Engineers and quote reference dfd22084.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o Davison Flynn Duke confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10