

Mr Kajaruban Kaliyugavarathan
16 Godwin Close
Sewardstone Road
E
E4 7RQ


Date: 12/03/2026
Our Ref: 00031985/HASSANA
Your Ref: EHR97928

To the Court REPAIRABLE REPORT

Dear Sirs,

Client: **Mr Kajaruban Kaliyugavarathan**

We refer to your instructions received on **10 March 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: AUDI Q4 E-TRON S LINE 40		Colour: GREY	Speedo: 26359 Miles	
Reg No: EX24KKV	Registered: Mar 2024	Type: Estate	Trans: Automatic	
Vin No: WAUZZZFZ9RP017176	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manfd: 2024			
Brakes: Not Known	Tax Exp:			Spare Tyre Not Known
Steering: Not Known	Fuel: Electric			Centre Belt Not Tested
Extras: Not Seen	C.C.: 0			
Air Bags Deployed: Not Known	BHP: 201.	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Damage: Light Collision/Impact Rear	Incident: 07/03/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Vehicle Value: £28,085.00		Repair Cost: £1,243.57 inc VAT (4.43% of PAV)	Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light collision/impact damage to the rear.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Bumper Moulding, Car Care Kit, Sundry Parts

Specialist/Sundry charges:-Epa, Pas 2060 / Aries, Methods Research Specialist, Bsi Compliance

Remove And Refit parts:-Description, Rear Bumper Cover Cpl Remove And Refit, Rear Bumper Moulding

Parts to check:-Rear Upper Bumper, Rear Lower Bumper, Rear Bumper Support, Adas Exploration, Qc & Road Test, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vacuum, Power Down Ev/Hybrid, Electric Risk Assess, Est Pre Wash

COST OF REPAIRS

The repairers, South East Automotive Ltd (Tel. 02089840022), have compiled an estimate in the sum of £850.00 plus parts at manufacturer's list prices plus £118.00 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 10 hours at a rate of £85.00 per hour. The cost of the necessary replacement parts will be approximately £68.31, the specialist/sundry charges will be £118.00, the VAT liability on this repair will amount to some £207.26 giving a total repair cost of £1,243.57 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 13/03/2024. The corresponding Glass's Guide (model code: 358326001) adjusted retail value for vehicles of this type and age in the March 2026 guide is £28,085.00 at 26359 Miles, trade value is £25,249.00 and mid value is £26,667.00. We place the pre-accident value of this particular vehicle at £28,085.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £1,250.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have issued verbal authorisation to the repairers to proceed with the work, on the 12th March 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE


In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

A rectangular box containing a handwritten signature in black ink that reads "H. ANWAR".

Hassan Anwar ATA VDA
Exclusive Vehicle Assessors