

Our Ref: htu26022

Your Ref: AP63EYL

Date: 10/06/2026

FAO The Court
C/O HTU Assessors Ltd
The Old Courthouse
18-22 St Peters Churchyard
Derby
DE1 1NN

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Sabaal Ahmed: 06/06/2026

In accordance with your instructions received on 08/06/2026 requesting us to provide an independent accident damage report, we assessed the damage on 09/06/2026. Vehicle located at ITV Solutions, Cotton Brook Road, Derby, Derbyshire, DE23 8YJ. Our findings are as detailed below:


Make	VOLKSWAGEN	Registration	AP63EYL
Model	PASSAT HIGHLINE TDI	Status	T/Loss
Category	N	Salvage Value	£114.75
Repair Cost	£4,598.32	Legal Status	Roadworthy
Engineer Value	£2,295.00	Impact Magnitude	Light to Moderate



Impact Area



Document produced
using the EVA system



Our Ref: htu26022

Your Ref: AP63EYL

Date: 10/06/2026

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the left hand side.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £2,180.25 which represents the pre-accident engineer value of the vehicle of £2,295.00 less the value of the salvage of £114.75.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £114.75. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£2,295.00
Trade Value	£1,606.00
Engineer's Value	£2,295.00
Glass's Code	L8V6
VIN	WVWZZZ3CZEE070759
Odometer	224028
Engine	1968
Fuel	Diesel
Extras	
Condition	Good



Our Ref: htu26022

Your Ref: AP63EYL

Date: 10/06/2026

Main new parts required

Left Front Door Shell
Left Front Door Lower Cover
Left Front Door Outer Handle Seal
Left Front Door Insulation

Left Front Door Seal
Left Front Door Electric Window Regulator
Left Front Door Trim Outer Seal
Left Front Door Trim Support Kit

Repairs required

Left Rear Door Shell


Additional operations

nsf door protective strip
.Assessment Damage Appraisal Charge
.Pre repair cleaning charge
.Standard shutdown
.System Diagnostic Check (Post Repair)
.Vehicle Care Kit
Corrosion Protection
Load / Unload vehicle to ramp
Polish
Paint Left Front Wing, Complete
Paint Left Front Door Protective Moulding
Paint Left Rear Door, Complete
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

bolts for door hinges
.Environmental Charge
.QC & Road Test
.Sundries
.System Diagnostic Check (Pre Repair)
.Wash/Clean
Corrosion Protection additional panel
Panel repair sundries (including body fi
Second man lift
Paint Left Front Door, Complete
Paint Left Front Door Outer Handle
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

Repair Cost Calculations

Hours	19.60
Hourly Rate	£83.28
Total Labour	£1,632.29
Parts	£1,151.40
Paint/Materials	£720.72
Specialist/Other	£327.52
Sub total	£3,831.93
Vat	£766.39
Total Estimated Cost	£4,598.32




Our Ref: ht26022

Your Ref: AP63EYL

Date: 10/06/2026






Our Ref: ht26022

Your Ref: AP63EYL

Date: 10/06/2026






Our Ref: ht26022

Your Ref: AP63EYL

Date: 10/06/2026






Our Ref: ht26022

Your Ref: AP63EYL

Date: 10/06/2026






Our Ref: ht26022

Your Ref: AP63EYL

Date: 10/06/2026






Our Ref: ht26022

Your Ref: AP63EYL

Date: 10/06/2026






Our Ref: htu26022

Your Ref: AP63EYL

Date: 10/06/2026






Our Ref: ht26022

Your Ref: AP63EYL

Date: 10/06/2026





Our Ref: ht26022

Your Ref: AP63EYL

Date: 10/06/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk