

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

TOTAL LOSS REPORT

Dear Sirs



RE: Road traffic Accident: Mrs Surinder Gill: 25/09/2025


In accordance with your instructions received on 30/09/2025 requesting us to provide an independent accident damage report, we assessed the damage on 01/10/2025. Vehicle located at Image Based Assessment. Our findings are as detailed below:

Make	MERCEDES-BENZ	Registration	LL65WNE
Model	A 180 D SPORT AUTO	Status	T/Loss
Category	S	Salvage Value	£1,537.65
Repair Cost	£9,139.10	Legal Status	Unroadworthy
Engineer Value	£9,045.00	Impact Magnitude	Heavy



Impact Area





Our Ref: qdos251670

Your Ref: MFI/39932/1

Date: 01/10/2025

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered heavy collision/impact damage to the rear.

ENGINEER'S COMMENTS

Please note the vehicle is unroadworthy as the rear body has been compromised.

7/10/2025 - UPDATED REPORT: - The vehicle owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £9045.00

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £7,507.35 which represents the pre-accident engineer value of the vehicle of £9,045.00 less the value of the salvage of £1,537.65.

SALVAGE

Under the current salvage categorisation matrix, **within the scope of our inspection**, we consider that this is Category S, (Structural damage) and can be sold as repairable salvage. Further information is available www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £1,537.65. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£8,250.00
Trade Value	£6,110.00
Engineer's Value	£9,045.00
Glass's Code	7XQY
VIN	WDD1760122V118284
Odometer	70175
Engine	1461
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	



Our Ref: qdos251670

Your Ref: MFI/39932/1

Date: 01/10/2025

Main new parts required

Rear Bumper Lining
Right Rear Bumper Side Impact Absorber/Filler
Right Rear Bumper Side Impact Absorber (Tube)
Rear Bumper Reinforcement
Right Rear Bumper Side Upper Reinforcement
Left Rear Bumper Spacer
Rear Bumper Parking Aid Wiring
Right Rear Lamp, Complete
Right Side Panel Liner
Tailgate
Boot Lid/Back Door/Tailgate Striker
Boot Lid/Back Door/Tailgate Badge
Rear Window Repair/Bonding Kit (both)

Left Rear Bumper Side Impact Absorber/Filler
Left Rear Bumper Side Impact Absorber (Tube)
Rear Bumper Spoiler
Left Rear Bumper Side Upper Reinforcement
Rear Bumper Lower Reinforcement
Right Rear Bumper Spacer
Left Rear Lamp, Complete
Left Side Panel Liner
Rear Panel
Latch with Central Locking
Boot Lid/Tailgate Push Button
Left Side Emblem (Engine Designation)
Lower Tailgate/Back Door Trim

Repairs required

Spare Wheel Well

Additional operations

Jig set up, clamp and pull
Assessment Damage Appraisal Charge
Energy Cost Supplement
Identify the presence of ADAS
Panel Repair Sundries (including body fi
Sundries
System Diagnostic Check (Pre Repair)
Wheel alignment
Paint Right A-Post, Upper
Paint Right Rear Side Panel, Complete
Paint Rear Floor
Paint Rear Skirt, Centre e
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)


Final Inspection & Road Test
De-Nib/Polish
Environmental Charge
Panel Bonding Kit
Repair Method Research Charge
System Diagnostic Check (Post Repair)
Wash/Clean
Paint Left A-Post, Upper
Paint Left Rear Side Panel, Complete
Paint Tailgate (with Window Frame)
Paint Rear Panel, Complete
Paint Rear Bumper k/e
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)


Repair Cost Calculations

Hours	36.80
Hourly Rate	£80.00
Total Labour	£2,944.00
Parts	£2,696.30
Paint/Materials	£1,380.62
Specialist/Other	£595.00
Sub total	£7,615.92
Vat	£1,523.18
Total Estimated Cost	£9,139.10









Our Ref: qdos251670

Your Ref: MFI/39932/1

Date: 01/10/2025

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: qdos251670

Your Ref: MFI/39932/1

Date: 01/10/2025

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

Fee Note

LL65WNE.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference qdos251670.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10