

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Mr Sheinabia Dinani: 18/09/2025


In accordance with your instructions received on 19/09/2025 requesting us to provide an independent accident damage report, we assessed the damage on 23/09/2025. Vehicle located at Image Based Assessment. Our findings are as detailed below:

Make	MERCEDES-BENZ	Registration	PL71LUB
Model	E 300 AMG LN NGT ED	Status	T/Loss
Category	S	Salvage Value	£6,341.50
Repair Cost	£22,535.45	Legal Status	Unroadworthy
Engineer Value	£28,825.00	Impact Magnitude	Moderate to Heavy



Impact Area





Our Ref: qdos251582

Your Ref: AAN/MR/39783/2

Date: 25/09/2025

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate to heavy collision/impact damage to the left hand side.

ENGINEER'S COMMENTS

The mileage has been calculated from online MOT data.

Please note the bonnet and wing are made from aluminum.

25/9/2025 - Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the nearside front.

29/9/2025 - UPDATED REPORT: - The vehicle owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £28825.00

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £22,483.50 which represents the pre-accident engineer value of the vehicle of £28,825.00 less the value of the salvage of £6,341.50.

SALVAGE

Under the current salvage categorisation matrix, **within the scope of our inspection**, we consider that this is Category S, (Structural damage) and can be sold as repairable salvage. Further information is available www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £6,341.50. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£27,240.00
Trade Value	£22,760.00
Engineer's Value	£28,825.00
Glass's Code	
VIN	W1K2383832F179019
Odometer	76900
Engine	1991
Fuel	
Extras	
Condition	Good
Unrelated Damage	



Our Ref: qdos251582

Your Ref: AAN/MR/39783/2

Date: 25/09/2025

Main new parts required


Front Bumper Lining
Left Front Bumper Outer Bracket
Left Front Bumper Side Grille
Left Front Bumper Outer Distance-Sensor
Front Bumper Lining Clip
Front Bumper Lining Nut
Left Front Wing
Left Front Wing Liner, Front
Left Front Wing Closing Panel
Left Front Wing Panel Nut
Bonnet Insulation Repair/Fastening Kit
Bonnet Clip
Left Rear Bumper Side Bracket
Left Side Glass Repair/Bonding Kit
Left Side Panel Liner
Rear Window Repair/Bonding Kit
Rear Window Moulding
Left Front Suspension Strut w/Shock Absorber

Left Front Bumper Lower Support
Left Front Bumper Inner Bracket
Front Bumper Repair kit
Left Front Bumper Outer Distance-Sensor Brkt
Front Bumper Lining Screw
Left LED Headlamp (with Indicator)
Left Front Wing Repair Kit
Left Front Wing Liner, Rear
Left Front Wing Panel Screw
Bonnet
Bonnet Badge
Left Sill Panel Protective Mldg Rear Fastener
Left Rear Side Panel
Left Rear Wheelarch, Outer
Left Side Panel Upper Liner
Rear Window Primer
Left Front Suspension Lower Rear Arm

Repairs required

Left Front Door Shell

Rear Bumper Lining



Our Ref: qdos251582

Your Ref: AAN/MR/39783/2

Date: 25/09/2025


Additional operations

Check door mirror
 Assessment Damage Appraisal Charge
 Clamp and Pull
 Electric / hybrid risk assessment
 Energy cost supplement
 Load / Unload vehicle to ramp
 NSF tyre
 Pre repair cleaning charge (including sa
 Repair method research charge
 Second man lift (bonnet)
 Sundries
 System Diagnostic Check (Pre Repair)
 Vehicle Care Kit
 Water test
 Wheel Alignment (4 wheel)
 Paint Left Front Wing, Complete
 Paint Bonnet
 Paint Left Front Door, Complete F
 Paint Left Sill Panel Protective Moulding
 Paint Left Rear Side Panel, Complete F
 Paint Rear Bumper k/e
 Paint Prep. metal (on vehicle without pre-painting)
 Paint Colour mixing (1)

Alloy wheel refurbishment (diamond cut) NSF
 Boron Drill
 Corrosion Protection
 Electric / hybrid shutdown and power up
 Environmental Charge
 NSF tyre
 Panel repair sundries (including body fi
 QC & Road Test
 Seam Sealant
 Standard shutdown
 System Diagnostic Check (Post Repair)
 Touch up bolts
 Wash/Clean
 Welded / bonded panel (materials)
 Paint Front Bumper
 Paint Right Front Wing, Complete
 Paint Left A-Post, Inner Lower
 Paint Left Front Door Outer Handle
 Paint Left Roof Panel, Side
 Paint Boot Lid, Upper
 Paint Right Rear Bumper Towing Hook Cover
 Paint Prep. synthetics (combined-operation work)
 Paint Sample colour creation (1)

Repair Cost Calculations

Hours	67.10
Hourly Rate	£113.85
Total Labour	£7,639.34
Parts	£6,827.76
Paint/Materials	£2,816.86
Specialist/Other	£1,495.58
Sub total	£18,779.54
Vat	£3,755.91
Total Estimated Cost	£22,535.45




Our Ref: qdos251582

Your Ref: AAN/MR/39783/2

Date: 25/09/2025







Our Ref: qdos251582

Your Ref: AAN/MR/39783/2


Date: 25/09/2025














Our Ref: qdos251582

Your Ref: AAN/MR/39783/2

Date: 25/09/2025

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: qdos251582

Your Ref: AAN/MR/39783/2

Date: 25/09/2025

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

Fee Note

PL71LUB.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference qdos251582.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10