

Calculation

Client:	
Make / Model / Type:	Kia / e Niro 5 door SUV Model 2019 / e Niro EV (201bhp) 64 kWh Lithium-ion SUV Auto 2 [6.2021]
Glass's national Code	335662001
Vehicle Registration Number:	LT72PYX
VIN:	KNACP811UP5022010
Date:	21.9.2023
Paint system:	AZT
Hail damage logic:	ETG
Labour time unit:	1 Hour
Currency:	£
Database version:	2023.09.

Body		Repair type	Labour time	Overlap-time	Labour costs	Material costs
82850R00	Roof Moulding (L)	UI	0.20			0.00
82850R00	Roof Moulding (R)	UI	0.20			0.00
86651R00	Rear Bumper Lining	RP	0.60	0.80		155.92
NN	Rear Bumper Spoiler					
	Selected criteria: Park Assistant System Rear					
50200R00	Rear Bumper Side Impact	RP	0.00	1.00		36.43
	Absorber (Tube) (L)					
50200R00	Rear Bumper Side Impact	RP	0.00	1.00		36.43
	Absorber (Tube) (R)					
86630R00	Rear Bumper Reinforcement	RP	0.00	1.00		120.02
86612R00	Rear Bumper Protection Trim	RP	0.00	1.30		143.72
86695R00	Rear Bumper Stoneguard	RP	0.00	0.20		46.22
86613R00	Rear Bumper Side Bracket	RP	0.10	0.80		14.81
	(L)					
86613R00	Rear Bumper Side Bracket	RP	0.10	0.80		14.81
	(R)					
NN	Rear Bumper Lower Support	RP	0.00	0.90		2.72
	Annotation (time): Autovista opinion time					
NN	Rear Bumper Lower Support	RP	0.00	0.90		3.21
	(L)					
	Annotation (time): Autovista opinion time					
NN	Rear Bumper Lower Support	RP	0.00	0.90		3.21
	(R)					
	Annotation (time): Autovista opinion time					
NN	Rear Bumper Outer Bracket	RP	0.00	0.90		2.64
	(L)					
	Annotation (time): Autovista opinion time					
NN	Rear Bumper Outer Bracket	RP	0.00	0.90		2.64
	(R)					
	Annotation (time): Autovista opinion time					
NN	Rear Bumper Repair Kit	RP	0.00			0.00
95704R00	Rear Bumper Inner Side	RP	0.00	0.90		96.43
	Distance-Sensor (R)					
NN	Rear Bumper Lining Clip	RP	0.00			1.00
NN	Rear Bumper Lining Screw	RP	0.00			0.71
NN	Rear bumper lining Nut	RP	0.00			1.61
86647R00	Side Rear Fog Lamp,	RP	0.00	1.10		36.14
	Complete (L)					
86647R00	Side Rear Fog Lamp,	RP	0.00	1.10		36.14
	Complete (R)					
92506R00	Number Plate Lamp (L)	RP	0.00	0.30		10.74
NN	Side Panel Stoneguard (L)	RP	0.00			16.12
NN	Side Panel Stoneguard (R)	RP	0.00			16.12

NN	Side Panel Glass (Tinted) (L)	UI	0.00		0.00
NN	Side Panel Glass (Tinted) (R)	UI	0.00		0.00
NN	Rear Panel	RP	5.70		170.78
NN	Rear Seat Remove & Install				
86520R00	Rear Bumper Lining				
79002A00	Boot Lid/Back Door/Tailgate Striker				
85850R00	Side Panel Upper Interior Trim (L)				
85875R00	Sill Panel Rear Interior Trim (L)				
85776R00	Spare Wheel Trim				
	Annotation (time): Autovista opinion time				
NN	Rear Floor, Rear	R	2.50		0.00
NN	Rear Floor Side	RP	0.80		6.63
	Reinforcement, Rear (L)				
	Annotation (time): Autovista time net				
NN	Rear Floor Side	RP	0.80		6.63
	Reinforcement Rear (R)				
	Annotation (time): Autovista time net				
73700R00	Tailgate	RP	2.90	0.10	363.86
79003A00	Latch with Central Locking				
	Selected criteria: from 10.2018				
	Annotation (time): Time includes adjustment				
81230R00	Latch with Central Locking	RP	0.00	0.50	133.27
81210R00	Boot Lid/Back Door/Tailgate Striker	RP	0.00	0.50	22.87
	Annotation (time): Time includes adjustment				
87403R00	Boot Lid/Back Door/Tailgate	RP	0.00	0.20	34.14
	Badge				
	Selected criteria: from 10.2018				
87403R00	Side Type Designation (L)	RP	0.00	0.20	27.99
87403R00	Side Emblem (Engine Designation) (R)	RP	0.00	0.20	26.30
95755R00	Back-Up Camera	RP	0.00	0.40	561.76
NN	Rear Window Repair/Bonding Kit	RP	0.00		58.00 *
NN	Rear Window Spacing	RP	0.00		1.08
	Block/Sleeve				
NN	Rear Window Spacing	RP	0.00		1.08
	Block/Sleeve (L)				
NN	Rear Window Spacing	RP	0.00		1.08
	Block/Sleeve (R)				
NN	Rear Window Upper Spacing	RP	0.00		1.08
	Block/Sleeve (L)				
NN	Rear Window Upper Spacing	RP	0.00		1.08
	Block/Sleeve (R)				
NN	Rear Window Lower Spacing	RP	0.00		1.08
	Block/Sleeve (L)				
NN	Rear Window Lower Spacing	RP	0.00		1.08
	Block/Sleeve (R)				
85770R00	Rear Panel Interior Trim	RP	0.00	0.20	34.99 *
NN	Tailgate/Boot Lid Trim	RP	0.00		0.00
	Support Kit				
NN	Tailgate/Boot Lid Trim Clip	RP	0.00		0.85
NN	Tailgate/Boot Lid Trim Screw	RP	0.00		0.72
NN	Paint tailgate moulding	EC	0.50		52.14 F
NN	Rear Lower bumper diffuser	EC	0.00		150.00 F
NN	Tailgate handle moulding	PR	0.50		125.00 F
NN	Corrosion Protection	EC	0.50		22.00 F
	Materials				
NN	Number Plate Backing	EC	0.30		32.50 F
NN	Boron Drill	EC	0.00		59.00 F
NN	Car Care Kit	EC	0.00		9.00 F
NN	De-nib/ polish	EC	1.20 *		0.00 F
	Additional work (0.90): ..				
NN	Electric / hybrid shutdown and power up	EC	3.00		0.00 F
NN	Energy cost supplement	EC	0.00		75.00 F
NN	Estimate/Assessment Charge	EC	0.00		65.00 F
NN	Final Inspection & Road Test	EC	1.00		0.00 F
NN	Jig, clamp and pull	EC	4.50		0.00 F
NN	Panel Bonding Kit	EC	0.00		62.00 F
NN	PPE equipment	EC	0.00		12.50 F

NN	Rear camera reset	EC	0.00	80.00	F
NN	Repair Method Research Allowance	EC	0.00	40.00	F
NN	Santising of damaged vehicle (repair)	EC	0.00	40.00	F
NN	Seam Sealant	EC	0.00	18.00	F
NN	System Diagnostic Check (Post Repair)	EC	0.00	75.00	F
NN	System Diagnostic Check (Pre Repair)	EC	0.00	75.00	F
NN	Wash/Clean	EC	0.00	37.00	F
NN	Water test	EC	0.50	0.00	F
NN	Rear Camera reset	EC	0.00	80.00	F

Labour costs

0.00

Material costs

3,363.28

Total Body

£ 3,363.28

Auxiliary work		Repair type	Labour time	Overlap-time	Labour costs	Material costs
NN	Rear Side Panel Strip & Set-Up for Paint (L)	UI	0.40	0.30		0.00
87539R00	Rear Door Stoneguard (L)					
87751R00	Sill Panel Cover (Plastic) (L)					
87870R00	Side Panel W/arch Protective Moulding (L)					
87360R00	Rear Window Moulding (L)					
	Annotation (time): Autovista opinion time					
NN	Rear Side Panel Strip & Set-Up for Paint (R)	UI	0.40	0.30		0.00
87539R00	Rear Door Stoneguard (R)					
87751R00	Sill Panel Cover (Plastic) (R)					
87870R00	Side Panel W/arch Protective Moulding (R)					
87360R00	Rear Window Moulding (R)					
	Annotation (time): Autovista opinion time					

Labour costs

0.00

Material costs

0.00

Total Auxiliary work

£ 0.00

Paint	Paint type	Paint level	Labour time	Labour costs	Material costs
A-Post, Upper (L)	200	B	0.40		16.80
A-Post, Upper (R)	200	B	0.40		16.80
Rear Side Panel, Complete K (L)	200	B	0.60		93.80
Rear Side Panel, Complete K (R)	200	B	0.60		93.80
Tailgate (with Window Frame)	200	I	1.70		354.20
Annotation (price) Part made from aluminium					
Rear Floor	200	II	1.10		237.90
Rear Panel, Complete	200	I	2.10		174.80
Prep. metal (on vehicle without pre-painting)	200		1.70		100.43
Colour mixing (1)			0.30		0.00
Sample colour creation (1)			0.30		9.75

Labour costs

0.00

Material costs

1,098.28

Total Paint

£ 1,098.28

Summary	Labour rate	Labour time	Labour costs	Material costs
Body	0.00	25.90	0.00	3,363.28
Auxiliary work	0.00	0.80	0.00	
Paint	0.00	9.20	0.00	1,098.28

Total Labour	35.90	0.00	
Total Material			4,461.56
Repair costs excl. VAT			4,461.56
VAT (20.00 %)			892.31
Repair costs incl. VAT			£ 5,353.87

Part name	Part no.	Previous part no.	Material costs
Rear Bumper Lining	86610Q4030		155.92
Rear Bumper Side Impact Absorber (Tube)	86641Q4000		36.43
Rear Bumper Side Impact Absorber (Tube)	86642Q4000		36.43
Rear Bumper Reinforcement	86631Q4000		120.02
Rear Bumper Protection Trim	86612Q4000		143.72
Rear Bumper Stoneguard	86690Q4000		46.22
Rear Bumper Side Bracket	86613G5000		14.81
Rear Bumper Side Bracket	86614G5000		14.81
Rear Bumper Lower Support	86635Q4000		2.72
Rear Bumper Lower Support	86636Q4000		3.21
Rear Bumper Lower Support	86636Q4000		3.21
Rear Bumper Outer Bracket	86633Q4000		2.64
Rear Bumper Outer Bracket	86633Q4000		2.64
Rear Bumper Repair Kit	KET		0.00
Rear Bumper Inner Side Distance-Sensor	95720D30004SS		96.43
Rear Bumper Lining Clip	1420608250B		1.00
Rear Bumper Lining Screw	1249305167E		0.71
Rear bumper lining Nut	1334106007B		1.61
Side Rear Fog Lamp, Complete	92405Q4000		36.14
Side Rear Fog Lamp, Complete	92406Q4000		36.14
Number Plate Lamp	92501F6000		10.74
Side Panel Stoneguard	87539G5000		16.12
Side Panel Stoneguard	87549G5000		16.12
Rear Panel	69100G5500		170.78
Rear Floor Side Reinforcement, Rear	65652Q4000		6.63
Rear Floor Side Reinforcement Rear Tailgate	65662Q4000		6.63
Latch with Central Locking	73700G5001		363.86
Boot Lid/Back Door/Tailgate Striker	81230G5000		133.27
Boot Lid/Back Door/Tailgate Badge	812102S001		22.87
Side Type Designation	86310G5100		34.14
Side Emblem (Engine Designation)	86311G5000		27.99
Back-Up Camera	86312Q4000		26.30
Rear Window Repair/Bonding Kit	95760G5000		561.76
Rear Window Spacing Block/Sleeve	KET		58.00 *
Rear Window Spacing Block/Sleeve	861143D000		1.08
Rear Window Spacing Block/Sleeve	861143D000		1.08
Rear Window Spacing Block/Sleeve	861143D000		1.08
Rear Window Upper Spacing Block/Sleeve	861143D000		1.08
Rear Window Upper Spacing Block/Sleeve	861143D000		1.08
Rear Window Lower Spacing Block/Sleeve	861143D000		1.08
Rear Window Lower Spacing Block/Sleeve	861143D000		1.08
Rear Panel Interior Trim	861143D000		1.08
Tailgate/Boot Lid Trim Support Kit	85770Q4000WK		34.99 *
Tailgate/Boot Lid Trim Clip	KET		0.00
Tailgate/Boot Lid Trim Screw	8231527000		0.85
	1249205163		0.72
Total Parts			£ 2,254.14

Attention: Listed part numbers are for information only and CANNOT be used for ordering purposes.

Part name	Position no.
Roof Moulding	82850R00
Roof Moulding	82850R00
Rear Bumper Lining	86651R00
Rear Bumper Side Impact Absorber (Tube)	50200R00
Rear Bumper Side Impact Absorber (Tube)	50200R00
Rear Bumper Reinforcement	86630R00
Rear Bumper Protection Trim	86612R00
Rear Bumper Stoneguard	86695R00
Rear Bumper Side Bracket	86613R00
Rear Bumper Side Bracket	86613R00
Rear Bumper Lower Support	
Rear Bumper Lower Support	
Rear Bumper Lower Support	
Rear Bumper Outer Bracket	
Rear Bumper Outer Bracket	
Rear Bumper Repair Kit	
Rear Bumper Inner Side Distance-Sensor	95704R00
Rear Bumper Lining Clip	
Rear Bumper Lining Screw	
Rear bumper lining Nut	
Side Rear Fog Lamp, Complete	86647R00
Side Rear Fog Lamp, Complete	86647R00
Number Plate Lamp	92506R00
Side Panel Stoneguard	
Side Panel Stoneguard	
Side Panel Glass (Tinted)	
Side Panel Glass (Tinted)	
Rear Panel	
Rear Floor, Rear	
Rear Floor Side Reinforcement, Rear	
Rear Floor Side Reinforcement Rear	
Tailgate	73700R00
Latch with Central Locking	81230R00+79003A00
Boot Lid/Back Door/Tailgate Striker	81210R00+79002A00
Boot Lid/Back Door/Tailgate Badge	87403R00
Side Type Designation	87403R00
Side Emblem (Engine Designation)	87403R00
Back-Up Camera	95755R00
Rear Window Repair/Bonding Kit	
Rear Window Spacing Block/Sleeve	
Rear Window Spacing Block/Sleeve	
Rear Window Spacing Block/Sleeve	
Rear Window Upper Spacing Block/Sleeve	
Rear Window Upper Spacing Block/Sleeve	
Rear Window Lower Spacing Block/Sleeve	
Rear Window Lower Spacing Block/Sleeve	
Rear Side Panel Strip & Set-Up for Paint	
Rear Side Panel Strip & Set-Up for Paint	
Rear Panel Interior Trim	85770R00
Tailgate/Boot Lid Trim Support Kit	
Tailgate/Boot Lid Trim Clip	
Tailgate/Boot Lid Trim Screw	
Paint tailgate moulding	
Rear Lower bumper diffuser	
Tailgate handle moulding	
Corrosion Protection Materials	

Number Plate Backing
 Boron Drill
 Car Care Kit
 De-nib/ polish
 Electric / hybrid shutdown and power
 up
 Energy cost supplement
 Estimate/Assessment Charge
 Final Inspection & Road Test
 Jig, clamp and pull
 Panel Bonding Kit
 PPE equipment
 Rear camera reset
 Repair Method Research Allowance
 Santising of damaged vehicle (repair)
 Seam Sealant
 System Diagnostic Check (Post Repair)
 System Diagnostic Check (Pre Repair)
 Wash/Clean
 Water test
 Rear Camera reset

Abbreviations	Description
---------------	-------------

*	Price or time modified
F	User defined operations
L	LEFT
R	RIGHT
UI	Uninstall and install
RP	Replace
R	Repair
EC	Surcharge
PR	Partial repair
NN	No part number

Paint type	Paint level, Procedure, Method
------------	--------------------------------

B	Adjacent Panel Blend
200	2 Coat
I	New part
II	Inner surface

Selected criteria

Park Assistant System Rear
 with Back-Up Camera

Additional Fields

Paint material index	100.000 %
Part index	100.000 %

Glass's does not take responsibility for accuracy and completeness of data originating from vehicle manufacturers.