

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mrs M Flynn
43 Home Park Road
Saltash
Cornwall
PL12 6BH

Date: 22/12/2025
Our Ref: 00075725/GC
Your Ref: EHR93791


Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mrs M Flynn**

We refer to your instructions received on **12 December 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: VAUXHALL CORSA ELITE NAV PREMIU	Colour: WHITE	Speedo: 48769	Miles
Reg No: MT69XLW	Registered: Jan 2020	Type: 5 Door Hatchback	Trans: Manual
Vin No: VXKUPHNKKL4090087	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2020		Spare Tyre
Brakes: Not Known	Tax Exp:		Not Know
Steering: Not Known	Fuel: Petrol		Centre Belt
Extras: Not Seen	C.C.: 1199		Not Tested
Air Bags Deployed: Not Known	BHP: 99.2	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Moderate Accidental Damage LH Front Bumper	Incident: 03/12/2025	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno



Vehicle Value: £9,496.00	Repair Cost: £3,881.69 inc VAT	(40.88% of PAV)	Roadworthy: Yes
---------------------------------	---------------------------------------	-----------------	------------------------

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate accidental damage to the left hand front bumper, and to the left hand front wing.

ENGINEER'S COMMENTS

22/12/2025 - The vehicle is roadworthy subject to a four wheel alignment being carried out.

VEHICLE HISTORY CHECK

12/12/2025 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Front Bumper, L/F Bumper Bracket, Frt Bumper Clamp Kit, Frt Out Sens Brk Set, L/F Wing, L/F Wing Bracket Frt

Repaint only parts:-L/F Wing New Part Painting, Front Bumper New Part Paint K1r, L/F Door W/O Frame Surface Paint, Polish Per Panel Surface Paint, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Car Care Kit, E.P.A. Charge, 4 Wheel Alignment, Eis Charge, Transport To Dealer, Collect From Dealer, Replace Graphics, Adas Method Research, Pre Diagnostic Sweep, Post Diag Sweep, Energy Supplement, Manufacturer App, Sundry Part, Anti-Corrosion

Remove And Refit parts:-Bumper And L/F Wing, Renew Front Bumper (Removed), Add: R & R Park Assit Front Sensor, Renew Left Front Wing (Removed), Left Front Door Trim, L/F Door Foil, L/Frt Outer Door Channel Moulding, Left Mirror, Outer Handle L/Frt Door, Add: Adjust Headlamps, Remove Decal 4 Rep, Inspection Road Test And Final, Corrosion Prote To 1St Panel

Parts to check:-Check Wash & Vacuum, Check Shut Down Vehicle, Check Pre Repair Clean

DELETED PARTS

We advise that we have removed the following from the repairer's original estimate, as we do not consider they are required; L/F Wheel and Tyre, O/S/F Wing blend at this stage and should be subject to further checks or explanation

COST OF REPAIRS

The repairers, John Card Accident Repair Centre, 6 Miller Ct, Stonehouse, Plymouth, PL1 3LQ (Tel. 01752 263374), have compiled an estimate in the sum of £1,272.00 plus parts at manufacturer's list prices plus £824.28 for paint and materials plus £865.25 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £192.00 to £1,080.00 for the labour and £53.16 to £771.12 for paint and materials in their final account. The labour charge is based on 13.5 hours at a rate of £80.00 per hour. We have also agreed that the cost of paint and materials will be limited to £771.12. The cost of the necessary replacement parts will be approximately £870.16, the specialist/sundry charges will be £513.46, the VAT liability on this repair will amount to some £646.95 giving a total repair cost of £3,881.69 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £1,220.63.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 27/01/2020. The corresponding Glass's Guide retail value for vehicles of this type and age in the December 2025 guide is £9,496.00 at 48769 Miles, trade value is £7,239.00 and mid value is £8,367.50. We place the pre-accident value of this particular vehicle at £9,496.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £3,900.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 22nd December 2025, on your behalf.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of