

**Our Ref:** oak25382

**Your Ref:** PXS/MCPHEE/S45  
7473.001

**Date:** 21/11/2025

FAO The Court  
C/o Oakwood Solicitors  
1 West Regent Street  
Glasgow  
Scotland  
G2 1RW

### TOTAL LOSS REPORT

Dear Sirs


**RE: Road traffic Accident: Craig McPhee: 14/11/2025**

In accordance with your instructions received on 21/11/2025 requesting us to provide an independent accident damage report, we assessed the damage on 21/11/2025. Vehicle located at Image based assessment. Our findings are as detailed below:


|                |                           |                  |                     |
|----------------|---------------------------|------------------|---------------------|
| Make           | <b>CITROEN</b>            | Registration     | <b>YW16EBD</b>      |
| Model          | <b>C4 GRAND PICASSO S</b> | Status           | <b>T/Loss</b>       |
| Category       | <b>N</b>                  | Salvage Value    | <b>£550.00</b>      |
| Repair Cost    | <b>£4,970.26</b>          | Legal Status     | <b>Unroadworthy</b> |
| Engineer Value | <b>£5,500.00</b>          | Impact Magnitude | <b>Moderate</b>     |



Impact Area



Document produced  
using the EVA system



**Our Ref:** oak25382

**Your Ref:** PXS/MCPHEE/S45  
7473.001

**Date:** 21/11/2025

### **NATURE OF INCIDENT**

The vehicle has suffered moderate collision/impact damage to the right hand side.

### **ENGINEER'S COMMENTS**

Please note the vehicle is unroadworthy as we are advised the offside door no longer correctly operates.

### **VEHICLE HISTORY CHECK**

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

### **UNRELATED DAMAGE**

We noted the following damage on the vehicle which does not appear to relate to the claim under review and we have therefore classed it as unrelated damage; Offside Sill.

### **PRE-INCIDENT CONDITION**

The vehicle is considered to be in good condition for its age and type.

### **SETTLEMENT**


We consider that an equitable settlement would be £4,950.00 which represents the pre-accident engineer value of the vehicle of £5,500.00 less the value of the salvage of £550.00.

### **SALVAGE**

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at [www.abi.org.uk](http://www.abi.org.uk). We suggest that the sale of the salvage will realise in the order of £550.00. **We have not taken any action towards removal of the salvage at this time.**

## **Vehicle Data**

|                  |                          |
|------------------|--------------------------|
| Retail Value     | <b>£5,685.00</b>         |
| Trade Value      | <b>£3,695.00</b>         |
| Engineer's Value | <b>£5,500.00</b>         |
| Glass's Code     | <b>QBT3</b>              |
| VIN              | <b>VF73ABHZMGJ744056</b> |
| Odometer         | <b>91460</b>             |
| Engine           | <b>1560</b>              |
| Fuel             | <b>Diesel</b>            |
| Extras           |                          |
| Condition        | <b>Good</b>              |
| Unrelated Damage | <b>Offside Sill</b>      |



**Our Ref:** oak25382

**Your Ref:** PXS/MCPHEE/S45  
7473.001

**Date:** 21/11/2025

#### Main new parts required

Right Front Door Membrane  
Right Rear Door Membrane  
Right Rear Door Trim Support Kit  
Right Rear Door Trim Screw

Right Rear Door Shell  
Right Rear Door Sealing Compound  
Right Rear Door Trim Clip

#### Repairs required

Right Front Door Shell


#### Additional operations

ADAS Methods Research Fee  
Clamp And Pull  
Energy Cost Supplement  
Identify the presence of ADAS  
QC & Road test  
Standard Shutdown  
System Diagnostic Check (Post Repair)  
Vehicle Care Kit  
Paint Right Front Door, Complete  
Paint Right Rear Side Panel, Complete  
Paint Colour mixing (1)

Assessment Damage Appraisal Charge  
De-Nib/Polish  
Environmental Charge  
Panel Repair Sundries (including body fi  
Repair Method Research Charge  
Sundries  
System Diagnostic Check (Pre Repair)  
Wash/Clean  
Paint Right Rear Door, Complete  
Paint Prep. metal (on vehicle without pre-painting)  
Paint Sample colour creation (1)

### Repair Cost Calculations

|                      |                  |
|----------------------|------------------|
| Hours                | <b>21.80</b>     |
| Hourly Rate          | <b>£80.00</b>    |
| Total Labour         | <b>£1,744.00</b> |
| Parts                | <b>£1,010.99</b> |
| Paint/Materials      | <b>£893.54</b>   |
| Specialist/Other     | <b>£493.35</b>   |
| Sub total            | <b>£4,141.88</b> |
| Vat                  | <b>£828.38</b>   |
| Total Estimated Cost | <b>£4,970.26</b> |



**Our Ref:** oak25382

**Your Ref:** PXS/MCPHEE/S45  
7473.001

**Date:** 21/11/2025

