

FAO The Court

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: Mr Dayle Longford: 15/05/2026


In accordance with your instructions received on 16/05/2026 requesting us to provide an independent accident damage report, we assessed the damage on 21/05/2026. Vehicle located at Image-based Assessment. Our findings are as detailed below:

Make	BMW	Registration	16DL
Model	X3 XDRIVE20D M SPO	Status	Repair
Category		Salvage Value	
Repair Cost	£7,989.88	Legal Status	Unroadworthy
Engineer Value	£43,437.00	Impact Magnitude	Moderate



Impact Area





Our Ref: a.pch261213

Your Ref: 576299

Date: 21/05/2026

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand rear.

ENGINEER'S COMMENTS

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the offside rear / broken rear bumper.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION


The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £8,000.00 would be reasonable on this occasion.

Vehicle Data

Retail Value	£43,437.00
Trade Value	£39,528.00
Engineer's Value	£43,437.00
Glass's Code	
VIN	WBA16BZ070N291727
Odometer	8024
Engine	1995
Fuel	
Extras	
Condition	Good



Our Ref: a.pch261213

Your Ref: 576299

Date: 21/05/2026

Main new parts required

Rear Bumper Cover
Support Adapter
R/R Reflector
R/Air Intake Duct
R/R Bumper Prot Foil
Rear Bumper Carrier
Nut
R/R Carrier Seal
R/Out U-Sonic Sender
Rear Badge
L/Rivet
Tailgate Trim Clip
L/R Exhaust Rubber
Ctr Exh Pipe Rubber
Rr Exhaust Silencer
R/R Heat Insulation
Trim Grill
Sundry Parts

Rear Bumper Cover
Clip Fastening
R/R Out Bumper Brkt
L/R Bumper Prot Foil
R/Nut
R/R Bumper Bracket
L/R Carrier Seal
Rr Sensor Brkt Set
R/R Out Sensor Brkt
Rear Model Badge
R/Rivet
Clip Fastening
R/R Exhaust Rubber
Exhaust Clamp
R/Exhaust Cover
Exhaust Paste
Bracket

Repairs required

Right Rear Damage
Lower Tailgate

Outer Rear Panel

Additional operations

Paint Rear Bumper Cover New Part Paint K1r
Paint Lower Tailgate Repair Painting <50%
Blend R/R Wheelarch Trim Surface Paint Plast.
Paint Additional Masking Tailgate
Assessment Fee
Vehicle Care Kit
Corrosion Mat
Hybrid Full

Paint Outer Rear Panel Repair Painting <50%
Blend L/R Wheelarch Trim Surface Paint Plast.
Paint Denib / Polish Paint
Paint Preparation For Pre-Painting
Epa Charge
Paint Consumable
Panel Sundries P/P Specialist
Delivery To Client Returning Veh

Repair Cost Calculations

Hours	28.23
Hourly Rate	£103.06
Total Labour	£2,909.73
Parts	£2,532.40
Paint/Materials	£793.66
Specialist/Other	£422.43
Sub total	£6,658.23
Vat	£1,331.65
Total Estimated Cost	£7,989.88











































Our Ref: a.pch261213

Your Ref: 576299

Date: 21/05/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

N O'Reilly - ATA VDA AQP

engineers@collisionengineers.co.uk



Our Ref: a.pch261213

Your Ref: 576299

Date: 21/05/2026

FAO The Court

Fee Note

16DL.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £150.00

Sub Total: £150.00

VAT: £30.00

Total Due: £180.00

Payment

Please make cheques payable to Collision Engineers and quote reference a.pch261213.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10