

CASH IN LIEU REPORT

Report For:

FAO The Court
C/o QDOS Assistance
3rd Floor, Crown House
Manchester Road
Wilmslow
SK9 1BH

Date: 16/07/2026**Our Ref:** ap.qdos261789**Your Ref:** MFI/ND/46885/1**Matter:** Road Traffic Accident: Mrs Gurdip Kaur: 13/07/2026**CASH IN LIEU****UNROADWORTHY**

PRE-ACCIDENT VALUE

£4,011.00

LABOUR HOURS

25.90



CASH IN LIEU SETTLEMENT


£4,405.73

In accordance with your instructions received on 14/07/2026 requesting us to provide an independent accident damage report, we assessed the damage on 15/07/2026. Vehicle located at: Image Based Assessment. Our findings are as detailed below.

Vehicle Details

Make	KIA	Registration	PK12 TMZ
Model	PICANTO HALO ECODYNAMICS	VIN	KNABX312LCT122784
Odometer	50,500 miles	Engine / Fuel	1,248 cc · Petrol
Pre-Incident Condition	Good	Impact Magnitude	Moderate — right rear





Desktop Assessment

This report has been compiled from a desktop review of the information available relating to this claim.

Nature of Incident

The vehicle has suffered moderate collision/impact damage to the right rear.

Engineer's Comments

The mileage has been calculated from online data.

Please note the vehicle is unroadworthy due to the impacted wheel, tyre, suspension and broken/insecure rear bumper.

Vehicle History Check

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

Pre-Incident Condition


The vehicle is considered to be in good condition for its age and type.

Settlement

We recommend settlement by way of a cash in lieu payment based upon the estimated repair cost of £4,405.73.

Recommended cash in lieu settlement (estimated repair cost)

£4,405.73



Vehicle Data

Retail Value	£4,011.00
Trade Value	£2,848.00
Engineer's Value	£4,011.00
VIN	KNABX312LCT122784
Year	2012 (12 reg)
Odometer	50,500 miles
Engine	1,248 cc
Fuel	Petrol
Condition	Good

Repair Cost Calculation

Amount

Labour Hours	25.90
Hourly Rate	£83.28
Total Labour	£2,156.95
Parts	£278.44
Paint / Materials	£769.42
Specialist / Other	£466.63
Sub Total	£3,671.44
VAT (20%)	£734.29
Total Estimated Repair Cost	£4,405.73

Main New Parts Required

Rear Bumper Lining	Right Rear Bumper Outer Bracket
Rear Bumper Repair Kit	Rear Bumper Lining Clip
Rear Bumper Lining Screw	Rear Bumper Lining Nut
Left Side Glass Repair/Bonding Kit	Right Side Glass Repair/Bonding Kit
Right Rear Wheel Cover	

Repairs Required


Right Rear Side Panel with Sill Panel	Right Rear Side Panel Reinforcement
---------------------------------------	-------------------------------------

Additional Operations

Assessment Damage Appraisal Charge	Environmental Charge
Pre-repair Cleaning Charge	QC & Road Test
Standard Shutdown	Sundries
System Diagnostic Check (Post Repair)	System Diagnostic Check (Pre Repair)
Vehicle Care Kit	Wash/Clean
Clamp and Pull	Corrosion Protection
De-nib	OSR Tyre
Wheel Alignment (Check)	Yard Charge
Paint Left Rear Side Panel, Complete	Paint Right Rear Side Panel, Complete
Paint Left Fuel Filler Lid	Paint Rear Bumper k/b-c
Paint Prep. Metal (on vehicle without pre-painting)	Paint Prep. Synthetics (combined-operation work)
Paint Colour Mixing (1)	Paint Sample Colour Creation (1)

Vehicle Images





Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and/or manufacturer's data to compile the repair specification. Parts prices are subject to fluctuation and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully,

A Patterson — M.Inst.IAEA

Independent Automotive Engineer, Collision Engineers Ltd
Engineers@CollisionEngineers.co.uk



FEE NOTE

Bill To:

FAO The Court
C/o QDOS Assistance
3rd Floor, Crown House, Manchester Road
Wilmslow, SK9 1BH

Date: 16/07/2026**Our Ref:** ap.qdos261789**Your Ref:** MFI/ND/46885/1**Matter:** Road Traffic Accident: Mrs Gurdip Kaur: 13/07/2026

Description	Amount (£)
Vehicle Damage Assessment Report — PK12 TMZ	
Collate data, compile repair specification, calculate estimate, research valuation.	
Produce Vehicle Damage Assessment report.	100.00
Storage of all material case files and images.	
Subtotal (Net)	100.00
VAT @ 20%	20.00
TOTAL DUE	£120.00

Payment Details

Account Name	Collision Engineers Ltd	Bank	Lloyds Bank
Sort Code	30-12-80	Account Number	50858868
Payment Reference	ap.qdos261789	Remittance Email	accounts@collisionengineers.co.uk

Terms

As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid, in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

Any requests for addendum reports or letters, including those required for clarification, plus Counsel, Court or other meetings, will be subject to a further charge and subject to Civil Procedure Rule 35.6. The instructing party confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Thank you for your business.