

TEL: DACK MOTOR GROUP FAX:
LINCOLN FIELD BUSINESS PARK WHISBY ROAD
, LINCOLN
LINCOLNSHIRE LN6 3QW

Assessment Number: CH000036
Version: payg1261/2

Full Report
Printed: 20/12/2023

Summary Information

Claim

Authorisation Status:	Interim	Date of Incident:	24/05/2023
Work Provider:	OTHER	Able to Authorise Repairs:	Yes
Claim Reference:	21844/1	Repairs Authorised?	Yes
Policy Number:		VAT Portion Payable:	NonTaxable
Other Reference:		Repairer:	Non Approved
		Estimated Repair Time (Working Days):	4.0

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	YARIS CROSS Base Mo
Model Sheet Number:	Y1H
Engine:	1.5 LTR 85 KW
Registration Number:	YS71WKN
VIN Number:	JTDKBABBX0A013145
Registration Month:	February
Registration Year:	2022
Odometer:	7808 miles
Colour:	Blue
Paint Code:	8W7
Build Date:	FROM 10/2021
Selection Type:	AudaVIN+

Model Specs

FROM 10/2021
AUTO AIR CON
PRIVACY GLASS
FRT/RR ELECT WINDOWS
RADIO DIGITAL
6 SPEAKER
COMBI INSTRUMENT TFT
H-LAMP LED ADAPTIVE
LED TAILLAMPS
LED HEADLAMP
LED FOG LAMPS
REAR CENTRE ARMREST
EQUIPMENT N
ANTI-THEFT ALARM
KEYLESS ENTRY/DRIVE
1.5 LTR 85 KW
AUTO GEARBOX E-CVT
CRUISE CONT RADAR
PRE-CRASH SYSTEM
TYRES 205/65 HR 16
WHEELS 6.5J X 16
TYRE REPAIR KIT
FRONT DRIVE
ROOF RAILS
EUROPA MODEL
TWO COAT METALLIC

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Good	Severity of Impact:	Light
Steering Rim Ply:	Satisfactory	Vehicle Status on Inspection:	Roadworthy
Brakes Pedal Travel:	Satisfactory	Date of Inspection:	01/06/2023
Place of Inspection:	Owner		
Pre-Accident Damage:	GOOD		

TEL: DACK MOTOR GROUP FAX:
LINCOLN FIELD BUSINESS PARK WHISBY ROAD
, LINCOLN
LINCOLNSHIRE LN6 3QW

Assessment Number: CH000036

Version: payg1261/2

Full Report


Printed: 20/12/2023

Tyres Condition: Good


Tyres - Tread Depth (MM):

	Axes	Left Tyre Depth	Right Tyre Depth	
LHF	0	4.0	4.0	RHF
LHR	1	4.0	4.0	RHR

Damage Areas:



Direction of Impact:



**TEL: DACK MOTOR GROUP FAX:
LINCOLN FIELD BUSINESS PARK WHISBY ROAD
, LINCOLN
LINCOLNSHIRE LN6 3QW**

Assessment Number: CH000036
Version: payg1261/2

Full Report
Printed: 20/12/2023

Addresses

Fleet Manager
FLEETCARE

Repairer
DACK MOTOR GROUP LTD
Dack Bodyshop
LN63DH
Business Tel : 01522 437778
Email Address :
dave.hornsey@dack.co.uk

User Driver
ELAINE BLANKLEY
Mobile Tel : 07711895951
Email Address :
erblankley@outlook.com

Vehicle Location

DACK MOTOR GROUP LTD
Dack Bodyshop
LN63DH
Email Address : dave.hornsey@dack.co.uk

Cost Summary

Total Labour	£1,477.00
Total Paint/Material	£841.25
Total Parts	£607.07
Additional Costs	£160.00
Grand Total Exc VAT:	£3,085.32
20 % VAT:	£617.06
Grand Total Inc VAT:	£3,702.38
Excess:	£0.00

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price = £70.00/HR

Repair / Guide

Number	Description	Work Units
NO NUMBER	R + R L/A-PILLAR COVER	1.0
NO NUMBER	R + R R/A-PILLAR COVER	1.0
NO NUMBER	R + R L/R WHEELHOUSE	2.0
NO NUMBER	R + R R/R WHEELHOUSE	2.0
NO NUMBER	R + R TAILGATE TRIM	1.0
NO NUMBER	R + R REAR NUMBER PLATE	1.0
811201S)	R + R L/NUMBER PLATE LAMP	2.0
811201S)	R + R R/NUMBER PLATE LAMP	2.0
NO NUMBER	R + R TAILGATE MOULDING	1.0
B408	R + R LEFT INNER TAILLAMP	1.0
B408	R + R RIGHT INNER TAILLAMP	1.0
NO NUMBER	RENEW TAILGATE BADGE "VERSION"	5.0
750211	R + R BADGE "TOYOTA"	5.0

**TEL: DACK MOTOR GROUP FAX:
LINCOLN FIELD BUSINESS PARK WHISBY ROAD
, LINCOLN
LINCOLNSHIRE LN6 3QW**

Assessment Number: CH000036
Version: payg1261/2

Full Report
Printed: 20/12/2023

750171	RENEW BADGE "TOYOTA"	5.0
B420	RENEW REAR BUMPER	7.0
	INCLUDES: BUMPER AND ALL REQUIRED ATTACHED PARTS R + R	
B410)	R + R REAR BUMPER REINFORCEMENT	1.0
NO NUMBER	R + R R/R VENT GRILLE	1.0
B407	R + R LEFT TAIL LAMP	1.0
B407	R + R RIGHT TAIL LAMP	1.0
NO NUMBER	R + R LEFT REAR MUD FLAP	1.0
NO NUMBER	R + R RIGHT REAR MUD FLAP	1.0
751351	R + R L/DRIP RAIL MOULDING	4.0
751351	R + R R/DRIP RAIL MOULDING	4.0
NO NUMBER	R + R WHEEL/S (ADD/WORK)	1.0
420018)	R + R REAR WHEEL(S)	1.0
1000	REMOVE&REFIT EV DISCHARGE	20.0*
3482	REPAIR R/R SIDE PANEL	15.0*
2640	CHECK REAR BUMPER SUPPORT	
2711	CHECK END PANEL	
1000	CHECK AND CLEAN CAR	5.0*
1000	CHECK AND QUALITY CONTROL	5.0*
1000	CHECK AND ROAD TEST	3.0*
1000	CHECK VEH DIAG POST CHECK	10.0*
1000	CHECK VEH DIAG PRE CHECK	10.0*
Total Work Units		121.0
Total Panel / Mechanical Labour		12.10 HRS
		£847.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = £70.00/HR

Repair /Guide	Description	
Number	TWO COAT METALLIC	Work Units
2581	REAR BUMPER NEW PART PAINT K1R	8.0
2610	REAR BUMPER LWR CVR NEW PART PAINT K1R	4.0
3482	R/R SIDE PANEL REPAIR PAINTING <50%	13.0
2363	L/ROOF SECTION SURFACE PAINT	5.0
2364	R/ROOF SECTION SURFACE PAINT	5.0
2942	LOWER TAILGATE SURFACE PAINT	6.0
2987	BOOT/T-GATE MOULDINGSURFACE PAINT PLAST.	5.0
3481	L/R SIDE PANEL SURFACE PAINT	6.0
1000	MACHINE POLISH	5.0*
1000	PAINT HINGES SURFACE PAINT	5.0*
	PREPARATION FOR PRE-PAINTING	28.0
Total Work Units		90.0

**TEL: DACK MOTOR GROUP FAX:
LINCOLN FIELD BUSINESS PARK WHISBY ROAD
, LINCOLN
LINCOLNSHIRE LN6 3QW**

Assessment Number: CH000036
Version: payg1261/2

Full Report
Printed: 20/12/2023

Total Paintwork Labour 9.0 HRS. £630.00

MATERIAL COST - PAINT

COST

Total Paint Cost	£701.68
Sundry Paint Material	£100.43
Pre-Painting Sundry Materials	£39.14
 Total Excluding Pearlescent Uplift	 £701.68
Pearlescent Uplift @ 0.0%	£0.00
 Total Paint And Material Cost	 £841.25

PARTS

Price Valid: 08/12/2023

Guide No.	Description	Part Number	Bet.	Price
2581	REAR BUMPER	52159 YP918	0%	£120.57
2610	REAR BUMPER LWR CVR	52453 0D100	0%	£116.23
2618	R/R UPP BUMPER BRKT	52575 0D470	0%	£61.01
2634	R/R BUMPER SUPPORT	52562 0D220	0%	£36.42
3013	REAR MANUFACT BADGE	75403 48010	0%	£37.37
3014	BADGE "HYBRID"	75441 K2010	0%	£28.58
3015	BADGE MODEL	75442 K2010	0%	£25.66
3414	R/R BUMPER REFLECTOR	81910 47010	0%	£36.46
3652	R/R S-PANEL MOULDING	75605 K2011	0%	£90.32
3656	RIGHT RETAINER	52161 02030	0%	£6.16
3662	R/SCREW	90159 60623	0%	£2.02
4910	CLIP FASTENING	90467 10161	0%	£25.74

Sub Total	£586.54
Sundry Parts	£20.53
(3.5 %) Total Parts	£607.07

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
CAR CARE KIT Specialist	0%	£6.50
E.P.A. CHARGE Specialist	0%	£5.50
METHODS RESEARCH Specialist	0%	£35.00
ENERGY PAYMENT Specialist	0%	£75.00
COVID CLEAN Specialist	0%	£30.00

Assessment Number: CH000036
Version: payg1261/2

Full Report
Printed: 20/12/2023

Total Extras £152.00

19/12/2023

Labour	Total Panel/Mechanical	£847.00	
	Total Paintwork	£630.00	
Total Labour			£1,477.00
Total Paint/Material Costs			£841.25
Total Parts			£607.07
Additional Costs			
	Corrosion Protection Materials External	£8.00	
	Cost of Specialist	£152.00	
Total Additional Costs			£160.00
Grand Total Excl VAT			£3,085.32
	VAT @ 20 %		£617.06
Grand Total Incl VAT			£3,702.38
	Excess		£0.00

No assessment notes entered.