

Assessment Number: AUK09367
Version: vbra38ub/4

Full Report
Printed: 22/07/2022

Summary Information

Claim

Authorisation Status:	Interim	Date of Incident:	21/03/2022
Work Provider:	OTHER	Able to Authorise Repairs:	TBA
Claim Reference:	12500/1	Repairs Authorised?	TBA
Policy Number:		VAT Portion Payable:	TBA
Other Reference:		Repairer:	
		Estimated Repair Time (Working Days):	

Vehicle Details

Vehicle

Manufacturer:	HYUNDAI
Model:	I10 Classic
Model Sheet Number:	3028
Engine:	1.2 LTR 55/57KW
Registration Number:	YT62YPX
VIN Number:	MALAN51CLCM183043
Registration Month:	September
Registration Year:	2012
Odometer:	41533 miles
Colour:	SILVER
Paint Code:	RHM
Build Date:	FROM 05/2012
Selection Type:	AudaVIN+

Model Specs

FROM 05/2012
AIR CONDITIONING
TINTED WINDOWS
FRT SCREEN WITH VIN
CENTRAL LOCKING
FRT EL WDW REGULATOR
ASPH OUTER MIRROR
MANUAL DOOR MIRROR
AUDIO SYSTEM PA 710R
USB/AUX CONNECTION
DIP REAR VIEW MIRROR
HEADLAMP LEVELLING
REAR WIPER
REAR FOG LAMP
BELT WARNING DEVICE
BELT HEIGHT ADJUSTER
RAD GRILLE MLDG CHRO
SEATBELT TENSIONER
PAINTED BUMPER
R/F SEAT STORAGE BOX
1.2 LTR 55/57KW
5-SPEED
ELEC POWER STEERING
ABS
DRIVER AIRBAG
TYRES 165/60 TR 14
WHEELS 5J X 14
SPARE WHEEL
SIDE AIRBAGS
RR SPOILER/BR-LAMP
PROTECTIVE MOULDINGS
TWO COAT METALLIC

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
-------------------------	---------------------

**TEL: AUTOHAUS GREENFORD FAX:
0208 8109393 61 AINTREE ROAD 0208 8109333
PERIVALE
MIDDLESEX, UB6 7LA**

**Assessment Number: AUK09367
Version: vbra38ub/4**

**Full Report
Printed: 22/07/2022**

Steering Rim Ply:
Brakes Pedal Travel:
Place of Inspection:
Pre-Accident Damage:



Vehicle Status on Inspection:
Date of Inspection: 20/06/2022

Tyres Condition:
Tread Depth LHF:
Tread Depth LHR:

Tread Depth RHF:
Tread Depth RHR:

Damage Areas:

Direction of Impact:



Assessment Number: AUK09367
Version: vbra38ub/4

Full Report
Printed: 22/07/2022

Addresses

No addresses entered.

Cost Summary

Total Labour	£1,058.00
Total Paint/Material	£513.96
Total Parts	£480.37
Additional Costs	£31.00
Grand Total Exc VAT:	£2,083.33
20 % VAT:	£416.67
Grand Total Inc VAT:	£2,500.00
Excess:	TBA

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price = £57.50/HR

Repair / Guide

Number	Description	Work Units
86651R00)	R + R REAR BUMPER	5.0
	INCLUDES: BOTH REAR LAMPS REMOVE AND REFIT.	
86651R00)	RENEW REAR BUMPER COVER	7.0
	(BUMPER REMOVED)	
86630R00)	R + R REAR BUMPER CROSSMEMBER	1.0
87380R00	R + R TAILGATE OUTER HANDLE	2.0
NO NUMBER	R + R TAILGATE MONOGRAM	2.0
81750R00	R + R TAILGATE TRIM	2.0
98710R00)	R + R REAR WIPER MOTOR	1.0
86823R00	R + R LEFT REAR WHEELHOUSE SHELL	3.0
86823R0R	R + R RIGHT REAR WHEELHOUSE SHELL	3.0
85770R00	R + R REAR END PANEL TRIM	2.0
37110R00	R + R BATTERY	3.0
2711	REPAIR REAR PANEL	15.0*
2931	REPAIR BOOTLID/TAILGATE	25.0*
2711	CHECK REAR PANEL	
1000	CHECK METHODS	5.0*
1000	CHECK COVID CLEAN	5.0*
1000	CHECK PRE REPAIR SWEEP	7.0*
1000	CHECK POST REPAIR SWEEP	7.0*
1000	CHECK ROAD TEST	5.0*
1000	CHECK QUALITY CONTROL	5.0*
Total Work Units		105.0

**TEL: AUTOHAUS GREENFORD FAX:
0208 8109393 61 AINTREE ROAD 0208 8109333
PERIVALE
MIDDLESEX, UB6 7LA**

**Assessment Number: AUK09367
Version: vbra38ub/4**

**Full Report
Printed: 22/07/2022**

Total Panel / Mechanical Labour	10.50 HRS	£603.75
--	------------------	----------------

PAINT WORK

Time Basis 10 WU = 1 HR. Price = £57.50/HR

Repair /Guide	Description	
Number		Work Units
2583	REAR BUMPER COVER NEW PART PAINT K1R	10.0
2711	REAR PANEL REPAIR PAINTING <50%	11.0
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	14.0
3481	L/R SIDE PANEL SURFACE PAINT	6.0
3482	R/R SIDE PANEL SURFACE PAINT	6.0
1000	DE NIB SURFACE PAINT	4.0*
	PREPARATION FOR PRE-PAINTING	28.0
Total Work Units		79.0
Total Paintwork Labour		7.9 HRS. £454.25

MATERIAL COST - PAINT

COST

Total Paint Cost	£603.18
Sundry Paint Material	£93.37
Pre-Painting Sundry Materials	£37.68
Total Excluding Pearlescent Uplift	£603.18
Pearlescent Uplift @ 0.0%	£0.00
Discounted by 30%	-£220.27
Total Paint And Material Cost	£513.96

PARTS

Price Valid: 09/05/2022

Guide No.	Description	Part Number	Bet.	Held Date	Price
2583	REAR BUMPER COVER	866110X220	0%		£193.54
2597	L/R REFLECTOR	924050X100	0%		£12.99
2598	R/R REFLECTOR	924060X100	0%		£14.45
2625	L/R OUT BUMPER BRKT	866180X200	0%		£12.97
2626	R/R OUT BUMPER BRKT	866190X200	0%		£11.15
2627	L/SCREW	1244106207B	0%		£2.13
2628	R/SCREW	1244106207B	0%		£2.13
2640	REAR BUMPER SUPPORT	866300X200	0%		£126.38
3013	MANUFACTURER BADGE	863120X000	0%		£30.73

Assessment Number: AUK09367
Version: vbra38ub/4

Full Report
Printed: 22/07/2022

3015	REAR MANUFACT BADGE	863410X000	0%		£18.77
3017	EQUIPMENT BADGE	86330-0X000	0%		£24.17
3020	BADGE MODEL	863200X300	0%		£18.07

Sub Total		£467.48
Deduction from RRP	(0.0 %)	£0.00
Sundry Parts	(Fixed)	£12.89
	Total Parts	£480.37

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras				
	Description		Betterment	Price
	EPA	Specialist	0%	£22.00
	CAR CARE KIT	Specialist	0%	£9.00
			Total Extras	£31.00

Calculation 20/07/2022

Labour			
	Total Panel/Mechanical	£603.75	
	Total Paintwork	£454.25	
Total Labour			£1,058.00
Total Paint/Material Costs			£513.96
Total Parts			£480.37
Additional Costs			
	Cost of Specialist	£31.00	
Total Additional Costs			£31.00
Grand Total Excl VAT			£2,083.33
	VAT @ 20 %		£416.67
Grand Total Incl VAT			£2,500.00
	Excess		TBA

Assessment Notes

No assessment notes entered.