

Calculation

Client:	
Make / Model / Type:	Citroen / Dispatch Panel Van Model 2016 / Dispatch 1.5BlueHDi (100ps) (EU6d) S&S 2022.25 [12.2021]
Glass's national Code	347382001
Vehicle Registration Number:	ML23OXR
VIN:	VF7VBYHRMN7063433
Date:	26.11.2024
Paint system:	AZT
Hail damage logic:	ETG
Labour time unit:	1 Hour
Currency:	£
Database version:	2024.11.

Body		Repair type	Labour time	Overlap-time	Labour costs	Material costs
NN	Front Door Membrane (R)	RP	0.50	0.10	40.00	27.72
	Annotation (time): Autovista opinion time					
65620910	Rear Sliding Door Shell (R)	RP	1.70		136.00	1,189.85
65620410	Rear Sliding Door Shell (R)					
65620210	Rear Sliding Door Shell (R)					
65430910	Rear Door Membrane (R)					
NN	Rear Door Trim Upper Panel (R)					
	Annotation (time): Time includes adjustment					
65430910	Rear Door Membrane (R)	RP	0.00	0.30		30.00
65380910	Rear Door Lower Cover (R)	RP	0.00	0.20		89.75
NN	Rear Door Sealing Compound (R)	RP	0.00			9.24
NN	Rear Side Panel with Door Frame (R)	R	2.50		200.00	0.00
NN	Rear Door Trim Support Kit (R)	RP	0.00			54.16
NN	Rear Door Trim Clip (R)	RP	0.00			0.63
NN	Rear Door Trim Screw (R)	RP	0.00			0.00
Labour costs					376.00	
Material costs						1,401.35
Total Body						£ 1,777.35

Auxiliary work		Repair type	Labour time	Overlap-time	Labour costs	Material costs
NN	Front Door Strip & Set-Up for Paint (R)	UI	0.40		32.00	0.00
63380910	Front Door Lower Cover (R)					
NN	Front Door Outer Handle (R)					
	Annotation (time): Autovista opinion time					
NN	Body Filler	EC	0.00			11.00 F
NN	check wheel and tyre for damage	EC	0.10		8.00	0.00 F
NN	Clamp and Pull	EC	2.00		160.00	0.00 F
NN	Corrosion Protection	EC	0.40 *		32.00	19.00 F
	Additional work (0.10): ...					
NN	De-nib/ polish	EC	0.90 *		72.00	0.00 F
	Additional work (0.60): ...					
NN	Energy cost supplement	EC	0.00			50.00 F
NN	Environmental Charge	EC	0.00			28.00 F
NN	Estimate/Assessment Charge	EC	0.00			70.00 F

NN	PPE equipment	EC	0.00		12.50 F
NN	QC & Road Test	EC	1.00	80.00	0.00 F
NN	Remove decals for paint	EC	1.00	80.00	0.00 F
NN	Research Methods	EC	0.00		45.00 F
NN	Sanitising of damaged vehicle	EC	0.00		40.00 F
NN	Second man lift	EC	0.20	16.00	0.00 F
NN	Standard shutdown	EC	1.00	80.00	0.00 F
NN	Sundries	EC	0.00		49.04 F
NN	Supply and fit new decals	EC	0.00 *		350.00 F
NN	System Diagnostic Check (Post Repair)	EC	0.00		80.00 F
NN	System Diagnostic Check (Pre Repair)	EC	0.00		80.00 F
NN	Vehicle Care Kit	EC	0.00		10.00 F
NN	Wash/Clean	EC	1.00	80.00	0.00 F
NN	Wheel Alignment (4 wheel)	EC	0.00		108.00 F

Labour costs

640.00

Material costs

952.54

Total Auxiliary work

£ 1,592.54

Paint	Paint type	Paint level	Labour time	Labour costs	Material costs
Front Door, Complete K (R)	200	B	1.00	80.00	242.30
B-Post (R)	200	III	1.30	104.00	113.80
Side Door, Complete (Glazed) K (R)	200	I	2.30	184.00	536.80
Rear Door Protective Moulding (R)	200	K1R	0.40	32.00	43.10
Prep. metal (on vehicle without pre-painting)	200		1.70	136.00	109.44
Prep. synthetics (combined-operation work)	200		0.50	40.00	42.65
Colour mixing (1)			0.30	24.00	0.00
Sample colour creation (1)			0.30	24.00	10.61

Labour costs

624.00

Material costs

1,098.70

Total Paint

£ 1,722.70

Summary	Labour rate	Labour time	Labour costs	Material costs
Body	80.00	4.70	376.00	1,401.35
Auxiliary work	80.00	8.00	640.00	952.54
Paint	80.00	7.80	624.00	1,098.70

Total Labour

20.50

1,640.00

Total Material

3,452.59

Repair costs excl. VAT

5,092.59

VAT (20.00 %)

1,018.52

Repair costs incl. VAT

£ 6,111.11

Part name	Part no.	Previous part no.	Material costs
Front Door Membrane	9806515680		27.72
Rear Sliding Door Shell	9847296780		1,189.85
Rear Door Membrane	9809891480		30.00
Rear Door Lower Cover	98087489XT		89.75
Rear Door Sealing Compound	9984J3		9.24
Rear Door Trim Support Kit	6999GQ		54.16
Rear Door Trim Clip	9807218280		0.63
Rear Door Trim Screw	KET		0.00

Total Parts**£ 1,401.35**

Attention: Listed part numbers are for information only and CANNOT be used for ordering purposes.

Part name	Position no.
Front Door Membrane	
Rear Sliding Door Shell	65620910
Rear Door Membrane	65430910
Rear Door Lower Cover	65380910
Rear Door Sealing Compound	
Rear Side Panel with Door Frame	
Front Door Strip & Set-Up for Paint	
Rear Door Trim Support Kit	
Rear Door Trim Clip	
Rear Door Trim Screw	
Body Filler	
check wheel and tyre for damage	
Clamp and Pull	
Corrosion Protection	
De-nib/ polish	
Energy cost supplement	
Environmental Charge	
Estimate/Assessment Charge	
PPE equipment	
QC & Road Test	
Remove decals for paint	
Research Methods	
Sanitising of damaged vehicle	
Second man lift	
Standard shutdown	
Sundries	
Supply and fit new decals	
System Diagnostic Check (Post Repair)	
System Diagnostic Check (Pre Repair)	
Vehicle Care Kit	
Wash/Clean	
Wheel Alignment (4 wheel)	

Abbreviations	Description
*	Price or time modified
F	User defined operations
R	RIGHT
RP	Replace
R	Repair
UI	Uninstall and install
EC	Surcharge
NN	No part number

Paint type	Paint level, Procedure, Method
B	Adjacent Panel Blend
200	2 Coat
III	Repair up to 50%
I	New part
K1R	Part priming/part raw

Additional Fields	
Paint material index	100.000 %
Part index	100.000 %

Glass's does not take responsibility for accuracy and completeness of data originating from vehicle

manufacturers.