TMS320C28x Extended Instruction Sets

Technical Reference Manual



Literature Number: SPRUHS1A

March 2014-Revised December 2015



Contents

Pref	ace		5
1	Floa	ting Point Unit (FPU)	9
	1.1	Overview	
		1.1.1 Compatibility with the C28x Fixed-Point CPU	
	1.2	Components of the C28x plus Floating-Point CPU	
		1.2.1 Emulation Logic	
		1.2.2 Memory Map	
		1.2.3 On-Chip Program and Data	
		1.2.4 CPU Interrupt Vectors	
		1.2.5 Memory Interface	
	1.3	CPU Register Set	
		1.3.1 CPU Registers	
	1.4	Pipeline	
		1.4.1 Pipeline Overview	
		1.4.2 General Guidelines for Floating-Point Pipeline Alignment	
		1.4.3 Moves from FPU Registers to C28x Registers	
		1.4.4 Moves from C28x Registers to FPU Registers	
		1.4.5 Parallel Instructions	
		1.4.6 Invalid Delay Instructions	
		1.4.7 Optimizing the Pipeline	
	1.5	Floating Point Unit Instruction Set	
	1.0	1.5.1 Instruction Descriptions	
		1.5.2 Instructions	
_	000		
2		Viterbi, Complex Math and CRC Unit-II (VCU-II)	
	2.1	Overview	
	2.2	Components of the C28x Plus VCU	
		2.2.1 Emulation Logic	
		2.2.2 Memory Map	
		2.2.3 CPU Interrupt Vectors	
		2.2.4 Memory Interface	
		2.2.5 Address and Data Buses	
		2.2.6 Alignment of 32-Bit Accesses to Even Addresses	
	2.3	Register Set	
		2.3.1 VCU Register Set	
		2.3.2 VCU Status Register (VSTATUS)	
		2.3.3 Repeat Block Register (RB)	52
	2.4	Pipeline	54
		2.4.1 Pipeline Overview	
		2.4.2 General Guidelines for VCU Pipeline Alignment	54
		2.4.3 Parallel Instructions 15	55
		2.4.4 Invalid Delay Instructions	56
	2.5	Instruction Set	59
		2.5.1 Instruction Descriptions	59
		2.5.2 General Instructions	31
		2.5.3 Arithmetic Math Instructions)5



www.ti.com

		2.5.4	Complex Math Instructions	212
		2.5.5	Cyclic Redundancy Check (CRC) Instructions	271
		2.5.6	Deinterleaver Instructions	287
		2.5.7	FFT Instructions	303
		2.5.8	Galois Instructions	331
		2.5.9	Viterbi Instructions	344
	2.6	Round	ing Mode	379
3	Trigo	nomet	ric Math Unit (TMU)	381
	3.1		ew	
	3.2	Compo	onents of the C28x+FPU Plus TMU	382
		3.2.1	Interrupt Context Save and Restore	382
	3.3	Data F	ormat	382
	3.4	Pipelin	e	383
		3.4.1	Pipeline and Register Conflicts	383
		3.4.2	Delay Slot Requirements	385
		3.4.3	Effect of Delay Slot Operations on the Flags	386
		3.4.4	Multi-Cycle Operations in Delay Slots	386
		3.4.5	Moves From FPU Registers to C28x Registers	386
	3.5	II UMT	nstruction Set	
		3.5.1	Instruction Descriptions	
		3.5.2	Common Restrictions	
		3.5.3	Instructions	389
Rev	ision H	istory		403



List of Figures

1-1.	FPU Functional Block Diagram	. 10
1-2.	C28x With Floating-Point Registers	. 14
1-3.	Floating-point Unit Status Register (STF)	. 16
1-4.	Repeat Block Register (RB)	. 18
1-5.	FPU Pipeline	. 19
2-1.	C28x + VCU Block Diagram	142
2-2.	C28x + FPU + VCU Registers	146
2-3.	VCU Status Register (VSTATUS)	149
2-4.	Repeat Block Register (RB)	
2-5.	C28x + FCU + VCU Pipeline	
	List of Tables	
1-1.	28x Plus Floating-Point CPU Register Summary	. 15
1-2.	Floating-point Unit Status (STF) Register Field Descriptions	
1-3.	Repeat Block (RB) Register Field Descriptions	
1-4.	Operand Nomenclature	
1-5.	Summary of Instructions	. 29
2-1.	Viterbi Decode Performance	
2-2.	Complex Math Performance	141
2-3.	VCU Register Set	147
2-4.	28x CPU Register Summary	148
2-5.	VCU Status (VSTATUS) Register Field Descriptions	149
2-6.	Operation Interaction With VSTATUS Bits	150
2-7.	Repeat Block (RB) Register Field Descriptions	152
2-8.	Operations Requiring a Delay Slot(s)	155
2-9.	Operand Nomenclature	159
2-10.	INSTRUCTION dest, source1, source2 Short Description	
2-11.	General Instructions	161
2-12.	Arithmetic Math Instructions	205
2-13.	Complex Math Instructions	212
2-14.	CRC Instructions	271
2-15.	Deinterleaver Instructions	287
2-16.	FFT Instructions	303
2-17.	Galois Field Instructions	331
2-18.	Viterbi Instructions	344
2-19.	Example: Values Before Shift Right	379
2-20.	Example: Values after Shift Right	379
2-21.	Example: Addition with Right Shift and Rounding	379
2-22.	Example: Addition with Rounding After Shift Right	379
2-23.	Shift Right Operation With and Without Rounding	380
3-1.	TMU Supported Instructions	382
3-2.	IEEE 32-Bit Single Precision Floating-Point Format	382
3-3.	Delay Slot Requirements for TMU Instructions	385
3-4.	Operand Nomenclature	388
3-5.	Summary of Instructions	389



Read This First

This document describes the architecture, pipeline, and instruction sets of the TMU, VCU-II, and FPU accelerators.

About This Manual

The TMS320C2000™ digital signal processor (DSP) platform is part of the TMS320™ DSP family.

Notational Conventions

This document uses the following conventions.

- Hexadecimal numbers are shown with the suffix h or with a leading 0x. For example, the following number is 40 hexadecimal (decimal 64): 40h or 0x40.
- Registers in this document are shown as figures and described in tables.
 - Each register figure shows a rectangle divided into fields that represent the fields of the register.
 Each field is labeled with its bit name, its beginning and ending bit numbers above, and its read/write properties below. A legend explains the notation used for the properties
 - Reserved bits in a register figure designate a bit that is used for future device expansion.

Related Documentation

The following books describe the TMS320x28x and related support tools that are available on the TI website:

Data Manual and Errata—

- SPRS439— TMS320F28335, TMS320F28334, TMS320F28332, TMS320F28235, TMS320F28234, TMS320F28232 Digital Signal Controllers (DSCs) Data Manual contains the pinout, signal descriptions, as well as electrical and timing specifications for the F2833x/2823x devices.
- SPRZ272— TMS320F28335, F28334, F28332, TMS320F28235, F28234, F28232 Digital Signal Controllers (DSCs) Silicon Errata describes the advisories and usage notes for different versions of silicon.

CPU User's Guides—

- SPRU430 TMS320C28x CPU and Instruction Set Reference Guide describes the central processing unit (CPU) and the assembly language instructions of the TMS320C28x fixed-point digital signal processors (DSPs). It also describes emulation features available on these DSPs.
- SPRUEO2 TMS320C28x Floating Point Unit and Instruction Set Reference Guide describes the floating-point unit and includes the instructions for the FPU.

Peripheral Guides—

- <u>SPRU566</u> TMS320x28xx, 28xxx DSP Peripheral Reference Guide describes the peripheral reference guides of the 28x digital signal processors (DSPs).
- SPRUFB0 TMS320x2833x, 2823x System Control and Interrupts Reference Guide describes the various interrupts and system control features of the 2833x and 2823x digital signal controllers (DSCs).
- <u>SPRU812</u> TMS320x2833x, 2823x Analog-to-Digital Converter (ADC) Reference Guide describes how to configure and use the on-chip ADC module, which is a 12-bit pipelined ADC.
- <u>SPRU949</u> TMS320x2833x, 2823x DSC External Interface (XINTF) Reference Guide describes the XINTF, which is a nonmultiplexed asynchronous bus, as it is used on the 2833x and 2823x devices.



Related Documentation www.ti.com

- SPRU963 TMS320x2833x, 2823x Boot ROM Reference Guide describes the purpose and features of the bootloader (factory-programmed boot-loading software) and provides examples of code. It also describes other contents of the device on-chip boot ROM and identifies where all of the information is located within that memory.
- SPRUFB7 TMS320x2833x, 2823x Multichannel Buffered Serial Port (McBSP) Reference Guide describes the McBSP available on the 2833x and 2823x devices. The McBSPs allow direct interface between a DSP and other devices in a system.
- SPRUFB8 TMS320x2833x, 2823x Direct Memory Access (DMA) Module Reference Guide describes the DMA on the 2833x and 2823x devices.
- SPRUG04 TMS320x2833x, 2823x Enhanced Pulse Width Modulator (ePWM) Module Reference Guide describes the main areas of the enhanced pulse width modulator that include digital motor control, switch mode power supply control, UPS (uninterruptible power supplies), and other forms of power conversion.
- SPRUG02 TMS320x2833x, 2823x High-Resolution Pulse Width Modulator (HRPWM) Reference Guide describes the operation of the high-resolution extension to the pulse width modulator (HRPWM).
- SPRUFG4 TMS320x2833x, 2823x Enhanced Capture (eCAP) Module Reference Guide describes the enhanced capture module. It includes the module description and registers.
- SPRUG05 TMS320x2833x, 2823x Enhanced Quadrature Encoder Pulse (eQEP) Module Reference Guide describes the eQEP module, which is used for interfacing with a linear or rotary incremental encoder to get position, direction, and speed information from a rotating machine in high-performance motion and position control systems. It includes the module description and registers.
- <u>SPRUEU1</u> TMS320x2833x, 2823x Enhanced Controller Area Network (eCAN) Reference Guide describes the eCAN that uses established protocol to communicate serially with other controllers in electrically noisy environments.
- SPRUFZ5 TMS320x2833x, 2823x Serial Communications Interface (SCI) Reference Guide describes the SCI, which is a two-wire asynchronous serial port, commonly known as a UART. The SCI modules support digital communications between the CPU and other asynchronous peripherals that use the standard non-return-to-zero (NRZ) format.
- SPRUEU3 TMS320x2833x, 2823x DSC Serial Peripheral Interface (SPI) Reference Guide describes the SPI a high-speed synchronous serial input/output (I/O) port that allows a serial bit stream of programmed length (one to sixteen bits) to be shifted into and out of the device at a programmed bit-transfer rate.
- SPRUG03 TMS320x2833x, 2823x Inter-Integrated Circuit (I2C) Module Reference Guide describes the features and operation of the inter-integrated circuit (I2C) module.

Tools Guides—

- SPRU513 TMS320C28x Assembly Language Tools v5.0.0 User's Guide describes the assembly language tools (assembler and other tools used to develop assembly language code), assembler directives, macros, common object file format, and symbolic debugging directives for the TMS320C28x device.
- SPRU514 TMS320C28x Optimizing C/C++ Compiler v5.0.0 User's Guide describes the TMS320C28x[™] C/C++ compiler. This compiler accepts ANSI standard C/C++ source code and produces TMS320 DSP assembly language source code for the TMS320C28x device.
- SPRU608 TMS320C28x Instruction Set Simulator Technical Overview describes the simulator, available within the Code Composer Studio for TMS320C2000 IDE, that simulates the instruction set of the C28x™ core.
- <u>SPRU625</u> TMS320C28x DSP/BIOS 5.32 Application Programming Interface (API) Reference Guide describes development using DSP/BIOS.



www.ti.com Related Documentation

Trademarks

TMS320C28x, C28x, TMS320C2000 are trademarks of Texas Instruments.



Related Documentation www.ti.com



Floating Point Unit (FPU)

The TMS320C2000[™] DSP family consists of fixed-point and floating-point digital signal controllers (DSCs). TMS320C2000[™] Digital Signal Controllers combine control peripheral integration and ease of use of a microcontroller (MCU) with the processing power and C efficiency of Tl's leading DSP technology. This chapter provides an overview of the architectural structure and components of the C28x plus floating-point unit CPU.

Topic Page

1.1	Overview	10
1.2	Components of the C28x plus Floating-Point CPU	11
1.3	CPU Register Set	13
1.4	Pipeline	19
1.5	Floating Point Unit Instruction Set	26



Overview www.ti.com

1.1 Overview

The C28x plus floating-point (C28x+FPU) processor extends the capabilities of the C28x fixed-point CPU by adding registers and instructions to support IEEE single-precision floating point operations. This device draws from the best features of digital signal processing; reduced instruction set computing (RISC); and microcontroller architectures, firmware, and tool sets. The DSC features include a modified Harvard architecture and circular addressing. The RISC features are single-cycle instruction execution, register-to-register operations, and modified Harvard architecture (usable in Von Neumann mode). The microcontroller features include ease of use through an intuitive instruction set, byte packing and unpacking, and bit manipulation. The modified Harvard architecture of the CPU enables instruction and data fetches to be performed in parallel. The CPU can read instructions and data while it writes data simultaneously to maintain the single-cycle instruction operation across the pipeline. The CPU does this over six separate address/data buses.

Throughout this document the following notations are used:

- C28x refers to the C28x fixed-point CPU.
- C28x plus Floating-Point and C28x+FPU both refer to the C28x CPU with enhancements to support IEEE single-precision floating-point operations.

1.1.1 Compatibility with the C28x Fixed-Point CPU

No changes have been made to the C28x base set of instructions, pipeline, or memory bus architecture. Therefore, programs written for the C28x CPU are completely compatible with the C28x+FPU and all of the features of the C28x documented in *TMS320C28x DSP CPU and Instruction Set Reference Guide* (literature number SPRU430) apply to the C28x+FPU.

Figure 1-1 shows basic functions of the FPU.




Figure 1-1. FPU Functional Block Diagram



1.1.1.1 Floating-Point Code Development

When developing C28x floating-point code use Code Composer Studio 3.3, or later, with at least service release 8. The C28x compiler V5.0, or later, is also required to generate C28x native floating-point opcodes. This compiler is available via Code Composer Studio update advisor as a seperate download. V5.0 can generate both fixed-point as well as floating-point code. To build floating-point code use the compiler switches:-v28 and - -float_support = fpu32. In Code Composer Studio 3.3 the float_support option is in the build options under compiler-> advanced: floating point support. Without the float_support flag, or with float_support = none, the compiler will generate fixed-point code.

When building for C28x floating-point make sure all associated libraries have also been built for floating-point. The standard run-time support (RTS) libraries built for floating-point included with the compiler have fpu32 in their name. For example rts2800_fpu32.lib and rts2800_fpu_eh.lib have been built for the floating-point unit. The "eh" version has exception handling for C++ code. Using the fixed-point RTS libraries in a floating-point project will result in the linker issuing an error for incompatible object files.

To improve performance of native floating-point projects, consider using the *C28x FPU Fast RTS Library* (SPRC664). This library contains hand-coded optimized math routines such as division, square root, atan2, sin and cos. This library can be linked into your project before the standard runtime support library to give your application a performance boost. As an example, the standard RTS library uses a polynomial expansion to calculate the sin function. The Fast RTS library, however, uses a math look-up table in the boot ROM of the device. Using this look-up table method results in approximately a 20 cycle savings over the standard RTS calculation.

1.2 Components of the C28x plus Floating-Point CPU

The C28x+FPU contains:

- A central processing unit for generating data and program-memory addresses; decoding and executing instructions; performing arithmetic, logical, and shift operations; and controlling data transfers among CPU registers, data memory, and program memory
- A floating-point unit for IEEE single-precision floating point operations.
- Emulation logic for monitoring and controlling various parts and functions of the device and for testing device operation. This logic is identical to that on the C28x fixed-point CPU.
- Signals for interfacing with memory and peripherals, clocking and controlling the CPU and the
 emulation logic, showing the status of the CPU and the emulation logic, and using interrupts. This logic
 is identical to the C28x fixed-point CPU.

Some features of the C28x+FPU central processing unit are:

- Fixed-Point instructions are pipeline protected. This pipeline for fixed-point instructions is identical to that on the C28x fixed-point CPU. The CPU implements an 8-phase pipeline that prevents a write to and a read from the same location from occurring out of order. See Figure 1-5.
- Some floating-point instructions require pipeline alignment. This alignment is done through software to allow the user to improve performance by taking advantage of required delay slots.
- Independent register space. These registers function as system-control registers, math registers, and data pointers. The system-control registers are accessed by special instructions.
- Arithmetic logic unit (ALU). The 32-bit ALU performs 2s-complement arithmetic and Boolean logic operations.
- Floating point unit (FPU). The 32-bit FPU performs IEEE single-precision floating-point operations.
- Address register arithmetic unit (ARAU). The ARAU generates data memory addresses and increments or decrements pointers in parallel with ALU operations.
- Barrel shifter. This shifter performs all left and right shifts of fixed-point data. It can shift data to the left by up to 16 bits and to the right by up to 16 bits.
- Fixed-Point Multiplier. The multiplier performs 32-bit x 32-bit 2s-complement multiplication with a 64-bit result. The multiplication can be performed with two signed numbers, two unsigned numbers, or one signed number and one unsigned number.



1.2.1 Emulation Logic

The emulation logic is identical to that on the C28x fixed-point CPU. This logic includes the following features:

- Debug-and-test direct memory access (DT-DMA). A debug host can gain direct access to the content
 of registers and memory by taking control of the memory interface during unused cycles of the
 instruction pipeline.
- A counter for performance benchmarking.
- Multiple debug events. Any of the following debug events can cause a break in program execution:
 - A breakpoint initiated by the ESTOP0 or ESTOP1 instruction.
 - An access to a specified program-space or data-space location.

When a debug event causes the C28x to enter the debug-halt state, the event is called a break event.

· Real-time mode of operation.

For more details about these features, refer to the *TMS320C28x DSP CPU and Instruction Set Reference Guide* (literature number SPRU430.

1.2.2 Memory Map

Like the C28x, the C28x+FPU uses 32-bit data addresses and 22-bit program addresses. This allows for a total address reach of 4G words (1 word = 16 bits) in data space and 4M words in program space. Memory blocks on all C28x+FPU designs are uniformly mapped to both program and data space. For specific details about each of the map segments, see the data sheet for your device.

1.2.3 On-Chip Program and Data

All C28x+FPU based devices contain at least two blocks of single access on-chip memory referred to as M0 and M1. Each of these blocks is 1K words in size. M0 is mapped at addresses 0x0000 – 0x03FF and M1 is mapped at addresses 0x0400 – 0x07FF. Like all other memory blocks on the C28x+FPU devices, M0 and M1 are mapped to both program and data space. Therefore, you can use M0 and M1 to execute code or for data variables. At reset, the stack pointer is set to the top of block M1. Depending on the device, it may also have additional random-access memory (RAM), read-only memory (ROM), external interface zones, or flash memory.

1.2.4 CPU Interrupt Vectors

The C28x+FPU interrupt vectors are identical to those on the C28x CPU. Sixty-four addresses in program space are set aside for a table of 32 CPU interrupt vectors. The CPU vectors can be mapped to the top or bottom of program space by way of the VMAP bit. For more information about the CPU vectors, see *TMS320C28x DSP CPU and Instruction Set Reference Guide* (literature number SPRU430). For devices with a peripheral interrupt expansion (PIE) block, the interrupt vectors will reside in the PIE vector table and this memory can be used as program memory.

1.2.5 Memory Interface

The C28x+FPU memory interface is identical to that on the C28x. The C28x+FPU memory map is accessible outside the CPU by the memory interface, which connects the CPU logic to memories, peripherals, or other interfaces. The memory interface includes separate buses for program space and data space. This means an instruction can be fetched from program memory while data memory is being accessed. The interface also includes signals that indicate the type of read or write being requested by the CPU. These signals can select a specified memory block or peripheral for a given bus transaction. In addition to 16-bit and 32-bit accesses, the C28x+FPU supports special byte-access instructions that can access the least significant byte (LSByte) or most significant byte (MSByte) of an addressed word. Strobe signals indicate when such an access is occurring on a data bus.

1.2.5.1 Address and Data Buses

Like the C28x, the memory interface has three address buses:

PAB: Program address bus



www.ti.com CPU Register Set

The PAB carries addresses for reads and writes from program space. PAB is a 22-bit bus.

DRAB: Data-read address bus

The 32-bit DRAB carries addresses for reads from data space.

DWAB: Data-write address bus

The 32-bit DWAB carries addresses for writes to data space.

The memory interface also has three data buses:

PRDB: Program-read data bus

The PRDB carries instructions during reads from program space. PRDB is a 32-bit bus.

· DRDB: Data-read data bus

The DRDB carries data during reads from data space. DRDB is a 32-bit bus.

DWDB: Data-/Program-write data bus

The 32-bit DWDB carries data during writes to data space or program space.

A program-space read and a program-space write cannot happen simultaneously because both use the PAB. Similarly, a program-space write and a data-space write cannot happen simultaneously because both use the DWDB. Transactions that use different buses can happen simultaneously. For example, the CPU can read from program space (using PAB and PRDB), read from data space (using DRAB and DRDB), and write to data space (using DWAB and DWDB) at the same time. This behavior is identical to the C28x CPU.

1.2.5.2 Alignment of 32-Bit Accesses to Even Addresses

The C28x+FPU CPU expects memory wrappers or peripheral-interface logic to align any 32-bit read or write to an even address. If the address-generation logic generates an odd address, the CPU will begin reading or writing at the previous even address. This alignment does not affect the address values generated by the address-generation logic.

Most instruction fetches from program space are performed as 32-bit read operations and are aligned accordingly. However, alignment of instruction fetches are effectively invisible to a programmer. When instructions are stored to program space, they do not have to be aligned to even addresses. Instruction boundaries are decoded within the CPU.

You need to be concerned with alignment when using instructions that perform 32-bit reads from or writes to data space.

1.3 CPU Register Set

The C28x+FPU architecture is the same as the C28x CPU with an extended register and instruction set to support IEEE single-precision floating point operations. This section describes the extensions to the C28x architecture

1.3.1 CPU Registers

Devices with the C28x+FPU include the standard C28x register set plus an additional set of floating-point unit registers. The additional floating-point unit registers are the following:

- Eight floating-point result registers, RnH (where n = 0 7)
- Floating-point Status Register (STF)
- Repeat Block Register (RB)

All of the floating-point registers except the repeat block register are shadowed. This shadowing can be used in high priority interrupts for fast context save and restore of the floating-point registers.

Figure 1-2 shows a diagram of both register sets and Table 1-1 shows a register summary. For information on the standard C28x register set, see the *TMS320C28x DSP CPU and Instruction Set Reference Guide* (literature number <u>SPRU430</u>).



CPU Register Set www.ti.com

Figure 1-2. C28x With Floating-Point Registers

Standard	C28x	Rea	ister	Set

ACC (32-bit)
P (32-bit)
XT (32-bit)
XAR0 (32-bit)
XAR1 (32-bit)
XAR2 (32-bit)
XAR3 (32-bit)
XAR4 (32-bit)
XAR5 (32-bit)
XAR6 (32-bit)
XAR7 (32-bit)
PC (22-bit)
RPC (22-bit)
DP (16-bit)

SP (16-bit)	
ST0 (16-bit)	
ST1 (16-bit)	
IER (16-bit)	
IFR (16-bit)	
DBGIER (16-bit)	

Additional 32-bit FPU Registers

R0H (32-bit)
R1H (32-bit)
R2H (32-bit)
R3H (32-bit)
R4H (32-bit)
R5H (32-bit)
R6H (32-bit)
R7H (32-bit)
FPU Status Register (STF)
Repeat Block Register (RB)

FPU registers R0H - R7H and STF are shadowed for fast context save and restore



www.ti.com CPU Register Set

Table 1-1. 28x Plus Floating-Point CPU Register Summary

Register	C28x CPU	C28x+FPU	Size	Description	Value After Reset
ACC	Yes	Yes	32 bits	Accumulator	0x0000000
AH	Yes	Yes	16 bits	High half of ACC	0x0000
AL	Yes	Yes	16 bits	Low half of ACC	0x0000
XAR0	Yes	Yes	32 bits	Auxiliary register 0	0x0000000
XAR1	Yes	Yes	32 bits	Auxiliary register 1	0x0000000
XAR2	Yes	Yes	32 bits	Auxiliary register 2	0x0000000
XAR3	Yes	Yes	32 bits	Auxiliary register 3	0x0000000
XAR4	Yes	Yes	32 bits	Auxiliary register 4	0x0000000
XAR5	Yes	Yes	32 bits	Auxiliary register 5	0x0000000
XAR6	Yes	Yes	32 bits	Auxiliary register 6	0x0000000
XAR7	Yes	Yes	32 bits	Auxiliary register 7	0x0000000
AR0	Yes	Yes	16 bits	Low half of XAR0	0x0000
AR1	Yes	Yes	16 bits	Low half of XAR1	0x0000
AR2	Yes	Yes	16 bits	Low half of XAR2	0x0000
AR3	Yes	Yes	16 bits	Low half of XAR3	0x0000
AR4	Yes	Yes	16 bits	Low half of XAR4	0x0000
AR5	Yes	Yes	16 bits	Low half of XAR5	0x0000
AR6	Yes	Yes	16 bits	Low half of XAR6	0x0000
AR7	Yes	Yes	16 bits	Low half of XAR7	0x0000
DP	Yes	Yes	16 bits	Data-page pointer	0x0000
IFR	Yes	Yes	16 bits	Interrupt flag register	0x0000
IER	Yes	Yes	16 bits	Interrupt enable register	0x0000
DBGIER	Yes	Yes	16 bits	Debug interrupt enable register	0x0000
Р	Yes	Yes	32 bits	Product register	0x0000000
PH	Yes	Yes	16 bits	High half of P	0x0000
PL	Yes	Yes	16 bits	Low half of P	0x0000
PC	Yes	Yes	22 bits	Program counter	0x3FFFC0
RPC	Yes	Yes	22 bits	Return program counter	0x0000000
SP	Yes	Yes	16 bits	Stack pointer	0x0400
ST0	Yes	Yes	16 bits	Status register 0	0x0000
ST1	Yes	Yes	16 bits	Status register 1	0x080B ⁽¹⁾
XT	Yes	Yes	32 bits	Multiplicand register	0x0000000
Т	Yes	Yes	16 bits	High half of XT	0x0000
TL	Yes	Yes	16 bits	Low half of XT	0x0000
ROH	No	Yes	32 bits	Floating-point result register 0	0.0
R1H	No	Yes	32 bits	Floating-point result register 1	0.0
R2H	No	Yes	32 bits	Floating-point result register 2	0.0
R3H	No	Yes	32 bits	Floating-point result register 3	0.0
R4H	No	Yes	32 bits	Floating-point result register 4	0.0
R5H	No	Yes	32 bits	Floating-point result register 5	0.0
R6H	No	Yes	32 bits	Floating-point result register 6 0.0	
R7H	No	Yes	32 bits	Floating-point result register 7 0.0	
STF	No	Yes	32 bits	Floating-point status register	0x0000000
RB	No	Yes	32 bits	Repeat block register	0x0000000

⁽¹⁾ Reset value shown is for devices without the VMAP signal and MOM1MAP signal pinned out. On these devices both of these signals are tied high internal to the device.



CPU Register Set www.ti.com

1.3.1.1 Floating-Point Status Register (STF)

The floating-point status register (STF) reflects the results of floating-point operations. There are three basic rules for floating point operation flags:


- 1. Zero and negative flags are set based on moves to registers.
- 2. Zero and negative flags are set based on the result of compare, minimum, maximum, negative and absolute value operations.
- 3. Overflow and underflow flags are set by math instructions such as multiply, add, subtract and 1/x. These flags may also be connected to the peripheral interrupt expansion (PIE) block on your device. This can be useful for debugging underflow and overflow conditions within an application.

As on the C28x, program flow is controlled by C28x instructions that read status flags in the status register 0 (ST0). If a decision needs to be made based on a floating-point operation, the information in the STF register needs to be loaded into ST0 flags (Z,N,OV,TC,C) so that the appropriate branch conditional instruction can be executed. The MOVST0 FLAGinstruction is used to load the current value of specified STF flags into the respective bits of ST0. When this instruction executes, it will also clear the latched overflow and underflow flags if those flags are specified.

Example 1-1. Moving STF Flags to the ST0 Register



Figure 1-3. Floating-point Unit Status Register (STF)



LEGEND: R/W = Read/Write; R = Read only; -n = value after reset

Table 1-2. Floating-point Unit Status (STF) Register Field Descriptions

Bits	Field	Value	Description		
31	SHDWS		Shadow Mode Status Bit		
		0	This bit is forced to 0 by the RESTORE instruction.		
		1	This bit is set to 1 by the SAVE instruction.		
			This bit is not affected by loading the status register either from memory or from the shadow values.		
30 - 10	Reserved	0	Reserved for future use		
9	RND32		Round 32-bit Floating-Point Mode		
		0	If this bit is zero, the MPYF32, ADDF32 and SUBF32 instructions will round to zero (truncate).		
		1	If this bit is one, the MPYF32, ADDF32 and SUBF32 instructions will round to the nearest even value.		
8 - 7	Reserved	0	Reserved for future use		
6	TF		Test Flag		
			The TESTTF instruction can modify this flag based on the condition tested. The SETFLG and SAVE instructions can also be used to modify this flag.		
		0	The condition tested with the TESTTF instruction is false.		
		1	The condition tested with the TESTTF instruction is true.		



www.ti.com CPU Register Set

Table 1-2. Floating-point Unit Status (STF) Register Field Descriptions (continued)

Bits	Field	Value	Description			
5	ZI		Zero Integer Flag			
			The following instructions modify this flag based on the integer value stored in the destination register: MOV32, MOVD32, MOVDD32 The SETFLG and SAVE instructions can also be used to modify this flag.			
		0	The integer value is not zero.			
		1	The integer value is zero.			
4	NI		Negative Integer Flag			
			The following instructions modify this flag based on the integer value stored in the destination register: MOV32, MOVD32, MOVDD32 The SETFLG and SAVE instructions can also be used to modify this flag.			
		0	The integer value is not negative.			
		1	The integer value is negative.			
3	ZF		Zero Floating-Point Flag (1) (2)			
			The following instructions modify this flag based on the floating-point value stored in the destination register: MOV32, MOVD32, MOVDD32, ABSF32, NEGF32 The CMPF32, MAXF32, and MINF32 instructions modify this flag based on the result of the operation. The SETFLG and SAVE instructions can also be used to modify this flag			
		0	The floating-point value is not zero.			
		1	The floating-point value is zero.			
2	NF		Negative Floating-Point Flag (1) (2)			
			The following instructions modify this flag based on the floating-point value stored in the destination register: MOV32, MOVD32, MOVDD32, ABSF32, NEGF32 The CMPF32, MAXF32, and MINF32 instructions modify this flag based on the result of the operation. The SETFLG and SAVE instructions can also be used to modify this flag.			
		0	The floating-point value is not negative.			
		1	The floating-point value is negative.			
1	LUF		Latched Underflow Floating-Point Flag			
			The following instructions will set this flag to 1 if an underflow occurs: MPYF32, ADDF32, SUBF32, MACF32, EINVF32, EISQRTF32			
		0	An underflow condition has not been latched. If the MOVST0 instruction is used to copy this bit to ST0, then LUF will be cleared.			
		1	An underflow condition has been latched.			
0	LVF		Latched Overflow Floating-Point Flag			
			The following instructions will set this flag to 1 if an overflow occurs: MPYF32, ADDF32, SUBF32, MACF32, EINVF32, EISQRTF32			
		0	An overflow condition has not been latched. If the MOVST0 instruction is used to copy this bit to ST0, then LVF will be cleared.			
		1	An overflow condition has been latched.			

⁽¹⁾ A negative zero floating-point value is treated as a positive zero value when configuring the ZF and NF flags.

⁽²⁾ A DeNorm floating-point value is treated as a positive zero value when configuring the ZF and NF flags.



CPU Register Set www.ti.com

1.3.1.2 Repeat Block Register (RB)


The repeat block instruction (RPTB) is a new instruction for C28x+FPU. This instruction allows you to repeat a block of code as shown in Example 1-2.

Example 1-2. The Repeat Block (RPTB) Instruction uses the RB Register

```
; find the largest element and put its address in XAR6
 MOV32 ROH, *XAR0++;
 .align 2
                                ; Aligns the next instruction to an even address
 NOP
                               ; Makes RPTB odd aligned - required for a block size of 8
                               ; RA is set to 1
 RPTB
         VECTOR_MAX_END, AR7
 MOVL
         ACC, XARO
         R1H,*XAR0++
                               ; RSIZE reflects the size of the RPTB block
 MOV32
 MAXF32 ROH,R1H
                                ; in this case the block size is 8
 MOVSTO NF, ZF
         XAR6,ACC,LT
 TVOM.
 VECTOR_MAX_END:
                                ; RE indicates the end address. RA is cleared
```

The C28x_FPU hardware automatically populates the RB register based on the execution of a RPTB instruction. This register is not normally read by the application and does not accept debugger writes.

Figure 1-4. Repeat Block Register (RB)



LEGEND: R = Read only; -n = value after reset

Table 1-3. Repeat Block (RB) Register Field Descriptions

Bits	Field	Value	Description	
31	RAS		Repeat Block Active Shadow Bit	
			When an interrupt occurs the repeat active, RA, bit is copied to the RAS bit and the RA bit is cleared. When an interrupt return instruction occurs, the RAS bit is copied to the RA bit and RAS is cleared.	
		0	A repeat block was not active when the interrupt was taken.	
		1	A repeat block was active when the interrupt was taken.	
30	RA		Repeat Block Active Bit	
		0	This bit is cleared when the repeat counter, RC, reaches zero.	
			When an interrupt occurs the RA bit is copied to the repeat active shadow, RAS, bit and RA is cleared. When an interrupt return, IRET, instruction is executed, the RAS bit is copied to the RA bit and RAS is cleared.	
		1	This bit is set when the RPTB instruction is executed to indicate that a RPTB is currently active.	
29-23	RSIZE		Repeat Block Size	
			This 7-bit value specifies the number of 16-bit words within the repeat block. This field is initialized when the RPTB instruction is executed. The value is calculated by the assembler and inserted into the RPTB instruction's RSIZE opcode field.	
		0-7	Illegal block size.	
		8/9-0x7F	A RPTB block that starts at an even address must include at least 9 16-bit words and a block that starts at an odd address must include at least 8 16-bit words. The maximum block size is 127 16-bit words. The codegen assembler will check for proper block size and alignment.	



www.ti.com **Pipeline**

Table 1-3. Repeat Block (RB) Register Field Descriptions (continued)

Bits	Field	Value	Description
22-16	RE		Repeat Block End Address
			This 7-bit value specifies the end address location of the repeat block. The RE value is calculated by hardware based on the RSIZE field and the PC value when the RPTB instruction is executed.
			RE = lower 7 bits of (PC + 1 + RSIZE)
15-0	RC		Repeat Count
		0	The block will not be repeated; it will be executed only once. In this case the repeat active, RA, bit will not be set.
		1- 0xFFFF	This 16-bit value determines how many times the block will repeat. The counter is initialized when the RPTB instruction is executed and is decremented when the PC reaches the end of the block. When the counter reaches zero, the repeat active bit is cleared and the block will be executed one more time. Therefore the total number of times the block is executed is RC+1.

1.4 **Pipeline**

The pipeline flow for C28x instructions is identical to that of the C28x CPU described in TMS320C28x DSP CPU and Instruction Set Reference Guide (SPRU430). Some floating-point instructions, however, use additional execution phases and thus require a delay to allow the operation to complete. This pipeline alignment is achieved by inserting NOPs or non-conflicting instructions when required. Software control of delay slots allows you to improve performance of an application by taking advantage of the delay slots and filling them with non-conflicting instructions. This section describes the key characteristics of the pipeline with regards to floating-point instructions. The rules for avoiding pipeline conflicts are small in number and simple to follow and the C28x+FPU assembler will help you by issuing errors for conflicts.

1.4.1 Pipeline Overview

The C28x FPU pipeline is identical to the C28x pipeline for all standard C28x instructions. In the decode2 stage (D2), it is determined if an instruction is a C28x instruction or a floating-point unit instruction. The pipeline flow is shown in Figure 1-5. Notice that stalls due to normal C28x pipeline stalls (D2) and memory waitstates (R2 and W) will also stall any C28x FPU instruction. Most C28x FPU instructions are single cycle and will complete in the FPU E1 or W stage which aligns to the C28x pipeline. Some instructions will take an additional execute cycle (E2). For these instructions you must wait a cycle for the result from the instruction to be available. The rest of this section will describe when delay cycles are required. Keep in mind that the assembly tools for the C28x+FPU will issue an error if a delay slot has not been handled correctly.

Fetch Decode Exe Write Read C28x pipeline F1 F2 D1 D2 R1 R2 Ε W F2 **FPU** instruction D R E1 Load Store CMP/MIN/MAX/NEG/ABS MPY/ADD/SUB/MACF32

Figure 1-5. FPU Pipeline



Pipeline www.ti.com

1.4.2 General Guidelines for Floating-Point Pipeline Alignment

While the C28x+FPU assembler will issue errors for pipeline conflicts, you may still find it useful to understand when software delays are required. This section describes three guidelines you can follow when writing C28x+FPU assembly code.

Floating-point instructions that require delay slots have a 'p' after their cycle count. For example '2p' stands for 2 pipelined cycles. This means that an instruction can be started every cycle, but the result of the instruction will only be valid one instruction later.

There are three general guidelines to determine if an instruction needs a delay slot:

- 1. Floating-point math operations (multiply, addition, subtraction, 1/x and MAC) require 1 delay slot.
- 2. Conversion instructions between integer and floating-point formats require 1 delay slot.
- 3. Everything else does not require a delay slot. This includes minimum, maximum, compare, load, store, negative and absolute value instructions.

There are two exceptions to these rules. First, moves between the CPU and FPU registers require special pipeline alignment that is described later in this section. These operations are typically infrequent. Second, the MACF32 R7H, R3H, mem32, *XAR7 instruction has special requirements that make it easier to use. Refer to the MACF32 instruction description for details.

An example of the 32-bit ADDF32 instruction is shown in Example 1-3. ADDF32 is a 2p instruction and therefore requires one delay slot. The destination register for the operation, R0H, will be updated one cycle after the instruction for a total of 2 cycles. Therefore, a NOP or instruction that does not use R0H must follow this instruction.

Any memory stall or pipeline stall will also stall the floating-point unit. This keeps the floating-point unit aligned with the C28x pipeline and there is no need to change the code based on the waitstates of a memory block.

Please note that on certain devices instructions make take additional cycles to complete under specific conditions. These exceptions will be documented in the device errata.

Example 1-3. 2p Instruction Pipeline Alignment

```
ADDF32 R0H, #1.5, R1H ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction
; <-- ADDF32 completes, R0H updated

NOP ; Any instruction
```

1.4.3 Moves from FPU Registers to C28x Registers

When transferring from the floating-point unit registers to the C28x CPU registers, additional pipeline alignment is required as shown in Example 1-4 and Example 1-5.

Example 1-4. Floating-Point to C28x Register Software Pipeline Alignment

```
; MINF32: 32-bit floating-point minimum: single-cycle operation
; An alignment cycle is required before copying R0H to ACC
MINF32 R0H, R1H ; Single-cycle instruction
; <-- R0H is valid
NOP ; Alignment cycle
MOV32 @ACC, R0H ; Copy R0H to ACC
```

For 1-cycle FPU instructions, one delay slot is required between a write to the floating-point register and the transfer instruction as shown in Example 1-4. For 2p FPU instructions, two delay slots are required between a write to the floating-point register and the transfer instruction as shown in Example 1-5.



www.ti.com Pipeline

Example 1-5. Floating-Point to C28x Register Software Pipeline Alignment

```
; ADDF32: 32-bit floating-point addition: 2p operation
; An alignment cycle is required before copying ROH to ACC
ADDF32 ROH, R1H, #2 ; ROH = R1H + 2, 2 pipeline cycle instruction
NOP ; 1 delay cycle or non-conflicting instruction
; <-- ROH is valid
NOP ; Alignment cycle
MOV32 @ACC, ROH ; Copy ROH to ACC
```

1.4.4 Moves from C28x Registers to FPU Registers

Transfers from the standard C28x CPU registers to the floating-point registers require four alignment cycles. For the 2833x, 2834x, 2806x, 28M35xx and 28M26xx, the four alignment cycles can be filled with NOPs or any non-conflicting instruction except for FRACF32, U116TOF32, I16TOF32, F32TOUI32, and F32TOI32. These instructions cannot replace any of the four alignment NOPs. On newer devices any non-conflicting instruction can go into the four alignment cycles. Please refer to the device errata for specific exceptions to these rules.

Example 1-6. C28x Register to Floating-Point Register Software Pipeline Alignment

```
; Four alignment cycles are required after copying a standard 28x CPU
; register to a floating-point register.
;
MOV32 R0H,@ACC ; Copy ACC to R0H
NOP
NOP
NOP
NOP
NOP
; Wait 4 cycles
ADDF32 R2H,R1H,R0H ; R0H is valid
```

1.4.5 Parallel Instructions

Parallel instructions are single opcodes that perform two operations in parallel. This can be a math operation in parallel with a move operation, or two math operations in parallel. Math operations with a parallel move are referred to as 2p/1 instructions. The math portion of the operation takes two pipelined cycles while the move portion of the operation is single cycle. This means that NOPs or other non conflicting instructions must be inserted to align the math portion of the operation. An example of an add with parallel move instruction is shown in Example 1-7.

Example 1-7. 2p/1 Parallel Instruction Software Pipeline Alignment

Parallel math instructions are referred to as 2p/2p instructions. Both math operations take 2 cycles to complete. This means that NOPs or other non conflicting instructions must be inserted to align the both math operations. An example of a multiply with parallel add instruction is shown in Example 1-8.



Pipeline www.ti.com

Example 1-8. 2p/2p Parallel Instruction Software Pipeline Alignment

1.4.6 Invalid Delay Instructions

Most instructions can be used in delay slots as long as source and destination register conflicts are avoided. The C28x+FPU assembler will issue an error anytime you use an conflicting instruction within a delay slot. The following guidelines can be used to avoid these conflicts.

NOTE: Destination register conflicts in delay slots:

Any operation used for pipeline alignment delay must not use the same destination register as the instruction requiring the delay. See Example 1-9.

In Example 1-9 the MPYF32 instruction uses R2H as its destination register. The next instruction should not use R2H as its destination. Since the MOV32 instruction uses the R2H register a pipeline conflict will be issued by the assembler. This conflict can be resolved by using a register other than R2H for the MOV32 instruction as shown in Example 1-10.



www.ti.com Pipeline

Example 1-9. Destination Register Conflict

```
; Invalid delay instruction. Both instructions use the same destination register
MPYF32 R2H, R1H, R0H ; 2p instruction
MOV32 R2H, mem32 ; Invalid delay instruction
```

Example 1-10. Destination Register Conflict Resolved

```
; Valid delay instruction

MPYF32 R2H, R1H, R0H ; 2p instruction MOV32 R1H, mem32

; Valid delay

; <-- MPYF32 completes, R2H valid
```

NOTE:

Instructions in delay slots cannot use the instruction's destination register as a source register.

Any operation used for pipeline alignment delay must not use the destination register of the instruction requiring the delay as a source register as shown in Example 1-11. For parallel instructions, the current value of a register can be used in the parallel operation before it is overwritten as shown in Example 1-13.

In Example 1-11 the MPYF32 instruction again uses R2H as its destination register. The next instruction should not use R2H as its source since the MPYF32 will take an additional cycle to complete. Since the ADDF32 instruction uses the R2H register a pipeline conflict will be issued by the assembler. This conflict can be resolved by using a register other than R2H or by inserting a non-conflicting instruction between the MPYF32 and ADDF32 instructions. Since the SUBF32 does not use R2H this instruction can be moved before the ADDF32 as shown in Example 1-12.

Example 1-11. Destination/Source Register Conflict

```
; Invalid delay instruction. ADDF32 should not use R2H as a source operand

MPYF32 R2H, R1H, R0H ; 2p instruction

ADDF32 R3H, R3H, R2H ; Invalid delay instruction

SUBF32 R4H, R1H, R0H
```

Example 1-12. Destination/Source Register Conflict Resolved

```
; Valid delay instruction.

MPYF32 R2H, R1H, R0H ; 2p instruction

SUBF32 R4H, R1H, R0H ; Valid delay for MPYF32

ADDF32 R3H, R3H, R2H ; <-- MPYF32 completes, R2H valid

NOP ; <-- SUBF32 completes, R4H valid
```

It should be noted that a source register for the 2nd operation within a parallel instruction can be the same as the destination register of the first operation. This is because the two operations are started at the same time. The 2nd operation is not in the delay slot of the first operation. Consider Example 1-13 where the MPYF32 uses R2H as its destination register. The MOV32 is the 2nd operation in the instruction and can freely use R2H as a source register. The contents of R2H before the multiply will be used by MOV32.



Pipeline www.ti.com

Example 1-13. Parallel Instruction Destination/Source Exception

```
; Valid parallel operation.

MPYF32 R2H, R1H, R0H ; 2p/1 instruction

|| MOV32 mem32, R2H ; <-- Uses R2H before the MPYF32

; <-- mem32 updated

NOP ; <-- Delay for MPYF32

; <-- R2H updated
```

Likewise, the source register for the 2nd operation within a parallel instruction can be the same as one of the source registers of the first operation. The MPYF32 operation in Example 1-14 uses the R1H register as one of its sources. This register is also updated by the MOV32 register. The multiplication operation will use the value in R1H before the MOV32 updates it.

Example 1-14. Parallel Instruction Destination/Source Exception

```
; Valid parallel instruction

MPYF32 R2H, R1H, R0H; 2p/l instruction

|| MOV32 R1H, mem32; Valid

NOP; <-- MOV32 completes, R1H valid

; <-- MPYF32, R2H valid
```

NOTE: Operations within parallel instructions cannot use the same destination register.

When two parallel operations have the same destination register, the result is invalid.

For example, see Example 1-15.

If both operations within a parallel instruction try to update the same destination register as shown in Example 1-15 the assembler will issue an error.

Example 1-15. Invalid Destination Within a Parallel Instruction

```
; Invalid parallel instruction. Both operations use the same destination register MPYF32 R2H, R1H, R0H; 2p/1 instruction || MOV32 R2H, mem32; Invalid
```

Some instructions access or modify the STF flags. Because the instruction requiring a delay slot will also be accessing the STF flags, these instructions should not be used in delay slots. These instructions are SAVE, SETFLG, RESTORE and MOVSTO.

NOTE: Do not use SAVE, SETFLG, RESTORE, or the MOVST0 instruction in a delay slot.



www.ti.com Pipeline

1.4.7 Optimizing the Pipeline

The following example shows how delay slots can be used to improve the performance of an algorithm. The example performs two Y = MX+B operations. In Example 1-16, no optimization has been done. The Y = MX+B calculations are sequential and each takes 7 cycles to complete. Notice there are NOPs in the delay slots that could be filled with non-conflicting instructions. The only requirement is these instructions must not cause a register conflict or access the STF register flags.

Example 1-16. Floating-Point Code Without Pipeline Optimization

```
; Using NOPs for alignment cycles, calculate the following:
; Y1 = M1*X1 + B1
; Y2 = M2*X2 + B2
; Calculate Y1
  MOV32 ROH,@M1 ; Load ROH with M1 - single cycle MOV32 R1H,@X1 ; Load R1H with X1 - single cycle
                           ; Load R1H with X1 - single cycle
  MPYF32 R1H,R1H,R0H
                           ; R1H = M1 * X1
                                            - 2p operation
|| MOV32 R0H,@B1
                           ; Load ROH with B1 - single cycle
                           ; Wait for MPYF32 to complete
  NOP
                           ; <-- MPYF32 completes, R1H is valid
  ADDF32 R1H,R1H,R0H
                          ; R1H = R1H + R0H - 2p operation
                           ; Wait for ADDF32 to complete
                           ; <-- ADDF32 completes, R1H is valid
                           ; Save R1H in Y1 - single cycle
  MOV32 @Y1,R1H
; Calculate Y2
  MOV32 ROH,@M2
                           ; Load ROH with M2 - single cycle
  MOV32 R1H,@X2
                          ; Load R1H with X2 - single cycle
  MPYF32 R1H,R1H,R0H
                           ; R1H = M2 * X2 - 2p operation
|| MOV32 R0H,@B2
                           ; Load ROH with B2 - single cycle
                           ; Wait for MPYF32 to complete
                           ; <-- MPYF32 completes, R1H is valid
  ADDF32 R1H,R1H,R0H
                           ; R1H = R1H + R0H
NOP
                            ; Wait for ADDF32 to complete
                            ; <-- ADDF32 completes, R1H is valid
  MOV32 @Y2,R1H
                            ; Save R1H in Y2
; 14 cycles
; 48 bytes
```

The code shown in Example 1-17 was generated by the C28x+FPU compiler with optimization enabled. Notice that the NOPs in the first example have now been filled with other instructions. The code for the two Y = MX+B calculations are now interleaved and both calculations complete in only nine cycles.



Example 1-17. Floating-Point Code With Pipeline Optimization

```
; Using non-conflicting instructions for alignment cycles,
; calculate the following:
; Y1 = M1*X1 + B1
; Y2 = M2*X2 + B2
            R2H,@X1 ; Load R2H with X1 - single cycle R1H,@M1 ; Load R1H with M1 - single cycle
   MOV32
   MOV32
MPYF32 R3H,R2H,R1H ; R3H = M1 * X1 - 2p operation | MOV32 R0H,@M2 ; Load R0H with M2 - single cycle
                              ; Load R1H with X2 - single cycle
   MOV32 R1H,@X2
                              ; <-- MPYF32 completes, R3H is valid
   MPYF32 R0H,R1H,R0H ; R0H = M2 * X2 - 2p operation
| \; | \; MOV32 R4H,@B1 \; ; Load R4H with B1 - single cycle
                              ; <-- MOV32 completes, R4H is valid
   ADDF32 R1H,R4H,R3H ; R1H = B1 + M1*X1 - 2p operation MOV32 R2H,@B2 ; Load R2H with B2 - single cycle ; <-- MPYF32 completes, R0H is valid
|| MOV32
   ADDF32 ROH,R2H,R0H ; ROH = B2 + M2*X2 - 2p operation
                              ; <-- ADDF32 completes, R1H is valid
   MOV32 @Y1,R1H
                              ; Store Y1
                              ; <-- ADDF32 completes, ROH is valid
   MOV32 @Y2,R0H
                              ; Store Y2
; 9 cycles
; 36 bytes
```

1.5 Floating Point Unit Instruction Set

This chapter describes the assembly language instructions of the TMS320C28x plus floating-point processor. Also described are parallel operations, conditional operations, resource constraints, and addressing modes. The instructions listed here are an extension to the standard C28x instruction set. For information on standard C28x instructions, see the *TMS320C28x DSP CPU and Instruction Set Reference Guide* (literature number SPRU430).

1.5.1 Instruction Descriptions

This section gives detailed information on the instruction set. Each instruction may present the following information:

- Operands
- Opcode
- Description
- Exceptions
- Pipeline
- Examples
- See also

The example INSTRUCTION is shown to familiarize you with the way each instruction is described. The example describes the kind of information you will find in each part of the individual instruction description and where to obtain more information. On the C28x+FPU instructions, follow the same format as the C28x. The source operand(s) are always on the right and the destination operand(s) are on the left.

The explanations for the syntax of the operands used in the instruction descriptions for the TMS320C28x plus floating-point processor are given in Table 1-4. For information on the operands of standard C28x instructions, see the TMS320C28x DSP CPU and Instruction Set Reference Guide (SPRU430).



Table 1-4. Operand Nomenclature

Symbol	Description					
#16FHi	16-bit immediate (hex or float) value that represents the upper 16-bits of an IEEE 32-bit floating-point value. Lower 16-bits of the mantissa are assumed to be zero.					
#16FHiHex	16-bit immediate hex value that represents the upper 16-bits of an IEEE 32-bit floating-point value. Lower 16-bits of the mantissa are assumed to be zero.					
#16FLoHex	A 16-bit immediate hex value that represents the lower 16-bits of an IEEE 32-bit floating-point value					
#32Fhex	32-bit immediate value that represents an IEEE 32-bit floating-point value					
#32F	Immediate float value represented in floating-point representation					
#0.0	Immediate zero					
#RC	16-bit immediate value for the repeat count					
*(0:16bitAddr)	16-bit immediate address, zero extended					
CNDF	Condition to test the flags in the STF register					
FLAG	Selected flags from STF register (OR) 11 bit mask indicating which floating-point status flags to change					
label	Label representing the end of the repeat block					
mem16	Pointer (using any of the direct or indirect addressing modes) to a 16-bit memory location					
mem32	Pointer (using any of the direct or indirect addressing modes) to a 32-bit memory location					
RaH	R0H to R7H registers					
RbH	R0H to R7H registers					
RcH	R0H to R7H registers					
RdH	R0H to R7H registers					
ReH	R0H to R7H registers					
RfH	R0H to R7H registers					
RB	Repeat Block Register					
STF	FPU Status Register					
VALUE	Flag value of 0 or 1 for selected flag (OR) 11 bit mask indicating the flag value; 0 or 1					



INSTRUCTION dest1, source1, source2 Short Description

Operands

dest1	description for the 1st operand for the instruction
source1	description for the 2nd operand for the instruction
source2	description for the 3rd operand for the instruction

Each instruction has a table that gives a list of the operands and a short description. Instructions always have their destination operand(s) first followed by the source operand(s).

Opcode This section shows the opcode for the instruction.

Description Detailed description of the instruction execution is described. Any constraints on the

operands imposed by the processor or the assembler are discussed.

Restrictions Any constraints on the operands or use of the instruction imposed by the processor are

discussed.

Pipeline This section describes the instruction in terms of pipeline cycles as described in

Section 1.4.

Example Examples of instruction execution. If applicable, register and memory values are given

before and after instruction execution. All examples assume the device is running with the OBJMODE set to 1. Normally the boot ROM or the c-code initialization will set this

bit.

See Also Lists related instructions.

29



1.5.2 Instructions

The instructions are listed alphabetically, preceded by a summary.

Table 1-5. Summary of Instructions

T	itle	Page
	ABSF32 RaH, RbH — 32-bit Floating-Point Absolute Value	31
	ADDF32 RaH, #16FHi, RbH —32-bit Floating-Point Addition	32
	ADDF32 RaH, RbH, #16FHi —32-bit Floating-Point Addition	
	ADDF32 RaH, RbH, RcH — 32-bit Floating-Point Addition	36
	ADDF32 RdH, ReH, RfH MOV32 mem32, RaH —32-bit Floating-Point Addition with Parallel Move	38
	ADDF32 RdH, ReH, RfH MOV32 RaH, mem32 — 32-bit Floating-Point Addition with Parallel Move	40
	CMPF32 RaH, RbH — 32-bit Floating-Point Compare for Equal, Less Than or Greater Than	42
	CMPF32 RaH, #16FHi — 32-bit Floating-Point Compare for Equal, Less Than or Greater Than	43
	CMPF32 RaH, #0.0 — 32-bit Floating-Point Compare for Equal, Less Than or Greater Than	45
	EINVF32 RaH, RbH —32-bit Floating-Point Reciprocal Approximation	46
	EISQRTF32 RaH, RbH — 32-bit Floating-Point Square-Root Reciprocal Approximation	48
	F32TOI16 RaH, RbH — Convert 32-bit Floating-Point Value to 16-bit Integer	5 0
	F32TOI16R RaH, RbH — Convert 32-bit Floating-Point Value to 16-bit Integer and Round	51
	F32TOI32 RaH, RbH — Convert 32-bit Floating-Point Value to 32-bit Integer	52
	F32TOUI16 RaH, RbH — Convert 32-bit Floating-Point Value to 16-bit Unsigned Integer	53
	F32TOUI16R RaH, RbH — Convert 32-bit Floating-Point Value to 16-bit Unsigned Integer and Round	54
	F32TOUI32 RaH, RbH — Convert 32-bit Floating-Point Value to 16-bit Unsigned Integer	
	FRACF32 RaH, RbH — Fractional Portion of a 32-bit Floating-Point Value	56
	I16TOF32 RaH, RbH — Convert 16-bit Integer to 32-bit Floating-Point Value	
	I16TOF32 RaH, mem16 — Convert 16-bit Integer to 32-bit Floating-Point Value	
	I32TOF32 RaH, mem32 — Convert 32-bit Integer to 32-bit Floating-Point Value	
	I32TOF32 RaH, RbH — Convert 32-bit Integer to 32-bit Floating-Point Value	
	MACF32 R3H, R2H, RdH, ReH, RfH —32-bit Floating-Point Multiply with Parallel Add	61
	MACF32 R3H, R2H, RdH, ReH, RfH MOV32 RaH, mem32 —32-bit Floating-Point Multiply and Accumulate with Parallel Move	63
	MACF32 R7H, R3H, mem32, *XAR7++ —32-bit Floating-Point Multiply and Accumulate	65
	MACF32 R7H, R6H, RdH, ReH, RfH —32-bit Floating-Point Multiply with Parallel Add	67
	MACF32 R7H, R6H, R6H, R6H, RfH MOV32 RaH, mem32 —32-bit Floating-Point Multiply and Accumulate with Parallel Move	69
	MAXF32 RaH, RbH —32-bit Floating-Point Maximum	
	MAXF32 RaH, #16FHi — 32-bit Floating-Point Maximum	
	MAXF32 RaH, RbH MOV32 RcH, RdH —32-bit Floating-Point Maximum with Parallel Move	
	MINF32 RaH, RbH — 32-bit Floating-Point Minimum.	74
	MINF32 RaH, #16FHi — 32-bit Floating-Point Minimum	75
	MINF32 RaH, RbH MOV32 RcH, RdH —32-bit Floating-Point Minimum with Parallel Move	76
	MOV16 mem16, RaH — Move 16-bit Floating-Point Register Contents to Memory	77
	MOV32 *(0:16bitAddr), loc32 — Move the Contents of loc32 to Memory	78
	MOV32 ACC, RaH — Move 32-bit Floating-Point Register Contents to ACC	7 9
	MOV32 loc32, *(0:16bitAddr) — Move 32-bit Value from Memory to loc32	80
	MOV32 mem32, RaH — Move 32-bit Floating-Point Register Contents to Memory	81
	MOV32 mem32, STF — Move 32-bit STF Register to Memory	
	MOV32 P, RaH — Move 32-bit Floating-Point Register Contents to P	
	MOV32 RaH, ACC — Move the Contents of ACC to a 32-bit Floating-Point Register	
	MOV32 RaH, mem32 {, CNDF} — Conditional 32-bit Move	
	MOV32 RaH, P — Move the Contents of P to a 32-bit Floating-Point Register	88



Table 1-5. Summary of Instructions (continued)

MOV32 RaH, RbH {, CNDF} — Conditional 32-bit Move	89
MOV32 RaH, XARn — Move the Contents of XARn to a 32-bit Floating-Point Register	90
MOV32 RaH, XT — Move the Contents of XT to a 32-bit Floating-Point Register	91
MOV32 STF, mem32 — Move 32-bit Value from Memory to the STF Register	92
MOV32 XARn, RaH — Move 32-bit Floating-Point Register Contents to XARn	93
MOV32 XT, RaH — Move 32-bit Floating-Point Register Contents to XT	94
MOVD32 RaH, mem32 — Move 32-bit Value from Memory with Data Copy	95
MOVF32 RaH, #32F — Load the 32-bits of a 32-bit Floating-Point Register	96
MOVI32 RaH, #32FHex — Load the 32-bits of a 32-bit Floating-Point Register with the immediate	. 97
MOVIZ RaH, #16FHiHex — Load the Upper 16-bits of a 32-bit Floating-Point Register	98
MOVIZF32 RaH, #16FHi — Load the Upper 16-bits of a 32-bit Floating-Point Register	. 99
MOVST0 FLAG —Load Selected STF Flags into ST0	100
MOVXI RaH, #16FLoHex — Move Immediate to the Low 16-bits of a Floating-Point Register	101
MPYF32 RaH, RbH, RcH —32-bit Floating-Point Multiply	102
MPYF32 RaH, #16FHi, RbH —32-bit Floating-Point Multiply	103
MPYF32 RaH, RbH, #16FHi — 32-bit Floating-Point Multiply	105
MPYF32 RaH, RbH, RcH ADDF32 RdH, ReH, RfH —32-bit Floating-Point Multiply with Parallel Add	107
MPYF32 RdH, ReH, RfH MOV32 RaH, mem32 — 32-bit Floating-Point Multiply with Parallel Move	109
MPYF32 RdH, ReH, RfH ∥MOV32 mem32, RaH —32-bit Floating-Point Multiply with Parallel Move	111
MPYF32 RaH, RbH, RcH SUBF32 RdH, ReH, RfH — 32-bit Floating-Point Multiply with Parallel Subtract	
NEGF32 RaH, RbH{, CNDF} — Conditional Negation	113
POP RB — Pop the RB Register from the Stack	114
PUSH RB — Push the RB Register onto the Stack	116
RESTORE —Restore the Floating-Point Registers	117
RPTB label, loc16 — Repeat A Block of Code	
RPTB label, #RC — Repeat a Block of Code	
SAVE FLAG, VALUE —Save Register Set to Shadow Registers and Execute SETFLG	123
SETFLG FLAG, VALUE —Set or clear selected floating-point status flags	125
SUBF32 RaH, RbH, RcH —32-bit Floating-Point Subtraction	126
SUBF32 RaH, #16FHi, RbH —32-bit Floating Point Subtraction	
SUBF32 RdH, ReH, RfH ∥MOV32 RaH, mem32 —32-bit Floating-Point Subtraction with Parallel Move	
SUBF32 RdH, ReH, RfH ∥MOV32 mem32, RaH —32-bit Floating-Point Subtraction with Parallel Move	130
SWAPF RaH, RbH{, CNDF} —Conditional Swap	
TESTTF CNDF — Test STF Register Flag Condition	133
UI16TOF32 RaH, mem16 — Convert unsigned 16-bit integer to 32-bit floating-point value	134
UI16TOF32 RaH, RbH — Convert unsigned 16-bit integer to 32-bit floating-point value	
UI32TOF32 RaH, mem32 — Convert Unsigned 32-bit Integer to 32-bit Floating-Point Value	
UI32TOF32 RaH, RbH — Convert Unsigned 32-bit Integer to 32-bit Floating-Point Value	
ZERO RaH —Zero the Floating-Point Register RaH	
ZEROA —Zero All Floating-Point Registers	139



ABSF32 RaH, RbH 32-bit Floating-Point Absolute Value

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)

Opcode

LSW: 1110 0110 1001 0101 MSW: 0000 0000 00bb baaa

Description

The absolute value of RbH is loaded into RaH. Only the sign bit of the operand is modified by the ABSF32 instruction.

```
if (RbH < 0) {RaH = -RbH}
else {RaH = RbH}</pre>
```

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	Yes	Yes	No	No	

The STF register flags are modified as follows:

```
NF = 0;
ZF = 0;
if ( RaH[30:23] == 0) ZF = 1;
```

Pipeline

This is a single-cycle instruction.

Example

```
MOVIZF32 R1H, #-2.0 ; R1H = -2.0 (0xC0000000)
ABSF32 R1H, R1H ; R1H = 2.0 (0x40000000), ZF = NF = 0

MOVIZF32 R0H, #5.0 ; R0H = 5.0 (0x40A00000)
ABSF32 R0H, R0H ; R0H = 5.0 (0x40A00000), ZF = NF = 0

MOVIZF32 R0H, #0.0 ; R0H = 0.0
ABSF32 R1H, R0H ; R1H = 0.0 ZF = 1, NF = 0
```

See also

NEGF32 RaH, RbH{, CNDF}



ADDF32 RaH, #16FHi, RbH 32-bit Floating-Point Addition

Operands

RaH	floating-point destination register (R0H to R7H)
#16FHi	A 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0.
RbH	floating-point source register (R0H to R7H)

Opcode

LSW: 1110 1000 10II IIII MSW: IIII IIII IIbb baaa

Description

Add RbH to the floating-point value represented by the immediate operand. Store the result of the addition in RaH.

#16FHi is a 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0. #16FHi is most useful for representing constants where the lowest 16-bits of the mantissa are 0. Some examples are 2.0 (0x40000000), 4.0 (0x40800000), 0.5 (0x3F000000), and -1.5 (0xBFC00000). The assembler will accept either a hex or float as the immediate value. That is, the value -1.5 can be represented as #-1.5 or #0xBFC0.

RaH = RbH + #16FHi:0

This instruction can also be written as ADDF32 RaH, RbH, #16FHi.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if ADDF32 generates an underflow condition.
- LVF = 1 if ADDF32 generates an overflow condition.

Pipeline

This is a 2 pipeline-cycle instruction (2p). That is:

```
ADDF32 RaH, #16FHi, RbH ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction
; <-- ADDF32 completes, RaH updated

NOP
```

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example

```
; Add to R1H the value 2.0 in 32-bit floating-point format
 ADDF32 R0H, \#2.0, R1H ; R0H = 2.0 + R1H
 NOP
                          ; Delay for ADDF32 to complete
                           ; <-- ADDF32 completes, ROH updated
 NOP
; Add to R3H the value -2.5 in 32-bit floating-point format
 ADDF32 R2H, \#-2.5, R3H ; R2H = -2.5 + R3H
 NOP
                          ; Delay for ADDF32 to complete
                           ; <-- ADDF32 completes, R2H updated
 NOP
; Add to R5H the value 0x3FC00000 (1.5)
 ADDF32 R5H, \#0x3FC0, R5H; R5H = 1.5 + R5H
                           ; Delay for ADDF32 to complete
                           ; <-- ADDF32 completes, R5H updated
```



NOP

See also ADDF32 RaH, RbH, #16FHi ADDF32 RaH, RbH, RcH

ADDF32 RdH, ReH, RfH || MOV32 RaH, mem32 ADDF32 RdH, ReH, RfH || MOV32 mem32, RaH

MACF32 R3H, R2H, RdH, ReH, RfH

MPYF32 RaH, RbH, RcH | ADDF32 RdH, ReH, RfH

;



ADDF32 RaH, RbH, #16FHi 32-bit Floating-Point Addition

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)
#16FHi	A 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0.

Opcode

LSW: 1110 1000 10II IIII MSW: IIII IIII IIbb baaa

Description

Add RbH to the floating-point value represented by the immediate operand. Store the result of the addition in RaH.

#16FHi is a 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0. #16FHi is most useful for representing constants where the lowest 16-bits of the mantissa are 0. Some examples are 2.0 (0x40000000), 4.0 (0x40800000), 0.5 (0x3F000000), and -1.5 (0xBFC00000). The assembler will accept either a hex or float as the immediate value. That is, the value -1.5 can be represented as #-1.5 or #0xBFC0.

RaH = RbH + #16FHi:0

This instruction can also be written as ADDF32 RaH, #16FHi, RbH.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if ADDF32 generates an underflow condition.
- LVF = 1 if ADDF32 generates an overflow condition.

Pipeline

This is a 2 pipeline-cycle instruction (2p). That is:

```
ADDF32 RaH, #16FHi, RbH ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction
; <-- ADDF32 completes, RaH updated

NOP
```

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example

```
; Add to R1H the value 2.0 in 32-bit floating-point format
 ADDF32 R0H, R1H, \#2.0; R0H = R1H + 2.0
                           ; Delay for ADDF32 to complete
 NOP
                           ; <-- ADDF32 completes, ROH updated
 NOP
; Add to R3H the value -2.5 in 32-bit floating-point format
 ADDF32 R2H, R3H, \#-2.5 ; R2H = R3H + (-2.5)
 NOP
                           ; Delay for ADDF32 to complete
                           ; <-- ADDF32 completes, R2H updated
 NOP
                           ; Add to R5H the value 0x3FC00000 (1.5)
 ADDF32 R5H, R5H, \#0x3FC0 ; R5H = R5H + 1.5
                           ; Delay for ADDF32 to complete
                           ; <-- ADDF32 completes, R5H updated
```



NOP ;

See also ADDF32 RaH, RbH, #16FHi ADDF32 RaH, RbH, RcH

ADDF32 RdH, ReH, RfH || MOV32 RaH, mem32 ADDF32 RdH, ReH, RfH || MOV32 mem32, RaH

MACF32 R3H, R2H, RdH, ReH, RfH

MPYF32 RaH, RbH, RcH | ADDF32 RdH, ReH, RfH



ADDF32 RaH, RbH, RcH 32-bit Floating-Point Addition

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)
RcH	floating-point source register (R0H to R7H)

Opcode

LSW: 1110 0111 0001 0000 MSW: 0000 000c ccbb baaa

Description

Add the contents of RcH to the contents of RbH and load the result into RaH.

RaH = RbH + RcH

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if ADDF32 generates an underflow condition.
- LVF = 1 if ADDF32 generates an overflow condition.

Pipeline

This is a 2 pipeline-cycle instruction (2p). That is:

```
ADDF32 RaH, RbH, RcH ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction

; <-- ADDF32 completes, RaH updated

NOP
```

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example

Calculate Y = M1*X1 + B1. This example assumes that M1, X1, B1 and Y are all on the same data page.

```
MOVW DP, #M1 ; Load the data page MOV32 R0H,@M1 ; Load R0H with M1 MOV32 R1H,@X1 ; Load R1H with X1 MPYF32 R1H,R1H,R0H ; Multiply M1*X1
```

|| MOV32 ROH,@B1 ; and in parallel load ROH with B1

NOP ; <-- MOV32 complete ; <-- MPYF32 complete

ADDF32 R1H,R1H,R0H ; Add M*X1 to B1 and store in R1H

NOP

; <-- ADDF32 complete
; Store the result</pre>

Calculate Y = A + B

MOV32 @Y1,R1H

MOVL XAR4, #A

MOV32 ROH, *XAR4 ; Load ROH with A

MOVL XAR4, #B

MOV32 R1H, *XAR4 ; Load R1H with B ADDF32 R0H,R1H,R0H ; Add A + B R0H=R0H+R1H

MOVL XAR4, #Y

MOV32 *XAR4,R0H

; < -- ADDF32 complete
; Store the result</pre>

See also

ADDF32 RaH, RbH, #16FHi ADDF32 RaH, #16F, RbH

ADDF32 RdH, ReH, RfH || MOV32 RaH, mem32



ADDF32 RdH, ReH, RfH || MOV32 mem32, RaH MACF32 R3H, R2H, RdH, ReH, RfH MPYF32 RaH, RbH, RcH || ADDF32 RdH, ReH, RfH



ADDF32 RdH, ReH, RfH || MOV32 mem32, RaH 32-bit Floating-Point Addition with Parallel Move

Operands

RdH	floating-point destination register for the ADDF32 (R0H to R7H)
ReH	floating-point source register for the ADDF32 (R0H to R7H)
RfH	floating-point source register for the ADDF32 (R0H to R7H)
mem32	pointer to a 32-bit memory location. This will be the destination of the MOV32.
RaH	floating-point source register for the MOV32 (R0H to R7H)

Opcode

LSW: 1110 0000 0001 fffe MSW: eedd daaa mem32

Description

Perform an ADDF32 and a MOV32 in parallel. Add RfH to the contents of ReH and store the result in RdH. In parallel move the contents of RaH to the 32-bit location pointed to by mem32. mem32 addresses memory using any of the direct or indirect addressing modes supported by the C28x CPU.

RdH = ReH + RfH, [mem32] = RaH

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if ADDF32 generates an underflow condition.
- LVF = 1 if ADDF32 generates an overflow condition.

Pipeline

ADDF32 is a 2 pipeline-cycle instruction (2p) and MOV32 takes a single cycle. That is:

```
ADDF32 RdH, ReH, RfH ; 2 pipeline cycles (2p)

|| MOV32 mem32, RaH ; 1 cycle
; <-- MOV32 completes, mem32 updated
NOP ; 1 cycle delay or non-conflicting instruction
; <-- ADDF32 completes, RdH updated
NOP
```

Any instruction in the delay slot must not use RdH as a destination register or use RdH as a source operand.

Example

```
ADDF32 R3H, R6H, R4H
                         ; (A) R3H = R6H + R4H and R7H = I3
 | MOV32 R7H, *-SP[2]
                         ; <-- R7H vali
   SUBF32 R6H, R6H, R4H ; (B) R6H = R6H - R4H
                         ; <-- ADDF32 (A) completes, R3H valid
   SUBF32 R3H, R1H, R7H ; (C) R3H = R1H - R7H and store R3H (A)
 || MOV32 *+XAR5[2], R3H ;
                         ; <-- SUBF32 (B) completes, R6H valid
                          ; <-- MOV32 completes, (A) stored
   ADDF32 R4H, R7H, R1H ; R4H = D = R7H + R1H and store R6H (B)
 || MOV32 *+XAR5[6], R6H ;
                         ; <-- SUBF32 (C) completes, R3H valid
                         ; <-- MOV32 completes, (B) stored
   MOV32 *+XAR5[0], R3H ; store R3H (C)
                         ; <-- MOV32 completes, (C) stored
                         ; <-- ADDF32 (D) completes, R4H valid
   MOV32 *+XAR5[4], R4H ; store R4H (D) ;
```



; <-- MOV32 completes, (D) stored

See also ADDF32 RaH, #16FHi, RbH

ADDF32 Rah, #16Fhi, Rbh, #16Fhi ADDF32 Rah, Rbh, Rch

MACF32 R3H, R2H, RdH, ReH, RfH

MPYF32 RaH, RbH, RcH || ADDF32 RdH, ReH, RfH ADDF32 RdH, ReH, RfH || MOV32 RaH, mem32



ADDF32 RdH, ReH, RfH || MOV32 RaH, mem32 32-bit Floating-Point Addition with Parallel Move

Operands

RdH	floating-point destination register for the ADDF32 (R0H to R7H). RdH cannot be the same register as RaH.
ReH	floating-point source register for the ADDF32 (R0H to R7H)
RfH	floating-point source register for the ADDF32 (R0H to R7H)
RaH	floating-point destination register for the MOV32 (R0H to R7H). RaH cannot be the same register as RdH.
mem32	pointer to a 32-bit memory location. This is the source for the MOV32.

Opcode

```
LSW: 1110 0011 0001 fffe MSW: eedd daaa mem32
```

Description

Perform an ADDF32 and a MOV32 operation in parallel. Add RfH to the contents of ReH and store the result in RdH. In parallel move the contents of the 32-bit location pointed to by mem32 to RaH. mem32 addresses memory using any of the direct or indirect addressing modes supported by the C28x CPU.

```
RdH = ReH + RfH,
RaH = [mem32]
```

Restrictions

The destination register for the ADDF32 and the MOV32 must be unique. That is, RaH and RdH cannot be the same register.

Any instruction in the delay slot must not use RdH as a destination register or use RdH as a source operand.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	Yes	Yes	Yes	Yes	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if ADDF32 generates an underflow condition.
- LVF = 1 if ADDF32 generates an overflow condition.

The MOV32 Instruction will set the NF, ZF, NI and ZI flags as follows:

```
NF = RaH(31);
ZF = 0;
if(RaH(30:23) == 0) { ZF = 1; NF = 0; }
NI = RaH(31);
ZI = 0;
if(RaH(31:0) == 0) ZI = 1;
```

Pipeline

The ADDF32 takes 2 pipeline cycles (2p) and the MOV32 takes a single cycle. That is:

```
ADDF32 RdH, ReH, RfH ; 2 pipeline cycles (2p)

|| MOV32 RaH, mem32 ; 1 cycle
; <-- MOV32 completes, RaH updated NOP
; 1 cycle delay or non-conflicting instruction
; <-- ADDF32 completes, RdH updated
NOP
```

www.ti.com

ADDF32 RdH, ReH, RfH ||MOV32 RaH, mem32 — 32-bit Floating-Point Addition with Parallel Move

Calculate Y = A + B - C: Example

```
MOVL XAR4, #A
  MOV32 ROH, *XAR4 ; Load ROH with A
  MOVL XAR4, #B
  MOV32 R1H, *XAR4 ; Load R1H with B
  MOVL XAR4, #C
  ADDF32 ROH,R1H,R0H ; Add A + B and in parallel
|| MOV32 R2H, *XAR4 ; Load R2H with C
                     ; <-- MOV32 complete
  MOVL XAR4, #Y
                      ; ADDF32 complete
  SUBF32 ROH,ROH,R2H ; Subtract C from (A + B)
  NOP ;
                      <-- SUBF32 completes
                    ; Store the result
  MOV32 *XAR4,R0H
```

See also

ADDF32 RaH, #16FHi, RbH ADDF32 RaH, RbH, #16FHi ADDF32 RaH, RbH, RcH

ADDF32 RdH, ReH, RfH | MOV32 mem32, RaH

MACF32 R3H, R2H, RdH, ReH, RfH

MPYF32 RaH, RbH, RcH | ADDF32 RdH, ReH, RfH

41



CMPF32 RaH, RbH 32-bit Floating-Point Compare for Equal, Less Than or Greater Than

Operands

RaH	floating-point source register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)

Opcode

LSW: 1110 0110 1001 0100 MSW: 0000 0000 00bb baaa

Description

Set ZF and NF flags on the result of RaH - RbH. The CMPF32 instruction is performed as a logical compare operation. This is possible because of the IEEE format offsetting the exponent. Basically the bigger the binary number, the bigger the floating-point value.

Special cases for inputs:

- Negative zero will be treated as positive zero.
- A denormalized value will be treated as positive zero.
- Not-a-Number (NaN) will be treated as infinity.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	Yes	Yes	No	No	

The STF register flags are modified as follows:

```
If(RaH == RbH) {ZF=1, NF=0}
If(RaH > RbH) {ZF=0, NF=0}
If(RaH < RbH) {ZF=0, NF=1}</pre>
```

Pipeline

This is a single-cycle instruction.

Example

```
; Behavior of {\ensuremath{\mathsf{ZF}}} and {\ensuremath{\mathsf{NF}}} flags for different comparisons
```

```
MOVIZF32 R0H, #5.0 ; R0H = 5.0 (0x40A00000)

CMPF32 R1H, R0H ; ZF = 0, NF = 1

CMPF32 R0H, R1H ; ZF = 0, NF = 0

CMPF32 R0H, R0H ; ZF = 1, NF = 0
```

; Using the result of a compare for loop control

```
Loop:
MOV32 R0H,*XAR4++ ; Load R0H
MOV32 R1H,*XAR3++ ; Load R1H
CMPF32 R1H, R0H ; Set/clear ZF and NF
```

MOVSTO ZF, NF ; Copy ZF and NF to STO Z and N bits

BF Loop, GT ; Loop if R1H > R0H

See also

CMPF32 RaH, #16FHi CMPF32 RaH, #0.0 MAXF32 RaH, #16FHi MAXF32 RaH, RbH MINF32 RaH, #16FHi MINF32 RaH, RbH



CMPF32 RaH, #16FHi 32-bit Floating-Point Compare for Equal, Less Than or Greater Than

Operands

RaH	floating-point source register (R0H to R7H)
#16FHi	A 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0.

Opcode

```
LSW: 1110 1000 0001 0III MSW: IIII IIII IIII Iaaa
```

Description

Compare the value in RaH with the floating-point value represented by the immediate operand. Set the ZF and NF flags on (RaH - #16FHi:0).

#16FHi is a 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0. This addressing mode is most useful for constants where the lowest 16-bits of the mantissa are 0. Some examples are 2.0 (0x40000000), 4.0 (0x40800000), 0.5 (0x3F000000), and -1.5 (0xBFC00000). The assembler will accept either a hex or float as the immediate value. That is, -1.5 can be represented as #-1.5 or #0xBFC0.

The CMPF32 instruction is performed as a logical compare operation. This is possible because of the IEEE floating-point format offsets the exponent. Basically the bigger the binary number, the bigger the floating-point value.

Special cases for inputs:

- Negative zero will be treated as positive zero.
- Denormalized value will be treated as positive zero.
- Not-a-Number (NaN) will be treated as infinity.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	Yes	Yes	No	No	

The STF register flags are modified as follows:

```
If(RaH == #16FHi:0) {ZF=1, NF=0}
If(RaH > #16FHi:0) {ZF=0, NF=0}
If(RaH < #16FHi:0) {ZF=0, NF=1}</pre>
```

Pipeline

This is a single-cycle instruction

Example

```
; Behavior of ZF and NF flags for different comparisons
    MOVIZF32 R1H, #-2.0 ; R1H = -2.0 (0xC0000000)
    MOVIZF32 R0H, #5.0 ; R0H = 5.0 (0x40A00000)
    CMPF32 R1H, #-2.2 ; ZF = 0, NF = 0
    CMPF32 R0H, #6.5 ; ZF = 0, NF = 1
    CMPF32 R0H, #5.0 ; ZF = 1, NF = 0

; Using the result of a compare for loop control

Loop:
    MOV32 R1H,*XAR3++ ; Load R1H
    CMPF32 R1H, #2.0 ; Set/clear ZF and NF
    MOVSTO ZF, NF ; Copy ZF and NF to STO Z and N bits
    BF Loop, GT ; Loop if R1H > #2.0
```

See also

CMPF32 RaH, #0.0 CMPF32 RaH, RbH MAXF32 RaH, #16FHi



MAXF32 RaH, RbH MINF32 RaH, #16FHi MINF32 RaH, RbH



CMPF32 RaH, #0.0 32-bit Floating-Point Compare for Equal, Less Than or Greater Than

Operands

RaH	floating-point source register (R0H to R7H)
#0.0	zero

Opcode

LSW: 1110 0101 1010 0aaa

Description

Set the ZF and NF flags on (RaH - #0.0). The CMPF32 instruction is performed as a logical compare operation. This is possible because of the IEEE floating-point format offsets the exponent. Basically the bigger the binary number, the bigger the floating-point value.

Special cases for inputs:

- Negative zero will be treated as positive zero.
- Denormalized value will be treated as positive zero.
- Not-a-Number (NaN) will be treated as infinity.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	Yes	Yes	No	No

The STF register flags are modified as follows:

```
If(RaH == #0.0) {ZF=1, NF=0}
If(RaH > #0.0) {ZF=0, NF=0}
If(RaH < #0.0) {ZF=0, NF=1}
```

Pipeline

This is a single-cycle instruction.

Example

```
; Behavior of ZF and NF flags for different comparisons
 MOVIZF32 ROH, \#5.0; ROH = 5.0 (0x40A00000)
 MOVIZF32 R1H, \#-2.0; R1H = -2.0 (0xC0000000)
 MOVIZF32 R2H, \#0.0; R2H = 0.0 (0x00000000)
 CMPF32 R0H, #0.0
                     ; ZF = 0, NF = 0
                   ; ZF = 0, NF = 1
 CMPF32 R1H, #0.0
  CMPF32 R2H, #0.0
                    ; ZF = 1, NF = 0
; Using the result of a compare for loop control
:gool
 MOV32 R1H, *XAR3++ ; Load R1H
```

```
CMPF32 R1H, #0.0 ; Set/clear ZF and NF
MOVSTO ZF, NF
                 ; Copy ZF and NF to STO Z and N bits
BF Loop, GT
                  ; Loop if R1H > #0.0
```

See also

CMPF32 RaH, #0.0 CMPF32 RaH, #16FHi MAXF32 RaH, #16FHi MAXF32 RaH, RbH MINF32 RaH, #16FHi MINF32 RaH, RbH



EINVF32 RaH, RbH 32-bit Floating-Point Reciprocal Approximation

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)

Opcode

```
LSW: 1110 0110 1001 0011 MSW: 0000 0000 00bb baaa
```

Description

This operation generates an estimate of 1/X in 32-bit floating-point format accurate to approximately 8 bits. This value can be used in a Newton-Raphson algorithm to get a more accurate answer. That is:

```
Ye = Estimate(1/X);
Ye = Ye*(2.0 - Ye*X)
Ye = Ye*(2.0 - Ye*X)
```

After two iterations of the Newton-Raphson algorithm, you will get an exact answer accurate to the 32-bit floating-point format. On each iteration the mantissa bit accuracy approximately doubles. The EINVF32 operation will not generate a negative zero, DeNorm or NaN value.

RaH = Estimate of 1/RbH

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	Yes	Yes

The STF register flags are modified as follows:

- LUF = 1 if EINVF32 generates an underflow condition.
- LVF = 1 if EINVF32 generates an overflow condition.

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

```
EINVF32 RaH, RbH ; 2p

NOP ; 1 cycle delay or non-conflicting instruction
; <-- EINVF32 completes, RaH updated

NOP
```

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.



Example

Calculate Y = A/B. A fast division routine similar to that shown below can be found in the C28x FPU Fast RTS Library (SPRC664).

```
MOVL XAR4, #A
MOV32 ROH, *XAR4
                              ; Load ROH with A
MOVL XAR4, #B
MOV32 R1H, *XAR4
                              ; Load R1H with B
LCR DIV
                              ; Calculate ROH = ROH / R1H
MOV32 *XAR4, R0H
. . . .
DIV:
EINVF32
          R2H, R1H
                              ; R2H = Ye = Estimate(1/B)
CMPF32
          ROH, #0.0
                              ; Check if A == 0
          R3H, R2H, R1H
                              ; R3H = Ye*B
MPYF32
NOP
SUBF32
          R3H, #2.0, R3H
                              ; R3H = 2.0 - Ye*B
NOP
                              ; R2H = Ye = Ye*(2.0 - Ye*B)
MPYF32
          R2H, R2H, R3H
NOP
MPYF32
          R3H, R2H, R1H
                              ; R3H = Ye*B
CMPF32
          R1H, #0.0
                              ; Check if B == 0.0
SUBF32
          R3H, #2.0, R3H
                              ; R3H = 2.0 - Ye*B
          ROH, ROH, EQ
NEGF32
                              ; Fixes sign for A/0.0
          R2H, R2H, R3H
                              ; R2H = Ye = Ye*(2.0 - Ye*B)
MPYF32
NOP
MPYF32
          ROH, ROH, R2H
                              ; ROH = Y = A*Ye = A/B
LRETR
```

See also

EISQRTF32 RaH, RbH



EISQRTF32 RaH, RbH 32-bit Floating-Point Square-Root Reciprocal Approximation

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)

Opcode

```
LSW: 1110 0110 1001 0010 MSW: 0000 0000 00bb baaa
```

Description

This operation generates an estimate of 1/sqrt(X) in 32-bit floating-point format accurate to approximately 8 bits. This value can be used in a Newton-Raphson algorithm to get a more accurate answer. That is:

```
Ye = Estimate(1/sqrt(X));
Ye = Ye*(1.5 - Ye*Ye*X/2.0)
Ye = Ye*(1.5 - Ye*Ye*X/2.0)
```

After 2 iterations of the Newton-Raphson algorithm, you will get an exact answer accurate to the 32-bit floating-point format. On each iteration the mantissa bit accuracy approximately doubles. The EISQRTF32 operation will not generate a negative zero, DeNorm or NaN value.

RaH = Estimate of 1/sqrt (RbH)

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	Yes	Yes

The STF register flags are modified as follows:

- LUF = 1 if EISQRTF32 generates an underflow condition.
- LVF = 1 if EISQRTF32 generates an overflow condition.

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

```
EINVF32 RaH, RbH ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction
; <-- EISQRTF32 completes, RaH updated

NOP
```

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.



Example

Calculate the square root of X. A square-root routine similar to that shown below can be found in the *C28x FPU Fast RTS Library* (SPRC664).

```
; Y = sqrt(X)
; Ye = Estimate(1/sqrt(X));
; Ye = Ye*(1.5 - Ye*Ye*X*0.5)
; Ye = Ye*(1.5 - Ye*Ye*X*0.5)
; Y = X*Ye
_sqrt:
                           ; ROH = X on entry
EISQRTF32 R1H, R0H
                           ; R1H = Ye = Estimate(1/sqrt(X))
                          ; R2H = X*0.5
MPYF32
         R2H, R0H, #0.5
MPYF32
          R3H, R1H, R1H
                           ; R3H = Ye*Ye
NOP
MPYF32
          R3H, R3H, R2H
                           ; R3H = Ye*Ye*X*0.5
NOP
SUBF32
          R3H, #1.5, R3H
                          ; R3H = 1.5 - Ye*Ye*X*0.5
NOP
MPYF32
          R1H, R1H, R3H
                            ; R2H = Ye = Ye*(1.5 - Ye*Ye*X*0.5)
NOP
                            ; R3H = Ye*X*0.5
MPYF32
          R3H, R1H, R2H
NOP
MPYF32
          R3H, R1H, R3H
                            ; R3H = Ye*Ye*X*0.5
NOP
          R3H, #1.5, R3H
                          ; R3H = 1.5 - Ye*Ye*X*0.5
SUBF32
          ROH, #0.0
                           ; Check if X == 0
CMPF32
          R1H, R1H, R3H
                           ; R2H = Ye = Ye*(1.5 - Ye*Ye*X*0.5)
MPYF32
NOP
MOV32
          R1H, R0H, EQ
                          ; If X is zero, change the Ye estimate to 0
          ROH, ROH, R1H
MPYF32
                          ; ROH = Y = X*Ye = sqrt(X)
LRETR
```

See also

EINVF32 RaH, RbH



F32TOI16 RaH, RbH Convert 32-bit Floating-Point Value to 16-bit Integer

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)

Opcode LSW: 1110 0110 1000 1100

MSW: 0000 0000 00bb baaa

Description Convert a 32-bit floating point value in RbH to a 16-bit integer and truncate. The result

will be stored in RaH.

RaH(15:0) = F32TOI16(RbH)

RaH(31:16) = sign extension of RaH(15)

Flags

This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

```
F32TOI16 RaH, RbH; 2 pipeline cycles (2p)
```

NOP ; 1 cycle delay or non-conflicting instruction

; <-- F32TOI16 completes, RaH updated

NOP

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example

```
MOVIZF32 R0H, #5.0 ; R0H = 5.0 (0x40A00000)

F32TOI16 R1H, R0H ; R1H(15:0) = F32TOI16(R0H)
; R1H(31:16) = Sign extension of R1H(15)

MOVIZF32 R2H, #-5.0 ; R2H = -5.0 (0xC0A00000)
; <-- F32TOI16 complete, R1H(15:0) = 5 (0x0005)
; R1H(31:16) = 0 (0x0000)

F32TOI16 R3H, R2H ; R3H(15:0) = F32TOI16(R2H)
; R3H(31:16) = Sign extension of R3H(15)

NOP ; 1 Cycle delay for F32TOI16 to complete
; <-- F32TOI16 complete, R3H(15:0) = -5 (0xFFFB)
; R3H(31:16) = (0xFFFF)
```

See also

F32TOI16R RaH, RbH F32TOUI16 RaH, RbH F32TOUI16R RaH, RbH I16TOF32 RaH, RbH I16TOF32 RaH, mem16 UI16TOF32 RaH, mem16 UI16TOF32 RaH, RbH



F32TOI16R RaH, RbH Convert 32-bit Floating-Point Value to 16-bit Integer and Round

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)

Opcode LSW: 1110 0110 1000 1100 MSW: 1000 0000 00bb baaa

DescriptionConvert the 32-bit floating point value in RbH to a 16-bit integer and round to the nearest

even value. The result is stored in RaH.

RaH(15:0) = F32ToI16round(RbH)
RaH(31:16) = sign extension of RaH(15)

Flags

This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

```
F32TOI16R RaH, RbH ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction
; <-- F32TOI16R completes, RaH updated

NOP
```

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example

See also

F32TOI16 RaH, RbH F32TOUI16 RaH, RbH F32TOUI16R RaH, RbH I16TOF32 RaH, RbH I16TOF32 RaH, mem16 UI16TOF32 RaH, mem16 UI16TOF32 RaH, RbH



F32TOI32 RaH, RbH Convert 32-bit Floating-Point Value to 32-bit Integer

Operands

RaH floating-point destination register (R0H to R7H)

RbH floating-point source register (R0H to R7H)

Opcode LSW: 1110 0110 1000 1000 MSW: 0000 0000 00bb baaa

Description Convert the 32-bit floating-point value in RbH to a 32-bit integer value and truncate.

Store the result in RaH.

RaH = F32TOI32(RbH)

Flags This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline This is a 2 pipeline cycle (2p) instruction. That is:

F32T0I32 RaH, RbH ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction

; <-- F32T0I32 completes, RaH updated

NOP

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example

MOVF32 R2H, #11204005.0 ; R2H = 11204005.0 (0x4B2AF5A5)

F32TOI32 R3H, R2H ; R3H = F32TOI32 (R2H)

MOVF32 R4H, #-11204005.0 ; R4H = -11204005.0 (0xCB2AF5A5)

; <-- F32TOI32 complete,

; R3H = 11204005 (0x00AAF5A5)

F32TOI32 R5H, R4H ; R5H = F32TOI32 (R4H)

NOP ; 1 Cycle delay for F32T0I32 to complete

; <-- F32TOI32 complete, ; R5H = -11204005 (0xFF550A5B)

See also F32TOUI32 RaH, RbH

I32TOF32 RaH, RbH I32TOF32 RaH, mem32 UI32TOF32 RaH, RbH UI32TOF32 RaH, mem32



F32TOUI16 RaH, RbH Convert 32-bit Floating-Point Value to 16-bit Unsigned Integer

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)

Opcode LSW: 1110 0110 1000 1110

MSW: 0000 0000 00bb baaa

DescriptionConvert the 32-bit floating point value in RbH to an unsigned 16-bit integer value and

truncate to zero. The result will be stored in RaH. To instead round the integer to the nearest even value use the F32TOUI16R instruction.

RaH(15:0) = F32ToUI16(RbH) RaH(31:16) = 0x0000

Flags

This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

```
F32TOUI16 RaH, RbH ; 2 pipeline cycles (2p)
```

NOP ; 1 cycle delay or non-conflicting instruction

; <-- F32TOUI16 completes, RaH updated

NOP

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example

```
MOVIZF32 R4H, #9.0
                      ; R4H = 9.0 (0x41100000)
F32TOUI16 R5H, R4H
                      ; R5H (15:0) = F32TOUI16 (R4H)
                       ; R5H (31:16) = 0 \times 00000
MOVIZF32 R6H, #-9.0
                      ; R6H = -9.0 (0xC1100000)
                       ; <-- F32TOUI16 complete, R5H (15:0) = 9.0 (0x0009)
                                                  R5H (31:16) = 0.0 (0x0000)
F32TOUI16 R7H, R6H
                       ; R7H (15:0) = F32TOUI16 (R6H)
                       ; R7H (31:16) = 0x0000
NOP
                       ; 1 Cycle delay for F32TOUI16 to complete
                       ; <-- F32TOUI16 complete, R7H (15:0) = 0.0 (0x0000)
                                                  R7H (31:16) = 0.0 (0x0000)
```

See also

Submit Documentation Feedback

F32TOI16 RaH, RbH F32TOUI16R RaH, RbH F32TOUI16R RaH, RbH I16TOF32 RaH, RbH I16TOF32 RaH, mem16 UI16TOF32 RaH, mem16 UI16TOF32 RaH, RbH



F32TOUI16R RaH, RbH Convert 32-bit Floating-Point Value to 16-bit Unsigned Integer and Round

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)

Opcode

LSW: 1110 0110 1000 1110 MSW: 1000 0000 00bb baaa

Description

Convert the 32-bit floating-point value in RbH to an unsigned 16-bit integer and round to the closest even value. The result will be stored in RaH. To instead truncate the converted value, use the F32TOUI16 instruction.

RaH(15:0) = F32ToUI16round(RbH)

RaH(31:16) = 0x0000

Flags

This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

```
F32TOUI16R RaH, RbH ; 2 pipeline cycles (2p)
```

NOP ; 1 cycle delay or non-conflicting instruction ; <-- F32TOUI16R completes, RaH updated

NOP

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example

```
MOVIZ R5H, \#0x412C ; R5H = 0x412C
MOVXI R5H, #0xCCCD
                    ; R5H = 0xCCCD
                     ; R5H = 10.8 (0x412CCCCD)
F32TOUI16R R6H, R5H ; R6H (15:0) = F32TOUI16round (R5H)
                     ; R6H (31:16) = 0 \times 0000
MOVF32 R7H, #-10.8
                    ; R7H = -10.8 (0x0xC12CCCCD)
                     ; <-- F32TOUI16R complete,
                     ; R6H (15:0) = 11.0 (0x000B)
                     ; R6H (31:16) = 0.0 (0x0000)
F32TOUI16R R0H, R7H; R0H (15:0) = F32TOUI16round (R7H)
                     ; R0H (31:16) = 0x0000
NOP
                     ; 1 Cycle delay for F32TOUI16R to complete
                     ; <-- F32TOUI16R complete,
                     ; R0H (15:0) = 0.0 (0x0000)
                     ; R0H (31:16) = 0.0 (0x0000)
```

See also

F32TOI16 RaH, RbH F32TOI16R RaH, RbH F32TOUI16 RaH, RbH I16TOF32 RaH, RbH I16TOF32 RaH, mem16 UI16TOF32 RaH, mem16 UI16TOF32 RaH, RbH



F32TOUI32 RaH, RbH Convert 32-bit Floating-Point Value to 16-bit Unsigned Integer

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)

Opcode LSW: 1110 0110 1000 1010 MSW: 0000 0000 00bb baaa

Description Convert the 32-bit floating-point value in RbH to an unsigned 32-bit integer and store the

result in RaH.

RaH = F32ToUI32(RbH)

Flags This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline This is a 2 pipeline cycle (2p) instruction. That is:

F32TOUI32 RaH, RbH ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction

; <-- F32TOUI32 completes, RaH updated

NOP

Any instruction in the delay slot must not use RaH as a destination register or use RaH

as a source operand.

Example MOVIZF32 R6H, #12.5 ; R6H = 12.5 (0x41480000)

F32TOUI32 R7H, R6H ; R7H = F32TOUI32 (R6H)
MOVIZF32 R1H, #-6.5 ; R1H = -6.5 (0xC0D00000)

; <-- F32TOUI32 complete, R7H = 12.0 (0x0000000C)

NOP ; 1 Cycle delay for F32TOUI32 to complete

; <-- F32TOUI32 complete, R2H = 0.0 (0x00000000)

See also F32TOI32 RaH, RbH

I32TOF32 RaH, RbH I32TOF32 RaH, mem32 UI32TOF32 RaH, RbH UI32TOF32 RaH, mem32



FRACF32 RaH, RbH Fractional Portion of a 32-bit Floating-Point Value

Operands

RaH floating-point destination register (R0H to R7H)

RbH floating-point source register (R0H to R7H)

Opcode LSW: 1110 0110 1111 0001

MSW: 0000 0000 00bb baaa

Description Returns in RaH the fractional portion of the 32-bit floating-point value in RbH

Flags This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No

Pipeline This is a 2 pipeline cycle (2p) instruction. That is:

FRACF32 RaH, RbH; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction

; <-- FRACF32 completes, RaH updated

NOP

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example MOVIZF32 R2H, #19.625; R2H = 19.625 (0x419D0000)

FRACF32 R3H, R2H ; R3H = FRACF32 (R2H)

NOP ; 1 Cycle delay for FRACF32 to complete

; <-- FRACF32 complete, R3H = 0.625 (0x3F200000)

See also



I16TOF32 RaH, RbH Convert 16-bit Integer to 32-bit Floating-Point Value

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)

Opcode LSW: 1110 0110 1000 1101 MSW: 0000 0000 00bb baaa

Description Convert the 16-bit signed integer in RbH to a 32-bit floating point value and store the

result in RaH.

RaH = I16ToF32 RbH

Flags This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example

```
MOVIZ R0H, #0x0000 ; R0H[31:16] = 0.0 (0x0000)

MOVXI R0H, #0x0004 ; R0H[15:0] = 4.0 (0x0004)

I16TOF32 R1H, R0H ; R1H = I16TOF32 (R0H)

MOVIZ R2H, #0x0000 ; R2H[31:16] = 0.0 (0x0000)

; <--I16TOF32 complete, R1H = 4.0 (0x40800000)

MOVXI R2H, #0xFFFC ; R2H[15:0] = -

4.0 (0xFFFC) I16TOF32 R3H, R2H ; R3H = I16TOF32 (R2H)

NOP ; 1 Cycle delay for I16TOF32 to complete

; <-- I16TOF32 complete, R3H = -4.0 (0xC0800000)
```

See also

F32TOI16 RaH, RbH F32TOI16R RaH, RbH F32TOUI16 RaH, RbH F32TOUI16R RaH, RbH I16TOF32 RaH, mem16 UI16TOF32 RaH, mem16 UI16TOF32 RaH, RbH



I16TOF32 RaH, mem16 Convert 16-bit Integer to 32-bit Floating-Point Value

Operands

RaH	floating-point destination register (R0H to R7H)
mem316	16-bit source memory location to be converted

Opcode LSW: 1110 0010 1100 1000 MSW: 0000 0aaa mem16

Description Convert the 16-bit signed integer indicated by the mem16 pointer to a 32-bit floating-

point value and store the result in RaH.

RaH = I16ToF32[mem16]

Flags This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline This is a 2 pipeline cycle (2p) instruction. That is:

I16TOF32 RaH, mem16 ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction

; <-- I16TOF32 completes, RaH updated

NOP

Any instruction in the delay slot must not use RaH as a destination register or use RaH

as a source operand.

Example MOVW DP, #0x0280; DP = 0x0280

MOV @0, #0x0004 ; [0x00A000] = 4.0 (0x0004) I16TOF32 R0H, @0 ; R0H = I16TOF32 [0x00A000] MOV @1, #0xFFFC ; [0x00A001] = -4.0 (0xFFFC)

; <--I16TOF32 complete, R0H = 4.0 (0x40800000)

I16TOF32 R1H, @1 ; R1H = I16TOF32 [0x00A001]

NOP ; 1 Cycle delay for I16TOF32 to complete

; <-- I16TOF32 complete, R1H = -4.0 (0xC0800000)

See also F32TOI16 RaH, RbH

F32TOI16R RaH, RbH F32TOUI16 RaH, RbH F32TOUI16R RaH, RbH I16TOF32 RaH, RbH UI16TOF32 RaH, mem16 UI16TOF32 RaH, RbH



132TOF32 RaH, mem32 Convert 32-bit Integer to 32-bit Floating-Point Value

Operands

RaH	floating-point destination register (R0H to R7H)
mem32	32-bit source for the MOV32 operation. mem32 means that the operation can only address memory using any of the direct or indirect addressing modes supported by the C28x CPU

Opcode LSW: 1110 0010 1000 1000 MSW: 0000 0aaa mem32

Description Convert the 32-bit signed integer indicated by the mem32 pointer to a 32-bit floating

point value and store the result in RaH.

RaH = I32ToF32[mem32]

Flags This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline This is a 2 pipeline cycle (2p) instruction. That is:

I32TOF32 RaH, mem32 ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction

; <-- I32TOF32 completes, RaH updated

NOP

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example MOVW DP, #0x0280; DP = 0x0280

MOV @0, #0x1111; [0x00A000] = 4369 (0x1111) MOV @1, #0x1111; [0x00A001] = 4369 (0x1111)

> ; Value of the 32 bit signed integer present in ; 0x00A001 and 0x00A000 is +286331153 (0x11111111)

I32TOF32 R1H, @0 ; R1H = I32TOF32 (0x11111111)

NOP ; 1 Cycle delay for I32TOF32 to complete

; <-- I32TOF32 complete, R1H = 286331153 (0x4D8888888)

See also F32TOI32 RaH, RbH

F32TOUI32 RaH, RbH I32TOF32 RaH, RbH UI32TOF32 RaH, RbH UI32TOF32 RaH, mem32



I32TOF32 RaH, RbH Convert 32-bit Integer to 32-bit Floating-Point Value

Operands

RaH floating-point destination register (R0H to R7H)

RbH floating-point source register (R0H to R7H)

Opcode LSW: 1110 0110 1000 1001 MSW: 0000 0000 00bb baaa

Description Convert the signed 32-bit integer in RbH to a 32-bit floating-point value and store the

result in RaH.

RaH = I32ToF32(RbH)

Flags This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline This is a 2 pipeline cycle (2p) instruction. That is:

I32TOF32 RaH, RbH; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction

; <-- I32TOF32 completes, RaH updated

NOP

Any instruction in the delay slot must not use RaH as a destination register or use RaH

as a source operand.

Example MOVIZ R2H, #0x1111; R2H[31:16] = 4369 (0x1111)

MOVXI R2H, #0x1111; R2H[15:0] = 4369 (0x1111)

; Value of the 32 bit signed integer present

; in R2H is +286331153 (0x11111111)

I32TOF32 R3H, R2H; R3H = I32TOF32 (R2H)

NOP ; 1 Cycle delay for I32TOF32 to complete

; <-- I32TOF32 complete, R3H = 286331153 (0x4D888888)

See also F32TOI32 RaH, RbH

F32TOUI32 RaH, RbH I32TOF32 RaH, mem32 UI32TOF32 RaH, RbH UI32TOF32 RaH, mem32



MACF32 R3H, R2H, RdH, ReH, RfH 32-bit Floating-Point Multiply with Parallel Add

Operands

This instruction is an alias for the parallel multiply and add instruction. The operands are translated by the assembler such that the instruction becomes:

MPYF32 RdH, RaH, RbH || ADDF32 R3H, R3H, R2H

R3H	floating-point destination and source register for the ADDF32
R2H	floating-point source register for the ADDF32 operation (R0H to R7H)
RdH	floating-point destination register for MPYF32 operation (R0H to R7H) RdH cannot be R3H
ReH	floating-point source register for MPYF32 operation (R0H to R7H)
RfH	floating-point source register for MPYF32 operation (R0H to R7H)

Opcode

LSW: 1110 0111 0100 00ff MSW: feee dddc ccbb baaa

Description

This instruction is an alias for the parallel multiply and add, MACF32 || ADDF32, instruction.

RdH = ReH * RfH R3H = R3H + R2H

Restrictions

The destination register for the MPYF32 and the ADDF32 must be unique. That is, RdH

cannot be R3H.

Flags

This instruction modifies the following flags in the STF register:.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if MPYF32 or ADDF32 generates an underflow condition.
- LVF = 1 if MPYF32 or ADDF32 generates an overflow condition.

Pipeline

Both MPYF32 and ADDF32 take 2 pipeline cycles (2p) That is:

```
MPYF32 RaH, RbH, RcH ; 2 pipeline cycles (2p)

|| ADDF32 RdH, ReH, RfH ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction

; <-- MPYF32, ADDF32 complete, RaH, RdH updated

NOP
```

Any instruction in the delay slot must not use RaH or RdH as a destination register or as a source operand.



```
Example
                         Perform 5 multiply and accumulate operations:
                         1st multiply: A = X0 * Y0
                     ;
                         2nd multiply: B = X1 * Y1
                         3rd multiply: C = X2 * Y2
                         4th multiply: D = X3 * Y3
                         5th multiply: E = X3 * Y3
                         Result = A + B + C + D + E
                        MOV32 R0H, *XAR4++
                                                      ; R0H = X0
                        MOV32 R1H, *XAR5++
                                                      ; R1H = Y0
                                                      ; R2H = A = X0 * Y0
                        MPYF32 R2H, R0H, R1H
                                                      ; In parallel ROH = X1
                     | MOV32 R0H, *XAR4++
                        MOV32 R1H, *XAR5++
                                                      ; R1H = Y1
                                                      ; R3H = B = X1 * Y1
                                                     ; In parallel ROH = X2
                        MPYF32 R3H, R0H, R1H
                     | MOV32 R0H, *XAR4++
                        MOV32 R1H, *XAR5++
                                                      ; R1H = Y2
                                                      ; R3H = A + B
                                                      ; R2H = C = X2 * Y2
                        MACF32 R3H, R2H, R2H, R0H, R1H; In parallel R0H = X3
                      | MOV32 R0H, *XAR4++
                        MOV32 R1H, *XAR5++
                                                      ; R1H = Y3
                                                      ; R3H = (A + B) + C
                                                      ; R2H = D = X3 * Y3
                        MACF32 R3H, R2H, R2H, R0H, R1H; In parallel R0H = X4
                      || MOV32 R0H, *XAR4
                        MOV32 R1H, *XAR5
                                                     ; R1H = Y4
                     ; The next MACF32 is an alias for
                      ; MPYF32 | ADDF32
                                                      ; R2H = E = X4 * Y4
                        MACF32 R3H, R2H, R2H, R0H, R1H; in parallel R3H = (A + B + C) + D
                                                      ; Wait for MPYF32 | ADDF32 to complete
                        ADDF32 R3H, R3H, R2H
                                                      ; R3H = (A + B + C + D) + E
                        NOP
                                                      ; Wait for ADDF32 to complete
                        MOV32 @Result, R3H
                                                      ; Store the result
See also
                     MACF32 R3H, R2H, RdH, ReH, RfH | MOV32 RaH, mem32
                     MACF32 R7H, R3H, mem32, *XAR7++
                     MACF32 R7H, R6H, RdH, ReH, RfH
                     MACF32 R7H, R6H, RdH, ReH, RfH || MOV32 RaH, mem32
                     MPYF32 RaH, RbH, RcH | ADDF32 RdH, ReH, RfH
```

www.ti.com MACF32 R3H, R2H, RdH, ReH, RfH ||MOV32 RaH, mem32 — 32-bit Floating-Point Multiply and Accumulate with Parallel Move

MACF32 R3H, R2H, RdH, ReH, RfH || MOV32 RaH, mem32 32-bit Floating-Point Multiply and Accumulate with Parallel Move

Operands

R3H	floating-point destination/source register R3H for the add operation
R2H	floating-point source register R2H for the add operation
RdH	floating-point destination register (R0H to R7H) for the multiply operation RdH cannot be the same register as RaH
ReH	floating-point source register (R0H to R7H) for the multiply operation
RfH	floating-point source register (R0H to R7H) for the multiply operation
RaH	floating-point destination register for the MOV32 operation (R0H to R7H). RaH cannot be R3H or the same register as RdH.
mem32	32-bit source for the MOV32 operation

Opcode

```
LSW: 1110 0011 0011 fffe MSW: eedd daaa mem32
```

Description

Multiply and accumulate the contents of floating-point registers and move from register to memory. The destination register for the MOV32 cannot be the same as the destination registers for the MACF32.

```
R3H = R3H + R2H,
RdH = ReH * RfH,
RaH = [mem32]
```

Restrictions

The destination registers for the MACF32 and the MOV32 must be unique. That is, RaH cannot be R3H and RaH cannot be the same register as RdH.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	Yes	Yes	Yes	Yes	Yes	Yes

The STF register flags are modified as follows:

- LUF = 1 if MACF32 (add or multiply) generates an underflow condition.
- LVF = 1 if MACF32 (add or multiply) generates an overflow condition.

MOV32 sets the NF, ZF, NI and ZI flags as follows:

```
NF = RaH(31);
ZF = 0;
if(RaH(30:23) == 0) { ZF = 1; NF = 0; }
NI = RaH(31);
ZI = 0;
if(RaH(31:0) == 0) ZI = 1;
```

Pipeline

The MACF32 takes 2 pipeline cycles (2p) and the MOV32 takes a single cycle. That is:

```
MACF32 R3H, R2H, RdH, ReH, RfH; 2 pipeline cycles (2p)

| MOV32 RaH, mem32; 1 cycle
; <-- MOV32 completes, RaH updated

NOP; 1 cycle delay for MACF32; <-- MACF32 completes, R3H, RdH updated

NOP
```

Any instruction in the delay slot for this version of MACF32 must not use R3H or RdH as a destination register or R3H or RdH as a source operand.

MACF32 R3H, R2H, RdH, ReH, RfH || MOV32 RaH, mem32 — 32-bit Floating-Point Multiply and Accumulate with Parallel Move

```
Example
                         Perform 5 multiply and accumulate operations:
                         1ST multiply: A = X0 * Y0
                         2nd multiply: B = X1 * Y1
                         3rd multiply: C = X2 * Y2
                        4TH multiply: D = X3 * Y3
                         5th multiply: E = X3 * Y3
                         Result = A + B + C + D + E
                         MOV32 R0H, *XAR4++
                                                      ; ROH = XO
                         MOV32 R1H, *XAR5++
                                                      ; R1H = Y0
                                                      ; R2H = A = X0 * Y0
                         MPYF32 R2H, R0H, R1H
                                                      ; In parallel ROH = X1
                     || MOV32 R0H, *XAR4++
                         MOV32 R1H, *XAR5++
                                                      ; R1H = Y1
                                                      ; R3H = B = X1 * Y1
                         MPYF32 R3H, R0H, R1H
                                                      ; In parallel ROH = X2
                     || MOV32 R0H, *XAR4++
                         MOV32 R1H, *XAR5++
                                                      ; R1H = Y2
                                                      ; R3H = A + B
                                                      ; R2H = C = X2 * Y2
                         MACF32 R3H, R2H, R2H, R0H, R1H; In parallel R0H = X3
                     | MOV32 R0H, *XAR4++
                         MOV32 R1H, *XAR5++
                                                      ; R1H = Y3
                                                      ; R3H = (A + B) + C
                                                       ; R2H = D = X3 * Y3
                         MACF32 R3H, R2H, R2H, R0H, R1H ; In parallel R0H = X4
                     || MOV32 R0H, *XAR4
                         MOV32 R1H, *XAR5
                                                      ; R1H = Y4
                                                      ; R2H = E = X4 * Y4
                         MPYF32 R2H, R0H, R1H
                                                      ; in parallel R3H = (A + B + C) + D
                     | ADDF32 R3H, R3H, R2H
                                                      ; Wait for MPYF32 || ADDF32 to complete
                         ADDF32 R3H, R3H, R2H
                                                      ; R3H = (A + B + C + D) + E
                         NOP
                                                      ; Wait for ADDF32 to complete
                         MOV32 @Result, R3H
                                                       ; Store the result
See also
                     MACF32 R3H, R2H, RdH, ReH, RfH
                     MACF32 R7H, R3H, mem32, *XAR7++
                     MACF32 R7H, R6H, RdH, ReH, RfH
                     MACF32 R7H, R6H, RdH, ReH, RfH || MOV32 RaH, mem32
                     MPYF32 RaH, RbH, RcH | ADDF32 RdH, ReH, RfH
```



MACF32 R7H, R3H, mem32, *XAR7++ 32-bit Floating-Point Multiply and Accumulate

Operands

R7H	floating-point destination register
R3H	floating-point destination register
mem32	pointer to a 32-bit source location
*XAR7++	32-bit location pointed to by auxiliary register 7, XAR7 is post incremented.

Opcode

LSW: 1110 0010 0101 0000 MSW: 0001 1111 mem32

Description

Perform a multiply and accumulate operation. When used as a standalone operation, the MACF32 will perform a single multiply as shown below:

```
Cycle 1: R3H = R3H + R2H, R2H = [mem32] * [XAR7++]
```

This instruction is the only floating-point instruction that can be repeated using the single repeat instruction (RPT ||). When repeated, the destination of the accumulate will alternate between R3H and R7H on each cycle and R2H and R6H are used as temporary storage for each multiply.

```
Cycle 1: R3H = R3H + R2H, R2H = [mem32] * [XAR7++] Cycle 2: R7H = R7H + R6H, R6H = [mem32] * [XAR7++] Cycle 3: R3H = R3H + R2H, R2H = [mem32] * [XAR7++] Cycle 4: R7H = R7H + R6H, R6H = [mem32] * [XAR7++] etc...
```

Restrictions

R2H and R6H will be used as temporary storage by this instruction.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	Yes	Yes

The STF register flags are modified as follows:

- LUF = 1 if MACF32 generates an underflow condition.
- LVF = 1 if MACF32 generates an overflow condition.

Pipeline

When repeated the MACF32 takes 3 + N cycles where N is the number of times the instruction is repeated. When repeated, this instruction has the following pipeline restrictions:

NOP

NOP



MACF32 can also be used standalone. In this case, the instruction takes 2 cycles and the following pipeline restrictions apply:

```
<instruction1>
                                     ; No restriction
<instruction2>
                                     ; Cannot be a 2p instruction that writes
                                     ; to R2H, R3H, R6H or R7H
MACF32 R7H, R3H, *XAR6, *XAR7
                                     ; R3H = R3H + R2H, R2H = [mem32] * [XAR7++]
                                     ; <--
R2H and R3H are valid (note: no delay required)
NOP
   ZERO R2H
                                          ; Zero the accumulation registers
   ZERO R3H
                                          ; and temporary multiply storage
registers
   ZERO R6H
   ZERO R7H
  RPT #3
                                          ; Repeat MACF32 N+1 (4) times
| MACF32 R7H, R3H, *XAR6++, *XAR7++
   ADDF32 R7H, R7H, R3H
                                          ; Final accumulate
```

Cascading of RPT || MACF32 is allowed as long as the first and subsequent counts are even. Cascading is useful for creating interruptible windows so that interrupts are not delayed too long by the RPT instruction. For example:

; <-- ADDF32 completes, R7H valid

```
ZERO R2H
                                             ; Zero the accumulation registers
   ZERO R3H
                                             ; and temporary multiply storage
registers
  ZERO R6H
   ZERO R7H
  RPT #3
                                            ; Execute MACF32 N+1 (4) times
|| MACF32 R7H, R3H, *XAR6++, *XAR7++ RPT #5 ; Execute MACF32 N+1 (6) times
|| MACF32 R7H, R3H, *XAR6++, *XAR7++ RPT #N ; Repeat MACF32 N+1 times where N+1
is even
| MACF32 R7H, R3H, *XAR6++, *XAR7++
   ADDF32 R7H, R7H, R3H
                                             ; Final accumulate
   NOP
                                             ; <-- ADDF32 completes, R7H valid
```

See also

Example

MACF32 R3H, R2H, RdH, ReH, RfH || MOV32 RaH, mem32 MACF32 R7H, R6H, RdH, ReH, RfH || MOV32 RaH, mem32 MPYF32 RaH, RbH, RcH || ADDF32 RdH, ReH, RfH



MACF32 R7H, R6H, RdH, ReH, RfH 32-bit Floating-Point Multiply with Parallel Add

Operands

This instruction is an alias for the parallel multiply and add instruction. The operands are translated by the assembler such that the instruction becomes:

MPYF32 RdH, RaH, RbH | | ADDF32 R7H, R7H, R6H

R7H	floating-point destination and source register for the ADDF32
R6H	floating-point source register for the ADDF32 operation (R0H to R7H)
RdH	floating-point destination register for MPYF32 operation (R0H to R7H) RdH cannot be R3H
ReH	floating-point source register for MPYF32 operation (R0H to R7H)
RfH	floating-point source register for MPYF32 operation (R0H to R7H)

Opcode

LSW: 1110 0111 0100 00ff MSW: feee dddc ccbb baaa

Description

This instruction is an alias for the parallel multiply and add, MACF32 || ADDF32, instruction.

RdH = RaH * RbH R7H = R6H + R6H

Restrictions

The destination register for the MPYF32 and the ADDF32 must be unique. That is, RdH cannot be R7H.

Cannot

Flags

This instruction modifies the following flags in the STF register:.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if MPYF32 or ADDF32 generates an underflow condition.
- LVF = 1 if MPYF32 or ADDF32 generates an overflow condition.

Pipeline

Both MPYF32 and ADDF32 take 2 pipeline cycles (2p) That is:

```
MPYF32 RaH, RbH, RcH; 2 pipeline cycles (2p)

|| ADDF32 RdH, ReH, RfH; 2 pipeline cycles (2p)

NOP; 1 cycle delay or non-conflicting instruction; <-- MPYF32, ADDF32 complete, RaH, RdH updated

NOP
```

Any instruction in the delay slot must not use RaH or RdH as a destination register or as a source operand.



```
Example
                         Perform 5 multiply and accumulate operations:
                     ;
                         1st multiply: A = X0 * Y0
                     ;
                         2nd multiply: B = X1 * Y1
                         3rd multiply: C = X2 * Y2
                         4th multiply: D = X3 * Y3
                         5th multiply: E = X3 * Y3
                        Result = A + B + C + D + E
                                                       ; R0H = X0
                        MOV32 R0H, *XAR4++
                                                       ; R1H = Y0
                        MOV32 R1H, *XAR5++
                                                       ; R6H = A = X0 * Y0
                        MPYF32 R6H, R0H, R1H
                                                       ; In parallel ROH = X1
                     | MOV32 R0H, *XAR4++
                        MOV32 R1H, *XAR5++
                                                      ; R1H = Y1
                                                      ; R7H = B = X1 * Y1
                                                      ; In parallel ROH = X2
                        MPYF32 R7H, R0H, R1H
                     | MOV32 R0H, *XAR4++
                        MOV32 R1H, *XAR5++
                                                      ; R1H = Y2
                                                      ; R7H = A + B
                                                       ; R6H = C = X2 * Y2
                        MACF32 R7H, R6H, R6H, R0H, R1H ; In parallel R0H = X3
                     | MOV32 R0H, *XAR4++
                        MOV32 R1H, *XAR5++
                                                      ; R1H = Y3
                                                       ; R7H = (A + B) + C
                                                       ; R6H = D = X3 * Y3
                        MACF32 R7H, R6H, R6H, R0H, R1H ; In parallel R0H = X4
                     || MOV32 R0H, *XAR4
                        MOV32 R1H, *XAR5
                                                      ; R1H = Y4
                     ; Next MACF32 is an alias for
                     ; MPYF32 || ADDF32
                        MACF32 R7H, R6H, R6H, R0H, R1H ; R6H = E = X4 * Y4
                                                       ; in parallel R7H = (A + B + C) + D
                                                       ; Wait for MPYF32 || ADDF32 to complete
                        ADDF32 R7H, R7H, R6H
                                                      ; R7H = (A + B + C + D) + E
                        NOP
                                                       ; Wait for ADDF32 to complete
                        MOV32 @Result, R7H
                                                       ; Store the result
                     MACF32 R3H, R2H, RdH, ReH, RfH
See also
                     MACF32 R3H, R2H, RdH, ReH, RfH | MOV32 RaH, mem32
                     MACF32 R7H, R3H, mem32, *XAR7++
                     MACF32 R7H, R6H, RdH, ReH, RfH | MOV32 RaH, mem32
                     MPYF32 RaH, RbH, RcH | ADDF32 RdH, ReH, RfH
```

www.ti.com MACF32 R7H, R6H, RdH, ReH, RfH ||MOV32 RaH, mem32 — 32-bit Floating-Point Multiply and Accumulate with Parallel Move

MACF32 R7H, R6H, R6H, R6H, RfH || MOV32 RaH, mem32 32-bit Floating-Point Multiply and Accumulate with Parallel Move

Operands

R7H	floating-point destination/source register R7H for the add operation
R6H	floating-point source register R6H for the add operation
RdH	floating-point destination register (R0H to R7H) for the multiply operation. RdH cannot be the same register as RaH.
ReH	floating-point source register (R0H to R7H) for the multiply operation
RfH	floating-point source register (R0H to R7H) for the multiply operation
RaH	floating-point destination register for the MOV32 operation (R0H to R7H). RaH cannot be R3H or the same as RdH.
mem32	32-bit source for the MOV32 operation

Opcode

```
LSW: 1110 0011 1100 fffe MSW: eedd daaa mem32
```

Description

Multiply/accumulate the contents of floating-point registers and move from register to memory. The destination register for the MOV32 cannot be the same as the destination registers for the MACF32.

```
R7H = R7H + R6H
RdH = ReH * RfH,
RaH = [mem32]
```

Restrictions

The destination registers for the MACF32 and the MOV32 must be unique. That is, RaH cannot be R7H and RaH cannot be the same register as RdH.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	Yes	Yes	Yes	Yes	Yes	Yes

The STF register flags are modified as follows:

- LUF = 1 if MACF32 (add or multiply) generates an underflow condition.
- LVF = 1 if MACF32 (add or multiply) generates an overflow condition.

The MOV32 Instruction will set the NF, ZF, NI and ZI flags as follows:

```
NF = RaH(31);
ZF = 0;
if(RaH(30:23) == 0) {ZF = 1;
NF = 0;} NI = RaH(31);
ZI = 0;
if(RaH(31:0) == 0) ZI = 1;
```

Pipeline

The MACF32 takes 2 pipeline cycles (2p) and the MOV32 takes a single cycle. That is:



Example

```
Perform 5 multiply and accumulate operations:
   1st multiply: A = X0 * Y0
   2nd multiply: B = X1 * Y1
   3rd multiply: C = X2 * Y2
   4th multiply: D = X3 * Y3
   5th multiply: E = X3 * Y3
   Result = A + B + C + D + E
   MOV32 R0H, *XAR4++
                                 ; ROH = XO
   MOV32 R1H, *XAR5++
                                 ; R1H = Y0
                                 ; R6H = A = X0 * Y0
   MPYF32 R6H, R0H, R1H
                                 ; In parallel ROH = X1
|| MOV32 R0H, *XAR4++
   MOV32 R1H, *XAR5++
                                 ; R1H = Y1
                                 ; R7H = B = X1 * Y1
   MPYF32 R7H, R0H, R1H
                                 ; In parallel ROH = X2
|| MOV32 R0H, *XAR4++
   MOV32 R1H, *XAR5++
                                 ; R1H = Y2
                                 ; R7H = A + B
                                 ; R6H = C = X2 * Y2
   MACF32 R7H, R6H, R6H, R0H, R1H; In parallel R0H = X3
| MOV32 R0H, *XAR4++
   MOV32 R1H, *XAR5++
                                 ; R1H = Y3
                                 ; R7H = (A + B) + C
                                  ; R6H = D = X3 * Y3
  MACF32 R7H, R6H, R6H, R0H, R1H ; In parallel R0H = X4
|| MOV32 R0H, *XAR4
  MOV32 R1H, *XAR5
                                 ; R1H = Y4
                                 ; R6H = E = X4 * Y4
  MPYF32 R6H, R0H, R1H
                                 ; in parallel R7H = (A + B + C) + D
| ADDF32 R7H, R7H, R6H
                                 ; Wait for MPYF32 | ADDF32 to complete
  ADDF32 R7H, R7H, R6H
                                 ; R7H = (A + B + C + D) + E
  NOP
                                 ; Wait for ADDF32 to complete
  MOV32 @Result, R7H
                                  ; Store the result
```

See also

MACF32 R7H, R3H, mem32, *XAR7++ MACF32 R3H, R2H, RdH, ReH, RfH || MOV32 RaH, mem32 MPYF32 RaH, RbH, RcH || ADDF32 RdH, ReH, RfH



MAXF32 RaH, RbH 32-bit Floating-Point Maximum

Operands

B.11	(I c)
RaH	floating-point source/destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)

Opcode LSW: 1110 0110 1001 0110 MSW: 0000 0000 00bb baaa

Description if (RaH < RbH) RaH = RbH

Special cases for the output from the MAXF32 operation:

- · NaN output will be converted to infinity
- A denormalized output will be converted to positive zero.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	Yes	Yes	No	No	

The ZF and NF flags are configured on the result of the operation, not the result stored in the destination register.

if(RaH == RbH){ZF=1, NF=0}
if(RaH > RbH) {ZF=0, NF=0}
if(RaH < RbH) {ZF=0, NF=1}</pre>

Pipeline

This is a single-cycle instruction.

Example

```
ROH, #5.0
                       ; ROH = 5.0 (0x40A00000)
MOVIZF32
                      ; R1H = -2.0 (0xC0000000)
MOVIZF32
           R1H, #-2.0
                      ; R2H = -1.5 (0xBFC00000)
           R2H, #-1.5
MOVIZF32
                       ; R2H = -1.5, ZF = NF = 0
           R2H, R1H
MAXF32
MAXF32
           R1H, R2H
                      ; R1H = -1.5, ZF = 0, NF = 1
           R2H, R0H
                      ; R2H = 5.0, ZF = 0, NF = 1
MAXF32
MAXF32
          ROH, R2H
                      ; R2H = 5.0, ZF = 1, NF = 0
```

See also

CMPF32 RaH, RbH CMPF32 RaH, #16FHi CMPF32 RaH, #0.0

MAXF32 RaH, RbH || MOV32 RcH, RdH

MAXF32 RaH, #16FHi MINF32 RaH, RbH MINF32 RaH, #16FHi



MAXF32 RaH, #16FHi 32-bit Floating-Point Maximum

Operands

RaH	floating-point source/destination register (R0H to R7H)
#16FHi	A 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0.

Opcode

LSW: 1110 1000 0010 0III MSW: IIII IIII IIII Iaaa

Description

Compare RaH with the floating-point value represented by the immediate operand. If the immediate value is larger, then load it into RaH.

```
if(RaH < #16FHi:0) RaH = #16FHi:0
```

#16FHi is a 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0. This addressing mode is most useful for constants where the lowest 16-bits of the mantissa are 0. Some examples are 2.0 (0x40000000), 4.0 (0x40800000), 0.5 (0x3F000000), and -1.5 (0xBFC00000). The assembler will accept either a hex or float as the immediate value. That is, -1.5 can be represented as #-1.5 or #0xBFC0.

Special cases for the output from the MAXF32 operation:

- NaN output will be converted to infinity
- A denormalized output will be converted to positive zero.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	Yes	Yes	No	No	

The ZF and NF flags are configured on the result of the operation, not the result stored in the destination register.

```
if(RaH == #16FHi:0) {ZF=1, NF=0}
if(RaH > #16FHi:0) {ZF=0, NF=0}
if(RaH < #16FHi:0) {ZF=0, NF=1}</pre>
```

Pipeline

This is a single-cycle instruction.

Example

```
MOVIZF32
            ROH, #5.0
                         ; ROH = 5.0 (0x40A00000)
            R1H, #4.0
                         ; R1H = 4.0 (0x40800000)
MOVIZF32
            RIH, #4.0 ; RIH = 4.0 (0x40800000)
R2H, #-1.5 ; R2H = -1.5 (0xBFC00000)
MOVIZF32
                         ; ROH = 5.5, ZF = 0, NF = 1
MAXF32
           ROH, #5.5
          R1H, \#2.5; R1H = 4.0, ZF = 0, NF = 0
MAXF32
MAXF32
          R2H, \#-1.0 ; R2H = -1.0, ZF = 0, NF = 1
            R2H, \#-1.0 ; R2H = -1.5, ZF = 1, NF = 0
MAXF32
```

See also

MAXF32 RaH, RbH

MAXF32 RaH, RbH || MOV32 RcH, RdH

MINF32 RaH, RbH MINF32 RaH, #16FHi



MAXF32 RaH, RbH ||MOV32 RcH, RdH 32-bit Floating-Point Maximum with Parallel Move

Operands

RaH	floating-point source/destination register for the MAXF32 operation (R0H to R7H) RaH cannot be the same register as RcH	
RbH	floating-point source register for the MAXF32 operation (R0H to R7H)	
RcH	floating-point destination register for the MOV32 operation (R0H to R7H) RcH cannot be the same register as RaH	
RdH	floating-point source register for the MOV32 operation (R0H to R7H)	

Opcode

LSW: 1110 0110 1001 1100 MSW: 0000 dddc ccbb baaa

Description

If RaH is less than RbH, then load RaH with RbH. Thus RaH will always have the maximum value. If RaH is less than RbH, then, in parallel, also load RcH with the contents of RdH.

```
if(RaH < RbH) { RaH = RbH; RcH = RdH; }</pre>
```

The MAXF32 instruction is performed as a logical compare operation. This is possible because of the IEEE floating-point format offsets the exponent. Basically the bigger the binary number, the bigger the floating-point value.

Special cases for the output from the MAXF32 operation:

- NaN output will be converted to infinity
- A denormalized output will be converted to positive zero.

Restrictions

The destination register for the MAXF32 and the MOV32 must be unique. That is, RaH cannot be the same register as RcH.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	Yes	Yes	No	No

The ZF and NF flags are configured on the result of the operation, not the result stored in the destination register.

```
if(RaH == RbH){ZF=1, NF=0}
if(RaH > RbH) {ZF=0, NF=0}
if(RaH < RbH) {ZF=0, NF=1}</pre>
```

Pipeline

This is a single-cycle instruction.

Example

```
MOVIZF32
             ROH, #5.0
                          ; ROH = 5.0 (0x40A00000)
  MOVIZF32
             R1H, #4.0
                         ; R1H = 4.0 (0x40800000)
  MOVIZF32 R2H, \#-1.5; R2H = -1.5 (0xBFC00000)
  MOVIZF32
             R3H, \#-2.0 ; R3H =-2.0 (0xC0000000)
             ROH, R1H
                         ; ROH = 5.0, R3H = -1.5, ZF = 0, NF = 0
  MAXF32
| MOV32
             R3H, R2H
  MAXF32
             R1H, R0H
                          ; R1H = 5.0, R3H = -1.5, ZF = 0, NF = 1
MOV32
             R3H, R2H
  MAXF32
             ROH, R1H
                          ; ROH = 5.0, R2H = -1.5, ZF = 1, NF = 0
| MOV32
             R2H, R1H
```

See also

MAXF32 RaH, RbH MAXF32 RaH, #16FHi



MINF32 RaH, RbH 32-bit Floating-Point Minimum

Operands

RaH	floating-point source/destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)

Opcode LSW: 1110 0110 1001 0111 MSW: 0000 0000 00bb baaa

Description if(RaH > RbH) RaH = RbH

Special cases for the output from the MINF32 operation:

- NaN output will be converted to infinity
- A denormalized output will be converted to positive zero.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	Yes	Yes	No	No

; R0H = 5.0 (0x40A00000)

The ZF and NF flags are configured on the result of the operation, not the result stored in the destination register.

 $if(RaH == RbH){ZF=1, NF=0}$ $if(RaH > RbH) \{ZF=0, NF=0\}$ $if(RaH < RbH) \{ZF=0, NF=1\}$

Pipeline

This is a single-cycle instruction.

Example MOVIZF32

```
ROH, #5.0
          R1H, #4.0 ; R1H = 4.0 (0x40800000)
R2H, #-1.5 ; R2H = -1.5 (0xBFC00000)
MOVIZF32
MOVIZF32
           ROH, R1H ; ROH = 4.0, ZF = 0, NF = 0
MINF32
           R1H, R2H; R1H = -1.5, ZF = 0, NF = 0
MINF32
MINF32
           R2H, R1H; R2H = -1.5, ZF = 1, NF = 0
           R1H, R0H ; R2H = -1.5, ZF = 0, NF = 1
MINF32
```

See also

MAXF32 RaH, RbH MAXF32 RaH, #16FHi MINF32 RaH, #16FHi

MINF32 RaH, RbH | MOV32 RcH, RdH



MINF32 RaH, #16FHi 32-bit Floating-Point Minimum

Operands

RaH	floating-point source/destination register (R0H to R7H)
#16FHi	A 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0.

Opcode

LSW: 1110 1000 0011 0III MSW: IIII IIII IIII Iaaa

Description

Compare RaH with the floating-point value represented by the immediate operand. If the immidate value is smaller, then load it into RaH.

```
if(RaH > #16FHi:0) RaH = #16FHi:0
```

#16FHi is a 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0. This addressing mode is most useful for constants where the lowest 16-bits of the mantissa are 0. Some examples are 2.0 (0x40000000), 4.0 (0x40800000), 0.5 (0x3F000000), and -1.5 (0xBFC00000). The assembler will accept either a hex or float as the immediate value. That is, -1.5 can be represented as #-1.5 or #0xBFC0.

Special cases for the output from the MINF32 operation:

- NaN output will be converted to infinity
- A denormalized output will be converted to positive zero.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	Yes	Yes	No	No	

The ZF and NF flags are configured on the result of the operation, not the result stored in the destination register.

```
if(RaH == #16FHi:0) {ZF=1, NF=0}
if(RaH > #16FHi:0) {ZF=0, NF=0}
if(RaH < #16FHi:0) {ZF=0, NF=1}</pre>
```

Pipeline

This is a single-cycle instruction.

Example

```
MOVIZF32
            ROH, #5.0
                         ; ROH = 5.0 (0x40A00000)
                         ; R1H = 4.0 (0x40800000)
MOVIZF32
            R1H, #4.0
                        ; R1H = 4.0 (0xBFC00000)
; R2H = -1.5 (0xBFC00000)
MOVIZF32
            R2H, #-1.5
                         ; ROH = 5.0, ZF = 0, NF = 1
MINF32
            ROH, #5.5
           R1H, #2.5 ; R1H = 2.5, ZF = 0, NF = 0
MINF32
MINF32
            R2H, \#-1.0; R2H = -1.5, ZF = 0, NF = 1
            R2H, \#-1.5; R2H = -1.5, ZF = 1, NF = 0
MINF32
```

See also

MAXF32 RaH, #16FHi MAXF32 RaH, RbH MINF32 RaH, RbH

MINF32 RaH, RbH | MOV32 RcH, RdH



MINF32 RaH, RbH || MOV32 RcH, RdH 32-bit Floating-Point Minimum with Parallel Move

Operands

RaH	floating-point source/destination register for the MIN32 operation (R0H to R7H) RaH cannot be the same register as RcH	
RbH	floating-point source register for the MIN32 operation (R0H to R7H)	
RcH	floating-point destination register for the MOV32 operation (R0H to R7H) RcH cannot be the same register as RaH	
RdH	floating-point source register for the MOV32 operation (R0H to R7H)	

Opcode

```
LSW: 1110 0110 1001 1101 MSW: 0000 dddc ccbb baaa
```

Description

```
if(RaH > RbH) { RaH = RbH; RcH = RdH; }
```

Special cases for the output from the MINF32 operation:

- NaN output will be converted to infinity
- A denormalized output will be converted to positive zero.

Restrictions

The destination register for the MINF32 and the MOV32 must be unique. That is, RaH cannot be the same register as RcH.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	Yes	Yes	No	No

The ZF and NF flags are configured on the result of the operation, not the result stored in the destination register.

```
if(RaH == RbH){ZF=1, NF=0}
if(RaH > RbH) {ZF=0, NF=0}
if(RaH < RbH) {ZF=0, NF=1}</pre>
```

Pipeline

This is a single-cycle instruction.

Example

```
MOVIZF32
             ROH, #5.0
                         ; ROH = 5.0 (0x40A00000)
  MOVIZF32
             R1H, #4.0
                         ; R1H = 4.0 (0x40800000)
  MOVIZF32
             R2H, #-1.5
                         ; R2H = -1.5 (0xBFC00000)
             R3H, #-2.0
  MOVIZF32
                         ; R3H = -2.0 (0xC0000000)
  MINF32
             ROH, R1H
                         ; ROH = 4.0, R3H = -1.5, ZF = 0, NF = 0
| MOV32
             R3H, R2H
             R1H, R0H
                         ; R1H = 4.0, R3H = -1.5, ZF = 1, NF = 0
  MINF32
MOV32
             R3H, R2H
  MINF32
             R2H, R1H
                         ; R2H = -1.5, R1H = 4.0, ZF = 1, NF = 1
| MOV32
             R1H, R3H
```

See also

MINF32 RaH, RbH MINF32 RaH, #16FHi



MOV16 mem16, RaH Move 16-bit Floating-Point Register Contents to Memory

Operands

mem16 points to the 16-bit destination memory

RaH floating-point source register (R0H to R7H)

Opcode LSW: 1110 0010 0001 0011 MSW: 0000 0aaa mem16

Description Move 16-bit value from the lower 16-bits of the floating-point register (RaH[15:0]) to the

location pointed to by mem16.

[mem16] = RaH[15:0]

Flags No flags STF flags are affected.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline This is a single-cycle instruction.

Example MOVW DP, #0x02C0; DP = 0x02C0

MOVXI R4H, #0x0003; R4H = 3.0 (0x0003)

MOV16 @0, R4H ; [0x00B000] = 3.0 (0x0003

See also MOVIZ RaH, #16FHiHex

MOVIZF32 RaH, #16FHi MOVXI RaH, #16FLoHex



MOV32 *(0:16bitAddr), loc32 Move the Contents of loc32 to Memory

Operands

0:16bitAddr 16-bit immediate address, zero extended

loc32 32- bit source location

Opcode LSW: 1011 1101 loc32 MSW: IIII IIII IIII IIII

Description Move the 32-bit value in loc32 to the memory location addressed by 0:16bitAddr. The

EALLOW bit in the ST1 register is ignored by this operation.

[0:16bitAddr] = [loc32]

Flags This instruction does not modify any STF register flags.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline This is a two-cycle instruction.

Example MOVIZ R5H, #0x1234 ; R5H[31:16] = 0x1234

MOVXI R5H, #0xABCD ; R5H[15:0] = 0xABCD NOP ; 1 Alignment Cycle MOV32 ACC, R5H ; ACC = 0x1234ABCD MOV32 *(0xA000), @ACC ; [0x00A000] = ACC NOP

; 1 Cycle delay for MOV32 to complete
; <-- MOV32 *(0:16bitAddr), loc32 complete,
; [0x00A000] = 0xABCD, [0x00A001] = 0x1234</pre>

See also MOV32 mem32, RaH

MOV32 mem32, STF

MOV32 loc32, *(0:16bitAddr)



MOV32 ACC, RaH Move 32-bit Floating-Point Register Contents to ACC

Operands

Description

accumulator
֡

RaH floating-point source register (R0H to R7H)

Opcode LSW: 1011 1111 10c32 MSW: IIII IIII IIII IIII

If the condition is true, then move the 32-bit value referenced by mem32 to the floating-

point register indicated by RaH.

ACC = RaH

Flags No STF flags are affected.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Z and N flag in status register zero (ST0) of the 28x CPU are affected.

Pipeline

While this is a single-cycle instruction, additional pipeline alignment is required when copying a floating-point register to a C28x register. If the move follows a single cycle floating point instruction, a single alignment cycle must be added. For example:

```
MINF32 ROH,R1H; Single-cycle instruction NOP; 1 alignment cycle MOV32 @ACC,R0H; Copy ROH to ACC NOP; Any instruction
```

If the move follows a 2 pipeline-cycle floating point instruction, then two alignment cycles must be used. For example:

```
ADDF32 R2H, R1H, R0H; 2 pipeline instruction (2p)

NOP; 1 cycle delay for ADDF32 to complete
; <-- ADDF32 completes, R2H is valid

NOP; 1 alignment cycle MOV32 ACC, R2H; copy R2H into ACC, takes 2 cycles
; <-- MOV32 completes, ACC is valid

NOP; Any instruction
```

Example

ADDF32 R2H, R1H, R0H; 2 pipeline instruction (2p)

NOP ; 1 cycle delay for ADDF32 to complete ; < -- ADDF32 completes, R2H is valid

NOP ; 1 alignment cycle

MOV32 ACC, R2H ; copy R2H into ACC, takes 2 cycles ; <-- MOV32 completes, ACC is valid

NOP ; Any instruction

MOVIZF32 R0H, #2.5 ; R0H = 2.5 = 0x40200000

F32TOUI32 R0H, R0H

NOP ; Delay for conversion instruction ; < -- Conversion complete, ROH valid

NOP ; Alignment cycle MoV32 P, R0H ; $P = 2 = 0 \times 000000002$

See also

MOV32 P, RaH MOV32 XARn, RaH MOV32 XT, RaH



MOV32 loc32, *(0:16bitAddr) Move 32-bit Value from Memory to loc32

Operands

loc32 destination location

0:16bitAddr 16-bit address of the 32-bit source value

Opcode LSW: 1011 1111 loc32
MSW: IIII IIII IIII IIII

Description Copy the 32-bit value referenced by 0:16bitAddr to the location indicated by loc32.

[loc32] = [0:16bitAddr]

Flags No STF flags are affected. If loc32 is the ACC register, then the Z and N flag in status

register zero (ST0) of the 28x CPU are affected.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline This is a 2 cycle instruction.

Example MOVW DP, #0x0300 ; DP = 0x0300

MOV @0, #0xFFFF ; [0x00C000] = 0xFFFF;MOV @1, #0x1111 ; [0x00C001] = 0x1111;

MOV32 @ACC, *(0xC000); AL = [0x00C000], AH = [0x00C001] NOP ; 1 Cycle delay for MOV32 to complete ; <-- MOV32 complete, AL = 0xFFFF, AH = 0x1111

See also MOV32 RaH, mem32{, CNDF}

MOV32 *(0:16bitAddr), loc32

MOV32 STF, mem32 MOVD32 RaH, mem32



MOV32 mem32, RaH Move 32-bit Floating-Point Register Contents to Memory

Operands

RaH	floating-point register (R0H to R7H)
mem32	points to the 32-bit destination memory

Opcode LSW: 1110 0010 0000 0011 MSW: 0000 0aaa mem32

Description Move from memory to STF.

[mem32] = RaH

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

No flags affected.

Pipeline

This is a single-cycle instruction.

Example

```
Perform 5 multiply and accumulate operations:
   1st multiply: A = X0 * Y0
   2nd multiply: B = X1 * Y1
   3rd multiply: C = X2 * Y2
   4th multiply: D = X3 * Y3
   5th multiply: E = X3 * Y3
   Result = A + B + C + D + E
   MOV32 R0H, *XAR4++
                                ; R0H = X0
   MOV32 R1H, *XAR5++
                                ; R1H = Y0
                                 ; R6H = A = X0 * Y0
   MPYF32 R6H, R0H, R1H
                                 ; In parallel ROH = X1
| MOV32 ROH, *XAR4++
   MOV32 R1H, *XAR5++
                                ; R1H = Y1
                                ; R7H = B = X1 * Y1
   MPYF32 R7H, R0H, R1H
                                ; In parallel ROH = X2
| MOV32 R0H, *XAR4++
   MOV32 R1H, *XAR5++
                                 ; R1H = Y2
                                 ; R7H = A + B
                                 ; R6H = C = X2 * Y2
   MACF32 R7H, R6H, R6H, R0H, R1H; In parallel R0H = X3
|| MOV32 R0H, *XAR4++
   MOV32 R1H, *XAR5++
                                ; R1H = Y3
                                 ; R3H = (A + B) + C
                                 ; R6H = D = X3 * Y3
   MACF32 R7H, R6H, R6H, R0H, R1H; In parallel R0H = X4
|| MOV32 ROH, *XAR4
   MOV32 R1H, *XAR5
                                 ; R1H = Y4
                                ; R6H = E = X4 * Y4
   MPYF32 R6H, R0H, R1H
                                 ; in parallel R7H = (A + B + C) + D
|| ADDF32 R7H, R7H, R2H
                                 ; Wait for MPYF32 | ADDF32 to complete
```



ADDF32 R7H, R7H, R6H

; R7H = (A + B + C + D) + E NOP

; Wait for ADDF32 to complete

MOV32 @Result, R7H

; Store the result

See also

MOV32 *(0:16bitAddr), loc32

MOV32 mem32, STF



MOV32 mem32, STF Move 32-bit STF Register to Memory

Operands

STF floating-point status register
mem32 points to the 32-bit destination memory

Opcode LSW: 1110 0010 0000 0000 MSW: 0000 0000 mem32

Description Copy the floating-point status register, STF, to memory.

[mem32] = STF

Flags This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

No flags affected.

Pipeline This is a single-cycle instruction.

Example 1 MOVW DP, #0x0280; DP = 0x0280

MOVIZF32 R0H, #2.0 ; R0H = 2.0 (0x40000000) MOVIZF32 R1H, #3.0 ; R1H = 3.0 (0x40400000)

CMPF32 R0H, R1H ; ZF = 0, NF = 1, STF = 0x00000004

MOV32 @0, STF ; [0x00A000] = 0x00000004

Example 2

CMPF32 R2H, R3H ; ZF = 0, NF = 1, STF = 0x00000004

MOV32 R3H, R2H, LT ; R3H = 3.0 (0x40400000) MOV32 STF, *--SP ; Restore STF from stack

See also MOV32 mem32, RaH

MOV32 *(0:16bitAddr), loc32

MOVSTO FLAG



MOV32 P, RaH Move 32-bit Floating-Point Register Contents to P

Operands

P 28x product register P

RaH floating-point source register (R0H to R7H)

Opcode LSW: 1011 1111 loc32
MSW: IIII IIII IIII IIII

Description Move the 32-bit value in RaH to the 28x product register P.

P = RaH

Flags No flags affected in floating-point unit.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	_

Pipeline

While this is a single-cycle instruction, additional pipeline alignment is required when copying a floating-point register to a C28x register. If the move follows a single cycle floating point instruction, a single alignment cycle must be added. For example:

MINF32 ROH,RlH ; Single-cycle instruction NOP ; 1 alignment cycle MOV32 @ACC,ROH ; Copy ROH to ACC NOP ; Any instruction

If the move follows a 2 pipeline-cycle floating point instruction, then two alignment cycles must be used. For example:

ADDF32 R2H, R1H, R0H ; 2 pipeline instruction (2p)

NOP ; 1 cycle delay for ADDF32 to complete ; <-- ADDF32 completes, R2H is valid

NOP ; 1 alignment cycle

MOV32 ACC, R2H ; copy R2H into ACC, takes 1 cycle

; <-- MOV32 completes, ACC is valid NOP; Any instruction

Example MOVIZF32 R0H, #2.5 ; R0H = 2.5 = 0x40200000

F32TOUI32 ROH, ROH

NOP ; Delay for conversion instruction ; <-- Conversion complete, ROH valid

NOP ; Alignment cycle MoV32 P, R0H ; P = 2 = 0x000000002

See also MOV32 ACC, RaH

MOV32 XARn, RaH MOV32 XT, RaH



MOV32 RaH, ACC Move the Contents of ACC to a 32-bit Floating-Point Register

Operands

RaH floating-point destination register (R0H to R7H)

ACC accumulator

Opcode LSW: 1011 1101 10c32

MSW: IIII IIII IIII IIII

Description Move the 32-bit value in ACC to the floating-point register RaH.

RaH = ACC

Flags This instruction does not modify any STF register flags.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	_

Pipeline

While this is a single-cycle instruction, additional pipeline alignment is required. Four alignment cycles are required after any copy from a standard 28x CPU register to a floating-point register. The four alignment cycles can be filled with any non-conflicting instructions except for the following: FRACF32, UI16TOF32, I16TOF32, F32TOUI32, and F32TOI32.

MOV32 R0H,@ACC ; Copy ACC to R0H NOP ; Wait 4 cycles

NOP ; Do not use FRACF32, UI16TOF32 NOP ; I16TOF32, F32TOUI32 or F32TOI32

NOP

; <-- ROH is valid

Example MOV AH, #0x0000

MOV AL, #0x0200 ; ACC = 512

MOV32 ROH, ACC

NOP NOP

NOP UI32TOF32 ROH, ROH ; ROH = 512.0 (0x44000000)

See also MOV32 RaH, P

MOV32 RaH, XARn MOV32 RaH, XT



MOV32 RaH, mem32 {, CNDF} Conditional 32-bit Move

Operands

RaH	floating-point destination register (R0H to R7H)
mem32	pointer to the 32-bit source memory location
CNDF	optional condition.

Opcode

```
LSW: 1110 0010 1010 CNDF
MSW: 0000 0aaa mem32
```

Description

If the condition is true, then move the 32-bit value referenced by mem32 to the floating-point register indicated by RaH.

```
if (CNDF == TRUE) RaH = [mem32]
```

CNDF is one of the following conditions:

Encode (1)	CNDF	Description	STF Flags Tested
0000	NEQ	Not equal to zero	ZF == 0
0001	EQ	Equal to zero	ZF == 1
0010	GT	Greater than zero	ZF == 0 AND NF == 0
0011	GEQ	Greater than or equal to zero	NF == 0
0100	LT	Less than zero	NF == 1
0101	LEQ	Less than or equal to zero	ZF == 1 AND NF == 1
1010	TF	Test flag set	TF == 1
1011	NTF	Test flag not set	TF == 0
1100	LU	Latched underflow	LUF == 1
1101	LV	Latched overflow	LVF == 1
1110	UNC	Unconditional	None
1111	UNCF (2)	Unconditional with flag modification	None

⁽¹⁾ Values not shown are reserved.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	Yes	Yes	Yes	Yes	No	No	

```
if(CNDF == UNCF)
{
  NF = RaH(31); ZF = 0;
  if(RaH[30:23] == 0) { ZF = 1; NF = 0; } NI = RaH[31]; ZI = 0;
  if(RaH[31:0] == 0) ZI = 1;
}
else No flags modified;
```

Pipeline

This is a single-cycle instruction.

This is the default operation if no CNDF field is specified. This condition will allow the ZF, NF, ZI, and NI flags to be modified when a conditional operation is executed. All other conditions will not modify these flags.





Example	MOVW	DP, #	0x0300	;	DP = 0x0300			
	MOV	@0,#	#0x5555	;	[0x00C000] = 0x5555			
	MOV	@1, #	#0x5555	;	[0x00C001] = 0x5555			
	MOVIZF32	R3H,	#7.0	;	R3H = 7.0 (0x40E00000)			
	MOVIZF32	R4H,	#7.0	;	R4H = 7.0 (0x40E00000)			
	MAXF32	RЗH,	R4H	;	ZF = 1, $NF = 0$			
	MOV32	R1H,	@0, EQ	;	R1H = 0x55555555			
See also	MOV32 F				DF}			
	MOVD32 RaH, mem32							



MOV32 RaH, P Move the Contents of P to a 32-bit Floating-Point Register

Operands

RaH floating-point register (R0H to R7H)
P product register

Opcode

LSW: 1011 1101 loc32 MSW: IIII IIII IIII IIII

Description

Move the 32-bit value in the product register, P, to the floating-point register RaH.

RaH = P

Flags

This instruction does not modify any STF register flags.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline

While this is a single-cycle instruction, additional pipeline alignment is required. Four alignment cycles are required after any copy from a standard 28x CPU register to a floating-point register. The four alignment cycles can be filled with any non-conflicting instructions except for the following: FRACF32, UI16TOF32, I16TOF32, F32TOUI32, and F32TOI32.

```
MOV32 ROH,@P ; Copy P to ROH

NOP ; Wait 4 alignment cycles

NOP ; Do not use FRACF32, UI16TOF32

NOP ; I16TOF32, F32TOUI32 or F32TOI32

NOP ;

; <-- ROH is valid
```

; Instruction can use ROH as a source

Example MOV PH, #0x0000

MOV PL, #0x0200 ; P = 512

MOV32 ROH, P

NOP NOP NOP

UI32TOF32 R0H, R0H ; R0H = 512.0 (0x44000000)

See also MOV32 RaH, ACC

MOV32 RaH, XARn MOV32 RaH, XT



MOV32 RaH, RbH {, CNDF} Conditional 32-bit Move

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)
CNDF	optional condition.

Opcode

LSW: 1110 0110 1100 CNDF MSW: 0000 0000 00bb baaa

Description

If the condition is true, then move the 32-bit value referenced by mem32 to the floating-point register indicated by RaH.

if (CNDF == TRUE) RaH = RbH

CNDF is one of the following conditions:

Encode (1)	CNDF	Description	STF Flags Tested
0000	NEQ	Not equal to zero	ZF == 0
0001	EQ	Equal to zero	ZF == 1
0010	GT	Greater than zero	ZF == 0 AND NF == 0
0011	GEQ	Greater than or equal to zero	NF == 0
0100	LT	Less than zero	NF == 1
0101	LEQ	Less than or equal to zero	ZF == 1 AND NF == 1
1010	TF	Test flag set	TF == 1
1011	NTF	Test flag not set	TF == 0
1100	LU	Latched underflow	LUF == 1
1101	LV	Latched overflow	LVF == 1
1110	UNC	Unconditional	None
1111	UNCF (2)	Unconditional with flag modification	None

⁽¹⁾ Values not shown are reserved.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	Yes	Yes	Yes	Yes	No	No

```
 \begin{split} & \text{if}(\text{CNDF} == \text{UNCF}) \; \big\{ \; \text{NF} = \text{RaH}(31) \, ; \; \text{ZF} = 0 \, ; \\ & \text{if}(\text{RaH}[30:23] == 0) \; \big\{ \text{ZF} = 1 \, ; \; \text{NF} = 0 \, ; \big\} \; \text{NI} = \text{RaH}(31) \, ; \; \text{ZI} = 0 \, ; \\ & \text{if}(\text{RaH}[31:0] == 0) \; \text{ZI} = 1 \, ; \; \big\} \; \text{else No flags modified} \, ; \\ \end{aligned}
```

Pipeline

This is a single-cycle instruction.

Example MOVIZF32 R3H, #8.0 ; R3H = 8.0 (0x41000000) MOVIZF32 R4H, #7.0 ; R4H = 7.0 (0x40E00000) MAXF32 R3H, R4H ; ZF = 0, NF = 0 MOV32 R1H, R3H, GT; R1H = 8.0 (0x41000000)

See also

MOV32 RaH, mem32{, CNDF}

This is the default operation if no CNDF field is specified. This condition will allow the ZF, NF, ZI, and NI flags to be modified when a conditional operation is executed. All other conditions will not modify these flags.



MOV32 RaH, XARn Move the Contents of XARn to a 32-bit Floating-Point Register

Operands

RaH floating-point register (R0H to R7H)

XARn auxiliary register (XAR0 - XAR7)

Opcode LSW: 1011 1101 10c32

MSW: IIII IIII IIII IIII

Description Move the 32-bit value in the auxiliary register XARn to the floating point register RaH.

RaH = XARn

Flags This instruction does not modify any STF register flags.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	_

Pipeline

While this is a single-cycle instruction, additional pipeline alignment is required. Four alignment cycles are required after any copy from a standard 28x CPU register to a floating-point register. The four alignment cycles can be filled with any non-conflicting instructions except for the following: FRACF32, UI16TOF32, I16TOF32, F32TOUI32, and F32TOI32.

MOV32 R0H,@XAR7 ; Copy XAR7 to R0H NOP ; Wait 4 alignment cycles NOP ; Do not use FRACF32, UI16TOF32 NOP ; I16TOF32, F32TOUI32 or F32TOI32 NOP ;

OP ,

; <-- ROH is valid

ADDF32 R2H,R1H ,R0H ; Instruction can use R0H as a source

Example MOVL XAR1, #0x0200; XAR1 = 512

MOV32 ROH, XAR1

NOP NOP NOP

UI32TOF32 R0H, R0H; R0H = 512.0 (0x44000000)

See also MOV32 RaH, ACC

MOV32 RaH, P MOV32 RaH, XT



MOV32 RaH, XT Move the Contents of XT to a 32-bit Floating-Point Register

Operands

RaH floating-point register (R0H to R7H)
XT auxiliary register (XAR0 - XAR7)

Opcode LSW: 1011 1101 10c32

MSW: IIII IIII IIII IIII

Description Move the 32-bit value in temporary register, XT, to the floating-point register RaH.

RaH = XT

Flags This instruction does not modify any STF register flags.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No

Pipeline

While this is a single-cycle instruction, additional pipeline alignment is required. Four alignment cycles are required after any copy from a standard 28x CPU register to a floating-point register. The four alignment cycles can be filled with any non-conflicting instructions except for the following: FRACF32, UI16TOF32, I16TOF32, F32TOUI32, and F32TOI32.

MOV32 R0H, XT ; Copy XT to R0H NOP ; Wait 4 alignment cycles NOP ; Do not use FRACF32, UI16TOF32 NOP ; I16TOF32, F32TOUI32 or F32TOI32 NOP ;

ADDF32 R2H,R1H,R0H; Instruction can use R0H as a sourc

; <-- ROH is valid

Example MOVIZF32 R6H, #5.0 ; R6H = 5.0 (0x40A00000)

NOP ; 1 Alignment cycle

MOV32 XT, R6H ; XT = 5.0 (0x40A00000)MOV32 R1H, XT ; R1H = 5.0 (0x40A00000)

See also MOV32 RaH, ACC

MOV32 RaH, P MOV32 RaH, XARn



MOV32 STF, mem32 Move 32-bit Value from Memory to the STF Register

Operands

STF floating-point unit status register
mem32 pointer to the 32-bit source memory location

Opcode

LSW: 1110 0010 1000 0000 MSW: 0000 0000 mem32

Description Move from memory to the floating-point unit's status register STF.

STF = [mem32]

Flags This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	Yes							

Restoring status register will overwrite all flags.

Pipeline This is a single-cycle instruction.

Example 1 MOVW DP, #0x0300 ; DP = 0x0300

MOV @2, #0x020C ; [0x00C002] = 0x020CMOV @3, #0x0000 ; [0x00C003] = 0x0000MOV32 STF, @2 ; STF = 0x0000020C

MOVF32 R2H, #3.0 ; R2H = 3.0 (0x40400000) MOVF32 R3H, #5.0 ; R3H = 5.0 (0x40A00000)

CMPF32 R2H, R3H ; ZF = 0, NF = 1, STF = 0x00000004

MOV32 R3H, R2H, LT ; R3H = 3.0 (0x40400000) MOV32 STF, *--SP ; Restore STF from stack

See also MOV32 mem32, STF

MOVST0 FLAG



MOV32 XARn, RaH Move 32-bit Floating-Point Register Contents to XARn

Operands

XARn 28x auxiliary register (XAR0 - XAR7)

RaH floating-point source register (R0H to R7H)

Opcode LSW: 1011 1111 10c32

MSW: IIII IIII IIII IIII

Description Move the 32-bit value from the floating-point register RaH to the auxiliary register XARn.

XARn = RaH

Flags No flags affected in floating-point unit.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline

While this is a single-cycle instruction, additional pipeline alignment is required when copying a floating-point register to a C28x register. If the move follows a single cycle floating point instruction, a single alignment cycle must be added. For example:

MINF32 ROH,R1H ; Single-cycle instruction NOP ; 1 alignment cycle MOV32 @ACC,R0H ; Copy ROH to ACC NOP ; Any instruction

If the move follows a 2 pipeline-cycle floating point instruction, then two alignment cycles must be used. For example:

ADDF32 R2H, R1H, R0H ; 2 pipeline instruction (2p)

NOP ; 1 cycle delay for ADDF32 to complete ; <-- ADDF32 completes, R2H is valid

NOP ; 1 alignment cycle

MOV32 ACC, R2H ; copy R2H into ACC, takes 1 cycle ; <-- MOV32 completes, ACC is valid

NOP ; Any instruction

Example MOVIZF32 R0H, #2.5 ; R0H = 2.5 = 0x40200000

F32TOUI32 R0H, R0H

NOP ; Delay for conversion instruction ; <-- Conversion complete, ROH valid

NOP ; Alignment cycle

MOV32 XAR0, R0H ; XAR0 = $2 = 0 \times 00000002$

See also MOV32 ACC, RaH

MOV32 P, RaH MOV32 XT, RaH



MOV32 XT, RaH Move 32-bit Floating-Point Register Contents to XT

Operands

XT temporary register

RaH floating-point source register (R0H to R7H)

Opcode

LSW: 1011 1111 loc32 MSW: IIII IIII IIII IIII

Description

Move the 32-bit value in RaH to the temporary register XT.

XT = RaH

Flags

No flags affected in floating-point unit.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline

While this is a single-cycle instruction, additional pipeline alignment is required when copying a floating-point register to a C28x register. If the move follows a single cycle floating point instruction, a single alignment cycle must be added. For example:

```
MINF32 R0H,R1H ; Single-cycle instruction
NOP ; 1 alignment cycle
MOV32 @XT,R0H ; Copy R0H to ACC NOP
; Any instruction
```

If the move follows a 2 pipeline-cycle floating point instruction, then two alignment cycles must be used. For example:

```
ADDF32 R2H, R1H, R0H ; 2 pipeline instruction (2p)

NOP ; 1 cycle delay for ADDF32 to complete
; <-- ADDF32 completes, R2H is valid

NOP ; 1 alignment cycle
MOV32 XT, R2H ; copy R2H into ACC, takes 1 cycle
; <-- MOV32 completes, ACC is valid

NOP ; Any instruction
```

Example

MOVIZF32 R0H, #2.5 ; R0H = 2.5 = 0x40200000

F32TOUI32 ROH, ROH

NOP ; Delay for conversion instruction ; <-- Conversion complete, ROH valid

See also

MOV32 ACC, RaH MOV32 P, RaH MOV32 XARn, RaH



MOVD32 RaH, mem32 Move 32-bit Value from Memory with Data Copy

Operands

RaH	floating-point register (R0H to R7H)
mem32	pointer to the 32-bit source memory location

Opcode LSW: 1110 0010 0010 0011 MSW: 0000 0aaa mem32

Description Move the 32-bit value referenced by mem32 to the floating-point register indicated by

RaH.

RaH = [mem32] [mem32+2] = [mem32]

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	Yes	Yes	Yes	Yes	No	No

```
NF = RaH[31];
    ZF = 0;
    if(RaH[30:23] == 0){          ZF = 1;          NF = 0;     }
    NI = RaH[31];
    ZI = 0;
    if(RaH[31:0] == 0)     ZI = 1;
```

Pipeline This is a single-cycle instruction.

Example MOVW DP, #0x02C0; DP = 0x02C0

MOV @2, #0x0000 ; [0x00B002] = 0x0000 MOV @3, #0x4110 ; [0x00B003] = 0x4110 MOVD32 R7H, @2 ; R7H = 0x41100000,

; [0x00B004] = 0x0000, [0x00B005] = 0x4110

See also

MOV32 RaH, mem32 {,CNDF}



MOVF32 RaH, #32F Load the 32-bits of a 32-bit Floating-Point Register

Operands

This instruction is an alias for MOVIZ and MOVXI instructions. The second operand is translated by the assembler such that the instruction becomes:

MOVIZ RaH, #16FHiHex MOVXI RaH, #16FLoHex

RaH	floating-point destination register (R0H to R7H)
#32F	immediate float value represented in floating-point representation

Opcode

```
LSW: 1110 1000 0000 0III (opcode of MOVIZ RaH, #16FHiHex)
MSW: IIII IIII IIII Iaaa

LSW: 1110 1000 0000 1III (opcode of MOVXI RaH, #16FLoHex)
MSW: IIII IIII IIII Iaaa
```

Description

Note: This instruction accepts the immediate operand only in floating-point representation. To specify the immediate value as a hex value (IEEE 32-bit floating-point format) use the MOVI32 RaH, #32FHex instruction.

Load the 32-bits of RaH with the immediate float value represented by #32F.

#32F is a float value represented in floating-point representation. The assembler will only accept a float value represented in floating-point representation. That is, 3.0 can only be represented as #3.0. #0x40400000 will result in an error.

RaH = #32F

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No

Pipeline

Depending on #32FH, this instruction takes one or two cycles. If all of the lower 16-bits of the IEEE 32-bit floating-point format of #32F are zeros, then the assembler will convert MOVF32 into only MOVIZ instruction. If the lower 16-bits of the IEEE 32-bit floating-point format of #32F are not zeros, then the assembler will convert MOVF32 into MOVIZ and MOVXI instructions.

Example

```
MOVF32 R1H, #3.0 ; R1H = 3.0 (0x40400000)
; Assembler converts this instruction as
; MOVIZ R1H, #0x4040

MOVF32 R2H, #0.0 ; R2H = 0.0 (0x00000000)
; Assembler converts this instruction as
; MOVIZ R2H, #0x0

MOVF32 R3H, #12.265 ; R3H = 12.625 (0x41443D71)
; Assembler converts this instruction as
; MOVIZ R3H, #0x4144
; MOVXI R3H, #0x4144
; MOVXI R3H, #0x3D71
```

See also

MOVIZ RaH, #16FHiHex MOVXI RaH, #16FLoHex MOVI32 RaH, #32FHex MOVIZF32 RaH, #16FHi



MOVI32 RaH, #32FHex Load the 32-bits of a 32-bit Floating-Point Register with the immediate

Operands

This instruction is an alias for MOVIZ and MOVXI instructions. The second operand is translated by the assembler such that the instruction becomes:

MOVIZ RaH, #16FHiHex
MOVXI RaH, #16FLoHex

RaH	floating-point register (R0H to R7H)
#32FHex	A 32-bit immediate value that represents an IEEE 32-bit floating-point value.

Opcode

```
LSW: 1110 1000 0000 0III (opcode of MOVIZ Rah, #16FHiHex)
MSW: IIII IIII IIII Iaaa

LSW: 1110 1000 0000 1III (opcode of MOVXI Rah, #16FLoHex)
MSW: IIII IIII IIII IIII Iaaa
```

Description

Note: This instruction only accepts a hex value as the immediate operand. To specify the immediate value with a floating-point representation use the MOVF32 RaH, #32F instruction.

Load the 32-bits of RaH with the immediate 32-bit hex value represented by #32Fhex.

#32Fhex is a 32-bit immediate hex value that represents the IEEE 32-bit floating-point value of a floating-point number. The assembler will only accept a hex immediate value. That is, 3.0 can only be represented as #0x40400000. #3.0 will result in an error.

RaH = #32FHex

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline

Depending on #32FHex, this instruction takes one or two cycles. If all of the lower 16-bits of #32FHex are zeros, then assembler will convert MOVI32 to the MOVIZ instruction. If the lower 16-bits of #32FHex are not zeros, then assembler will convert MOVI32 to a MOVIZ and a MOVXI instruction.

Example

```
MOVI32 R1H, #0x40400000 ; R1H = 0x40400000 ; Assembler converts this instruction as ; MOVIZ R1H, #0x4040 MOVI32 R2H, #0x00000000 ; R2H = 0x00000000 ; Assembler converts this instruction as ; MOVIZ R2H, #0x0 MOVI32 R3H, #0x40004001 ; R3H = 0x40004001 ; Assembler converts this instruction as ; MOVIZ R3H, #0x4000 ; MOVIX R3H, #0x4001 MOVI32 R4H, #0x00004040 ; R4H = 0x00004040 ; Assembler converts this instruction as ; MOVIZ R4H, #0x0000 ; MOVXI R4H, #0x4040
```

See also

MOVIZ RaH, #16FHiHex MOVXI RaH, #16FLoHex MOVF32 RaH, #32F MOVIZF32 RaH, #16FHi



MOVIZ RaH, #16FHiHex Load the Upper 16-bits of a 32-bit Floating-Point Register

Operands

RaH	floating-point register (R0H to R7H)
#16FHiHex	A 16-bit immediate hex value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0.

Opcode

LSW: 1110 1000 0000 0III MSW: IIII IIII IIII Iaaa

Description

Note: This instruction only accepts a hex value as the immediate operand. To specify the immediate value with a floating-point representation use the MOVIZF32 pseudo instruction.

Load the upper 16-bits of RaH with the immediate value #16FHiHex and clear the low 16-bits of RaH.

#16FHiHex is a 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0. The assembler will only accept a hex immediate value. That is, -1.5 can only be represented as #0xBFC0. #-1.5 will result in an error.

By itself, MOVIZ is useful for loading a floating-point register with a constant in which the lowest 16-bits of the mantissa are 0. Some examples are 2.0 (0x4000000), 4.0 (0x40800000), 0.5 (0x3F000000), and -1.5 (0xBFC00000). If a constant requires all 32-bits of a floating-point register to be initialized, then use MOVIZ along with the MOVXI instruction.

Rah[31:16] = #16FHiHexRah[15:0] = 0

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline

This is a single-cycle instruction.

Example

; Load R0H with -1.5 (0xBFC00000)

MOVIZ R0H, #0xBFC0; R0H = 0xBFC00000

; Load R0H with pi = 3.141593 (0x40490FDB) MOVIZ R0H, #0x4049 ; R0H = 0x40490000 MOVXI R0H, #0x0FDB ; R0H = 0x40490FDB

See also

MOVIZF32 RaH, #16FHi MOVXI RaH, #16FLoHex



MOVIZF32 RaH, #16FHi Load the Upper 16-bits of a 32-bit Floating-Point Register

Operands

RaH	floating-point register (R0H to R7H)
#16FHi	A 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0.

Opcode

```
LSW: 1110 1000 0000 0III MSW: IIII IIII IIII Iaaa
```

Description

Load the upper 16-bits of RaH with the value represented by #16FHi and clear the low 16-bits of RaH.

#16FHi is a 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0. This addressing mode is most useful for constants where the lowest 16-bits of the mantissa are 0. Some examples are 2.0 (0x40000000), 4.0 (0x40800000), 0.5 (0x3F000000), and -1.5 (0xBFC00000). #16FHi can be specified in hex or float. That is, -1.5 can be represented as #-1.5 or #0xBFC0.

MOVIZF32 is an alias for the MOVIZ RaH, #16FHiHex instruction. In the case of MOVIZF32 the assembler will accept either a hex or float as the immediate value and encodes it into a MOVIZ instruction. For example, MOVIZF32 RaH, #-1.5 will be encoded as MOVIZ RaH, 0xBFC0.

```
RaH[31:16] = #16FHi
RaH[15:0] = 0
```

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline

This is a single-cycle instruction.

Example

```
; ROH = 3.0 = 0x40400000
MOVIZF32 R0H, #3.0
MOVIZF32 R1H, #1.0
                         ; R1H = 1.0 = 0x3F800000
MOVIZF32 R2H, #2.5
                         ; R2H = 2.5 = 0x40200000
                        ; R3H = -5.5 = 0xC0B00000
MOVIZF32 R3H, #-5.5
MOVIZF32 R4H, #0xC0B0
                        ; R4H = -5.5 = 0xC0B00000
Load R5H with pi = 3.141593 (0x40490000)
 MOVIZF32 R5H, \#3.141593; R5H = 3.140625 (0x40490000)
Load ROH with a more accurate pi = 3.141593 (0x40490FDB)
  MOVIZF32 R0H, #0x4049
                       ; R0H = 0x40490000
  MOVXI ROH, #0x0FDB
                         ; ROH = 0x40490FDB
```

See also

MOVIZ RaH, #16FHiHex MOVXI RaH, #16FLoHex



MOVSTO FLAG

Load Selected STF Flags into ST0

Operands

|--|

Opcode

LSW: 1010 1101 FFFF FFFF

Description

Load selected flags from the STF register into the ST0 register of the 28x CPU where FLAG is one or more of TF, CI, ZI, ZF, NI, NF, LUF or LVF. The specified flag maps to the ST0 register as follows:

- Set OV = 1 if LVF or LUF is set. Otherwise clear OV.
- Set N = 1 if NF or NI is set. Otherwise clear N.
- Set Z = 1 if ZF or ZI is set. Otherwise clear Z.
- Set C = 1 if TF is set. Otherwise clear C.
- Set TC = 1 if TF is set. Otherwise clear TF.

If any STF flag is not specified, then the corresponding ST0 register bit is not modified.

Restrictions

Do not use the MOVST0 instruction in the delay slots for pipelined operations. Doing so can yield invalid results. To avoid this, the proper number of NOPs or non-pipelined instructions must be inserted before the MOVST0 operation.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	Yes	Yes

When the flags are moved to the C28x ST0 register, the LUF or LVF flags are automatically cleared if selected.

Pipeline

This is a single-cycle instruction.

Example

Program flow is controlled by C28x instructions that read status flags in the status register 0 (ST0). If a decision needs to be made based on a floating-point operation, the information in the STF register needs to be loaded into ST0 flags (Z,N,OV,TC,C) so that the appropriate branch conditional instruction can be executed. The MOVST0 FLAG instruction is used to load the current value of specified STF flags into the respective bits of ST0. When this instruction executes, it will also clear the latched overflow and underflow flags if those flags are specified.

```
Loop:

MOV32 R0H,*XAR4++

MOV32 R1H,*XAR3++

CMPF32 R1H, R0H

MOVST0 ZF, NF

BF Loop, GT ; Loop if (R1H > R0H)
```

See also

MOV32 mem32, STF MOV32 STF, mem32



MOVXI RaH, #16FLoHex Move Immediate to the Low 16-bits of a Floating-Point Register

Operands

Ra floating-point register (R0H to R7H)

#16FLoHex A 16-bit immediate hex value that represents the lower 16-bits of an IEEE 32-bit floating-point value. The upper 16-bits will not be modified.

Opcode LSW: 1110 1000 0000 1III MSW: IIII IIII IIII Iaaa

Description Load the low 16-bits of RaH with the immediate value #16FLoHex. #16FLoHex

represents the lower 16-bits of an IEEE 32-bit floating-point value. The upper 16-bits of RaH will not be modified. MOVXI can be combined with the MOVIZ or MOVIZF32

instruction to initialize all 32-bits of a RaH register.

RaH[15:0] = #16FLoHex RaH[31:16] = Unchanged

Flags

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline This is a single-cycle instruction.

Example ; Load ROH with pi = 3.141593 (0x40490FDB)

MOVIZ R0H, #0x4049; R0H = 0x40490000MOVXI R0H, #0x0FDB; R0H = 0x40490FDB

See also MOVIZ RaH, #16FHiHex

MOVIZF32 RaH, #16FHi



MPYF32 RaH, RbH, RcH 32-bit Floating-Point Multiply

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)
RcH	floating-point source register (R0H to R7H)

Opcode

LSW: 1110 0111 0000 0000 MSW: 0000 000c ccbb baaa

Description

Multiply the contents of two floating-point registers.

RaH = RbH * RcH

Flags

This instruction modifies the following flags in the STF register:.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if MPYF32 generates an underflow condition.
- LVF = 1 if MPYF32 generates an overflow condition.

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

```
MPYF32 RaH, RbH, RcH ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction
; <-- MPYF32 completes, RaH updated

NOP
```

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example

Calculate Y = A * B:

```
MOVL XAR4, #A

MOV32 R0H, *XAR4 ; Load R0H with A

MOVL XAR4, # B

MOV32 R1H, *XAR4 ; Load R1H with B

MPYF32 R0H,R1H,R0H ; Multiply A * B

MOVL XAR4, #Y

; <--MPYF32 complete

MOV32 *XAR4,R0H ; Save the result
```

See also

MPYF32 RaH, #16FHi, RbH

MPYF32 RaH, RbH, RcH || ADDF32 RdH, ReH, RfH MPYF32 RdH, ReH, RfH || MOV32 RaH, mem32 MPYF32 RdH, ReH, RfH || MOV32 mem32, RaH MPYF32 RaH, RbH, RcH || SUBF32 RdH, ReH, RfH MACF32 R3H, R2H, RdH, ReH, RfH || MOV32 RaH, mem32



MPYF32 RaH, #16FHi, RbH 32-bit Floating-Point Multiply

Operands

RaH	floating-point destination register (R0H to R7H)
#16FHi	A 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0.
RcH	floating-point source register (R0H to R7H)

Opcode

LSW: 1110 1000 01II IIII MSW: IIII IIII IIbb baaa

Description

Multiply RbH with the floating-point value represented by the immediate operand. Store the result of the addition in RaH.

#16FHi is a 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0. #16FHi is most useful for representing constants where the lowest 16-bits of the mantissa are 0. Some examples are 2.0 (0x40000000), 4.0 (0x40800000), 0.5 (0x3F000000), and -1.5 (0xBFC00000). The assembler will accept either a hex or float as the immediate value. That is, the value -1.5 can be represented as #-1.5 or #0xBFC0.

RaH = RbH * #16FHi:0

This instruction can also be written as MPYF32 RaH, RbH, #16FHi.

Flags

This instruction modifies the following flags in the STF register:.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if MPYF32 generates an underflow condition.
- LVF = 1 if MPYF32 generates an overflow condition.

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

```
MPYF32 RaH, #16FHi, RbH ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction
; <-- MPYF32 completes, RaH updated

NOP
```

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example 1

```
MOVIZF32 R3H, #2.0 ; R3H = 2.0 (0x40000000)

MPYF32 R4H, #3.0, R3H ; R4H = 3.0 * R3H

MOVL XAR1, #0xB006 ; <-- Non conflicting instruction

; <-- MPYF32 complete, R4H = 6.0 (0x40C00000)

MOV32 *XAR1, R4H ; Save the result in memory location 0xB006

;Same as above example but #16FHi is represented in Hex

MOVIZF32 R3H, #2.0 ; R3H = 2.0 (0x40000000)

MPYF32 R4H, #0x4040, R3H ; R4H = 0x4040 * R3H

; 3.0 is represented as 0x40400000 in

: IEFE 754 32-bit format
```

Example 2



MPYF32 RaH, RbH, #16FHi See also

MPYF32 RaH, RbH, RcH MPYF32 RaH, RbH, RcH || ADDF32 RdH, ReH, RfH



MPYF32 RaH, RbH, #16FHi 32-bit Floating-Point Multiply

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)
#16FHi	A 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0.

Opcode

LSW: 1110 1000 01II IIII MSW: IIII IIII IIbb baaa

Description

Multiply RbH with the floating-point value represented by the immediate operand. Store the result of the addition in RaH.

#16FHi is a 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0. #16FHi is most useful for representing constants where the lowest 16-bits of the mantissa are 0. Some examples are 2.0 (0x40000000), 4.0 (0x40800000), 0.5 (0x3F000000), and -1.5 (0xBFC00000). The assembler will accept either a hex or float as the immediate value. That is, the value -1.5 can be represented as #-1.5 or #0xBFC0.

RaH = RbH * #16FHi:0

This instruction can also be writen as MPYF32 RaH, #16FHi, RbH.

Flags

This instruction modifies the following flags in the STF register:.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if MPYF32 generates an underflow condition.
- LVF = 1 if MPYF32 generates an overflow condition.

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

```
MPYF32 RaH, RbH, #16FHi ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction
; <-- MPYF32 completes, RaH updated

NOP
```

Any instruction in the delay slot must not use RaH as a destination register or use RaH as a source operand.

Example 1

Example 2

```
MOVIZF32 R3H, #2.0
                              ; R3H = 2.0 (0x40000000)
   MPYF32 R4H, R3H, #3.0
                              ; R4H = R3H * 3.0
   MOVL
           XAR1, #0xB008
                               ; <-- Non conflicting instruction
                               ; <-- MPYF32 complete, R4H = 6.0 (0x40C00000)
  MOV32
                               ; Save the result in memory location 0xB008
            *XAR1, R4H
;Same as above example but #16FHi is represented in Hex
   MOVIZF32 R3H, \#2.0 ; R3H = 2.0 (0x40000000)
   MPYF32 R4H, R3H, \#0x4040 ; R4H = R3H * 0x4040
                              ; 3.0 is represented as 0x40400000 in
                              ; IEEE 754 32-bit format
   MOVL
            XAR1, #0xB008
                             ; <-- Non conflicting instruction
                              ; <-- MPYF32 complete, R4H = 6.0 (0x40C00000)
```

MOV32

*XAR1, R4H

; Save the result in memory location 0xB008



See also

MPYF32 RaH, #16FHi, RbH MPYF32 RaH, RbH, RcH



MPYF32 RaH, RbH, RcH ||ADDF32 RdH, ReH, RfH 32-bit Floating-Point Multiply with Parallel Add

Operands

RaH	floating-point destination register for MPYF32 (R0H to R7H) RaH cannot be the same register as RdH
RbH	floating-point source register for MPYF32 (R0H to R7H)
RcH	floating-point source register for MPYF32 (R0H to R7H)
RdH	floating-point destination register for ADDF32 (R0H to R7H) RdH cannot be the same register as RaH
ReH	floating-point source register for ADDF32 (R0H to R7H)
RfH	floating-point source register for ADDF32 (R0H to R7H)

Opcode

LSW: 1110 0111 0100 00ff MSW: feee dddc ccbb baaa

Description

Multiply the contents of two floating-point registers with parallel addition of two registers.

RaH = RbH * RcH RdH = ReH + RfH

This instruction can also be written as:

MACF32 RaH, RbH, RcH, RdH, ReH, RfH

Restrictions

The destination register for the MPYF32 and the ADDF32 must be unique. That is, RaH cannot be the same register as RdH.

Flags

This instruction modifies the following flags in the STF register:.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	Yes	Yes

The STF register flags are modified as follows:

- LUF = 1 if MPYF32 or ADDF32 generates an underflow condition.
- LVF = 1 if MPYF32 or ADDF32 generates an overflow condition.

Pipeline

Both MPYF32 and ADDF32 take 2 pipeline cycles (2p) That is:

```
MPYF32 RaH, RbH, RcH; 2 pipeline cycles (2p)

|| ADDF32 RdH, ReH, RfH; 2 pipeline cycles (2p)

NOP; 1 cycle delay or non-conflicting instruction; <-- MPYF32, ADDF32 complete, RaH, RdH updated

NOP
```

Any instruction in the delay slot must not use RaH or RdH as a destination register or as a source operand.



```
Example
                         Perform 5 multiply and accumulate operations:
                     ;
                         1st multiply: A = X0 * Y0
                     ;
                         2nd multiply: B = X1 * Y1
                         3rd multiply: C = X2 * Y2
                         4th multiply: D = X3 * Y3
                         5th multiply: E = X3 * Y3
                         Result = A + B + C + D + E
                        MOV32 R0H, *XAR4++
                                                       ; R0H = X0
                        MOV32 R1H, *XAR5++
                                                       ; R1H = Y0
                                                       ; R2H = A = X0 * Y0
                        MPYF32 R2H, R0H, R1H
                                                       ; In parallel ROH = X1
                     | MOV32 R0H, *XAR4++
                        MOV32 R1H, *XAR5++
                                                      ; R1H = Y1
                                                      ; R3H = B = X1 * Y1
                        MPYF32 R3H, R0H, R1H
                                                      ; In parallel ROH = X2
                     | MOV32 ROH, *XAR4++
                        MOV32 R1H, *XAR5++
                                                      ; R1H = Y2
                                                       ; R3H = A + B
                                                       ; R2H = C = X2 * Y2
                        MACF32 R3H, R2H, R2H, R0H, R1H; In parallel R0H = X3
                      || MOV32 R0H, *XAR4++
                        MOV32 R1H, *XAR5++
                                                      ; R1H = Y3
                                                       ; R3H = (A + B) + C
                                                       ; R2H = D = X3 * Y3
                        MACF32 R3H, R2H, R2H, R0H, R1H; In parallel R0H = X4
                     || MOV32 R0H, *XAR4
                        MOV32 R1H, *XAR5
                                                       ; R1H = Y4
                                                       ; R2H = E = X4 * Y4
                        MPYF32 R2H, R0H, R1H
                                                      ; in parallel R3H = (A + B + C) + D
                     | ADDF32 R3H, R3H, R2H
                        NOP
                                                       ; Wait for MPYF32 | ADDF32 to complete
                        ADDF32 R3H, R3H, R2H
                                                      ; R3H = (A + B + C + D) + E NOP
                                                       ; Wait for ADDF32 to complete
                        MOV32 @Result, R3H
                                                       ; Store the result
See also
                     MACF32 R3H, R2H, RdH, ReH, RfH
                     MACF32 R3H, R2H, RdH, ReH, RfH | MOV32 RaH, mem32
                     MACF32 R7H, R3H, mem32, *XAR7++
                     MACF32 R7H, R6H, RdH, ReH, RfH
                     MACF32 R7H, R6H, RdH, ReH, RfH | MOV32 RaH, mem32
```



MPYF32 RdH, ReH, RfH || MOV32 RaH, mem32 32-bit Floating-Point Multiply with Parallel Move

Operands

RdH	floating-point destination register for the MPYF32 (R0H to R7H) RdH cannot be the same register as RaH
ReH	floating-point source register for the MPYF32 (R0H to R7H)
RfH	floating-point source register for the MPYF32 (R0H to R7H)
RaH	floating-point destination register for the MOV32 (R0H to R7H) RaH cannot be the same register as RdH
mem32	pointer to a 32-bit memory location. This will be the source of the MOV32.

Opcode LSW: 1110 0011 0000 fffe
MSW: eedd daaa mem32

Description Multiply the contents of two floating-point registers and load another.

RdH = ReH * RfH RaH = [mem32]

Restrictions The destination register for the MPYF32 and the MOV32 must be unique. That is, RaH

cannot be the same register as RdH.

Flags This instruction modifies the following flags in the STF register:.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	Yes	Yes	Yes	Yes	Yes	Yes

The STF register flags are modified as follows:

- LUF = 1 if MPYF32 generates an underflow condition.
- LVF = 1 if MPYF32 generates an overflow condition.

The MOV32 Instruction will set the NF, ZF, NI and ZI flags as follows:

```
NF = RaH(31);
   ZF = 0;
   if(RaH(30:23) == 0) {    ZF = 1;    NF = 0;  }
   NI = RaH(31);
   ZI = 0;
   if(RaH(31:0) == 0)   ZI = 1;
```

Pipeline

MPYF32 takes 2 pipeline-cycles (2p) and MOV32 takes a single cycle. That is:

Any instruction in the delay slot must not use RdH as a destination register or as a source operand.



Example

Calculate Y = M1*X1 + B1. This example assumes that M1, X1, B1 and Y1 are all on the same data page.

```
MOVW DP, #M1
                      ; Load the data page
  MOV32 ROH,@M1
                      ; Load ROH with M1
  MOV32 R1H,@X1
                      ; Load R1H with X1
  MPYF32 R1H,R1H,R0H ; Multiply M1*X1
                     ; and in parallel load ROH with B1
|| MOV32 R0H,@B1
                      ; <-- MOV32 complete
  NOP
                      ; Wait 1 cycle for MPYF32 to complete
                      ; <-- MPYF32 complete
  ADDF32 R1H,R1H,R0H ; Add M*X1 to B1 and store in R1H
                      ; Wait 1 cycle for ADDF32 to complete
                      ; <-- ADDF32 complete
  MOV32 @Y1,R1H
                      ; Store the result
Calculate Y = (A * B) * C:
MOVL XAR4, #A
  MOV32 ROH, *XAR4 ; Load ROH with A
  MOVL XAR4, #B
  MOV32 R1H, *XAR4 ; Load R1H with B
  MOVL XAR4, #C
  MPYF32 R1H,R1H,R0H ; Calculate R1H = A * B
| MOV32 R0H, *XAR4
                      ; and in parallel load R2H with C
                      ; <-- MOV32 complete
  MOVL XAR4, #Y
                      ; <-- MPYF32 complete
  MPYF32 R2H,R1H,R0H ; Calculate Y = (A * B) * C
                      ; Wait 1 cycle for MPYF32 to complete
                      ; MPYF32 complete
  MOV32 *XAR4,R2H
MPYF32 RdH, ReH, RfH | MOV32 mem32, RaH
MACF32 R3H, R2H, RdH, ReH, RfH | MOV32 RaH, mem32
```

See also

MACF32 R7H, R6H, RdH, ReH, RfH | MOV32 RaH, mem32 MACF32 R7H, R3H, mem32, *XAR7++



MPYF32 RdH, ReH, RfH || MOV32 mem32, RaH 32-bit Floating-Point Multiply with Parallel Move

Operands

RdH	floating-point destination register for the MPYF32 (R0H to R7H)
ReH	floating-point source register for the MPYF32 (R0H to R7H)
RfH	floating-point source register for the MPYF32 (R0H to R7H)
mem32	pointer to a 32-bit memory location. This will be the destination of the MOV32.
RaH	floating-point source register for the MOV32 (R0H to R7H)

Opcode

LSW: 1110 0000 0000 fffe MSW: eedd daaa mem32

Description

Multiply the contents of two floating-point registers and move from memory to register.

RdH = ReH * RfH, [mem32] = RaH

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if MPYF32 generates an underflow condition.
- LVF = 1 if MPYF32 generates an overflow condition.

Pipeline

MPYF32 takes 2 pipeline-cycles (2p) and MOV32 takes a single cycle. That is:

```
MPYF32 RdH, ReH, RfH; 2 pipeline cycles (2p)

|| MOV32 mem32, RaH; 1 cycle; -- MOV32 completes, mem32 updated

NOP; 1 cycle delay or non-conflicting instruction; -- MPYF32 completes, RdH updated

NOP
```

Any instruction in the delay slot must not use RdH as a destination register or as a source operand.

Example

See also

MPYF32 RdH, ReH, RfH || MOV32 RaH, mem32 MACF32 R3H, R2H, RdH, ReH, RfH || MOV32 RaH, mem32 MACF32 R7H, R6H, RdH, ReH, RfH || MOV32 RaH, mem32 MACF32 R7H, R3H, mem32, *XAR7++



MPYF32 RaH, RbH, RcH ||SUBF32 RdH, ReH, RfH 32-bit Floating-Point Multiply with Parallel Subtract

Operands

RaH	floating-point destination register for MPYF32 (R0H to R7H) RaH cannot be the same register as RdH
RbH	floating-point source register for MPYF32 (R0H to R7H)
RcH	floating-point source register for MPYF32 (R0H to R7H)
RdH	floating-point destination register for SUBF32 (R0H to R7H) RdH cannot be the same register as RaH
ReH	floating-point source register for SUBF32 (R0H to R7H)
RfH	floating-point source register for SUBF32 (R0H to R7H)

Opcode

LSW: 1110 0111 0101 00ff MSW: feee dddc ccbb baaa

Description

Multiply the contents of two floating-point registers with parallel subtraction of two registers.

RaH = RbH * RcH, RdH = ReH - RfH

Restrictions

The destination register for the MPYF32 and the SUBF32 must be unique. That is, RaH cannot be the same register as RdH.

Flags

This instruction modifies the following flags in the STF register:.

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if MPYF32 or SUBF32 generates an underflow condition.
- LVF = 1 if MPYF32 or SUBF32 generates an overflow condition.

Pipeline

MPYF32 and SUBF32 both take 2 pipeline-cycles (2p). That is:

```
MPYF32 RaH, RbH, RcH; 2 pipeline cycles (2p)

|| SUBF32 RdH, ReH, RfH; 2 pipeline cycles (2p)

NOP; 1 cycle delay or non-conflicting instruction

; <-- MPYF32, SUBF32 complete. RaH, RdH updated
```

Any instruction in the delay slot must not use RaH or RdH as a destination register or as a source operand.

Example

```
MOVIZF32 R4H, #5.0 ; R4H = 5.0 (0x40A00000)

MOVIZF32 R5H, #3.0 ; R5H = 3.0 (0x40400000)

MPYF32 R6H, R4H, R5H ; R6H = R4H * R5H

|| SUBF32 R7H, R4H, R5H ; R7H = R4H - R5H NOP

; 1 cycle delay for MPYF32 || SUBF32 to complete

; <-- MPYF32 || SUBF32 complete,

; R6H = 15.0 (0x41700000), R7H = 2.0 (0x40000000)
```

See also

SUBF32 RaH, RbH, RcH SUBF32 RdH, ReH, RfH || MOV32 RaH, mem32 SUBF32 RdH, ReH, RfH || MOV32 mem32, RaH



NEGF32 RaH, RbH{, CNDF} Conditional Negation

Operands

RaH	floating-point destination register (R0H to R7H)
RbH	floating-point source register (R0H to R7H)
CNDF	condition tested

Opcode LSW: 1110 0110 1010 CNDF

MSW: 0000 0000 00bb baaa

Description if (CNDF == true) {RaH = - RbH }

else {RaH = RbH }

CNDF is one of the following conditions:

Encode (1)	CNDF	Description	STF Flags Tested
0000	NEQ	Not equal to zero	ZF == 0
0001	EQ	Equal to zero	ZF == 1
0010	GT	Greater than zero	ZF == 0 AND NF == 0
0011	GEQ	Greater than or equal to zero	NF == 0
0100	LT	Less than zero	NF == 1
0101	LEQ	Less than or equal to zero	ZF == 1 AND NF == 1
1010	TF	Test flag set	TF == 1
1011	NTF	Test flag not set	TF == 0
1100	LU	Latched underflow	LUF == 1
1101	LV	Latched overflow	LVF == 1
1110	UNC	Unconditional	None
1111	UNCF (2)	Unconditional with flag modification	None

⁽¹⁾ Values not shown are reserved.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	Yes	Yes	No	No	

Pipeline This is a single-cycle instruction.

Example MOVIZF32 R0H, #5.0 ; R0H = 5.0 (0x40A00000) MOVIZF32 R1H, #4.0 ; R1H = 4.0 (0x40800000)

MOVIZF32 R1H, #4.0 , R1H = 4.0 (0x40800000) MOVIZF32 R2H, #-1.5 ; R2H = -1.5 (0xBFC00000)

MPYF32 R4H, R1H, R2H; R4H = -6.0 MPYF32 R5H, R0H, R1H; R5H = 20.0 ; <-- R4H valid CMPF32 R4H, #0.0; NF = 1

; <-- R5H valid NEGF32 R4H, R4H, LT ; if NF = 1, R4H = 6.0

CMPF32 R5H, #0.0 ; NF = 0 NEGF32 R5H, R5H, GEQ ; if NF = 0, R4H = -20.0

See also ABSF32 RaH, RbH

This is the default operation if no CNDF field is specified. This condition will allow the ZF, NF, ZI, and NI flags to be modified when a conditional operation is executed. All other conditions will not modify these flags.



POP RB

Pop the RB Register from the Stack

Operands

RB repeat block register	

Opcode

LSW: 1111 1111 1111 0001

Description

Restore the RB register from stack. If a high-priority interrupt contains a RPTB instruction, then the RB register must be stored on the stack before the RPTB block and restored after the RTPB block. In a low-priority interrupt RB must always be saved and restored. This save and restore must occur when interrupts are disabled.

Flags

This instruction does not affect any flags floating-point Unit:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No

Pipeline

This is a single-cycle instruction.

Example

A high priority interrupt is defined as an interrupt that cannot itself be interrupted. In a high priority interrupt, the RB register must be saved if a RPTB block is used within the interrupt. If the interrupt service routine does not include a RPTB block, then you do not have to save the RB register.

```
; Repeat Block within a High-Priority Interrupt (Non-Interruptible)
                          ; RAS = RA, RA = 0
_Interrupt:
     . . .
     PUSH RB
                          ; Save RB register only if a RPTB block is used in the
     ISR
     . . .
     RPTB #BlockEnd, AL ; Execute the block AL+1 times
     . . .
     BlockEnd
                          ; End of block to be repeated
     . . .
                           ; Restore RB register
     POP RB
     IRET
                           ; RA = RAS, RAS = 0
```

A low-priority interrupt is defined as an interrupt that allows itself to be interrupted. The RB register must always be saved and restored in a low-priority interrupt. The RB register must stored before interrupts are enabled. Likewise before restoring the RB register interrupts must first be disabled.

```
; Repeat Block within a Low-Priority Interrupt (Interruptible)
                        ; RAS = RA, RA = 0
_Interrupt:
     PUSH RB
                         ; Always save RB register
     CLRC INTM
                         ; Enable interrupts only after saving RB
     . . .
                         ; ISR may or may not include a RPTB block
     . . .
     . . .
     SETC INTM
                         ; Disable interrupts before restoring RB
     POP RB
                         ; Always restore RB register
     . . .
                         ; RA = RAS, RAS = 0
     IRET
```





See also

PUSH RB RPTB #RSIZE, RC RPTB #RSIZE, loc16



PUSH RB

Push the RB Register onto the Stack

Operands

RB	repeat block register	

Opcode

LSW: 1111 1111 1111 0000

Description

Save the RB register on the stack. If a high-priority interrupt contains a RPTB instruction, then the RB register must be stored on the stack before the RPTB block and restored after the RTPB block. In a low-priority interrupt RB must always be saved and restored. This save and restore must occur when interrupts are disabled.

Flags

This instruction does not affect any flags floating-point Unit:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No

Pipeline

This is a single-cycle instruction for the first iteration, and zero cycles thereafter.

Example

A high priority interrupt is defined as an interrupt that cannot itself be interrupted. In a high priority interrupt, the RB register must be saved if a RPTB block is used within the interrupt. If the interrupt service routine does not include a RPTB block, then you do not have to save the RB register.

```
; Repeat Block within a High-Priority Interrupt (Non-Interruptible)
                          ; RAS = RA, RA = 0
_Interrupt:
     . . .
     PUSH RB
                           ; Save RB register only if a RPTB block is used in the
     ISR
     . . .
     RPTB #BlockEnd, AL ; Execute the block AL+1 times
     . . .
     . . .
     BlockEnd
                           ; End of block to be repeated
     POP RB
                           ; Restore RB register
     . . .
                           ; RA = RAS, RAS = 0
```

A low-priority interrupt is defined as an interrupt that allows itself to be interrupted. The RB register must always be saved and restored in a low-priority interrupt. The RB register must stored before interrupts are enabled. Likewise before restoring the RB register interrupts must first be disabled.

```
; Repeat Block within a Low-Priority Interrupt (Interruptible)
_Interrupt:
                          ; RAS = RA, RA = 0
      PUSH RB
                          ; Always save RB register
      CLRC INTM
                          ; Enable interrupts only after saving RB
      . . .
      . . .
                          ; ISR may or may not include a RPTB block
      . . .
      SETC INTM
                          ; Disable interrupts before restoring RB
      . . .
      POP
           RB
                          ; Always restore RB register
      IRET
                          ; RA = RAS, RAS = 0
```

See also

POP RB RPTB #RSIZE, RC RPTB #RSIZE, loc16



RESTORE

Restore the Floating-Point Registers

Operands

none This instruction does not have any operands

Opcode LSW: 1110 0101 0110 0010

Description Restore the floating-point register set (R0H - R7H and STF) from their shadow registers.

The SAVE and RESTORE instructions should be used in high-priority interrupts. That is interrupts that cannot themselves be interrupted. In low-priority interrupt routines the

floating-point registers should be pushed onto the stack.

Restrictions The RESTORE instruction cannot be used in any delay slots for pipelined operations.

Doing so will yield invalid results. To avoid this, the proper number of NOPs or non-

pipelined instructions must be inserted before the RESTORE operation.

; The following is INVALID

MPYF32 R2H, R1H, R0H ; 2 pipeline-cycle instruction (2p)

RESTORE ; INVALID, do not use RESTORE in a delay slot

; The following is VALID

MPYF32 R2H, R1H, R0H ; 2 pipeline-cycle instruction (2p)

NOP ; 1 delay cycle, R2H updated after this instruction

RESTORE ; VALID

Flags Restoring the status register will overwrite all flags:

TF ΖI NI ZF NF LUF LVF Flag Modified Yes Yes Yes Yes Yes Yes Yes

Pipeline

This is a single-cycle instruction.



Example

The following example shows a complete context save and restore for a high-priority interrupt. Note that the CPU automatically stores the following registers: ACC, P, XT, ST0, ST1, IER, DP, AR0, AR1 and PC. If an interrupt is low priority (that is it can be interrupted), then push the floating point registers onto the stack instead of using the SAVE and RESTORE operations.

```
; Interrupt Save
_HighestPriorityISR: ; Uninterruptable
            ; Align stack
ASP
PUSH RB
                   ; Save RB register if used in the ISR
PUSH AR1H:AR0H
                   ; Save other registers if used
PUSH XAR2
PUSH XAR3
PUSH XAR4
PUSH XAR5
PUSH XAR6
PUSH XAR7
PUSH XT
SPM
      0
                   ; Set default C28 modes
CLRC AMODE
CLRC PAGE0,OVM
SAVE RNDF32=1
                   ; Save all FPU registers
                   ; set default FPU modes
. . .
 . . .
; Interrupt Restore
                   ; Restore all FPU registers
RESTORE
POP
      XT
                   ; restore other registers
POP
      XAR7
POP
      XAR6
      XAR5
POP
POP
      XAR4
POP
      XAR3
POP
      XAR2
POP
      AR1H:AR0H
POP RB
                   ; restore RB register
NASP
                   ; un-align stack
IRET
                   ; return from interrupt
```

See also

SAVE FLAG, VALUE



RPTB label, loc16 Repeat A Block of Code

Operands

label	This label is used by the assembler to determine the end of the repeat block and to calculate RSIZE. This label should be placed immediately after the last instruction included in the repeat block.
loc16	16-bit location for the repeat count value.

Opcode

LSW: 1011 0101 0bbb bbbb MSW: 0000 0000 loc16

Description

Initialize repeat block loop, repeat count from [loc16]

Restrictions

- The maximum block size is ≤127 16-bit words.
- An even aligned block must be ≥ 9 16-bit words.
- An odd aligned block must be ≥ 8 16-bit words.
- Interrupts must be disabled when saving or restoring the RB register.
- · Repeat blocks cannot be nested.
- Any discontinuity type operation is not allowed inside a repeat block. This includes all call, branch, or TRAP instructions. Interrupts are allowed.
- Conditional execution operations are allowed.

Flags

This instruction does not affect any flags in the floating-point unit:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	_

Pipeline

This instruction takes four cycles on the first iteration and zero cycles thereafter. No special pipeline alignment is required.

Example

The minimum size for the repeat block is 9 words if the block is even-aligned and 8 words if the block is odd-aligned. If you have a block of 8 words, as in the following example, you can make sure the block is odd aligned by proceeding it by a .align 2 directive and a NOP instruction. The .align 2 directive will make sure the NOP is even-aligned. Since a NOP is a 16-bit instruction the RPTB will be odd-aligned. For blocks of 9 or more words, this is not required.

```
; Repeat Block of 8 Words (Interruptible)
; find the largest element and put its address in XAR6
  .align 2
 NOP
  RPTB
         VECTOR_MAX_END, AR7 ; Execute the block AR7+1 times
 MOVL
         ACC, XAR0
 MOV32
         R1H,*XAR0++
                               ; min size = 8, 9 words
 MAXF32 ROH,R1H
                               ; max size = 127 words
 MOVSTO NF.ZF
 MOVL
         XAR6,ACC,LT
VECTOR_MAX_END:
                               ; label indicates the end
                               ; RA is cleared
```

When an interrupt is taken the repeat active (RA) bit in the RB register is automatically copied to the repeat active shadow (RAS) bit. When the interrupt exits, the RAS bit is automatically copied back to the RA bit. This allows the hardware to keep track if a repeat loop was active whenever an interrupt is taken and restore that state automatically.



A high priority interrupt is defined as an interrupt that cannot itself be interrupted. In a high priority interrupt, the RB register must be saved if a RPTB block is used within the interrupt. If the interrupt service routine does not include a RPTB block, then you do not have to save the RB register.

```
; Repeat Block within a High-Priority Interrupt (Non-Interruptible)
                          ; RAS = RA, RA = 0
; Interrupt:
                          ; Save RB register only if a RPTB block is used in the
   PUSH RB
ISR
  RPTB #BlockEnd, AL
                         ; Execute the block AL+1 times
   . . .
   . . .
{\tt BlockEnd}
                         ; End of block to be repeated
   . . .
   POP RB
                         ; Restore RB register
   . . .
   IRET
                         ; RA = RAS, RAS = 0
```

A low-priority interrupt is defined as an interrupt that allows itself to be interrupted. The RB register must always be saved and restored in a low-priority interrupt. The RB register must stored before interrupts are enabled. Likewise before restoring the RB register interrupts must first be disabled.

```
; Repeat Block within a Low-Priority Interrupt (Interruptible)
; Interrupt:
                      ; RAS = RA, RA = 0
   . . .
  PUSH RB
                       ; Always save RB register
   . . .
                      ; Enable interrupts only after saving RB
  CLRC INTM
   . . .
   . . .
                       ; ISR may or may not include a RPTB block
  . . .
  . . .
                       ; Disable interrupts before restoring RB
  SETC INTM
   . . .
  POP RB
                       ; Always restore RB register
  IRET
                       ; RA = RAS, RAS = 0
```

See also

POP RB PUSH RB RPTB label, RC



RPTB label, #RC	Repeat a Block of Code
Operands	
label	This label is used by the assembler to determine the end of the repeat block and to calculate RSIZE. This label should be placed immediately after the last instruction included in the repeat block.
#RC	16-bit location

Opcode

LSW: 1011 0101 1bbb bbbb MSW: cccc cccc cccc

Description

Repeat a block of code. The repeat count is specified as a immediate value.

Restrictions

- The maximum block size is ≤127 16-bit words.
- An even aligned block must be ≥ 9 16-bit words.
- An odd aligned block must be ≥ 8 16-bit words.
- Interrupts must be disabled when saving or restoring the RB register.
- Repeat blocks cannot be nested.
- Any discontinuity type operation is not allowed inside a repeat block. This includes all call, branch or TRAP instructions. Interrupts are allowed.
- Conditional execution operations are allowed.

Flags

This instruction does not affect any flags int the floating-point unit:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	_

Pipeline

This instruction takes one cycle on the first iteration and zero cycles thereafter. No special pipeline alignment is required.

Example

The minimum size for the repeat block is 8 words if the block is even aligned and 9 words if the block is odd aligned. If you have a block of 8 words, as in the following example, you can make sure the block is odd aligned by proceeding it by a .align 2 directive and a NOP instruction. The .align 2 directive will make sure the NOP is even aligned. Since a NOP is a 16-bit instruction the RPTB will be odd aligned. For blocks of 9 or more words, this is not required.

```
; Repeat Block (Interruptible)
; find the largest element and put its address in XAR6
.align 2
NOP
RPTB
       VECTOR MAX END, #(4-1) ; Execute the block 4 times
MOVL
       ACC, XAR0
MOV32 R1H,*XAR0++
                                 ; 8 or 9 words block size 127 words
MAXF32 ROH,R1H
MOVSTO NF.ZF
MOVIT
       XAR6, ACC, LT
VECTOR_MAX_END:
                                 ; RE indicates the end address
                                ; RA is cleared
```

When an interrupt is taken the repeat active (RA) bit in the RB register is automatically copied to the repeat active shadow (RAS) bit. When the interrupt exits, the RAS bit is automatically copied back to the RA bit. This allows the hardware to keep track if a repeat loop was active whenever an interrupt is taken and restore that state automatically.



A high priority interrupt is defined as an interrupt that cannot itself be interrupted. In a high priority interrupt, the RB register must be saved if a RPTB block is used within the interrupt. If the interrupt service routine does not include a RPTB block, then you do not have to save the RB register.

```
; Repeat Block within a High-Priority Interrupt (Non-Interruptible)
                           ; RAS = RA, RA = 0
; Interrupt:
                           ; Save RB register only if a RPTB block is used in the
PUSH RB
ISR
. . .
RPTB #BlockEnd, #5
                           ; Execute the block 5+1 times
. . .
. . .
BlockEnd
                           ; End of block to be repeated
. . .
POP RB
                           ; Restore RB register
. . .
IRET
                           ; RA = RAS, RAS = 0
```

A low-priority interrupt is defined as an interrupt that allows itself to be interrupted. The RB register must always be saved and restored in a low-priority interrupt. The RB register must stored before interrupts are enabled. Likewise before restoring the RB register interrupts must first be disabled.

```
; Repeat Block within a Low-Priority Interrupt (Interruptible)
; Interrupt:
                           ; RAS = RA, RA = 0
. . .
PUSH RB
                           ; Always save RB register
CLRC INTM
                           ; Enable interrupts only after saving RB
. . .
. . .
                           ; ISR may or may not include a RPTB block
. . .
. . .
SETC INTM
                           ; Disable interrupts before restoring RB
. . .
POP RB
                           ; Always restore RB register
IRET
                           ; RA = RAS, RAS = 0
```

See also

POP RB PUSH RB RPTB #RSIZE, loc16



SAVE FLAG, VALUE Save Register Set to Shadow Registers and Execute SETFLG

Operands

FLAG	11 bit mask indicating which floating-point status flags to change.
VALUE	11 bit mask indicating the flag value; 0 or 1.

Opcode

LSW: 1110 0110 01FF FFFF MSW: FFFF FVVV VVVV VVVV

Description

This operation copies the current working floating-point register set (R0H to R7H and STF) to the shadow register set and combines the SETFLG FLAG, VALUE operation in a single cycle. The status register is copied to the shadow register before the flag values are changed. The STF[SHDWM] flag is set to 1 when the SAVE command has been executed. The SAVE and RESTORE instructions should be used in high-priority interrupts. That is interrupts that cannot themselves be interrupted. In low-priority interrupt routines the floating-point registers should be pushed onto the stack.

Restrictions

Do not use the SAVE instruction in the delay slots for pipelined operations. Doing so can yield invalid results. To avoid this, the proper number of NOPs or non-pipelined instructions must be inserted before the SAVE operation.

```
; The following is INVALID

MPYF32 R2H, R1H, R0H ; 2 pipeline-cycle instruction (2p)

SAVE RNDF32=1 ; INVALID, do not use SAVE in a delay slot

; The following is VALID

MPYF32 R2H, R1H, R0H ; 2 pipeline-cycle instruction (2p)

NOP ; 1 delay cycle, R2H updated after this instruction

SAVE RNDF32=1 ; VALID
```

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	Yes						

Any flag can be modified by this instruction.

Pipeline

This is a single-cycle instruction.

Example

To make it easier and more legible, the assembler will accept a FLAG=VALUE syntax for the STFLG operation as shown below:

```
SAVE RNDF32=0, TF=1, ZF=0 ; FLAG = 01001000100, VALUE = X0XX0XXX1XX MOVSTO TF, ZF, LUF ; Copy the indicated flags to STO ; Note: X means this flag will not be modified. ; The assembler will set these X values to 0.
```

The following example shows a complete context save and restore for a high priority interrupt. Note that the CPU automatically stores the following registers: ACC, P, XT, ST0, ST1, IER, DP, AR0, AR1 and PC.



```
_HighestPriorityISR:
           ;Align stack
ASP
PUSH RB
              ; Save RB register if used in the ISR
PUSH AR1H: AR0H ; Save other registers if used
PUSH XAR2
PUSH XAR3
PUSH XAR4
PUSH XAR5
PUSH XAR6
PUSH XAR7
PUSH XT
SPM 0
              ; Set default C28 modes
CLRC AMODE
CLRC PAGE0,OVM
SAVE RNDF32=0 ; Save all FPU registers
              ; set default FPU modes
. . .
. . .
RESTORE
              ; Restore all FPU registers
              ; restore other registers
POP XT
POP XAR7
POP XAR6
POP XAR5
POP XAR4
POP XAR3
POP XAR2
POP AR1H:AR0H
POP RB ; restore RB register
NASP
              ; un-align stack IRET
              ; return from interrupt
```

See also

RESTORE SETFLG FLAG, VALUE



SETFLG FLAG, VALUE Set or clear selected floating-point status flags

Operands

FLAG	11 bit mask indicating which floating-point status flags to change.
VALUE	11 bit mask indicating the flag value; 0 or 1.

Opcode

LSW: 1110 0110 00FF FFFF MSW: FFFF FVVV VVVV VVVV

Description

The SETFLG instruction is used to set or clear selected floating-point status flags in the STF register. The FLAG field is an 11-bit value that indicates which flags will be changed. That is, if a FLAG bit is set to 1 it indicates that flag will be changed; all other flags will not be modified. The bit mapping of the FLAG field is shown below:

10	9	8	7	6	5	4	3	2	1	0
reserved	RNDF32	reserved	reserved	TF	ZI	NI	ZF	NF	LUF	LVF

The VALUE field indicates the value the flag should be set to; 0 or 1.

Restrictions

Do not use the SETFLG instruction in the delay slots for pipelined operations. Doing so can yield invalid results. To avoid this, the proper number of NOPs or non-pipelined instructions must be inserted before the SETFLG operation.

```
; The following is INVALID
```

MPYF32 R2H, R1H, R0H ; 2 pipeline-cycle instruction (2p)
SETELG RNDE32=1 : INVALID do not use SETELG in a delay.

SETFLG RNDF32=1 ; INVALID, do not use SETFLG in a delay slot

; The following is VALID

MPYF32 R2H, R1H, R0H ; 2 pipeline-cycle instruction (2p)

NOP ; 1 delay cycle, R2H updated after this instruction

SETFLG RNDF32=1 ; VALID

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	Yes							

Any flag can be modified by this instruction.

Pipeline

This is a single-cycle instruction.

Example

To make it easier and legible, the assembler will accept a FLAG=VALUE syntax for the

STFLG operation as shown below: SETFLG RNDF32=0, TF=1, ZF=0; FLAG = 01001001000, VALUE = X0XX1XX0XXX

; Copy the indicated flags to STO; X means this flag is not modified.; The assembler will set X values to 0

See also

SAVE FLAG, VALUE

MOVSTO TF, ZF, LUF



SUBF32 RaH, RbH, RcH 32-bit Floating-Point Subtraction

Operands

RaH	floating-point destination register (R0H to R1)
RbH	floating-point source register (R0H to R1)
RcH	floating-point source register (R0H to R1)

Opcode

LSW: 1110 0111 0010 0000 MSW: 0000 000c ccbb baaa

Description

Subtract the contents of two floating-point registers

RaH = RbH - RcH

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if MPYF32 generates an underflow condition.
- LVF = 1 if MPYF32 generates an overflow condition.

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

```
SUBF32 RaH, RbH, RcH; 2 pipeline cycles (2p)

NOP; 1 cycle delay or non-conflicting instruction; <-- SUBF32 completes, RaH updated

NOP
```

Any instruction in the delay slot must not use RaH as a destination register or as a source operand.

Example

Calculate Y - A + B - C:

```
MOVL XAR4, #A

MOV32 R0H, *XAR4 ; Load R0H with A

MOVL XAR4, #B

MOV32 R1H, *XAR4 ; Load R1H with B

MOVL XAR4, #C

ADDF32 R0H,R1H,R0H ; Add A + B and in parallel

|| MOV32 R2H, *XAR4 ; Load R2H with C

; <-- ADDF32 complete

SUBF32 R0H,R0H,R2H ; Subtract C from (A + B)

NOP

; <-- SUBF32 completes

MOV32 *XAR4,R0H ; Store the result
```

See also

SUBF32 RaH, #16FHi, RbH SUBF32 RdH, ReH, RfH || MOV32 RaH, mem32 SUBF32 RdH, ReH, RfH || MOV32 mem32, RaH MPYF32 RaH, RbH, RcH || SUBF32 RdH, ReH, RfH



SUBF32 RaH, #16FHi, RbH 32-bit Floating Point Subtraction

Operands

RaH	floating-point destination register (R0H to R1)
#16FHi	A 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0.
RbH	floating-point source register (R0H to R1)

Opcode

LSW: 1110 1000 11II IIII MSW: IIII IIII IIbb baaa

Description

Subtract RbH from the floating-point value represented by the immediate operand. Store the result of the addition in RaH.

#16FHi is a 16-bit immediate value that represents the upper 16-bits of an IEEE 32-bit floating-point value. The low 16-bits of the mantissa are assumed to be all 0. #16FHi is most useful for representing constants where the lowest 16-bits of the mantissa are 0. Some examples are 2.0 (0x40000000), 4.0 (0x40800000), 0.5 (0x3F000000), and -1.5 (0xBFC00000). The assembler will accept either a hex or float as the immediate value. That is, the value -1.5 can be represented as #-1.5 or #0xBFC0.

RaH = #16FHi:0 - RbH

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	Yes	Yes	

The STF register flags are modified as follows:

- LUF = 1 if MPYF32 generates an underflow condition.
- LVF = 1 if MPYF32 generates an overflow condition.

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

```
SUBF32 RaH, #16FHi, RbH; 2 pipeline cycles (2p)

NOP; 1 cycle delay or non-conflicting instruction; <--- SUBF32 completes, RaH updated

NOP
```

Any instruction in the delay slot must not use RaH as a destination register or as a source operand.

Example

Calculate Y = 2.0 - (A + B):

```
MOVL XAR4, #A

MOV32 R0H, *XAR4 ; Load R0H with A

MOVL XAR4, #B

MOV32 R1H, *XAR4 ; Load R1H with B

ADDF32 R0H,R1H,R0H ; Add A + B and in parallel

NOP

; <-- ADDF32 complete

SUBF32 R0H,#2.0,R2H ; Subtract (A + B) from 2.0

NOP

; <-- SUBF32 completes

MOV32 *XAR4,R0H ; Store the result
```

See also

SUBF32 RaH, RbH, RcH SUBF32 RdH, ReH, RfH || MOV32 RaH, mem32 SUBF32 RdH, ReH, RfH || MOV32 mem32, RaH MPYF32 RaH, RbH, RcH || SUBF32 RdH, ReH, RfH



SUBF32 RdH, ReH, RfH || MOV32 RaH, mem32 32-bit Floating-Point Subtraction with Parallel Move

Operands

RdH	floating-point destination register (R0H to R7H) for the SUBF32 operation RdH cannot be the same register as RaH
ReH	floating-point source register (R0H to R7H) for the SUBF32 operation
RfH	floating-point source register (R0H to R7H) for the SUBF32 operation
RaH	floating-point destination register (R0H to R7H) for the MOV32 operation RaH cannot be the same register as RdH
mem32	pointer to 32-bit source memory location for the MOV32 operation

Opcode

```
LSW: 1110 0011 0010 fffe MSW: eedd daaa mem32
```

Description

Subtract the contents of two floating-point registers and move from memory to a floating-point register.

```
RdH = ReH - RfH, RaH = [mem32]
```

Restrictions

The destination register for the SUBF32 and the MOV32 must be unique. That is, RaH cannot be the same register as RdH.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	Yes	Yes	Yes	Yes	Yes	Yes

The STF register flags are modified as follows:

- LUF = 1 if SUBF32 generates an underflow condition.
- LVF = 1 if SUBF32 generates an overflow condition.

The MOV32 Instruction will set the NF, ZF, NI and ZI flags as follows:

```
NF = RaH(31);
ZF = 0;
if(RaH(30:23) == 0) { ZF = 1; NF = 0; }
NI = RaH(31);
ZI = 0;
if(RaH(31:0) == 0) ZI = 1;
```

Pipeline

SUBF32 is a 2 pipeline-cycle instruction (2p) and MOV32 takes a single cycle. That is:

```
SUBF32 RdH, ReH, RfH; 2 pipeline cycles (2p)

| MOV32 RaH, mem32; 1 cycle; --- MOV32 completes, RaH updated

NOP; 1 cycle delay or non-conflicting instruction; --- SUBF32 completes, RdH updated

NOP
```

Any instruction in the delay slot must not use RdH as a destination register or as a source operand.

www.ti.com SUBF32 RdH, ReH, RfH || MOV32 RaH, mem32 — 32-bit Floating-Point Subtraction with Parallel Move

Example

See also

SUBF32 RaH, RbH, RcH SUBF32 RaH, #16FHi, RbH

MPYF32 RaH, RbH, RcH | SUBF32 RdH, ReH, RfH



SUBF32 RdH, ReH, RfH || MOV32 mem32, RaH 32-bit Floating-Point Subtraction with Parallel Move

Operands

RdH	floating-point destination register (R0H to R7H) for the SUBF32 operation
ReH	floating-point source register (R0H to R7H) for the SUBF32 operation
RfH	floating-point source register (R0H to R7H) for the SUBF32 operation
mem32	pointer to 32-bit destination memory location for the MOV32 operation
RaH	floating-point source register (R0H to R7H) for the MOV32 operation

Opcode

LSW: 1110 0000 0010 fffe MSW: eedd daaa mem32

Description

Subtract the contents of two floating-point registers and move from a floating-point register to memory.

RdH = ReH - RfH, [mem32] = RaH

Flags

This instruction modifies the following flags in the STF register: SUBF32 RdH, ReH, RfH || MOV32 RaH, mem32

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	Yes	Yes

The STF register flags are modified as follows:

- LUF = 1 if SUBF32 generates an underflow condition.
- LVF = 1 if SUBF32 generates an overflow condition.

Pipeline

SUBF32 is a 2 pipeline-cycle instruction (2p) and MOV32 takes a single cycle. That is:

```
SUBF32 RdH, ReH, RfH; 2 pipeline cycles (2p)

|| MOV32 mem32, RaH; 1 cycle; -- MOV32 completes, mem32 updated

NOP; 1 cycle delay or non-conflicting instruction; -- ADDF32 completes, RdH updated

NOP
```

Any instruction in the delay slot must not use RdH as a destination register or as a source operand.

Example

```
ADDF32
         R3H, R6H, R4H; (A) R3H = R6H + R4H and R7H = I3
| MOV32
            R7H, *-SP[2] ;
                           ; <-- R7H valid
  SUBF32 R6H, R6H, R4H
                            ; (B) R6H = R6H - R4H
                          ; <-- ADDF32 (A) completes, R3H valid
  SUBF32 R3H, R1H, R7H
                            ; (C) R3H = R1H - R7H and store R3H (A)
| MOV32 *+XAR5[2], R3H
                          ; <-- SUBF32 (B) completes, R6H valid
                          ; <-- MOV32 completes, (A) stored
  ADDF32 R4H, R7H, R1H
                            ; R4H = D = R7H + R1H and store R6H (B)
|| MOV32 *+XAR5[6], R6H
                          ; <-- SUBF32 (C) completes, R3H valid
                          ; <-- MOV32 completes, (B) stored
  MOV32 *+XAR5[0], R3H
                          ; store R3H (C)
                          ; <-- MOV32 completes, (C) stored
                          ; <-- ADDF32 (D) completes, R4H valid
  MOV32 *+XAR5[4], R4H
                          ; store R4H (D)
                           ; <-- MOV32 completes, (D) stored
```



www.ti.com SUBF32 RdH, ReH, RfH || MOV32 mem32, RaH — 32-bit Floating-Point Subtraction with Parallel Move

See also SUBF32 RaH, RbH, RcH

SUBF32 RaH, #16FHi, RbH

SUBF32 RdH, ReH, RfH || MOV32 RaH, mem32 MPYF32 RaH, RbH, RcH || SUBF32 RdH, ReH, RfH



SWAPF RaH, RbH{, CNDF} Conditional Swap

Operands

RaH	floating-point register (R0H to R7H)
RbH	floating-point register (R0H to R7H)
CNDF	condition tested

Opcode LSW: 1110 0110 1110 CNDF

MSW: 0000 0000 00bb baaa

Description Conditional swap of RaH and RbH.

if (CNDF == true) swap RaH and RbH

CNDF is one of the following conditions:

Encode (1)	CNDF	Description	STF Flags Tested
0000	NEQ	Not equal to zero	ZF == 0
0001	EQ	Equal to zero	ZF == 1
0010	GT	Greater than zero	ZF == 0 AND NF == 0
0011	GEQ	Greater than or equal to zero	NF == 0
0100	LT	Less than zero	NF == 1
0101	LEQ	Less than or equal to zero	ZF == 1 AND NF == 1
1010	TF	Test flag set	TF == 1
1011	NTF	Test flag not set	TF == 0
1100	LU	Latched underflow	LUF == 1
1101	LV	Latched overflow	LVF == 1
1110	UNC	Unconditional	None
1111	UNCF (2)	Unconditional with flag modification	None

⁽¹⁾ Values not shown are reserved.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

No flags affected

Pipeline This is a single-cycle instruction.

Example ;find the largest element and put it in R1H

MOVL XAR1, #0xB000

MOV32 R1H, *XAR1 ; Initialize R1H

.align 2

NOP

RPTB LOOP_END, #(10-1); Execute the block 10 times MOV32 R2H, *XAR1++ ; Update R2H with next element

CMPF32 R2H, R1H ; Compare R2H with R1H

SWAPF R1H, R2H, GT ; Swap R1H and R2H if R2 > R1

NOP ; For minimum repeat block size

NOP ; For minimum repeat block size

LOOP_END:

⁽²⁾ This is the default operation if no CNDF field is specified. This condition will allow the ZF, NF, ZI, and NI flags to be modified when a conditional operation is executed. All other conditions will not modify these flags.



TESTTF CNDF Test STF Register Flag Condition

Operands

CNDF	condition to test		
------	-------------------	--	--

Opcode

LSW: 1110 0101 1000 CNDF

Description

Test the floating-point condition and if true, set the TF flag. If the condition is false, clear the TF flag. This is useful for temporarily storing a condition for later use.

if (CNDF == true) TF = 1; else TF = 0;

CNDF is one of the following conditions:

Encode (1)	CNDF	Description	STF Flags Tested
0000	NEQ	Not equal to zero	ZF == 0
0001	EQ	Equal to zero	ZF == 1
0010	GT	Greater than zero	ZF == 0 AND NF == 0
0011	GEQ	Greater than or equal to zero	NF == 0
0100	LT	Less than zero	NF == 1
0101	LEQ	Less than or equal to zero	ZF == 1 AND NF == 1
1010	TF	Test flag set	TF == 1
1011	NTF	Test flag not set	TF == 0
1100	LU	Latched underflow	LUF == 1
1101	LV	Latched overflow	LVF == 1
1110	UNC	Unconditional	None
1111	UNCF (2)	Unconditional with flag modification	None

⁽¹⁾ Values not shown are reserved.

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	Yes	No	No	No	No	No	No	

TF = 0; if (CNDF == true) TF = 1;

Note: If (CNDF == UNC or UNCF), the TF flag will be set to 1.

Pipeline

This is a single-cycle instruction.

Example

See also

⁽²⁾ This is the default operation if no CNDF field is specified. This condition will allow the ZF, NF, ZI, and NI flags to be modified when a conditional operation is executed. All other conditions will not modify these flags.



UI16TOF32 RaH, mem16 Convert unsigned 16-bit integer to 32-bit floating-point value

Operands

RaH	floating-point destination register (R0H to R7H)
mem16	pointer to 16-bit source memory location

Opcode LSW: 1110 0010 1100 0100 MSW: 0000 0aaa mem16

Description RaH = UI16ToF32[mem16]

NOP

source operand.

Flags

This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

```
UI16TOF32 RaH, mem16 ; 2 pipeline cycles (2p)
NOP ; 1 cycle delay or non-conflicting instruction
; <-- UI16TOF32 completes, RaH updated
```

Any instruction in the delay slot must not use RaH as a destination register or as a

Example

See also

F32TOI16 RaH, RbH F32TOI16R RaH, RbH F32TOUI16 RaH, RbH F32TOUI16R RaH, RbH I16TOF32 RaH, RbH I16TOF32 RaH, mem16 UI16TOF32 RaH, RbH



UI16TOF32 RaH, RbH Convert unsigned 16-bit integer to 32-bit floating-point value

Operands

RaH floating-point destination register (R0H to R7H)

RbH floating-point source register (R0H to R7H)

Opcode LSW: 1110 0110 1000 1111

MSW: 0000 0000 00bb baaa

Description RaH = UI16ToF32[RbH]

Flags This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No

Pipeline This is a 2 pipeline cycle (2p) instruction. That is:

UI16TOF32 RaH, RbH; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction

; <-- UI16TOF32 completes, RaH updated

NOP

Any instruction in the delay slot must not use RaH as a destination register or as a

source operand.

Example MOVXI R5H, #0x800F; R5H[15:0] = 32783 (0x800F)

UI16TOF32 R6H, R5H; R6H = UI16TOF32 (R5H[15:0])

NOP ; 1 cycle delay for UI16TOF32 to complete

; R6H = 32783.0 (0x47000F00)

See also F32TOI16 RaH, RbH

F32TOI16R RaH, RbH F32TOUI16 RaH, RbH F32TOUI16R RaH, RbH I16TOF32 RaH, RbH I16TOF32 RaH, mem16 UI16TOF32 RaH, mem16



UI32TOF32 RaH, mem32 Convert Unsigned 32-bit Integer to 32-bit Floating-Point Value

Operands

RaH	floating-point destination register (R0H to R7H)
mem32	pointer to 32-bit source memory location

Opcode LSW: 1110 0010 1000 0100

Description RaH = UI32ToF32[mem32]

MSW: 0000 0aaa mem32

Flags

This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No

Pipeline

This is a 2 pipeline cycle (2p) instruction. That is:

```
UI32TOF32 RaH, mem32 ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay non-conflicting instruction
; <-- UI32TOF32 completes, RaH updated

NOP
```

Any instruction in the delay slot must not use RaH as a destination register or as a source operand.

Example

```
; unsigned long X
; float Y, M, B
; ...
; Calculate Y = (float)X * M + B
 UI32TOF32 R0H, *-SP[2]; R0H = (float)X
 MOV32 R1H, *-SP[6]
                      ; R1H = M
                        ; <-- Conversion complete, ROH valid
 MPYF32 ROH, R1H, ROH ; ROH = (float)X * M
 MOV32 R1H, *-SP[8]
                        ; R1H = B
                        ; <-- MPYF32 complete, ROH valid
 ADDF32 ROH, ROH, R1H ; ROH = Y = (float)X * M + B
 NOP
                        ; <-- ADDF32 complete, ROH valid
 MOV32 *-[SP], R0H
                        ; Store Y
```

See also

F32TOI32 RaH, RbH F32TOUI32 RaH, RbH I32TOF32 RaH, mem32 I32TOF32 RaH, RbH UI32TOF32 RaH, RbH



UI32TOF32 RaH, RbH Convert Unsigned 32-bit Integer to 32-bit Floating-Point Value

Operands

RaH floating-point destination register (R0H to R7H)

RbH floating-point source register (R0H to R7H)

Opcode LSW: 1110 0110 1000 1011

MSW: 0000 0000 00bb baaa

Description RaH = UI32ToF32[RbH]

Flags This instruction does not affect any flags:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No

Pipeline This is a 2 pipeline cycle (2p) instruction. That is:

UI32TOF32 RaH, RbH; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction

; <-- UI32TOF32 completes, RaH updated

NOP

Any instruction in the delay slot must not use RaH as a destination register or as a

source operand.

Example MOVIZ R3H, #0x8000 ; R3H[31:16] = 0x8000

MOVXI R3H, #0x1111 ; R3H[15:0] = 0x1111 ; R3H = 2147488017 UI32TOF32 R4H, R3H ; R4H = UI32TOF32 (R3H)

NOP ; 1 cycle delay for UI32TOF32 to complete

; R4H = 2147488017.0 (0x4F000011)

See also F32TOI32 RaH, RbH

F32TOUI32 RaH, RbH I32TOF32 RaH, mem32 I32TOF32 RaH, RbH UI32TOF32 RaH, mem32



ZERO RaH Zero the Floating-Point Register RaH

Operands

RaH floating-point register (R0H to R7H)

Opcode LSW: 1110 0101 1001 0aaa

Description Zero the indicated floating-point register:

RaH = 0

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No

No flags affected.

Pipeline

This is a single-cycle instruction.

Example

```
for(i = 0; i < n; i++)
; {
; real += (x[2*i] * y[2*i]) - (x[2*i+1] * y[2*i+1]);
  imag += (x[2*i] * y[2*i+1]) + (x[2*i+1] * y[2*i]);
;}
; Assume AR7 = n-1
   ZERO R4H ; R4H = real = 0
   ZERO R5H; R5H = imag = 0
  MOV AL, AR7
  MOV ACC, AL << 2
  MOV ARO, ACC
  MOV32 R0H, *+XAR4[AR0]; R0H = x[2*i]
  MOV32 R1H, *+XAR5[AR0] ; R1H = y[2*i]
  ADD ARO, #2
  MPYF32 R6H, R0H, R1H; ; R6H = x[2*i] * y[2*i]
| | MOV32 R2H, *+XAR4[AR0] ; R2H = x[2*i+1]
  MPYF32 R1H, R1H, R2H ; R1H = y[2*i] * x[2*i+2]
| | MOV32 R3H, *+XAR5[AR0] ; R3H = y[2*i+1]
  MPYF32 R2H, R2H, R3H ; R2H = x[2*i+1] * y[2*i+1]
| ADDF32 R4H, R4H, R6H ; R4H += x[2*i] * y[2*i]
  MPYF32 ROH, ROH, R3H ; ROH = x[2*i] * y[2*i+1]
                         ; R5H += y[2*i] * x[2*i+2]
; R4H -= x[2*i+1] * y[2*i+1]
|| ADDF32 R5H, R5H, R1H
   SUBF32 R4H, R4H, R2H
   ADDF32 R5H, R5H,R0H
                          ; R5H += x[2*i] * y[2*i+1]
   BANZ LOOP , AR7--
```

See also

ZEROA



ZEROA

Zero All Floating-Point Registers

Operands

none

Opcode

LSW: 1110 0101 0110 0011

Description

Zero all floating-point registers:

R0H = 0 R1H = 0 R2H = 0 R3H = 0 R4H = 0 R5H = 0 R6H = 0 R7H = 0

Flags

This instruction modifies the following flags in the STF register:

Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	No	

No flags affected.

Pipeline

This is a single-cycle instruction.

Example

```
for(i = 0; i < n; i++)
; {
  real += (x[2*i] * y[2*i]) - (x[2*i+1] * y[2*i+1]);
  imag += (x[2*i] * y[2*i+1]) + (x[2*i+1] * y[2*i]);
;}
; Assume AR7 = n-1
   ZEROA ; Clear all RaH registers
LOOP
  MOV AL, AR7
  MOV ACC, AL << 2
  MOV ARO, ACC
  MOV32 R0H, *+XAR4[AR0]
                                 ; ROH = x[2*i]
  MOV32 R1H, *+XAR5[AR0]
                                   ; R1H = y[2*i]
  ADD AR0,#2
  MPYF32 R6H, R0H, R1H;
                                  ; R6H = x[2*i] * y[2*i]
|| MOV32 R2H, *+XAR4[AR0]
                                   ; R2H = x[2*i+1]
  MPYF32 R1H, R1H, R2H
                                  ; R1H = y[2*i] * x[2*i+2]
|| MOV32 R3H, *+XAR5[AR0]
                                  ; R3H = y[2*i+1]
  MPYF32 R2H, R2H, R3H
                                 ; R2H = x[2*i+1] * y[2*i+1]
                                  ; R4H += x[2*i] * y[2*i]
|| ADDF32 R4H, R4H, R6H
  MPYF32 ROH, ROH, R3H
                                 ; R0H = x[2*i] * y[2*i+1]
                                  ; R5H += y[2*i] * x[2*i+2]
| ADDF32 R5H, R5H, R1H
  SUBF32 R4H, R4H, R2H
                                   ; R4H -= x[2*i+1] * y[2*i+1]
  ADDF32 R5H, R5H,R0H
                                   ; R5H += x[2*i] * y[2*i+1]
  BANZ LOOP , AR7--
```

See also

ZERO RaH



C28 Viterbi, Complex Math and CRC Unit-II (VCU-II)

This chapter provides an overview of the architectural structure and instruction set of the Viterbi, Complex Math and CRC Unit (VCU-II) and describes the architecture, pipeline, instruction set, and interrupts. The VCU is a fully-programmable block which accelerates the performance of communications-based algorithms. In addition to eliminating the need for a second processor to manage the communications link, the performance gains of the VCU provides headroom for future system growth and higher bit rates or, conversely, enables devices to operate at a lower MHz to reduce system cost and power consumption.

Any references to VCU or VCU-II in this chapter relate to Type 2 specifically. Information pertaining to an older VCU will have the module type listed explicitly. See the *TMS320x28xx*, *28xxx DSP Peripheral Reference Guide* (SPRU566) for a list of all devices with a VCU module of the same type, to determine the differences between the types, and for a list of device-specific differences within a type.

Topic Page

2.1	Overview	141
2.2	Components of the C28x Plus VCU	142
2.3	Register Set	146
	Pipeline	
2.5	Instruction Set	159
	Rounding Mode	



www.ti.com Overview

2.1 Overview

The C28x with VCU (C28x+VCU) processor extends the capabilities of the C28x fixed-point or floating-point CPU by adding registers and instructions to support the following algorithm types:

Viterbi decoding

Viterbi decoding is commonly used in baseband communications applications. The viterbi decode algorithm consists of three main parts: branch metric calculations, compare-select (viterbi butterfly) and a traceback operation. Table 2-1 shows a summary of the VCU performance for each of these operations.

Table 2-1. Viterbi Decode Performance

Viterbi Operation	VCU Cycles
Branch Metric Calculation (code rate = 1/2)	1
Branch Metric Calculation (code rate = 1/3)	2p
Viterbi Butterfly (add-compare-select)	2 (1)
Traceback per Stage	3 (2)

⁽¹⁾ C28x CPU takes 15 cycles per butterfly.

Cyclic redundancy check (CRC)

CRC algorithms provide a straightforward method for verifying data integrity over large data blocks, communication packets, or code sections. The C28x+VCU can perform 8-, 16-, 24-, and 32-bit CRCs. For example, the VCU can compute the CRC for a block length of 10 bytes in 10 cycles. A CRC result register contains the current CRC which is updated whenever a CRC instruction is executed.

Complex math

Complex math is used in many applications. The VCU A few of which are:

Fast fourier transform (FFT)

The complex FFT is used in spread spectrum communications, as well in many signal processing algorithms.

Complex filters

Complex filters improve data reliability, transmission distance, and power efficiency. The C28x+VCU can perform a complex I and Q multiply with coefficients (four multiplies) in a single cycle. In addition, the C28x+VCU can read/write the real and imaginary parts of 16-bit complex data to memory in a single cycle.

Table 2-2 shows a summary of the VCU operations enabled by the VCU:

Table 2-2. Complex Math Performance

Complex Math Operation	VCU Cycles	Notes
Add Or Subtract	1	32 +/- 32 = 32-bit (Useful for filters)
Add or Subtract	1	16 +/- 32 = 15-bit (Useful for FFT)
Multiply	2р	16 x 16 = 32-bit
Multiply & Accumulate (MAC)	2р	32 + 32 = 32-bit, 16 x 16 = 32-bit
RPT MAC	2p+N	Repeat MAC. Single cycle after the first operation.

This C28x+VCU draws from the best features of digital signal processing; reduced instruction set computing (RISC); and microcontroller architectures, firmware, and tool sets. The C2000 features include a modified Harvard architecture and circular addressing. The RISC features are single-cycle instruction execution, register-to-register operations, and modified Harvard architecture (usable in Von Neumann mode). The microcontroller features include ease of use through an intuitive instruction set, byte packing and unpacking, and bit manipulation. The modified Harvard architecture of the CPU enables instruction and data fetches to be performed in parallel. The CPU can read instructions and data while it writes data simultaneously to maintain the single-cycle instruction operation across the pipeline. The CPU does this over six separate address/data buses.

Throughout this document the following notations are used:

⁽²⁾ C28x CPU takes 22 cycles per stage.



- C28x refers to the C28x fixed-point CPU.
- C28x plus Floating-Point and C28x+FPU both refer to the C28x CPU with enhancements to support IEEE single-precision floating-point operations.
- C28x plus VCU and C28x+VCU both refer to the C28x CPU with enhancements to support viterbidecode, complex math, forward error correcting algorithms, and CRC.
- Some devices have both the FPU and the VCU. These are referred to as C28x+FPU+VCU.

2.2 Components of the C28x Plus VCU

The VCU extends the capabilities of the C28x CPU and C28x+FPU processors by adding additional instructions. No changes have been made to existing instructions, pipeline, or memory bus architecture. Therefore, programs written for the C28x are completely compatible with the C28x+VCU. All of the features of the C28x documented in TMS320C28x DSP CPU and Instruction Set Reference Guide (literature number SPRU430) apply to the C28x+VCU. All features documented in the TMS320C28x Floating Point Unit and Instruction Set Reference Guide (SPRUE02) apply to the C28x+FPU+VCU.

Figure 2-1 shows the block diagram of the VCU.




Figure 2-1. C28x + VCU Block Diagram



The C28x+VCU contains the same features as the C28x fixed-point CPU:

- A central processing unit for generating data and program-memory addresses; decoding and executing instructions; performing arithmetic, logical, and shift operations; and controlling data transfers among CPU registers, data memory, and program memory.
- Emulation logic for monitoring and controlling various parts and functions of the device and for testing device operation. This logic is identical to that on the C28x fixed-point CPU.
- Signals for interfacing with memory and peripherals, clocking and controlling the CPU and the
 emulation logic, showing the status of the CPU and the emulation logic, and using interrupts. This logic
 is identical to the C28x fixed-point CPU.
- Arithmetic logic unit (ALU). The 32-bit ALU performs 2s-complement arithmetic and Boolean logic operations.
- Address register arithmetic unit (ARAU). The ARAU generates data memory addresses and increments or decrements pointers in parallel with ALU operations.
- Fixed-Point instructions are pipeline protected. This pipeline for fixed-point instructions is identical to that on the C28x fixed-point CPU. The CPU implements an 8-phase pipeline that prevents a write to and a read from the same location from occurring out of order.
- Barrel shifter. This shifter performs all left and right shifts of fixed-point data. It can shift data to the left by up to 16 bits and to the right by up to 16 bits.
- Fixed-Point Multiplier. The multiplier performs 32-bit x 32-bit 2s-complement multiplication with a 64-bit result. The multiplication can be performed with two signed numbers, two unsigned numbers, or one signed number and one unsigned number.

The VCU adds the following features:

- Instructions to support Cyclic Redundancy Check (CRC) or a polynomial code checksum
 - CRC8
 - CRC16
 - CRC32
 - CRC24
- Clocked at the same rate as the main CPU (SYSCLKOUT).
- Instructions to support a software implementation of a Viterbi Decoder of constraint length 4 7 and code rates of 1/2 and 1/3
 - Branch metrics calculations
 - Add-Compare Select or Viterbi Butterfly
 - Traceback
- · Complex Math Arithmetic Unit
 - Add or Subtract
 - Multiply
 - Multiply and Accumulate (MAC)
 - Repeat MAC (RPT || MAC).
- Independent register space. These registers function as source and destination registers for VCU instructions.
- Some VCU instructions require pipeline alignment. This alignment is done through software to allow the user to improve performance by taking advantage of required delay slots. See Section 2.4 for more information.

Devices with the floating-point unit also include:

- Floating point unit (FPU). The 32-bit FPU performs IEEE single-precision floating-point operations.
- Dedicated floating-point registers.



2.2.1 Emulation Logic

The emulation logic is identical to that on the C28x fixed-point CPU. This logic includes the following features. For more details about these features, refer to the TMS320C28x DSP CPU and Instruction Set Reference Guide (literature number SPRU430):

- Debug-and-test direct memory access (DT-DMA). A debug host can gain direct access to the content of registers and memory by taking control of the memory interface during unused cycles of the instruction pipeline
- A counter for performance benchmarking.
- Multiple debug events. Any of the following debug events can cause a break in program execution:
 - A breakpoint initiated by the ESTOP0 or ESTOP1 instruction.
 - An access to a specified program-space or data-space location. When a debug event causes the C28x to enter the debug-halt state, the event is called a break event.
- Real-time mode of operation.

2.2.2 Memory Map

Like the C28x, the C28x+VCU uses 32-bit data addresses and 22-bit program addresses. This allows for a total address reach of 4G words (1 word = 16 bits) in data space and 4M words in program space. Memory blocks on all C28x+VCU designs are uniformly mapped to both program and data space. For specific details about each of the map segments, see the device-specific data manual.

2.2.3 CPU Interrupt Vectors

The C28x+VCU interrupt vectors are identical to those on the C28x CPU. Sixty-four addresses in program space are set aside for a table of 32 CPU interrupt vectors. For more information about the CPU vectors, see TMS320C28x CPU and Instruction Set Reference Guide (literature number SPRU430). Typically the CPU interrupt vectors are only used during the boot up of the device by the boot ROM. Once an application has taken control it should initialize and enable the peripheral interrupt expansion block (PIE).

2.2.4 Memory Interface

The C28x+VCU memory interface is identical to that on the C28x. The C28x+VCU memory map is accessible outside the CPU by the memory interface, which connects the CPU logic to memories, peripherals, or other interfaces. The memory interface includes separate buses for program space and data space. This means an instruction can be fetched from program memory while data memory is being accessed. The interface also includes signals that indicate the type of read or write being requested by the CPU. These signals can select a specified memory block or peripheral for a given bus transaction. In addition to 16-bit and 32-bit accesses, the CPU supports special byte-access instructions that can access the least significant byte (LSByte) or most significant byte (MSByte) of an addressed word. Strobe signals indicate when such an access is occurring on a data bus.

2.2.5 Address and Data Buses

Like the C28x, the memory interface has three address buses:

- PAB: Program address bus: The 22-bit PAB carries addresses for reads and writes from program space.
- DRAB: Data-read address bus: The 32-bit DRAB carries addresses for reads from data space.
- DWAB: Data-write address bus: The 32-bit DWAB carries addresses for writes to data space.

The memory interface also has three data buses:

- PRDB: Program-read data bus: The 32-bit PRDB carries instructions during reads from program space.
- DRDB: Data-read data bus: The 32-bit DRDB carries data during reads from data space.
- DWDB: Data-/Program-write data bus: The 32-bit DWDB carries data during writes to data space or program space.



A program-space read and a program-space write cannot happen simultaneously because both use the PAB. Similarly, a program-space write and a data-space write cannot happen simultaneously because both use the DWDB. Transactions that use different buses can happen simultaneously. For example, the CPU can read from program space (using PAB and PRDB), read from data space (using DRAB and DRDB), and write to data space (using DWAB and DWDB) at the same time. This behavior is identical to the C28x CPU.

2.2.6 Alignment of 32-Bit Accesses to Even Addresses

The C28x+VPU expects memory wrappers or peripheral-interface logic to align any 32-bit read or write to an even address. If the address-generation logic generates an odd address, the CPU will begin reading or writing at the previous even address. This alignment does not affect the address values generated by the address-generation logic.

Most instruction fetches from program space are performed as 32-bit read operations and are aligned accordingly. However, alignment of instruction fetches are effectively invisible to a programmer. When instructions are stored to program space, they do not have to be aligned to even addresses. Instruction boundaries are decoded within the CPU.

You need to be concerned with alignment when using instructions that perform 32-bit reads from or writes to data space.



Register Set www.ti.com

2.3 Register Set

Devices with the C28x+VCU include the standard C28x register set plus an additional set of VCU specific registers. The additional VCU registers are the following:

Result registers: VR0, VR1... VR8Traceback registers: VT0, VT1

Configuration and status register: VSTATUS

CRC result register: VCRCRepeat block register: RB

Figure 2-2 shows the register sets for the 28x CPU, the FPU and the VCU. The following section discusses the VCU register set in detail.

Figure 2-2. C28x + FPU + VCU Registers

Standard	C28x	Register	Set
----------	------	----------	-----

Standard C28x Register Set
ACC (32-bit)
P (32-bit)
XT (32-bit)
XAR0 (32-bit)
XAR1 (32-bit)
XAR2 (32-bit)
XAR3 (32-bit)
XAR4 (32-bit)
XAR5 (32-bit)
XAR6 (32-bit)
XAR7 (32-bit)
PC (22-bit)
RPC (22-bit)
DP (16-bit)
SP (16-bit)
ST0 (16-bit)
ST1 (16-bit)
IER (16-bit)
IFR (16-bit)
DBGIER (16-bit)
DBGIER (10 bit)

Additional	32-bit	FPU	Registers

<u> </u>
R0H (32-bit)
R1H (32-bit)
R2H (32-bit)
R3H (32-bit)
R4H (32-bit)
R5H (32-bit)
1311 (32-011)
R6H (32-bit)
R7H (32-bit)
(32 314)
EDITO() D : ((CTE)
FPU Status Register (STF)
Repeat Block Register (RB)
FPU registers R0H - R7H and STF
are shadowed for fast context
save and restore
5475 4H4 1001010

Standard VCU Register Set

VR0
VR1
VR2
VR3
VR4
VR5
VR6
VR7
VR8
VT0
VT1
VSTATUS
VCRC
VSM0
VSM1
:
· :
VSM63



www.ti.com Register Set

2.3.1 VCU Register Set

Table 2-3 describes the VCU module register set. The last three columns indicate whether the particular module within the VCU can make use of the register.

Table 2-3. VCU Register Set

Register				Complex	
Name	Size	Description	Viterbi	Math	CRC
VR0	32 bits	General purpose register 0	Yes	Yes	No
VR1	32 bits	General purpose register 1	Yes	Yes	No
VR2	32 bits	General purpose register 2	Yes	Yes	No
VR3	32 bits	General purpose register 3	Yes	Yes	No
VR4	32 bits	General purpose register 4	Yes	Yes	No
VR5	32 bits	General purpose register 5	Yes	Yes	No
VR6	32 bits	General purpose register 6	Yes	Yes	No
VR7	32 bits	General purpose register 7	Yes	Yes	No
VR8	32 bits	General purpose register 8	Yes	No	No
VT0	32 bits	32-bit transition bit register 0	Yes	No	No
VT1	32 bits	32-bit transition bit register 1	Yes	No	No
VSTATUS	32 bits	VCU status and configuration register (1)	Yes	Yes	No
VCRC	32 bits	Cyclic redundancy check (CRC) result register	No	No	Yes
VSM0- VSM63	32 bits	Viterbi Decoding State Metric registers	Yes	No	No
VRx.By x = 0 - 7 y = 0 - 3	32 bits	Aliased address space for each byte of the VRx registers, left-shifted by one	No	No	No

⁽¹⁾ Debugger writes are not allowed to the VSTATUS register.

Table 2-4 lists the CPU registers available on devices with the C28x, the C28x+FPU, the C28x+VCU and the C28x+FPU+VCU.



Register Set www.ti.com

Table 2-4. 28x CPU Register Summary

Register	C28x CPU	C28x+FPU	C28x+VCU	C28x+FPU+VCU	Description
ACC	Yes	Yes	Yes	Yes	Fixed-point accumulator
AH	Yes	Yes	Yes	Yes	High half of ACC
AL	Yes	Yes	Yes	Yes	Low half of ACC
XAR0 - XAR7	Yes	Yes	Yes	Yes	Auxiliary register 0 - 7
AR0 - AR7	Yes	Yes	Yes	Yes	Low half of XAR0 - XAR7
DP	Yes	Yes	Yes	Yes	Data-page pointer
IFR	Yes	Yes	Yes	Yes	Interrupt flag register
IER	Yes	Yes	Yes	Yes	Interrupt enable register
DBGIER	Yes	Yes	Yes	Yes	Debug interrupt enable register
Р	Yes	Yes	Yes	Yes	Fixed-point product register
PH	Yes	Yes	Yes	Yes	High half of P
PL	Yes	Yes	Yes	Yes	Low half of P
PC	Yes	Yes	Yes	Yes	Program counter
RPC	Yes	Yes	Yes	Yes	Return program counter
SP	Yes	Yes	Yes	Yes	Stack pointer
ST0	Yes	Yes	Yes	Yes	Status register 0
ST1	Yes	Yes	Yes	Yes	Status register 1
XT	Yes	Yes	Yes	Yes	Fixed-point multiplicand register
Т	Yes	Yes	Yes	Yes	High half of XT
TL	Yes	Yes	Yes	Yes	Low half of XT
ROH - R7H	No	Yes	No	Yes	Floating-point Unit result registers
STF	No	Yes	No	Yes	Floating-point Uint status register
RB	No	Yes	Yes	Yes	Repeat block register
VR0 - VR8	No	No	Yes	Yes	VCU general purpose registers
VT0, VT1	No	No	Yes	Yes	VCU transition bit register 0 and 1
VSTATUS	No	No	Yes	Yes	VCU status and configuration
VCRC	No	No	Yes	Yes	CRC result register
VSM0-VSM63	No	No	Yes ⁽¹⁾	Yes ⁽¹⁾	Viterbi State Metric Registers
VRx.By x = 0 - 7 y = 0 - 3	No	No	Yes ⁽¹⁾	Yes ⁽¹⁾	Aliased address space for each byte of the VRx registers, left-shifted by one

⁽¹⁾ Present on Type-2 VCU only



www.ti.com Register Set


2.3.2 VCU Status Register (VSTATUS)

The VCU status register (VSTATUS) register is described in Figure 2-3. There is no single instruction to directly transfer the VSTATUS register to a C28x register. To transfer the contents:

- 1. Store VSTATUS into memory using VMOV32 mem32, VSTATUS instruction
- 2. Load the value from memory into a main C28x CPU register.

Configuration bits within the VSTATUS registers are set or cleared using VCU instructions.

Figure 2-3. VCU Status Register (VSTATUS)



LEGEND: R/W = Read/Write; R = Read only; -n = value after reset

Table 2-5. VCU Status (VSTATUS) Register Field Descriptions

Bits	Field	Value	Description
31	CRCMSGF LIP ⁽¹⁾		CRC Message Flip This bit affects the order in which the bits in the message are taken for CRC calculation by all the CRC instructions.
		0	Message bits are taken starting from most-significant to least-significant for CRC computation. In this case, bytes loaded from memory are fed directly for CRC computation.
		1	Message bits are taken starting from least-significant to most-significant for CRC computation. In this case, bytes loaded from memory are "flipped" and then fed for CRC computation.
30	DIVE ⁽¹⁾		Divide-by-zero Error
		0	Indicates whether a "divide by zero" occurred during a VMOD32 computation. This bit is cleared by executing the VCLRDIVE instruction
		1	
29-27	K ⁽¹⁾		Constraint Length for Viterbi Decoding
		0x7	This field sets the constraint length for the Viterbi decoding algorithm. It accepts values of 4 to 7. Values outside this range will be treated as 7 by the hardware.
		1	
26-24	GFORDER ⁽		Galois Field Polynomial Order
	1)	0x7	This field holds the Order of the polynomial for all the Galois Field instructions. This field is initialized by the VGFINIT mem16 instruction. The actual order of the polynomial is GFORDER+1
23-16	GFPOLY ⁽¹⁾		Galois Field Polynomial
		0	This field holds the Polynomial for all the Galois Field instructions. This field is initialized by the VGFINIT mem16 instruction.
		1	
15	OPACK ⁽¹⁾		Viterbi Traceback Packing Order This bit affects the packing order of the traceback output bits (using the VTRACE instructions)
		0	Big-endian (compatible with VCU Type-0 output packing order)
		1	Little-endian (VCU Type-2 mode)
14	CPACK ⁽¹⁾		Complex Packing Order This bit affects the packing order of the 16-bit real and 16-bit imaginary part of a complex numbers inside the 32-bit general purpose VRx register.
		0	VRx[31:16] holds Real part, VRx[15:0] holds Imaginary part (VCU-I compatible mode)
		1	VRx[31:16] holds Imaginary part; VRx[15:0] holds Real part

⁽¹⁾ Present on Type-2 VCU only.



Register Set www.ti.com

Table 2-5. VCU Status (VSTATUS) Register Field Descriptions (continued)

Bits	Field	Value	Description
13	OVRI		Overflow or Underflow Flag: Imaginary Part
		0	No overflow or underflow has been detected.
		1	Indicates an overflow or underflow has occurred during the computation of the imaginary part of operations shown in Table 10-6. This bit will be set regardless of the value of the VSTATUS[SAT] bit.OVRI bit will remain set until it is cleared by executing the VCLROVFI instruction.
12	OVFR		Overflow or Underflow Flag: Real Part
		0	No overflow or underflow has been detected.
		1	Indicates overflow or underflow has occurred during a real number calculation for operations shown in Table 2-6. This bit will be set regardless of the value of the VSTATUS[SAT] bit. This bit will remain set until it is cleared by executing the VCLROVFR instruction.
11	RND		Rounding
			When a right-shift operation is performed the lower bits of the value will be lost. The RND bit determines if the shifted value is rounded or if the shifted-out bits are simply truncated. This is described in Section 2.3.2. Operations which use right-shift and rounding are shown in Table 2-6. The RND bit is set by the VRNDON instruction and cleared by the VRNDOFF instruction.
		0	Rounding is not performed. Bits shifted out right are truncated.
		1	Rounding is performed. Refer to the instruction descriptions for information on how the operation is affected by the RND bit.
10	SAT		Saturation
			This bit determines whether saturation will be performed for operations shown in Table 2-6. The SAT bit is set by the VSATON instruction and is cleared by the VSATOFF instruction.
		0	No saturation is performed.
		1	Saturation is performed.
9-5	SHIFTL		Left Shift
			Operations which use left-shift are shown in Table 2-6 The shift SHIFTL field can be set or cleared by the VSETSHL instruction.
		0	No left shift.
		0x01 - 0x1F	Refer to the instruction description for information on how the operation is affected by the shift value. During the left-shift, the lower bits are filled with 0's.
4-0	SHIFTR		Right Shift
			Operations which use right-shift and rounding are shown in Table 2-6. The shift SHIFTR field can be set or cleared by the VSETSHR instruction.
		0	No right shift.
		0x01 - 0x1F	Refer to the instruction descriptions for information on how the operation is affected by the shift value. During the right-shift, the lower bits are lost, and the shifted value is sign extended. If rounding is enabled (VSTATUS[RND] == 1), then the value will be rounded instead of truncated.

Table 2-6 shows a summary of the operations that are affected by or modify bits in the VSTATUS register.

Table 2-6. Operation Interaction With VSTATUS Bits

Operation ⁽¹⁾	Description	OVFI	OVFR	RND	SAT	SHIFTL	SHIFTR	CPACK	OPACK	DIVE
VITDLADDSUB	Viterbi Add and Subtract Low	-	Y	-	Y	-	-	-	-	-
VITDHADDSUB	Viterbi Add and Subtract High	-	Y	-	Y	-	-	-	-	-
VITDLSUBADD	Viterbi Subtract and Add Low	-	Y	-	Y	-	-	-	-	-
VITDHSUBADD	Viterbi Subtract and Add High	-	Y	-	Y	-	-	-	-	-
VITBM2	Viterbi Branch Metric CR 1/2	-	Y	-	Y	-	-	-	-	-
VITBM3	Viterbi Branch Metric CR 1/3	-	Y	-	Y	-	-	-	-	-
VTRACE ⁽²⁾	Viterbi Trace-back	-	-	-	-	-	-	-	Υ	-

⁽¹⁾ Some parallel instructions also include these operations. In this case, the operation will also modify, or be affected by, VSTATUS bits as when used as part of a parallel instruction.

⁽²⁾ Present on Type-2 VCU only.



www.ti.com Register Set

Table 2-6. Operation Interaction With VSTATUS Bits (continued)

Operation ⁽¹⁾	Description	OVFI	OVFR	RND	SAT	SHIFTL	SHIFTR	CPACK	OPACK	DIVE
VITSTAGE ⁽²⁾	Viterbi Compute 32 Butterfly	-	Y	-	Y	-	-	-	-	-
VCADD	Complex 32 + 32 = 32	Υ	Y	Y	Y	-	Y	-	-	-
VCDADD16	Complex 16 + 32 = 32	Υ	Y	Y	Y	Υ	Υ	-	-	-
VCDSUB16	Complex 16 - 32 = 32	Υ	Y	Y	Y	Υ	Υ	-	-	-
VCMAC	Complex 32 + 32 = 32, 16 x 16 = 32	Υ	Y	Y	Y	-	Y	-	-	-
VCCMAC ⁽²⁾	Complex Conjugate 32 + 32 = 32, 16 x 16 = 32	Y	Y	Y	Y	-	Y	Y	-	-
VCMPY	Complex 16 x 16 = 32	Υ	Y	-	Y	-	-	Y	-	
VCCMPY ⁽²⁾	Complex Conjugate 16 x 16 = 32	Υ	Y	-	Y	-	-	Y	-	-
VCSUB	Complex 32 - 32 = 32	Υ	Y	Y	Υ	-	Υ	-	-	
VCCON ⁽²⁾	Complex Conjugate	Υ	-	-	Υ	-	-	Υ	-	
VCSHL16 ⁽²⁾	Complex Shift Left	Υ	Y	-	Y	-	-	Y	-	
VCHR16 ⁽²⁾	Complex Shift Right	-	-	Y	-	-	-	-	-	
VCMAG ⁽²⁾	Complex Number Magnitude	-	Y	Y	Y	-	-	-	-	-
VNEG	Two's Complement Negation	-	Υ	-	Y	-	-	-	-	-
VASHR32 ⁽²⁾	Arithmetic Shift Right	-	-	Y	-	-	-	-	-	
VASHL32 ⁽²⁾	Arithmetic Shift Left	-	Y	-	Y	-	-	-	-	-
VMPYADD ⁽²⁾	Arithmetic Multiply Add 16 + ((16 x 16) >> SHR) = 16		Y	Y	Y	-	Y	-	-	-
VCFFTx ⁽²⁾ Complex FFT calculation Y Y Y Step (x = 1 - 10)		Y	-	Y	-	-	-			
VMOD32	Modulo 32 % 16 = 16	-	-	-	-	-	-	-	-	Υ

Copyright © 2014–2015, Texas Instruments Incorporated

151



Register Set www.ti.com

2.3.3 Repeat Block Register (RB)


The repeat block instruction (RPTB) applies to devices with the C28x+FPU and the C28x+VCU. This instruction allows you to repeat a block of code as shown in Example 2-1.

Example 2-1. The Repeat Block (RPTB) Instruction uses the RB Register

```
; find the largest element and put its address in XAR6
; This example makes use of floating-point (C28x + FPU) instructions
   MOV32 R0H, *XAR0++;
   .align 2
                             ; Aligns the next instruction to an even address
   NOP
                            ; Makes RPTB odd aligned - required for a block size of 8
   RPTB VECTOR_MAX_END, AR7; RA is set to 1
   MOVL ACC, XAR0
                            ; RSIZE reflects the size of the RPTB block
   MOV32 R1H, *XAR0++
                             ; in this case the block size is 8
   MAXF32 ROH,R1H
   MOVSTO NF, ZF
   MOVL XAR6, ACC, LT
VECTOR_MAX_END:
                             ; RE indicates the end address. RA is cleared
```

The C28x FPU or VCU automatically populates the RB register based on the execution of a RPTB instruction. This register is not normally read by the application and does not accept debugger writes.

Figure 2-4. Repeat Block Register (RB)



LEGEND: R = Read only; -n = value after reset

Table 2-7. Repeat Block (RB) Register Field Descriptions

Bits	Field	Value	Description
31	RAS		Repeat Block Active Shadow Bit
			When an interrupt occurs the repeat active, RA, bit is copied to the RAS bit and the RA bit is cleared. When an interrupt return instruction occurs, the RAS bit is copied to the RA bit and RAS is cleared.
		0	A repeat block was not active when the interrupt was taken.
		1	A repeat block was active when the interrupt was taken.
30	RA		Repeat Block Active Bit
		0	This bit is cleared when the repeat counter, RC, reaches zero.
			When an interrupt occurs the RA bit is copied to the repeat active shadow, RAS, bit and RA is cleared. When an interrupt return, IRET, instruction is executed, the RAS bit is copied to the RA bit and RAS is cleared.
		1	This bit is set when the RPTB instruction is executed to indicate that a RPTB is currently active.
29-23	RSIZE		Repeat Block Size
			This 7-bit value specifies the number of 16-bit words within the repeat block. This field is initialized when the RPTB instruction is executed. The value is calculated by the assembler and inserted into the RPTB instruction's RSIZE opcode field.
		0-7	Illegal block size.
		8/9-0x7F	A RPTB block that starts at an even address must include at least 9 16-bit words and a block that starts at an odd address must include at least 8 16-bit words. The maximum block size is 127 16-bit words. The codegen assembler will check for proper block size and alignment.



www.ti.com Register Set

Table 2-7. Repeat Block (RB) Register Field Descriptions (continued)

Bits	Field	Value	Description
22-16	RE		Repeat Block End Address
			This 7-bit value specifies the end address location of the repeat block. The RE value is calculated by hardware based on the RSIZE field and the PC value when the RPTB instruction is executed.
			RE = lower 7 bits of (PC + 1 + RSIZE)
15-0	RC		Repeat Count
		0	The block will not be repeated; it will be executed only once. In this case the repeat active, RA, bit will not be set.
		1- 0xFFFF	This 16-bit value determines how many times the block will repeat. The counter is initialized when the RPTB instruction is executed and is decremented when the PC reaches the end of the block. When the counter reaches zero, the repeat active bit is cleared and the block will be executed one more time. Therefore the total number of times the block is executed is RC+1.



Pipeline www.ti.com

2.4 Pipeline

This section describes the VCU pipeline stages and presents cases where pipeline alignment must be considered.

2.4.1 Pipeline Overview

The C28x VCU pipeline is identical to the C28x pipeline for all standard C28x instructions. In the decode2 stage (D2), it is determined if an instruction is a C28x instruction, a FPU instruction, or a VCU instruction. The pipeline flow is shown in Figure 2-5.

Notice that stalls due to normal C28x pipeline stalls (D2) and memory waitstates (R2 and W) will also stall any C28x VCU instruction. Most C28x VCU instructions are single cycle and will complete in the VCU E1 or W stage which aligns to the C28x pipeline. Some instructions will take an additional execute cycle (E2). For these instructions you must wait a cycle for the result from the instruction to be available. The rest of this section will describe when delay cycles are required. Keep in mind that the assembly tools for the C28x+VCU will issue an error if a delay slot has not been handled correctly.




Figure 2-5. C28x + FCU + VCU Pipeline

2.4.2 General Guidelines for VCU Pipeline Alignment

The majority of the VCU instructions do not require any special pipeline considerations. This section lists the few operations that do require special consideration.

While the C28x+VCU assembler will issue errors for pipeline conflicts, you may still find it useful to understand when software delays are required. This section describes three guidelines you can follow when writing C28x+VCU assembly code.

VCU instructions that require delay slots have a 'p' after their cycle count. For example '2p' stands for 2 pipelined cycles. This means that an instruction can be started every cycle, but the result of the instruction will only be valid one instruction later.

Table 2-8 outlines the instructions that need delay slots.



www.ti.com Pipeline

Table 2-8.	Operations	Requiring	a Delay	v Slot(s)	١

Operation ⁽¹⁾	Description	Cycles
VITBM3	Viterbi Branch Metric CR 1/3	2p/2 ⁽²⁾
VCMAC	Complex 32 + 32 = 32, 16 x 16 = 32	2р
VCCMAC ⁽³⁾	Complex Conjugate 32 + 32 = 32, 16 x 16 = 32	2р
VCMPY	Complex 16 x 16 = 32	2р
VCCMPY ⁽³⁾	Complex Conjugate 16 x 16 = 32	2р
VCMAG ⁽³⁾	Complex Number Magnitude	2
VCFFTx ⁽³⁾	Complex FFT calculation step ($x = 1 - 10$)	2p/2 ⁽²⁾
VMOD32	Modulo 32 % 16 = 16	9р
VMPYADD ⁽³⁾	Arithmetic Multiply Add 16 + ((16 x 16) >> SHR) = 16	2р

⁽¹⁾ Some parallel instructions also include these operations. In this case, the operation will also modify, or be affected by, VSTATUS bits as when used as part of a parallel instruction.

An example of the complex multiply instruction is shown in Example 2-2. VCMPY is a 2p instruction and therefore requires one delay slot. The destination registers for the operation, VR2 and VR3, will be updated one cycle after the instruction for a total of two cycles. Therefore, a NOP or instruction that does not use VR2 or VR3 must follow this instruction.

Any memory stall or pipeline stall will also stall the VCU. This keeps the VCU aligned with the C28x pipeline and there is no need to change the code based on the waitstates of a memory block.

Example 2-2. 2p Instruction Pipeline Alignment

```
VCMPY VR3, VR2, VR1, VR0 ; 2 pipeline cycles (2p)

NOP ; 1 cycle delay or non-conflicting instruction
; <-- VCMPY completes, VR2 and VR3 updated

NOP ; Any instruction
```

2.4.3 Parallel Instructions

Parallel instructions are single opcodes that perform two operations in parallel. The guidelines provided in Section 2.4.2 apply to parallel instructions as well. In this case the cycle count will be given for both operations. For example, a branch metric calculation for code rate of 1/3 with a parallel load takes 2p/1 cycles. This means the branch metric portion of the operation takes two pipelined cycles while the move portion of the operation is single cycle. NOPs or other non conflicting instructions must be inserted to align the branch metric calculation portion of the operation as shown in Example 2-4.

Example 2-3. Branch Metric CR 1/2 Calculation with Parallel Load

⁽²⁾ Variations of the instruction execute differently. In these cases, the user is referred to the description Example 2-2 of the instruction(s) in Section 2.5.

⁽³⁾ Present on Type-2 VCU only.



Pipeline www.ti.com

Example 2-4. Branch Metric CR 1/3 Calculation with Parallel Load

2.4.4 Invalid Delay Instructions

All VCU, FPU and fixed-point instructions can be used in VCU instruction delay slots as long as source and destination register conflicts are avoided. The C28x+VCU assembler will issue an error anytime you use an conflicting instruction within a delay slot. The following guidelines can be used to avoid these conflicts.

NOTE: Destination register conflicts in delay slots:

Any operation used for pipeline alignment delay must not use the same destination register as the instruction requiring the delay. See Example 2-5.

In Example 2-5 the VCMPY instruction uses VR2 and VR3 as its destination registers. The next instruction should not use VR2 or VR3 as a destination. Since the VMOV32 instruction uses the VR3 register a pipeline conflict will be issued by the assembler. This conflict can be resolved by using a register other than VR2 for the VMOV32 instruction as shown in Example 2-6.



www.ti.com Pipeline

Example 2-5. Destination Register Conflict

```
; Invalid delay instruction.
; Both instructions use the same destination register (VR3)
;

VCMPY VR3, VR2, VR1, VR0 ; 2p instruction
VMOV32 VR3, mem32 ; Invalid delay instruction
; <-- VCMPY completes, VR3, VR2 are valid
```

Example 2-6. Destination Register Conflict Resolved

```
; Valid delay instruction
;
VCMPY VR3, VR2, VR1, VR0 ; 2p instruction
VMOV32 VR7, mem32 ; Valid delay instruction
```

NOTE: Instructions in delay slots cannot use the instruction's destination register as a source register.

Any operation used for pipeline alignment delay must not use the destination register of the instruction requiring the delay as a source register as shown in Example 2-7. For parallel instructions, the current value of a register can be used in the parallel operation before it is overwritten as shown in Example 2-9.

In Example 2-7 the VCMPY instruction again uses VR3 and VR2 as its destination registers. The next instruction should not use VR3 or VR2 as its source since the VCMPY will take an additional cycle to complete. Since the VCADD instruction uses the VR2 as a source register a pipeline conflict will be issued by the assembler. The use of VR3 will also cause a pipeline conflict. This conflict can be resolved by using a register other than VR2 or VR3 or by inserting a non-conflicting instruction between the VCMPY and VCADD instructions. Since the VNEG does not use VR2 or VR3 this instruction can be moved before the VCADD as shown in Example 2-8.

Example 2-7. Destination/Source Register Conflict

Example 2-8. Destination/Source Register Conflict Resolved

```
; Valid delay instruction.
;

VCMPY VR3, VR2, VR1, VR0 ; 2p instruction
VNEG VR0 ; Non conflicting instruction or NOP
VCADD VR5, VR4, VR3, VR2 ; <- VCMPY completes, VR3, VR2 valid
```

It should be noted that a source register for the second operation within a parallel instruction can be the same as the destination register of the first operation. This is because the two operations are started at the same time. The second operation is not in the delay slot of the first operation. Consider Example 2-9 where the VCMPY uses VR3 and VR2 as its destination registers. The VMOV32 is the second operation in the instruction and can freely use VR3 or VR2 as a source register. In the example, the contents of VR3 before the multiply will be used by MOV32.



Pipeline www.ti.com

Example 2-9. Parallel Instruction Destination/Source Exception

```
; Valid parallel operation.
;

VCMPY VR3, VR2, VR1, VR0 ; 2p/1 instruction

|| VMOV32 mem32, VR3 ; <-- Uses VR3 before the VCMPY update

; <-- mem32 updated

NOP ; <-- Delay for VCMPY
; <-- VR2, VR3 updated
```

Likewise, the source register for the second operation within a parallel instruction can be the same as one of the source registers of the first operation. The VCMPY operation in Example 2-10 uses the VR0 register as one of its sources. This register is also updated by the VMOV32 instruction. The multiplication operation will use the value in VR0 before the VMOV32 updates it.

Example 2-10. Parallel Instruction Destination/Source Exception

```
; Valid parallel operation.

VCMPY VR3, VR2, VR1, VR0 ; 2p/1 instruction

|| VMOV32 VR0, mem32 ; <-- Uses VR3 before the VCMPY update

; <-- mem32 updated

NOP ; <-- Delay for VCMPY

; <-- VR2, VR3 updated
```

NOTE: Operations within parallel instructions cannot use the same destination register.

When two parallel operations have the same destination register, the result is invalid.

```
For example, see Example 2-11.
```

If both operations within a parallel instruction try to update the same destination register as shown in Example 2-11 the assembler will issue an error.

Example 2-11. Invalid Destination Within a Parallel Instruction

```
; Invalid parallel instruction. Both operations use VR3 as a destination register;

VCMPY VR3, VR2, VR1, VR0 ; 2p/1 instruction

| VMOV32 VR3, mem32 ; <-- Invalid
```



www.ti.com Instruction Set

2.5 Instruction Set

This section describes the assembly language instructions of the VCU. Also described are parallel operations, conditional operations, resource constraints, and addressing modes. The instructions listed here are independent from C28x and C28x+FPU instruction sets.

2.5.1 Instruction Descriptions

This section gives detailed information on the instruction set. Each instruction may present the following information:

- Operands
- Opcode
- Description
- Exceptions
- Pipeline
- Examples
- See also

The example INSTRUCTION is shown to familiarize you with the way each instruction is described. The example describes the kind of information you will find in each part of the individual instruction description and where to obtain more information. VCU instructions follow the same format as the C28x; the source operand(s) are always on the right and the destination operand(s) are on the left.

The explanations for the syntax of the operands used in the instruction descriptions for the C28x VCU are given in Table 2-9.

Table 2-9. Operand Nomenclature

Symbol	Description
#16FHi	16-bit immediate (hex or float) value that represents the upper 16-bits of an IEEE 32-bit floating-point value. Lower 16-bits of the mantissa are assumed to be zero.
#16FHiHex	16-bit immediate hex value that represents the upper 16-bits of an IEEE 32-bit floating-point value. Lower 16-bits of the mantissa are assumed to be zero.
#16FLoHex	A 16-bit immediate hex value that represents the lower 16-bits of an IEEE 32-bit floating-point value
#32Fhex	32-bit immediate value that represents an IEEE 32-bit floating-point value
#32F	Immediate float value represented in floating-point representation
#0.0	Immediate zero
#5-bit	5-bit immediate unsigned value
addr	Opcode field indicating the addressing mode
Im(X), Im(Y)	Imaginary part of the input X or input Y
Im(Z)	Imaginary part of the output Z
Re(X), Re(Y)	Real part of the input X or input Y
Re(Z)	Real part of the output Z
mem16	Pointer (using any of the direct or indirect addressing modes) to a 16-bit memory location
mem32	Pointer (using any of the direct or indirect addressing modes) to a 32-bit memory location
VRa	VR0 - VR8 registers. Some instructions exclude VR8. Refer to the instruction description for details.
VR0H, VR1HVR7H	VR0 - VR7 registers, high half.
VR0L, VR1LVR7L	VR0 - VR7 registers, low half.
VT0, VT1	Transition bit register VT0 or VT1.
VSMn+1: VSMn	Pair of State Metric Registers (n = 0 : 62, n is even)
VRx.By	32 bit Aliased address space foe each byte of the VRx registers (x=0:7,y =0:3)

Each instruction has a table that gives a list of the operands and a short description. Instructions always have their destination operand(s) first followed by the source operand(s).



Instruction Set www.ti.com

Table 2-10. INSTRUCTION dest, source1, source2 Short Description

	Description
dest1	Description for the 1st operand for the instruction
source1	Description for the 2nd operand for the instruction
source2	Description for the 3rd operand for the instruction
Opcode	This section shows the opcode for the instruction
Description	Detailed description of the instruction execution is described. Any constraints on the operands imposed by the processor or the assembler are discussed.
Restrictions	Any constraints on the operands or use of the instruction imposed by the processor are discussed.
Pipeline	This section describes the instruction in terms of pipeline cycles as described in Section 2.4.
Example	Examples of instruction execution. If applicable, register and memory values are given before and after instruction execution. Some examples are code fragments while other examples are full tasks that assume the VCU is correctly configured and the main CPU has passed it data.
Operands	Each instruction has a table that gives a list of the operands and a short description. Instructions always have their destination operand(s) first followed by the source operand(s).



www.ti.com Instruction Set

2.5.2 General Instructions

The instructions are listed alphabetically, preceded by a summary.

Table 2-11. General Instructions

Title	Page
POP RB — Pop the RB Register from the Stack	162
PUSH RB — Push the RB Register onto the Stack	164
RPTB label, loc16 — Repeat A Block of Code	166
RPTB label, #RC — Repeat a Block of Code	168
VCLEAR VRa — Clear General Purpose Register	170
VCLEARALL —Clear All General Purpose and Transition Bit Registers	171
VCLRCPACK —Clears CPACK bit in the VSTATUS Register	172
VCLRCRCMSGFLIP —Clears CRCMSGFLIP bit in the VSTATUS Register	173
VCLROPACK —Clears OPACK bit in the VSTATUS Register	174
VCLROVFI —Clear Imaginary Overflow Flag	175
VCLROVFR —Clear Real Overflow Flag	176
VMOV16 mem16, VRaH — Store General Purpose Register, High Half	177
VMOV16 mem16, VRaL — Store General Purpose Register, Low Half	178
VMOV16 VRaH, mem16 — Load General Purpose Register, High Half	179
VMOV16 VRaL, mem16 — Load General Purpose Register, Low Half	180
VMOV32 *(0:16bitAddr), loc32 — Move the contents of loc32 to Memory	181
VMOV32 loc32, *(0:16bitAddr) — Move 32-bit Value from Memory to loc32	182
VMOV32 mem32, VRa — Store General Purpose Register	183
VMOV32 mem32, VSTATUS — Store VCU Status Register	184
VMOV32 mem32, VTa — Store Transition Bit Register	185
VMOV32 VRa, mem32 — Load 32-bit General Purpose Register	186
VMOV32 VRb, VRa — Move 32-bit Register to Register	187
VMOV32 VSTATUS, mem32 — Load VCU Status Register	188
VMOV32 VTa, mem32 — Load 32-bit Transition Bit Register	189
VMOVD32 VRa, mem32 — Load Register with Data Move	190
VMOVIX VRa, #16I — Load Upper Half of a General Purpose Register with I6-bit Immediate	191
VMOVZI VRa, #16I — Load General Purpose Register with Immediate	192
VMOVXI VRa, #16I — Load Low Half of a General Purpose Register with Immediate	193
VRNDOFF — Disable Rounding	194
VRNDON —Enable Rounding	195
VSATOFF — Disable Saturation	196
VSATON —Enable Saturation	197
VSETCPACK —Set CPACK bit in the VSTATUS Register	198
VSETCRCMSGFLIP —Set CRCMSGFLIP bit in the VSTATUS Register	199
VSETOPACK —Set OPACK bit in the VSTATUS Register	200
VSETSHL #5-bit —Initialize the Left Shift Value	201
VSETSHR #5-bit — Initialize the Left Shift Value	202
VSWAP32 VRb, VRa — 32-bit Register Swap	203
VXORMOV32 VRa, mem32 — 32-bit Load and XOR From Memory	204



POP RB

Pop the RB Register from the Stack

Operands

RB repeat block register

Opcode

LSW: 1111 1111 1111 0001

Description

Restore the RB register from stack. If a high-priority interrupt contains a RPTB instruction, then the RB register must be stored on the stack before the RPTB block and restored after the RTPB block. In a low-priority interrupt RB must always be saved and restored. This save and restore must occur when interrupts are disabled.

Flags

This instruction does not affect any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

A high priority interrupt is defined as an interrupt that cannot itself be interrupted. In a high priority interrupt, the RB register must be saved if a RPTB block is used within the interrupt. If the interrupt service routine does not include a RPTB block, then you do not have to save the RB register.

```
; Repeat Block within a High-Priority Interrupt (Non-Interruptible)
; Interrupt:
                         ; RAS = RA, RA = 0
  . . .
  PUSH RB
                         ; Save RB register only if a RPTB block is used in the ISR
  . . .
  RPTB _BlockEnd, AL ; Execute the block AL+1 times
  . . .
   . . .
_BlockEnd
                         ; End of block to be repeated
  . . .
  POP RB
                         ; Restore RB register ...
  IRET
                         ; RA = RAS, RAS = 0
```

A low-priority interrupt is defined as an interrupt that allows itself to be interrupted. The RB register must always be saved and restored in a low-priority interrupt. The RB register must stored before interrupts are enabled. Likewise before restoring the RB register interrupts must first be disabled.

```
; Repeat Block within a Low-Priority Interrupt (Interruptible)
; Interrupt:
                         ; RAS = RA, RA = 0
   . . .
  PUSH RB
                         ; Always save RB register
  CLRC INTM
                         ; Enable interrupts only after saving RB
  . . .
  . . .
; ISR may or may not include a RPTB block
  . . .
   . . .
  SETC INTM
                         ; Disable interrupts before restoring RB
  POP RB
                         ; Always restore RB register
  IRET
                         ; RA = RAS, RAS = 0
```

See also

PUSH RB



RPTB label, loc16 RPTB label, #RC



PUSH RB

Push the RB Register onto the Stack

Operands

RB repeat block register

Opcode

LSW: 1111 1111 1111 0000

Description

Save the RB register on the stack. If a high-priority interrupt contains a RPTB instruction, then the RB register must be stored on the stack before the RPTB block and restored after the RTPB block. In a low-priority interrupt RB must always be saved and restored. This save and restore must occur when interrupts are disabled.

Flags

This instruction does not affect any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

A high priority interrupt is defined as an interrupt that cannot itself be interrupted. In a high priority interrupt, the RB register must be saved if a RPTB block is used within the interrupt. If the interrupt service routine does not include a RPTB block, then you do not have to save the RB register.

```
; Repeat Block within a High-Priority Interrupt (Non-Interruptible)
; Interrupt:
                         ; RAS = RA, RA = 0
  . . .
  PUSH RB
                         ; Save RB register only if a RPTB block is used in the ISR
  . . .
  RPTB _BlockEnd, AL ; Execute the block AL+1 times
  . . .
   . . .
_BlockEnd
                         ; End of block to be repeated
  . . .
  POP RB
                         ; Restore RB register ...
  IRET
                         ; RA = RAS, RAS = 0
```

A low-priority interrupt is defined as an interrupt that allows itself to be interrupted. The RB register must always be saved and restored in a low-priority interrupt. The RB register must stored before interrupts are enabled. Likewise before restoring the RB register interrupts must first be disabled.

```
; Repeat Block within a Low-Priority Interrupt (Interruptible)
; Interrupt:
                         ; RAS = RA, RA = 0
   . . .
  PUSH RB
                         ; Always save RB register
   . . .
  CLRC INTM
                         ; Enable interrupts only after saving RB
  . . .
  . . .
; ISR may or may not include a RPTB block
  . . .
   . . .
  SETC INTM
                         ; Disable interrupts before restoring RB
  POP RB
                         ; Always restore RB register
  IRET
                         ; RA = RAS, RAS = 0
```

See also

POP RB



RPTB label, loc16 RPTB label, #RC



RPTB label, loc16 Repeat A Block of Code

Operands

label	This label is used by the assembler to determine the end of the repeat block and to calculate RSIZE. This label should be placed immediately after the last instruction included in the repeat block.
loc16	16-bit location for the repeat count value.

Opcode

```
LSW: 1011 0101 0bbb bbbb
MSW: 0000 0000 loc16
```

Description

Initialize repeat block loop, repeat count from [loc16]

Restrictions

- The maximum block size is ≤127 16-bit words.
- An even aligned block must be ≥ 9 16-bit words.
- An odd aligned block must be ≥ 8 16-bit words.
- Interrupts must be disabled when saving or restoring the RB register.
- Repeat blocks cannot be nested.
- Any discontinuity type operation is not allowed inside a repeat block. This includes all call, branch or TRAP instructions. Interrupts are allowed.
- Conditional execution operations are allowed.

Flags

This instruction does not affect any flags in the VSTATUS register.

Pipeline

This instruction takes four cycles on the first iteration and zero cycles thereafter. No special pipeline alignment is required.

Example

The minimum size for the repeat block is 8 words if the block is even aligned and 9 words if the block is odd aligned. If you have a block of 8 words, as in the following example, you can make sure the block is odd aligned by proceeding it by a .align 2 directive and a NOP instruction. The .align 2 directive will make sure the NOP is even aligned. Since a NOP is a 16-bit instruction the RPTB will be odd aligned. For blocks of 9 or more words, this is not required.

```
; Repeat Block of 8 Words (Interruptible)
;
; Note: This example makes use of floating-point (C28x+FPU) instructions
;
;
; find the largest element and put its address in XAR6
    .align 2
    NOP
    RPTB _VECTOR_MAX_END, AR7
; Execute the block AR7+1 times
    MOVL ACC,XAR0 MOV32 R1H,*XAR0++ ; min size = 8, 9 words
    MAXF32 R0H,R1H ; max size = 127 words
    MOVSTO NF,ZF
    MOVL XAR6,ACC,LT
_VECTOR_MAX_END: ; label indicates the end
    ; RA is cleared
```

When an interrupt is taken the repeat active (RA) bit in the RB register is automatically copied to the repeat active shadow (RAS) bit. When the interrupt exits, the RAS bit is automatically copied back to the RA bit. This allows the hardware to keep track if a repeat loop was active whenever an interrupt is taken and restore that state automatically.

A high priority interrupt is defined as an interrupt that cannot itself be interrupted. In a high priority interrupt, the RB register must be saved if a RPTB block is used within the



interrupt. If the interrupt service routine does not include a RPTB block, then you do not have to save the RB register.

```
; Repeat Block within a High-Priority Interrupt (Non-Interruptible)
; Interrupt:
                        ; RAS = RA, RA = 0
   PUSH RB
                        ; Save RB register only if a RPTB block is used in the ISR
   . . .
  RPTB _BlockEnd, AL ; Execute the block AL+1 times
   . . .
   . . .
_BlockEnd
                        ; End of block to be repeated
   . . .
   . . .
   POP RB
                         ; Restore RB register ...
   IRET
                         ; RA = RAS, RAS = 0
```

A low-priority interrupt is defined as an interrupt that allows itself to be interrupted. The RB register must always be saved and restored in a low-priority interrupt. The RB register must stored before interrupts are enabled. Likewise before restoring the RB register interrupts must first be disabled.

```
; Repeat Block within a Low-Priority Interrupt (Interruptible)
; Interrupt:
                        ; RAS = RA, RA = 0
  . . .
  PUSH RB
                        ; Always save RB register
  CLRC INTM
                        ; Enable interrupts only after saving RB
   . . .
  . . .
; ISR may or may not include a RPTB block
  . . .
                         ; Disable interrupts before restoring RB
  SETC INTM
   . . .
  POP RB
                        ; Always restore RB register
   . . .
  IRET
                        ; RA = RAS, RAS = 0
```

See also

POP RB PUSH RB RPTB label, #RC



RPTB label, #RC	Repeat a Block of Code		
Operands			
label	This label is used by the assembler to determine the end of the repeat block and to calculate RSIZE. This label should be placed immediately after the last instruction included in the repeat block.		
#RC	16-bit immediate value for the repeat count.		

Opcode

```
LSW: 1011 0101 1bbb bbbb MSW: cccc cccc cccc
```

Description

Repeat a block of code. The repeat count is specified as a immediate value.

Restrictions

- The maximum block size is ≤127 16-bit words.
- An even aligned block must be ≥ 9 16-bit words.
- An odd aligned block must be ≥ 8 16-bit words.
- Interrupts must be disabled when saving or restoring the RB register.
- Repeat blocks cannot be nested.
- Any discontinuity type operation is not allowed inside a repeat block. This includes all call, branch or TRAP instructions. Interrupts are allowed.
- Conditional execution operations are allowed.

Flags

This instruction does not affect any flags in the VSTATUS register.

Pipeline

This instruction takes one cycle on the first iteration and zero cycles thereafter. No special pipeline alignment is required.

Example

The minimum size for the repeat block is 8 words if the block is even aligned and 9 words if the block is odd aligned. If you have a block of 8 words, as in the following example, you can make sure the block is odd aligned by proceeding it by a .align 2 directive and a NOP instruction. The .align 2 directive will make sure the NOP is even aligned. Since a NOP is a 16-bit instruction the RPTB will be odd aligned. For blocks of 9 or more words, this is not required.

```
; Repeat Block of 8 Words (Interruptible)
;
; Note: This example makes use of floating-point (C28x+FPU) instructions
;
; find the largest element and put its address in XAR6
;
    .align 2
    NOP
    RPTB _VECTOR_MAX_END, AR7
; Execute the block AR7+1 times
    MOVL ACC,XAR0 MOV32 R1H,*XAR0++ ; min size = 8, 9 words
    MAXF32 R0H,R1H ; max size = 127 words
    MOVSTO NF,ZF
    MOVL XAR6,ACC,LT
_VECTOR_MAX_END: ; label indicates the end
    ; RA is cleared
```

When an interrupt is taken the repeat active (RA) bit in the RB register is automatically copied to the repeat active shadow (RAS) bit. When the interrupt exits, the RAS bit is automatically copied back to the RA bit. This allows the hardware to keep track if a repeat loop was active whenever an interrupt is taken and restore that state automatically.

A high priority interrupt is defined as an interrupt that cannot itself be interrupted. In a high priority interrupt, the RB register must be saved if a RPTB block is used within the



interrupt. If the interrupt service routine does not include a RPTB block, then you do not have to save the RB register.

```
; Repeat Block within a High-Priority Interrupt (Non-Interruptible)
; Interrupt:
                        ; RAS = RA, RA = 0
   PUSH RB
                        ; Save RB register only if a RPTB block is used in the ISR
   . . .
  RPTB #_BlockEnd, #5 ; Execute the block AL+1 times
   . . .
   . . .
_BlockEnd
                        ; End of block to be repeated
   . . .
   . . .
   POP RB
                         ; Restore RB register ...
   IRET
                         ; RA = RAS, RAS = 0
```

A low-priority interrupt is defined as an interrupt that allows itself to be interrupted. The RB register must always be saved and restored in a low-priority interrupt. The RB register must stored before interrupts are enabled. Likewise before restoring the RB register interrupts must first be disabled.

```
; Repeat Block within a Low-Priority Interrupt (Interruptible)
; Interrupt:
                        ; RAS = RA, RA = 0
  . . .
  PUSH RB
                        ; Always save RB register
  CLRC INTM
                        ; Enable interrupts only after saving RB
   . . .
  . . .
; ISR may or may not include a RPTB block
  . . .
                         ; Disable interrupts before restoring RB
  SETC INTM
   . . .
  POP RB
                        ; Always restore RB register
   . . .
  IRET
                        ; RA = RAS, RAS = 0
```

See also

POP RB **PUSH RB** RPTB label, loc16

169



VCLEAR VRa Clear General Purpose Register

Operands

VRa General purpose register: VR0, VR1... VR8

Opcode

LSW: 1110 0110 1111 1000 MSW: 0000 0000 0000 aaaa

Description

Clear the specified general purpose register.

VRa = 0x000000000;

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

See also

VCLEARALL VTCLEAR



VCLEARALL

Clear All General Purpose and Transition Bit Registers

Operands

none

Opcode

LSW: 1110 0110 1111 1001 MSW: 0000 0000 0000 0000

Description

Clear all of the general purpose registers (VR0, VR1... VR8) and the transition bit registers (VT0 and VT1).

```
VR0
     = 0x00000000;
     = 0x000000000;
VR0
VR2
    = 0x00000000;
VR3
    = 0x00000000;
VR4
    = 0 \times 000000000;
VR5
     = 0x00000000;
VR6
     = 0x00000000;
VR7
     = 0x00000000;
VR8
     = 0x00000000;
    = 0x00000000;
VT0
VT1 = 0x00000000;
VSM0 = 0x00000000
VSM1 = 0x00000000
VSM63 = 0x00000000
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

```
; Context save all VCU VRa and VTa registers
;

VMOV32 *SP++, VR0
VMOV32 *SP++, VR1
VMOV32 *SP++, VR2
VMOV32 *SP++, VR3
VMOV32 *SP++, VR4
VMOV32 *SP++, VR5
VMOV32 *SP++, VR6
VMOV32 *SP++, VR7
VMOV32 *SP++, VR7
VMOV32 *SP++, VR7
VMOV32 *SP++, VT1
;
; Clear VR0 - VR8, VT0 and VT1, VSM0 - VSM63
;
 VCLEARALL
;
; etc...
```

See also

VCLEAR VRa VTCLEAR



VCLRCPACK Clears CPACK bit in the VSTATUS Register

Operands

none

Opcode

LSW: 1110 0101 0010 0010 MSW: 0000 0000 0000 0000

Description

Clears the CPACK bit in the VSTATUS register. This causes the VCU to process complex data, in complex math operations, in the VRx registers as follows:

VRx[31:16] holds Real part, VRx[15:0] holds Imaginary part

Flags

This instruction clears the CPACK bit in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

See also

VSETCPACK



VCLRCRCMSGFLIP Clears CRCMSGFLIP bit in the VSTATUS Register

Operands

none

Opcode

LSW: 1110 0101 0010 1101 MSW: 0000 0000 0000 0000

Description

Clear the CRCMSGFLIP bit in the VSTATUS register. This causes the VCU to process message bits starting from most-significant to least-significant for CRC computation. In this case, bytes loaded from memory are fed directly for CRC computation.

Flags

This instruction clears the CRCMSGFLIP bit in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

; Clear the CRCMSGFLIP bit to have the CRC routine process the ; input message in big-endian format. The CRCMSGFLIP bit is ; cleared on reset $\,$

;

VCLRCRCMSGFLIP LCR _CRC_run8Bit

See also

VSETCRCMSGFLIP



VCLROPACK Clears OPACK bit in the VSTATUS Register

Operands

none

Opcode

LSW: 1110 0101 0010 0101 MSW: 0000 0000 0000 0000

Description

Clear the OPACK bit in the VSTATUS register. This bit affects the packing order of the traceback output bits (using the VTRACE instructions). When the bit is set to 0 it forces the bits generated from the traceback operation to be loaded through the LSb of the destination register (or memory location) with the older bits being left shifted.

Flags

This instruction clears the OPACK bit in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

See also VSETOPACK



VCLROVFI Clear Imaginary Overflow Flag

Operands

none

Opcode LSW: 1110 0101 0000 1011

Description Clear the real overflow flag in the VSTATUS register. To clear the real flag, use the

VCLROVFR instruction. The imaginary flag bit can be set by instructions shown in

Table 2-6. Refer to individual instruction descriptions for details.

VSTATUS[OVFR] = 0;

Flags This instruction clears the OVFI flag.

Pipeline This is a single-cycle instruction.

Example

See also VCLROVFR

VRNDON VSATFOFF VSATON



VCLROVFR Clear Real Overflow Flag

Operands

Description

none

Opcode LSW: 1110 0101 0000 1010

Clear the real overflow flag in the VSTATUS register. To clear the imaginary flag, use the VCLROVFI instruction. The imaginary flag bit can be set by instructions shown in

Table 2-6. Refer to individual instruction descriptions for details.

VSTATUS[OVFR] = 0;

Flags This instruction clears the OVFR flag.

Pipeline This is a single-cycle instruction.

Example

See also VCLROVFI

VRNDON VSATFOFF VSATON



VMOV16 mem16, VRaH Store General Purpose Register, High Half

Operands

mem16 Pointer to a 16-bit memory location. This will be the source for the VMOV16.

VRaH High word of a general purpose register: VR0H, VR1H...VR8H.

Opcode

LSW: 1110 0010 0001 1000 MSW: 0001 aaaa mem16

Description Store the upper 16-bits of the specified general purpose register into the 16-bit memory

location.

[mem16] = VRa[31:6];

Flags This instruction does not affect any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VMOV16 VRaH, mem16



VMOV16 mem16, VRaL Store General Purpose Register, Low Half

Operands

mem16 Pointer to a 16-bit memory location. This will be the destination of the VMOV16.

VRaL Low word of a general purpose register: VR0L, VR1L...VR8L.

Opcode

LSW: 1110 0010 0001 1000 MSW: 0000 aaaa mem16

Description Store the low 16-bits of the specified general purpose register into the 16-bit memory

location.

[mem16] = VRa[15:0];

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VMOV16 VRaL, mem16



VMOV16 VRaH, mem16 Load General Purpose Register, High Half

Operands

VRHL	High word of a general purpose register: VR0H, VR1HVR8H
mem16	Pointer to a 16-bit memory location. This will be the source for the VMOV16.

Opcode

```
LSW: 1110 0010 1100 1001
MSW: 0001 aaaa mem16
```

Description

Load the upper 16 bits of the specified general purpose register with the contents of

```
memory pointed to by mem16.
VRa[31:16] = [mem16];
```

Flags

This instruction does not affect any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

```
;1st Iteration
load u, a
VMOV32 VR6, VR0
           ; Save current {J,I} in VR6
; etc.
```

See also

VMOV16 mem16, VRaH



VMOV16 VRaL, mem16 Load General Purpose Register, Low Half

Operands

VRaL	Low word of a general purpose register: VR0L, VR1LVR8L
mem16	Pointer to a 16-bit memory location. This will be the source for the VMOV16.

Opcode

```
LSW: 1110 0010 1100 1001 MSW: 0000 aaaa mem16
```

Description

Load the lower 16 bits of the specified general purpose register with the contents of memory pointed to by mem16.

```
VRa[15:0] = [mem16];
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

```
; Loop will run 106 times for 212 inputs to decoder
; Code fragment from viterbi decoder
_LOOP:
; Calculate the branch metrics for code rate = 1/3
; Load VROL, VR1L and VR2L with inputs
; to the decoder from the array pointed to by XAR5
  VMOV16 VR0L, *XAR5++
   VMOV16 VR1L, *XAR5++
   VMOV16 VR2L, *XAR5++
; VR0L = BM0
; VROH = BM1
; VR1L = BM2
; VR1H = BM3
; VR2L = pt_old[0]
; VR2H = pt_old[1]
 VITBM3 VR0, VR1, VR2
 VMOV32 VR2, *XAR1++
; etc...
```

See also

VMOV16 mem16, VRaL



VMOV32 *(0:16bitAddr), loc32 Move the contents of loc32 to Memory

Operands

I*(0:16bitAddr) Address of 32-bit Destination Location (VCU register)
loc32 Source Location (CPU register)

Opcode

LSW: 1011 1101 loc32 MSW: IIII IIII IIII IIII

Description

Move the 32-bit value in loc32 to the memory location addressed by 0:16bitAddr. The

EALLOW bit in the ST1 register is ignored by this operation.

[0:16bitAddr] = [loc32]

Flags

This instruction does not affect any flags in the VSTATUS register.

Pipeline

This is a two-cycle instruction.

Example

; EALLOW ignored on write ; Four NOPs are needed after the operation so that the write to

; the VCU register takes effect before it is used in

; subsequent operations, for example VMOV32 VRa,@ACC ; VRa = ACC

NOP ; Pipeline alignment
NOP ; Pipeline alignment
NOP ; Pipeline alignment
NOP ; Pipeline alignment
VMOV32 *XAR7++, VRA ; [*XAR] = VRA

See also

VMOV32 VRa, mem32 VMOV32 VRb, VRa

VMOV32 loc32, *(0:16bitAddr)



VMOV32 loc32, *(0:16bitAddr) Move 32-bit Value from Memory to loc32

Operands

loc32 Destination Location (CPU register)

*(0:16bitAddr) Address of 32-bit Source Value (VCU register)

Opcode

LSW: 1011 1111 loc32 MSW: IIII IIII IIII IIII

Description

Copy the 32-bit value referenced by 0:16bitAddr to the location indicated by loc32

[loc32] = [0:16bitAddr]

Flags

This instruction does not affect any flags in the VSTATUS register.

Pipeline

This is two-cycle instruction.

Example

; A single NOP is needed before the operation so as to read the ; correct VCU's VRx register value $\,$

VMOV32 VRa,*XAR7++ ; VRa = [*XAR7]
NOP ; Pipeline alignment

VMOV32 @ACC, VRa ; ACC = VRa

; Two NOPs are needed before the operation so as to read the

See also

VMOV32 VRa, mem32 VMOV32 VRb, VRa

VMOV32 *(0:16bitAddr), loc32



VMOV32 mem32, VRa Store General Purpose Register

Operands

mem32 Pointer to a 32-bit memory location. This will be the destination of the VMOV32.

VRa General purpose register VR0, VR1... VR8

Opcode LSW: 1110 0010 0000 0100

MSW: 0000 aaaa mem32

Description Store the 32-bit contents of the specified general purpose register into the memory

location pointed to by mem32.

[mem32] = VRa;

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VMOV32 mem32, VSTATUS

VMOV32 mem32, VTa VMOV32 VRa, mem32 VMOV32 VTa, mem32



VMOV32 mem32, VSTATUS Store VCU Status Register

Operands

mem32 Pointer to a 32-bit memory location. This will be the destination of the VMOV32.

VSTATUS VCU status register.

Opcode LSW: 1110 0010 0000 1101

MSW: 0000 0000 mem32

Description Store the VSTATUS register into the memory location pointed to by mem32.

[mem32] = VSTATUS;

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VMOV32 mem32, VRa

VMOV32 mem32, VTa VMOV32 VRa, mem32 VMOV32 VSTATUS, mem32 VMOV32 VTa, mem32



VMOV32 mem32, VTa Store Transition Bit Register

Operands

mem32 pointer to a 32-bit memory location. This will be the destination of the VMOV32.

VTa Transition bits register VT0 or VT1

Opcode LSW: 1110 0010 0000 0101

MSW: 0000 00tt mem32

Description Store the 32-bits of the specified transition bits register into the memory location pointed

to by mem32.

[mem32] = VTa;

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VMOV32 mem32, VRa

VMOV32 mem32, VSTATUS VMOV32 VRa, mem32 VMOV32 VSTATUS, mem32 VMOV32 VTa, mem32



VMOV32 VRa, mem32 Load 32-bit General Purpose Register

Operands

VRa General purpose register VR0, VR1....VR8

mem32 Pointer to a 32-bit memory location. This will be the source of the VMOV32.

Opcode LSW: 1110 0011 1111 0000

MSW: 0000 aaaa mem32

Description Load the specified general purpose register with the 32-bit value in memory pointed to

by mem32.

VRa = [mem32];

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VMOV32 mem32, VRa

VMOV32 mem32, VSTATUS VMOV32 mem32, VTa VMOV32 VSTATUS, mem32 VMOV32 VTa, mem32



VMOV32 VRb, VRa Move 32-bit Register to Register

Operands

VRa General purpose destination register VR0....VR8
VRb General purpose source register VR0...VR8

Opcode LSW: 1110 0110 1111 0010 MSW: 0000 0010 bbbb aaaa

Description Move a 32-bit value from one general purpose VCU register to another.

VRa = [mem32];

Flags This instruction does not affect any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example ; Swap VRO and VR1 using VR2 as temporary storage

VMOV32 VR2, VR1 VMOV32 VR1, VR0 VMOV32 VR0, VR2

See also VMOV32 mem32, VRa

VMOV32 mem32, VSTATUS

VMOV32 mem32, VTa VMOV32 VTa, mem32



VMOV32 VSTATUS, mem32 Load VCU Status Register

Operands

VSTATUS VCU status register

mem32 Pointer to a 32-bit memory location. This will be the source of the VMOV32.

Opcode LSW: 1110 0010 1011 0000

MSW: 0000 0000 mem32

Description Load the VSTATUS register with the 32-bit value in memory pointed to by mem32.

VSTATUS = [mem32];

Flags This instruction modifies all bits within the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VMOV32 mem32, VSTATUS

VMOV32 mem32, VTa VMOV32 VRa, mem32 VMOV32 VTa, mem32



VMOV32 VTa, mem32 Load 32-bit Transition Bit Register

Operands

VTa Transition bit register: VT0, VT1

mem32 Pointer to a 32-bit memory location. This will be the source of the VMOV32.

Opcode LSW: 1110 0011 1111 0001

MSW: 0000 00tt mem32

Description Load the specified transition bit register with the 32-bit value in memory pointed to by

mem32 .

VTa = [mem32];

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VMOV32 mem32, VSTATUS

VMOV32 mem32, VTa VMOV32 VRa, mem32 VMOV32 VSTATUS, mem32



VMOVD32 VRa, mem32 Load Register with Data Move

Operands

VRa General purpose registger, VR0, VR1.... VR8
mem32 Pointer to a 32-bit memory location. This will be the source of the VMOV32.

Opcode

LSW: 1110 0010 0010 0100 MSW: 0000 aaaa mem32

Description

Load the specified general purpose register with the 32-bit value in memory pointed to by mem32. In addition, copy the next 32-bit value in memory to the location pointed to by

mem32.

VRa = [mem32];

[mem32 + 2] = [mem32];

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

See also



VMOVIX VRa, #16I Load Upper Half of a General Purpose Register with I6-bit Immediate

Operands

VRa General purpose registger, VR0, VR1... VR8

#16I 16-bit immediate value

Opcode LSW: 1110 0111 1110 IIII

MSW: IIII IIII IIII aaaa

Description Load the upper 16-bits of the specified general purpose register with an immediate

value. Leave the upper 16-bits of the register unchanged.

VRa[15:0] = unchanged; VRa[31:16] = #16I;

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VMOVZI VRa, #16I

VMOVXI VRa, #16I



VMOVZI VRa, #16I Load General Purpose Register with Immediate

Operands

VRa General purpose registger, VR0, VR1...VR8

#16I 16-bit immediate value

Opcode LSW: 1110 0111 1111 IIII

MSW: IIII IIII IIII aaaa

Description Load the lower 16-bits of the specified general purpose register with an immediate value.

Clear the upper 16-bits of the register.

VRa[15:0] = #16I; VRa[31:16] = 0x0000;

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VMOVIX VRa, #16I

VMOVXI VRa, #16I



VMOVXI VRa, #16I Load Low Half of a General Purpose Register with Immediate

Operands

VRa General purpose register, VR0 - VR8

#16I 16-bit immediate value

Opcode LSW: 1110 0111 0111 IIII

MSW: IIII IIII IIII aaaa

Description Load the lower 16-bits of the specified general purpose register with an immediate value.

Leave the upper 16 bits unchanged.

VRa[15:0] = #16I; VRa[31:16] = unchanged;

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VMOVIX VRa, #16I

VMOVZI VRa, #16I



Operands

none

Opcode

LSW: 1110 0101 0000 1001

Description

This instruction disables the rounding mode by clearing the RND bit in the VSTATUS register. When rounding is disabled, the result of the shift right operation for addition and subtraction operations will be truncated instead of rounded. The operations affected by rounding are shown in Table 2-6. Refer to the individual instruction descriptions for information on how rounding effects the operation. To enable rounding use the VRNDON instruction.

For more information on rounding, refer to Section 2.3.2.

VSTATUS[RND] = 0;

Flags This instruction clears the RND bit in the VSTATUS register. It does not change any

flags.

Pipeline This is a single-cycle instruction.

Example

See also VCLROVFI

VCLROVFR VRNDON VSATFOFF VSATON



VRNDON Enable Rounding

Operands

none

Opcode

LSW: 1110 0101 0000 1000

Description

This instruction enables the rounding mode by setting the RND bit in the VSTATUS register. When rounding is enabled, the result of the shift right operation for addition and subtraction operations will be rounded instead of being truncated. The operations affected by rounding are shown in Table 2-6. Refer to the individual instruction descriptions for information on how rounding effects the operation. To disable rounding use the VRNDOFF instruction.

For more information on rounding, refer to Section 2.3.2.

VSTATUS[RND] = 1;

Flags This instruction sets the RND bit in the VSTATUS register. It does not change any flags.

Pipeline This is a single-cycle instruction.

Example

See also VCLROVFI

VCLROVFR VRNDOFF VSATFOFF VSATON



VSATOFF Di	sable Saturation
------------	------------------

Operands

none

Opcode

LSW: 1110 0101 0000 0111

Description

This instruction disables the saturation mode by clearing the SAT bit in the VSTATUS register. When saturation is disabled, results of addition and subtraction are allowed to overflow or underflow. When saturation is enabled, results will instead be set to a maximum or minimum value instead of being allowed to overflow or underflow. To enable saturation use the VSATON instruction.

VSTATUS[SAT] = 0

Flags

This instruction clears the the SAT bit in the VSTATUS register. It does not change any

flags.

Pipeline

This is a single-cycle instruction.

Example

See also VCLROVFI

VCLROVFR VRNDOFF VRNDON VSATON



VSATON Enable Saturation

Operands

none

Opcode LSW: 1110 0101 0000 0110

Description This instruction enables the saturation mode by setting the SAT bit in the VSTATUS

register. When saturation is enables, results of addition and subtraction are not allowed to overflow or underflow. Results will, instead, be set to a maximum or minimum value.

To disable saturation use the VSATOFF instruction..

VSTATUS[SAT] = 1

Flags This instruction sets the SAT bit in the VSTATUS register. It does not change any flags.

Pipeline This is a single-cycle instruction.

Example

See also VCLROVFI

VCLROVFR VRNDOFF VRNDON VSATOFF



VSETCPACK Set CPACK bit in the VSTATUS Register

Operands

none

Opcode

LSW: 1110 0101 0010 0001

Description

Set the CPACK bit in the VSTATUS register. This causes the VCU to process complex data, in complex math operations, in the VRx registers as follows:

VRx[31:16] holds the Imaginary part, VRx[15:0] holds the Real part

Flags

This instruction sets the CPACK bit in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

; complex conjugate multiply | (a + jb)*(c + jd)=(ac+bd)+j(bc-ad) VSETCPACK ; cpack = 1 imag part in low word VMOV32 VR0, *XAR4++ ; load 1st complex input | a + jb > 0 VMOV32 VR1, *XAR4++ ; load second complex input | c + jd > 0

VCCMPY VR3, VR2, VR1, VR0

See also

VCLRCPACK



VSETCRCMSGFLIP Set CRCMSGFLIP bit in the VSTATUS Register

Operands

none

Opcode

LSW: 1110 0101 0010 1100

Description Set the CRCMSGFLIP bit in the VSTATUS register. This causes the VCU to process

message bits starting from least-significant to most-significant for CRC computation. In this case, bytes loaded from memory are "flipped" and then fed for CRC computation.

Flags This instruction sets the CRCMSGFLIP bit in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example ; Set the CRCMSGFLIP bit, each word has all its bits reversed

; prior to the CRC being calculated

;

VSETCRCMSGFLIP LCR _CRC_run8Bit VCLRCRCMSGFLIP

See also VCLRCRCMSGFLIP



VSETOPACK Set OPACK bit in the VSTATUS Register

Operands

none

Opcode

LSW: 1110 0101 0010 0011

Description

Set the OPACK bit in the VSTATUS register. This bit affects the packing order of the traceback output bits (using the instructions). When the bit is set to 1 it forces the bits generated from the traceback operation to be loaded through the MSb of the destination register (or memory location) with the older bits being right-shifted. This instruction sets

the OPACK bit in the VSTATUS register.

Flags

This instruction sets the OPACK bit in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

```
VSETOPACK
             ; VSTATUS.OPACK = 1, start packing the decoded
             ; bits from trace back into VT1 starting from the
             ; MSb, this obviates the need to manually flip the
             ; result each time
```

; etc...

See also

VCLROPACK



VSETSHL #5-bit Initialize to	the Left	Snitt	vaiue
------------------------------	----------	-------	-------

Operands

#5-bit 5-bit, unsigned, immediate value

Opcode LSW: 1110 0101 110s ssss

Description Load VSTATUS[SHIFTL] with an unsigned, 5-bit, immediate value. The left shift value

specifies the number of bits an operand is shifted by. A value of zero indicates no shift will be performed. The left shift is used by the and VCDSUB16 and VCDADD16 operations. Refer to the description of these instructions for more information. To load

the right shift value use the VSETSHR #5-bit instruction.

VSTATUS[VSHIFTL] = #5-bit

Flags This instruction changes the VSHIFTL value in the VSTATUS register. It does not

change any flags.

Pipeline This is a single-cycle instruction.

Example

See also VSETSHR #5-bit



VSETSHR #5-bit	Initialize the Left Shift Value
VOLIGIII #3-DIL	IIIIIIIIIILE LIIE LEIL SIIIIL VAIUE

Operands

#5-bit 5-bit, unsigned, immediate value

Opcode LSW: 1110 0101 010s ssss

Description Load VSTATUS[SHIFTR] with an unsigned, 5-bit, immediate value. The right shift value

specifies the number of bits an operand is shifted by. A value of zero indicates no shift will be performed. The right shift is used by the VCADD, VCSUB, VCDADD16 and VCDSUB16 operations. It is also used by the addition portion of the VCMAC. Refer to

the description of these instructions for more information.

VSTATUS[VSHIFTR] = #5-bit

Flags This instruction changes the VSHIFTR value in the VSTATUS register. It does not

change any flags.

Pipeline This is a single-cycle instruction.

Example

See also VSETSHL #5-bit





VSWAP32 VRb, VRa 32-bit Register Swap

Operands

VRb General purpose register VR0...VR8
VRab General purpose register VR0...VR8

Opcode LSW: 1110 0110 1111 0010

MSW: 0000 0011 bbbb aaaa

Description Swap the contents of the 32-bit general purpose VCU registers VRa and VRb.

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction.

Example ; Swap VRO and VR1 using VSWAP32 instruction

;

See also VMOV32 mem32, VSTATUS

VMOV32 mem32, VTa VMOV32 VRa, mem32 VMOV32VRbVRa VMOV32VTamem32



VXORMOV32 VRa, mem32 32-bit Load and XOR From Memory

Operands

Input Register	Value
VRa	General purpose register VR0VR8
mem32	Pointer to 32-bit memory location

Opcode

LSW: 1110 0011 1111 0000 MSW: 0000 aaaa MMMM MMMM

Description XOR the contents of the VRa register with a long word from memory and store the result

back into VRa

 $VRa = VRa ^mem32$

Flags This instruction does not affect any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example VXORMOV32 VR0, *+XAR4[0] ;VR0=VR0 ^ *XAR4[0]

See also



www.ti.com Instruction Set

2.5.3 Arithmetic Math Instructions

The instructions are listed alphabetically, preceded by a summary.

Table 2-12. Arithmetic Math Instructions

Title	
VASHL32 VRa << #5-bit —Arithmetic Shift Left	206
VASHR32 VRa >> #5-bit — Arithmetic Shift Right	207
VBITFLIP VRa — Bit Flip	208
VLSHL32 VRa << #5-bit —Logical Shift Left	209
VLSHR32 VRa >> #5-bit — Logical Shift Right	210
VNEG VRa —Two's Complement Negate	



VASHL32 VRa << #5-bit Arithmetic Shift Left

Operands

VRa VRa can be VR0 - VR7. VRa can not be VR8.

#5-bit 5-bit unsigned immediate value

Opcode LSW: 1110 0110 1111 0010 MSW: 0000 0111 IIII Iaaa

Description Arithmetic left shift of VRa

if (VSTATUS[SAT] == 1){

VRa = sat(VRa << #5-bit Immediate)
}else {
 VRa = VRa << #5-bit Immediate
}</pre>

Flags This instruction modifies the following bits in the VSTATUS register:

· OVFR is set if the 32-bit signed result after the shift left operation overflows

Pipeline This is a single-cycle instruction

Example VASHL32 VR4 << #16 ; VR4 := VR4 << 16

See also VASHR32 VRa>> #5-bit



VASHR32 VRa >> #5-bit Arithmetic Shift Right

Operands

VRa VRa can be VR0 - VR7. VRa can not be VR8.

#5-bit 5-bit unsigned immediate value

Opcode LSW: 1110 0110 1111 0010 MSW: 0000 1000 IIII Iaaa

Description Arithmetic right shift of VRa

If(VSTATUS[RND] == 1){
 VRa = rnd(VRa >> #5-bit Immediate)
}else {
 VRa = VRa >> #5-bit Immediate

}

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

See also VASHL32 VRa#5-bit



VBITFLIP VRa Bit Flip

Operands

VRa General purpose register VR0...VR8

Opcode LSW: 1010 0001 0010 aaaa

Description Reverse the bit order of VRa register

VRa[31:0] = VRa[0:31]

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example VBITFLIP VR1 ; VR1(31:0) := VR1(0:31)

See also



VLSHL32 VRa << #5-bit Logical Shift Left

Operands

VRa Can be VR0 - VR7. VRa can not be VR8.

#5-bit unsigned immediate value

Opcode LSW: 1110 0110 1111 0010

MSW: 0000 0101 IIII Iaaa

Description Logical right shift of VRa

VRa = VRa << #5-bit Immediate

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example VLSHL32 VR0 << #16 ; VR0 := VR0 << 16

See also VLSHL32 VRa>> #5-bit



VLSHR32 VRa >> #5-bit Logical Shift Right

Operands

VRa Can be VR0 - VR7. VRa can not be VR8.

#5-bit unsigned immediate value

Opcode LSW: 1110 0110 1111 0010

MSW: 0000 0110 IIII Iaaa

Description Logical right shift of VRa

VRa = VRa >> #5-bit Immediate

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example VLSHR32 VR0 >> #16 ; VR0 := VR0 >> 16 (no sign extension)

See also VLSHL32 VRa#5-bit



VNEG VRa

Two's Complement Negate

Operands

VRa

VRa can be VR0 - VR7. VRa can not be VR8.

Opcode

LSW: 1110 0101 0001 aaaa

Description

Complex add operation.

```
// SAT is VSTATUS[SAT]
//
  if (VRa == 0x800000000)
  {
    if(SAT == 1)
    {
       VRa = 0x7FFFFFFF;
    }
    else
    {
       VRa = 0x80000000;
    }
  }
  else
  {
    VRa = - VRa
  }
```

Flags

This instruction modifies the following bits in the VSTATUS register:

• OVFR is set if the input to the operation is 0x80000000.

Pipeline

This is a single-cycle instruction.

Example

See also

VCLROVFR VSATON VSATOFF



Instruction Set www.ti.com

2.5.4 Complex Math Instructions

The instructions are listed alphabetically, preceded by a summary.

Table 2-13. Complex Math Instructions

Title	Page
VCADD VR5, VR4, VR3, VR2 — Complex 32 + 32 = 32 Addition	213
VCADD VR5, VR4, VR3, VR2 VMOV32 VRa, mem32 — Complex 32+32 = 32 Add with Parallel Load	215
VCADD VR7, VR6, VR5, VR4 — Complex 32 + 32 = 32- Addition	217
VCCMAC VR5, VR4, VR3, VR2, VR1, VR0 — Complex Conjugate Multiply and Accumulate	219
VCCMAC VR5, VR4, VR3, VR2, VR1, VR0 VMOV32 VRa, mem32 —: Complex Conjugate Multiply and Accumulate with Parallel Load	221
VCCMAC VR7, VR6, VR5, VR4, mem32, *XAR7++ —Complex Conjugate Multiply and Accumulate	223
VCCMPY VR3, VR2, VR1, VR0 — Complex Conjugate Multiply	226
VCCMPY VR3, VR2, VR1, VR0 VMOV32 mem32, VRa — Complex Conjugate Multiply with Parallel Store	228
VCCMPY VR3, VR2, VR1, VR0 VMOV32 VRa, mem32 — Complex Conjugate Multiply with Parallel Load	230
VCCMAC VR5, VR4, VR3, VR2, VR1, VR0 — Complex Conjugate Multiply with Parallel Load	232
VCCON VRa — Complex Conjugate	
VCDADD16 VR5, VR4, VR3, VR2 — Complex 16 + 32 = 16 Addition	235
VCDADD16 VR5, VR4, VR3, VR2 VMOV32 VRa, mem32 — Complex Double Add with Parallel Load	
VCDSUB16 VR6, VR4, VR3, VR2 — Complex 16-32 = 16 Subtract	242
VCDSUB16 VR6, VR4, VR3, VR2 VMOV32 VRa, mem32 — Complex 16-32 = 16 Subtract with Parallel Load	246
VCFLIP VRa — Swap Upper and Lower Half of VCU Register	
VCMAC VR5, VR4, VR3, VR2, VR1, VR0 — Complex Multiply and Accumulate	
VCMAC VR7, VR6, VR5, VR4, mem32, *XAR7++ —Complex Multiply and Accumulate	252
VCMAC VR5, VR4, VR3, VR2, VR1, VR0 VMOV32 VRa, mem32 — Complex Multiply and Accumulate with Parallel	
	256
VCMAG VRb, VRa — Magnitude of a Complex Number	
VCMPY VR3, VR2, VR1, VR0 — Complex Multiply	
VCMPY VR3, VR2, VR1, VR0 VMOV32 mem32, VRa — Complex Multiply with Parallel Store	
VCMPY VR3, VR2, VR1, VR0 VMOV32 VRa, mem32 — Complex Multiply with Parallel Load	
VCSHL16 VRa << #4-bit — Complex Shift Left	
VCSHR16 VRa >> #4-bit — Complex Shift Right.	
VCSUB VR5, VR4, VR3, VR2 — Complex 32 - 32 = 32 Subtraction	
VCSUB VR5, VR4, VR3, VR2 VMOV32 VRa, mem32 — Complex Subtraction	269



VCADD VR5, VR4, VR3, VR2 Complex 32 + 32 = 32 Addition

Operands

Before the operation, the inputs should be loaded into registers as shown below. Each operand for this instruction includes a 32-bit real and a 32-bit imaginary part.

Input Register	Value
VR5	32-bit integer representing the real part of the first input: Re(X)
VR4	32-bit integer representing the imaginary part of the first input: Im(X)
VR3	32-bit integer representing the real part of the 2nd input: Re(Y)
VR2	32-bit integer representing the imaginary part of the 2nd input: Im(Y)

The result is also a complex number with a 32-bit real and a 32-bit imaginary part. The result is stored in VR5 and VR4 as shown below:

Output Register	Value
VR5	32-bit integer representing the real part of the result: Re(Z) = Re(X) + (Re(Y) >> SHIFTR)
VR4	32-bit integer representing the imaginary part of the result: $Im(Z) = Im(X) + (Im(Y) >> SHIFTR)$

Opcode

LSW: 1110 0101 0000 0010

Description

Complex 32 + 32 = 32-bit addition operation.

The second input operand (stored in VR3 and VR2) is shifted right by VSTATUS[SHIFR] bits before the addition. If VSTATUS[RND] is set, then bits shifted out to the right are rounded, otherwise these bits are truncated. The rounding operation is described in Section 2.3.2. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of an overflow or underflow.

```
// RND
          is VSTATUS[RND]
// SAT
         is VSTATUS[SAT]
// SHIFTR is VSTATUS[SHIFTR]
//
// X: VR5 = Re(X)
                     VR4 = Im(X)
// Y: VR3 = Re(Y)
                     VR2 = Im(Y)
11
// Calculate Z = X + Y
//
   if (RND == 1)
   {
      VR5 = VR5 + round(VR3 >> SHIFTR); // Re(Z)
      VR4 = VR4 + round(VR2 >> SHIFTR); // Im(Z)
   else
   {
     VR5 = VR5 + (VR3 >> SHIFTR);
                                         // Re(Z)
      VR4 = VR4 + (VR2 >> SHIFTR);
                                          // Im(Z)
   if (SAT == 1)
   {
      sat32(VR5);
      sat32(VR4);
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the VR5 computation (real part) overflows or underflows.
- OVFI is set if the VR4 computation (imaginary part) overflows or underflows.

Pipeline

This is a single-cycle instruction.



Example

See also VCADD VR5, VR4, VR3, VR2 || VMOV32 VRa, mem32

VCADD VR7, VR6, VR5, VR4

VCLROVFI VCLROVFR VRNDOFF VRNDON VSATON VSATOFF

VSETSHR #5-bit



VCADD VR5, VR4, VR3, VR2 | VMOV32 VRa, mem32 Complex 32+32 = 32 Add with Parallel Load

Operands

Before the operation, the inputs should be loaded into registers as shown below. Each complex number includes a 32-bit real and a 32-bit imaginary part.

Input Register	Value
VR5	32-bit integer representing the real part of the first input: Re(X)
VR4	32-bit integer representing the imaginary part of the first input: Im(X)
VR3	32-bit integer representing the real part of the 2nd input: Re(Y)
VR2	32-bit integer representing the imaginary part of the 2nd input: Im(Y)
mem32	pointer to a 32-bit memory location

The result is also a complex number with a 32-bit real and a 32-bit imaginary part. The result is stored in VR5 and VR4 as shown below:

Output Register	Value
VR5	32-bit integer representing the real part of the result: Re(Z) = Re(X) + (Re(Y) >> SHIFTR)
VR4	32-bit integer representing the imaginary part of the result: $Im(Z) = Im(X) + (Im(Y) >> SHIFTR)$
VRa	contents of the memory pointed to by [mem32]. VRa can not be VR5, VR4 or VR8.

Opcode

```
LSW: 1110 0011 1111 1000 MSW: 0000 aaaa mem32
```

Description

Complex 32 + 32 = 32-bit addition operation with parallel register load.

The second input operand (stored in VR3 and VR2) is shifted right by VSTATUS[SHIFR] bits before the addition. If VSTATUS[RND] is set, then bits shifted out to the right are rounded, otherwise these bits are truncated. The rounding operation is described in Section 2.3.2. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of an overflow or underflow.

In parallel with the addition, VRa is loaded with the contents of memory pointed to by mem32.

```
// RND
         is VSTATUS[RND]
         is VSTATUS[SAT]
// SAT
// SHIFTR is VSTATUS[SHIFTR]
11
// VR5 = Re(X)
                  VR4 = Im(X)
// VR3 = Re(Y)
                  VR2 = Im(Y)
//
//Z = X + Y
//
   if (RND == 1)
   {
      VR5 = VR5 + round(VR3 >> SHIFTR); // Re(Z)
      VR4 = VR4 + round(VR2 >> SHIFTR); // Im(Z)
   }
   else
   {
     VR5 = VR5 + (VR3 >> SHIFTR);
                                         // Re(Z)
      VR4 = VR4 + (VR2 >> SHIFTR);
                                         // Im(Z)
   if (SAT == 1)
   {
      sat32(VR5);
      sat32(VR4);
   VRa = [mem32];
```



VCADD VR5, VR4, VR3, VR2 || VMOV32 VRa, mem32 — Complex 32+32 = 32 Add with Parallel Load www

www.ti.com

Flags This instruction modifies the following bits in the VSTATUS register:

• OVFR is set if the VR5 computation (real part) overflows.

• OVFI is set if the VR4 computation (imaginary part) overflows.

Pipeline Both operations complete in a single cycle (1/1 cycles).

Example

See also VCADD VR7, VR6, VR5, VR4

VCLROVFI VCLROVFR VRNDOFF VRNDON VSATON VSATOFF

VSETSHR #5-bit



VCADD VR7, VR6, VR5, VR4 Complex 32 + 32 = 32- Addition

Operands

Before the operation, the inputs should be loaded into registers as shown below. Each complex number includes a 32-bit real and a 32-bit imaginary part.

Input Register	Value
VR7	32-bit integer representing the real part of the first input: Re(X)
VR6	32-bit integer representing the imaginary part of the first input: Im(X)
VR5	32-bit integer representing the real part of the 2nd input: Re(Y)
VR4	32-bit integer representing the imaginary part of the 2nd input: Im(Y)

The result is also a complex number with a 32-bit real and a 32-bit imaginary part. The result is stored in VR7 and VR6 as shown below:

Output Register	Value
VR6	32-bit integer representing the real part of the result: Re(Z) = Re(X) + (Re(Y) >> SHIFTR)
VR7	32-bit integer representing the imaginary part of the result: $Im(Z) = Im(X) + (Im(Y) >> SHIFTR)$

Opcode

LSW: 1110 0101 0010 1010

Description

Complex 32 + 32 = 32-bit addition operation.

The second input operand (stored in VR5 and VR4) is shifted right by VSTATUS[SHIFR] bits before the addition. If VSTATUS[RND] is set, then bits shifted out to the right are rounded, otherwise these bits are truncated. The rounding operation is described in Section 2.3.2. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of an overflow or underflow.

```
// RND
          is VSTATUS[RND]
// SAT
         is VSTATUS[SAT]
// SHIFTR is VSTATUS[SHIFTR]
//
// VR5 = Re(X)
                 VR4 = Im(X)
// VR3 = Re(Y)
                  VR2 = Im(Y)
11
//Z = X + Y
//
   if (RND == 1)
   {
      VR7 = VR7 + round(VR5 >> SHIFTR); // Re(Z)
      VR6 = VR6 + round(VR4 >> SHIFTR); // Im(Z)
   }
   else
   {
     VR7 = VR5 + (VR5 >> SHIFTR);
                                         // Re(Z)
      VR6 = VR4 + (VR4 >> SHIFTR);
                                          // Im(Z)
   if (SAT == 1)
   {
      sat32(VR7);
      sat32(VR6);
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the VR7 computation (real part) overflows.
- OVFI is set if the VR6 computation (imaginary part) overflows.

Pipeline

This is a single-cycle instruction.



Example

See also VCADD VR5, VR4, VR3, VR2

VCADD VR5, VR4, VR3, VR2 || VMOV32 VRa, mem32

VCLROVFI VCLROVFR VRNDOFF VRNDON VSATON VSATOFF

VSETSHR #5-bit



VCCMAC VR5, VR4, VR3, VR2, VR1, VR0 Complex Conjugate Multiply and Accumulate

Operands

Input Register (1)	Value
VR0	First Complex Operand
VR1	Second Complex Operand
VR2	Imaginary part of the Result
VR3	Real part of the Result
VR4	Imaginary part of the accumulation
VR5	Real part of the accumulation

The user will need to do one final addition to accumulate the final multiplications (Real-VR3 and Imaginary-VR2) into the result registers.

Opcode

LSW: 1110 0101 0000 1111

Description

Complex Conjugate Multiply Operation

```
// VR5 = Accumulation of the real part
// VR4 = Accumulation of the imaginary part
11
// VR0 = X + jX: VR0[31:16] = X, VR0[15:0] = jX
// VR1 = Y + jY: VR1[31:16] = Y, VR1[15:0] = jY
11
// Perform add
//
 if (RND == 1)
  {
   VR5 = VR5 + round(VR3 >> SHIFTR);
    VR4 = VR4 + round(VR2 >> SHIFTR);
  else
  {
   VR5 = VR5 + (VR3 >> SHIFTR);
   VR4 = VR4 + (VR2 >> SHIFTR);
//
// Perform multiply (X + jX) * (Y - jY)
11
 if(VSTATUS[CPACK] == 0){
   VR3 = VR0H * VR1H + VR0L * VR1L; Real result
   VR2 = VR0H * VR1L - VR0L * VR1H; Imaginary result
  }
  else
    VR3 = VR0L * VR1L + VR0H * VR1H; Real result
   VR2 = VR0L * VR1H - VR0H * VR1L; Imaginary result
  if(SAT == 1)
  {
    sat32(VR3);
    sat32(VR2);
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the VR3 computation (real part) overflows or underflows.
- OVFI is set if the VR2 computation (imaginary part) overflows or underflows.

Pipeline

This is a 2p-cycle instruction.

See also

VCLROVFI



VCLROVFR

VCCMAC VR5, VR4, VR3, VR2, VR1, VR0

VSATON VSATOFF www.ti.com

VCCMAC VR5, VR4, VR3, VR2, VR1, VR0 | VMOV32 VRa, mem32 — : Complex Conjugate Multiply and Accumulate with Parallel Load

VCCMAC VR5, VR4, VR3, VR2, VR1, VR0 | VMOV32 VRa, mem32 : Complex Conjugate Multiply and Accumulate with Parallel Load

Operands

Input Register	Value
VR0	First Complex Operand
VR1	Second Complex Operand
VR2	Imaginary part of the Result
VR3	Real part of the Result
√R4	Imaginary part of the accumulation
VR5	Real part of the accumulation
√Ra	Contents of the memory pointed to by mem32. VRa cannot be VR5, VR4 or VR8
mem32	Pointer to 32-bit memory location
	I need to do one final addition to accumulate the final multiplications (Real-VR3 and to the result registers

Imaginary-VR2) into the result registers.

Opcode

```
LSW: 1110 0011 1111 0111
MSW: 0001 aaaa mem32
```

Description

Complex Conjugate Multiply Operation with parallel load.

```
// VR5 = Accumulation of the real part
// VR4 = Accumulation of the imaginary part
11
// VR0 = X + jX: VR0[31:16] = X, VR0[15:0] = jX
// VR1 = Y + jY: VR1[31:16] = Y, VR1[15:0] = jY
//
// Perform add
//
 if (RND == 1)
  {
   VR5 = VR5 + round(VR3 >> SHIFTR);
   VR4 = VR4 + round(VR2 >> SHIFTR);
  }
  {
   VR5 = VR5 + (VR3 >> SHIFTR);
   VR4 = VR4 + (VR2 >> SHIFTR);
//
// Perform multiply (X + jX) * (Y - jY)
//
 If(VSTATUS[CPACK] == 0){
   VR3 = VR0H * VR1H + VR0L * VR1L; Real result
   VR2 = VR0H * VR1L - VR0L * VR1H; Imaginary result
  }
  else
  {
   VR3 = VR0L * VR1L + VR0H * VR1H; Real result
   VR2 = VR0L * VR1H - VR0H * VR1L; Imaginary result
  if(SAT == 1)
  {
   sat32(VR3);
   sat32(VR2);
  VRa = [mem32];
```



VCCMAC VR5, VR4, VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32 — : Complex Conjugate Multiply and Accumulate with Parallel Load www.ti.com

Flags This instruction modifies the following bits in the VSTATUS register:

• OVFR is set if the VR3 computation (real part) overflows or underflows.

• OVFI is set if the VR2 computation (imaginary part) overflows or underflows.

Pipeline This is a 2p-cycle instruction.

See also VCLROVFI

VCLROVFR

VCCMAC VR5, VR4, VR3, VR2, VR1, VR0

VSATON VSATOFF



VCCMAC VR7, VR6, VR5, VR4, mem32, *XAR7++ Complex Conjugate Multiply and Accumulate

Operands

The VMAC alternates which registers are used between each cycle. For odd cycles (1, 3, 5, and so on) the following registers are used:

Odd Cycle Input	Value
VR5	Previous real-part total accumulation: Re(odd_sum)
VR4	Previous imaginary-part total accumulation: Im(odd-sum)
VR1	Previous real result from the multiply: Re(odd-mpy)
VR0	Previous imaginary result from the multiply Im(odd-mpy)
[mem32]	Pointer to a 32-bit memory location representing the first input to the multiply
	If(VSTATUS[CPACK] == 0)
	[mem32][32:16] = Re(X)
	[mem32][15:0] = Im(X)
	If(VSTATUS[CPACK] == 1)
	[mem32][32:16] = Im(X)
	mem32][15:0] = Re(X)
XAR7	Pointer to a 32-bit memory location representing the second input to the multiply
	If(VSTATUS[CPACK] == 0)
	*XAR7[32:16] = Re(X)
	*XAR7[15:0] = Im(X)
	If(VSTATUS[CPACK] == 1)
	*XAR7[32:16] = Im(X)
	*XAR7 [15:0] = $Re(X)$

The result from the odd cycle is stored as shown below:

Odd Cycle Output	Value
VR5	32-bit real part of the total accumulation Re(odd_sum) = Re(odd_sum) + Re(odd_mpy)
VR4	32-bit imaginary part of the total accumulation Im(odd_sum) = Im(odd_sum) + Im(odd_mpy)
VR1	32-bit real result from the multiplication: Re(Z) = Re(X)*Re(Y) + Im(X)*Im(Y)
VR0	32-bit imaginary result from the multiplication: $Im(Z) = Re(X)*Im(Y) - Re(Y)*Im(X)$

For even cycles (2, 4, 6, and so on) the following registers are used:

Even Cycle Input	Value
VR7	Previous real-part total accumulation: Re(even_sum)
VR6	Previous imaginary-part total accumulation: Im(even-sum)
VR3	Previous real result from the multiply: Re(even-mpy)
VR2	Previous imaginary result from the multiply Im(even-mpy)
[mem32]	Pointer to a 32-bit memory location representing the first input to the multiply
	If(VSTATUS[CPACK] == 0)
	[mem32][32:16] = Re(X)
	[mem32][15:0] = Im(X)
	If(VSTATUS[CPACK] == 1)
	[mem32][32:16] = Im(X)



Even Cycle Input Value

mem32[15:0] = Re(X)

*XAR7 [15:0] = Re(X)

XAR7

Pointer to a 32-bit memory location representing the second input to the multiply If(VSTATUS[CPACK] == 0)*XAR7[32:16] = Re(X)*XAR7[15:0] = Im(X)If(VSTATUS[CPACK] == 1) *XAR7[32:16] = Im(X)

The result from even cycles is stored as shown below:

Even Cycle Output	Value
VR7	32-bit real part of the total accumulation Re(even_sum) = Re(even_sum) + Re(even_mpy)
VR6	32-bit imaginary part of the total accumulation Im(even_sum) = Im(even_sum) + Im(even_mpy)
VR3	32-bit real result from the multiplication: Re(Z) = Re(X)*Re(Y) + Im(X)*Im(Y)
VR2	32-bit imaginary result from the multiplication: $Im(Z) = Re(X)*Im(Y) - Re(Y)*Im(X)$

Opcode

```
LSW: 1110 0010 0101 0001
MSW: 0010 1111 mem32
```

Description

Perform a repeated complex conjugate multiply and accumulate operation. This instruction must be used with the single repeat instruction (RPT ||). The destination of the accumulate will alternate between VR7/VR6 and VR5/VR4 on each cycle.

```
// Cycle 1:
//
// Perform accumulate
//
 if(RND == 1)
    VR5 = VR5 + round(VR1 >> SHIFTR)
    VR4 = VR4 + round(VR0 >> SHIFTR)
  else
    VR5 = VR5 + (VR1 >> SHIFTR)
    VR4 = VR4 + (VR0 >> SHIFTR)
//
\ensuremath{//} X and Y array element \ensuremath{\text{0}}
//
    VR1 = Re(X)*Re(Y) + Im(X)*Im(Y)
    VR0 = Re(X)*Im(Y) - Re(Y)*Im(X)
// Cycle 2:
//
// Perform accumulate
//
  if(RND == 1)
    VR7 = VR7 + round(VR3 >> SHIFTR)
    VR6 = VR6 + round(VR2 >> SHIFTR)
```



```
else
  {
  VR7 = VR7 + (VR3 >> SHIFTR)
  VR6 = VR6 + (VR2 >> SHIFTR)
  }
//
// X and Y array element 1
 VR3 = Re(X)*Re(Y) + Im(X)*Im(Y)
 VR2 = Re(X)*Im(Y) - Re(Y)*Im(X)
// Cycle 3:
//
// Perform accumulate
//
 if(RND == 1)
  {
 VR5 = VR5 + round(VR1 >> SHIFTR)
 VR4 = VR4 + round(VR0 >> SHIFTR)
  }
 else
  {
 VR5 = VR5 + (VR1 >> SHIFTR)
 VR4 = VR4 + (VR0 >> SHIFTR)
  }
//
// X and Y array element 2
 VR1 = Re(X)*Re(Y) + Im(X)*Im(Y)
 VR0 = Re(X)*Im(Y) - Re(Y)*Im(X)
etc...
```

Restrictions

VR0, VR1, VR2, and VR3 will be used as temporary storage by this instruction.

Flags

The VSTATUS register flags are modified as follows:

- OVFR is set in the case of an overflow or underflow of the addition or subtraction operations.
- OVFI is set in the case an overflow or underflow of the imaginary part of the addition or subtraction operations.

Pipeline

The VCCMAC takes 2p + N cycles where N is the number of times the instruction is repeated. This instruction has the following pipeline restrictions:

See also

VCMAC VR7, VR6, VR5, VR4, mem32, *XAR7++



VCCMPY VR3, VR2, VR1, VR0 Complex Conjugate Multiply

Operands

Both inputs are complex numbers with a 16-bit real and 16-bit imaginary part. The result is a complex number with a 32-bit real and a 32-bit imaginary part. The result is stored in VR2 and VR3 as shown below:

Input Register	Value
VR0	First Complex Operand
VR1	Second Complex Operand
VR2	Imaginary part of the Result
VR3	Real part of the Result

The result is a complex number with a 16-bit real and a 16-bit imaginary part. The result is stored in VR5 as shown below:

Opcode

LSW: 1110 0101 0000 1110

Description

Complex Conjugate $16 \times 16 = 32$ -bit multiply operation.

If the VSTATUS[CPACK] bit is set, the low word of the input is treated as the real part while the upper word is treated as imaginary. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of a 32-bit overflow or underflow. The following operation is carried out:.

```
if(VSTATUS[CPACK] == 0) {
   VR3 = VR0H * VR1H + VR0L * VR1L; //Re(Z) = Re(X)*Re(Y) + Im(X)*Im(Y)
   VR2 = VR0H * VR1L - VR0L * VR1H; // Im(Z) = Re(X)*Im(Y) - Im(X)*Re(Y)
}else{
   VR3 = VR0L * VR1L + VR0H * VR1H; // Re(Z) = Re(X)*Re(Y) + Im(X)*Im(Y)
   VR2 = VR0L * VR1H - VR0H * VR1L; // Im(Z) = Re(X)*Im(Y) - Im(X)*Re(Y)
}
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the VR3 computation (real part) overflows or underflows.
- OVFI is set if the VR2 computation (imaginary part) overflows or underflows.

Pipeline

This is a 2p-cycle instruction. The instruction following this one should not use VR3 or VR2.

```
VCLRCPACK
                               ; cpack = 0 real part in high word
 VMOV32
          VR0, *XAR4++
                              ; load 1st complex input | jb + a
 VMOV32 VR1, *XAR4++ ; load second complex input | jd + c
 VCCMPY VR3, VR2, VR1, VR0 ; complex conjugate multiply
                               i (jb + a)*(jd + c)=(ac+bd)+j(bc-ad)
 NOP
  VMOV32
           *XAR5++, VR3
                               ; store real part first
           *XAR5++, VR2
  VMOV32
                               ; store imag part next
 VSETCPACK
                               ; cpack = 1 imag part in low word
           VRO, *XAR4++ ; load 1st complex input | a + jb
VR1, *XAR4++ ; load second complex input | c + jd
 VMOV32 VR0, *XAR4++
  VMOV32
           VR3, VR2, VR1, VR0 ; complex conjugate multiply
  VCCMPY
                               i(a + jb)*(c + jd)=(ac+bd)+j(bc-ad)
 NOP
                           ; store real part first
 VMOV32
           *XAR5++, VR3
 VMOV32
           *XAR5++, VR2
                               ; store imag part next
```

Example

See also

VCLROVFI VCLROVFR

VCCMAC VR5, VR4, VR3, VR2, VR1, VR0



VCCMAC VR5, VR4, VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32

VSETCPACK

VCLRCPACK

VSATON

VSATOFF



VCCMPY VR3, VR2, VR1, VR0 || VMOV32 mem32, VRa Complex Conjugate Multiply with Parallel Store

Operands

Both inputs are complex numbers with a 16-bit real and 16-bit imaginary part. The result is a complex number with a 32-bit real and a 32-bit imaginary part. The result is stored in VR2 and VR3 as shown below:

Input Register	Value
VR0	First Complex Operand
VR1	Second Complex Operand
VRa	Value to be stored
VR2	Imaginary part of the Result
VR3	Real part of the Result
mem32	Pointer to 32-bit memory location

The result is a complex number with a 16-bit real and a 16-bit imaginary part. The result is stored in VR5 as shown below:

Opcode

```
LSW: 1110 0011 0000 0111 MSW: 0001 aaaa mem32
```

Description

Complex Conjugate $16 \times 16 = 32$ -bit multiply operation.

If the VSTATUS[CPACK] bit is set, the low word of the input is treated as the real part while the upper word is treated as imaginary. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of a 32-bit overflow or underflow. The following operation is carried out:

```
if(VSTATUS[CPACK] == 0){
   VR3 = VR0H * VR1H + VR0L * VR1L; //Re(Z) = Re(X)*Re(Y) + Im(X)*Im(Y)
   VR2 = VR0H * VR1L - VR0L * VR1H; // Im(Z) = Re(X)*Im(Y) - Im(X)*Re(Y)
}else{
   VR3 = VR0L * VR1L + VR0H * VR1H; // Re(Z) = Re(X)*Re(Y) + Im(X)*Im(Y)
   VR2 = VR0L * VR1H - VR0H * VR1L; // Im(Z) = Re(X)*Im(Y) - Im(X)*Re(Y)
}
[mem32] = VRa;
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the VR3 computation (real part) overflows or underflows.
- OVFI is set if the VR2 computation (imaginary part) overflows or underflows.

Pipeline

This is a 2p/1-cycle instruction. The multply operation takes 2p cycles and the VMOV operation completes in a single cycle. The instruction following this one should not use VR3 or VR2.

Example

```
VCLRCPACK
                        ; cpack = 0 real part in high word
 VMOV32
           VRO, *XAR4++; load 1st complex input | jb + a
 VMOV32
           VR1, *XAR4++ ; load second complex input | jd + c
           VR3, VR2, VR1, VR0 ; complex conjugate multiply
 VCCMPY
VMOV32
           VR0, *XAR4++ ; (jb + a)*(jd + c)=(ac+bd)+j(bc-ad)
                        ; load 1st complex input | a + jb
 NOP
                        ; for next VCCMPY instr
 VMOV32 *XAR5++, VR3 ; store real part first
 VSETCPACK
                       ; cpack = 1 imag part in low word
           VR1, *XAR4++ ; load second complex input | c + jd
 VMOV32
 VCCMPY
           VR3, VR2, VR1, VR0; complex conjugate multiply
| VMOV32
           *XAR5++, VR2 ; (a + jb)*(c + jd)=(ac+bd)+j(bc-ad)
                        ; store imag part of first
                        ; VCCMPY instruction
 NOP
           *XAR5++, VR3 ; store real part first
 VMOV32
 VMOV32
           *XAR5++, VR2 ; store imag part next
 VCLRCPACK
```



www.ti.com VCCMPY VR3, VR2, VR1, VR0 || VMOV32 mem32, VRa — Complex Conjugate Multiply with Parallel Store

See also VCLROVFI

VCLROVFR

VCCMAC VR5, VR4, VR3, VR2, VR1, VR0

VCCMAC VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32

VSETCPACK VCLRCPACK VSATON

VSATOFF



VCCMPY VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32 Complex Conjugate Multiply with Parallel Load

Operands

Both inputs are complex numbers with a 16-bit real and 16-bit imaginary part. The result is a complex number with a 32-bit real and a 32-bit imaginary part. The result is stored in VR2 and VR3 as shown below:

Input Register	Value
VR0	First Complex Operand
VR1	Second Complex Operand
VRa	32-bit value pointed to by mem32. VRa can not be VR2, VR3 or VR8.
VR2	Imaginary part of the Result
VR3	Real part of the Result
mem32	Pointer to 32-bit memory location

The result is a complex number with a 16-bit real and a 16-bit imaginary part. The result is stored in VR5 as shown below:

Opcode

```
LSW: 1110 0011 1111 0110 MSW: 0001 aaaa mem32
```

Description

Complex Conjugate $16 \times 16 = 32$ -bit multiply operation.

If the VSTATUS[CPACK] bit is set, the low word of the input is treated as the real part while the upper word is treated as imaginary. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of a 32-bit overflow or underflow. The following operation is carried out:

```
if(VSTATUS[CPACK] == 0){
   VR3 = VR0H * VR1H + VR0L * VR1L; // Re(Z) = Re(X)*Re(Y) + Im(X)*Im(Y)
   VR2 = VR0H * VR1L - VR0L * VR1H; // Im(Z) = Re(X)*Im(Y) - Im(X)*Re(Y)
}else{
   VR3 = VR0L * VR1L + VR0H * VR1H; // Re(Z) = Re(X)*Re(Y) + Im(X)*Im(Y)
   VR2 = VR0L * VR1H - VR0H * VR1L; // Im(Z) = Re(X)*Im(Y) - Im(X)*Re(Y)
}
VRa = [mem32];
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the VR3 computation (real part) overflows or underflows.
- OVFI is set if the VR2 computation (imaginary part) overflows or underflows.

Pipeline

This is a 2p/1-cycle instruction. The multiply operation takes 2p cycles and the VMOV operation completes in a single cycle. The instruction following this one should not use VR3 or VR2.

Example

```
VCLRCPACK
                        ; cpack = 0 real part in high word
  VMOV32
           VRO, *XAR4++ ; load 1st complex input
                                                    | ib + a
           VR1, *XAR4++ ; load second complex input | jd + c
  VMOV32
           VR3, VR2, VR1, VR0 ; complex conjugate multiply
 VCCMPY
| VMOV32
           VR0, *XAR4++; (jb + a)*(jd + c)=(ac+bd)+j(bc-ad)
                        ; load 1st complex input
  NOP
                        ; for next VCCMPY instr
           *XAR5++, VR3 ; store real part first
  VMOV32
  VSETCPACK
                       ; cpack = 1 imag part in low word
 VMOV32
           VR1, *XAR4++ ; load second complex input | c + jd
           VR3, VR2, VR1, VR0; complex conjugate multiply
  VCCMPY
VMOV32
           *XAR5++, VR2 ; (a + jb)*(c + jd)=(ac+bd)+j(bc-ad)
                        ; store imag part of first
                        ; VCCMPY instruction
 NOP
  VMOV32
           *XAR5++, VR3 ; store real part first
  VMOV32
           *XAR5++, VR2 ; store imag part next
 VCLRCPACK
```



www.ti.com VCCMPY VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32 — Complex Conjugate Multiply with Parallel Load

See also VCLROVFI

VCLROVFR

VCCMAC VR5, VR4, VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32

VCCMAC VR5, VR4, VR3, VR2, VR1, VR0

VSETCPACK VCLRCPACK VSATON VSATOFF



VCCMAC VR5, VR4, VR3, VR2, VR1, VR0 Complex Conjugate Multiply with Parallel Load

Operands

Both inputs are complex numbers with a 16-bit real and 16-bit imaginary part. The result is a complex number with a 32-bit real and a 32-bit imaginary part. The result is stored in VR2 and VR3 as shown below:

Input Register	Value
VR0	First Complex Operand
VR1	Second Complex Operand
VRa	32-bit value pointed to by mem32. VRa can not be VR2, VR3 or VR8.
VR2	Imaginary part of the Result
VR3	Real part of the Result
mem32	Pointer to 32-bit memory location

The result is a complex number with a 16-bit real and a 16-bit imaginary part. The result is stored in VR5 as shown below:

Opcode

```
LSW: 1110 0101 0000 1111
```

Description

Complex Conjugate $16 \times 16 = 32$ -bit multiply operation.

If the VSTATUS[CPACK] bit is set, the low word of the input is treated as the real part while the upper word is treated as imaginary. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of a 32-bit overflow or underflow. The following operation is carried out:

```
if(VSTATUS[CPACK] == 0){
    VR3 = VR0H * VR1H + VR0L * VR1L; // Re(Z) = Re(X)*Re(Y) + Im(X)*Im(Y)
    VR2 = VR0H * VR1L - VR0L * VR1H; // Im(Z) = Re(X)*Im(Y) - Im(X)*Re(Y)
}else{
    VR3 = VR0L * VR1L + VR0H * VR1H; // Re(Z) = Re(X)*Re(Y) + Im(X)*Im(Y)
    VR2 = VR0L * VR1H - VR0H * VR1L; // Im(Z) = Re(X)*Im(Y) - Im(X)*Re(Y)
}
VRa = [mem32];
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the VR3 computation (real part) overflows or underflows.
- OVFI is set if the VR2 computation (imaginary part) overflows or underflows.

Pipeline

This is a 2p/1-cycle instruction. The multiply operation takes 2p cycles and the VMOV operation completes in a single cycle. The instruction following this one should not use VR3 or VR2.

Example

```
VCLRCPACK
                        ; cpack = 0 real part in high word
  VMOV32
           VR0, *XAR4++ ; load 1st complex input
           VR1, *XAR4++; load second complex input | jd + c
  VMOV32
 VCCMPY
           VR3, VR2, VR1, VR0 ; complex conjugate multiply
|VMOV32
           VR0, *XAR4++ ; (jb + a)*(jd + c)=(ac+bd)+j(bc-ad)
                        ; load 1st complex input
  NOP
                        ; for next VCCMPY instr
           *XAR5++, VR3 ; store real part first
  VMOV32
                       ; cpack = 1 imag part in low word
  VSETCPACK
 VMOV32
           VR1, *XAR4++; load second complex input | c + jd
           VR3, VR2, VR1, VR0; complex conjugate multiply
  VCCMPY
| VMOV32
           *XAR5++, VR2 ; (a + jb)*(c + jd)=(ac+bd)+j(bc-ad)
                        ; store imag part of first
                        ; VCCMPY instruction
 NOP
           *XAR5++, VR3 ; store real part first
  VMOV32
  VMOV32
           *XAR5++, VR2 ; store imag part next
  VCLRCPACK
```

See also

VCLROVFI



VCLROVFR

VCCMAC VR5, VR4, VR3, VR2, VR1, VR0

VCCMAC VR5, VR4, VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32

VSETCPACK

VCLRCPACK

VSATON

VSATOFF



VCCON VRa

Complex Conjugate

Operands

VRa

General purpose register: VR0, VR1....VR7. Cannot be VR8.

Opcode

Description

```
if(VSTATUS[CPACK] == 0){
   if(VSTATUS[SAT] == 1){
     VRaL = sat(- VraL)
   }else {
     VRaL = - VRaL
   }
}else {
   if(VSTATUS[SAT] == 1){
     VRaH = sat(- VraH)
   }else {
     VRaH = - VRAH
   }
}
```

LSW: 1110 0001 0001 aaaa

Flags

This instruction modifies the following bits in the VSTATUS register:

 OVFI is set in the case an overflow or underflow of the imaginary part of the conjugate operation.

Pipeline

This is a single-cycle instruction.

VR1

Example

VCCON

; VR1 := VR1^*

See also



VCDADD16 VR5, VR4, VR3, VR2 *Complex 16 + 32 = 16 Addition*

Operands

Before the operation, the inputs should be loaded into registers as shown below. The first operand is a complex number with a 16-bit real and 16-bit imaginary part. The second operand has a 32-bit real and a 32-bit imaginary part.

Input Register	Value
VR4H	16-bit integer:
	<pre>if(VSTATUS[CPACK]==0)</pre>
	Re(X)
	else
	Im(X)
VR4L	16-bit integer:
	<pre>if(VSTATUS[CPACK]==0)</pre>
	Im(X)
	else
	Re(X)
VR3	32-bit integer representing the real part of the 2nd input: Re(Y)
VR2	32-bit integer representing the imaginary part of the 2nd input: Im(Y)

The result is a complex number with a 16-bit real and a 16-bit imaginary part. The result is stored in VR5 as shown below:

Output Register	Value
VR5H	16-bit integer:
	<pre>if (VSTATUS[CPACK]==0){ Re(Z) = (Re(X) << SHIFTL) + (Re(Y)) >> SHIFTR } else { Im(Z) = (Im(X) << SHIFTL) + (Im(Y)) >> SHIFTR }</pre>
VR5L	16-bit integer:
	<pre>if (VSTATUS[CPACK] == 0) { Im(Z) = (Im(X) << SHIFTL) + (Im(Y)) >> SHIFTR } else { Re(Z) = (Re(X) << SHIFTL) + (Re(Y)) >> SHIFTR }</pre>

Opcode

LSW: 1110 0101 0000 0100

Description

Complex 16 + 32 = 16-bit operation. This operation is useful for algorithms similar to a complex FFT. The first operand is a complex number with a 16-bit real and 16-bit imaginary part. The second operand has a 32-bit real and a 32-bit imaginary part.

Before the addition, the first input is sign extended to 32-bits and shifted left by VSTATUS[VSHIFTL] bits. The result of the addition is left shifted by VSTATUS[VSHIFTR] before it is stored in VR5H and VR5L. If VSTATUS[RND] is set, then bits shifted out to the right are rounded, otherwise these bits are truncated. The rounding operation is described in Section 2.3.2. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of a 16-bit overflow or underflow.

```
// RND is VSTATUS[RND]
// SAT is VSTATUS[SAT]
// SHIFTR is VSTATUS[SHIFTR]
// SHIFTL is VSTATUS[SHIFTL]
//
// VSTATUS[CPACK] = 0
// VR4H = Re(X) 16-bit
// VR4L = Im(X) 16-bit
// VR3 = Re(Y) 32-bit
// VR2 = Im(Y) 32-bit
```



```
// Calculate Z = X + Y
                                       // 32-bit extended Re(X)
   temp1 = sign_extend(VR4H);
                                       // 32-bit extended Im(X)
   temp2 = sign_extend(VR4L);
   temp1 = (temp1 << SHIFTL) + VR3; // Re(Z) intermediate</pre>
   temp2 = (temp2 << SHIFTL) + VR2; // Im(Z) intermediate</pre>
   if (RND == 1)
      temp1 = round(temp1 >> SHIFTR);
      temp2 = round(temp2 >> SHIFTR);
   else
   {
      temp1 = truncate(temp1 >> SHIFTR);
      temp2 = truncate(temp2 >> SHIFTR);
   if (SAT == 1)
   {
      VR5H = sat16(temp1);
      VR5L = sat16(temp2);
   }
   else
   {
      VR5H = temp1[15:0];
      VR5L = temp2[15:0];
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the real-part computation (VR5H) overflows or underflows.
- OVFI is set if the imaginary-part computation (VR5L) overflows or underflows.

Pipeline

This is a single-cycle instruction.

Example

```
; Example: Z = X + Y
               (16-bit real + 16-bit imaginary)
; X = 4 + 3j
; Y = 13 + 12j
               (32-bit real + 32-bit imaginary)
; Real:
   temp1 = 0 \times 000000004 + 0 \times 000000000 = 0 \times 000000011
   VR5H = temp1[15:0] = 0x0011 = 17
; Imaginary:
   temp2 = 0x00000003 + 0x0000000C = 0x0000000F
   VR5L = temp2[15:0] = 0x000F = 15
   VSATOFF
                                 ; VSTATUS[SAT] = 0
   VRNDOFF
                                 ; VSTATUS[RND] = 0
   VSETSHR #0
                                ; VSTATUS[SHIFTR] = 0
   VSETSHL #0
                                 ; VSTATUS[SHIFTL] = 0
   VCLEARALL
                                 ; VR0, VR1...VR8 == 0
   VMOVXI VR3, #13
                                 ; VR3 = Re(Y) = 13
             VR2, #12
                                 ; VR2 = Im(Y) = 12
   IXVOMV
   IXVOMV
             VR4, #3
   XTVOMV
             VR4, #4
                                 ; VR4 = X = 0x00040003 = 4 + 3j
   VCDADD16 VR5, VR4, VR3, VR2 ; VR5 = Z = 0x0011000F = 17 + 15j
```

The next example illustrates the operation with a right shift value defined.

```
,
; Example: Z = X + Y with Right Shift
```



```
; X = 4 + 3j (16-bit real + 16-bit imaginary)
Y = 13 + 12j
              (32-bit real + 32-bit imaginary)
; Real:
   temp1 = (0x00000004 + 0x0000000D) >> 1
   temp1 = (0x00000011) >> 1 = 0x0000008.8
   VR5H = temp1[15:0] = 0x0008 = 8
; Imaginary:
   temp2 = (0x00000003 + 0x0000000C) >> 1
   temp2 = (0x0000000F) >> 1 = 0x0000007.8
   VR5L = temp2[15:0] = 0x0007 = 7
   VSATOFF
                               ; VSTATUS[SAT] = 0
   VRNDOFF
                               ; VSTATUS[RND] = 0
   VSETSHR #1
                               ; VSTATUS[SHIFTR] = 1
   VSETSHL #0
                              ; VSTATUS[SHIFTL] = 0
   VCLEARALL
                              ; VR0, VR1...VR8 == 0
   VMOVXI VR3, #13
                              ; VR3 = Re(Y) = 13
   IXVOMV
            VR2, #12
                              ; VR2 = Im(Y) = 12
   IXVOMV
            VR4, #3
   XIVOMV
            VR4, #4
                               ; VR4 = X = 0x00040003 = 4 + 3j
   VCDADD16 VR5, VR4, VR3, VR2 ; VR5 = Z = 0x00080007 = 8 +
```

The next example illustrates the operation with a right shift value defined as well as rounding.

```
; Example: Z = X + Y with Right Shift and Rounding
; X = 4 + 3j (16-bit real + 16-bit imaginary)
; Y = 13 + 12j (32-bit real + 32-bit imaginary)
; Real:
   temp1 = round((0x00000004 + 0x0000000D) >> 1)
   temp1 = round(0x00000011 >> 1)
   temp1 = round(0x0000008.8) = 0x00000009
   VR5H = temp1[15:0] = 0x0011 = 8
; Imaginary:
   temp2 = round(0x00000003 + 0x0000000C) >> 1)
   temp2 = round(0x0000000F >> 1)
   temp2 = round(0x0000007.8) = 0x00000008
   VR5L = temp2[15:0] = 0x0008 = 8
   VSATOFF
                                ; VSTATUS[SAT] = 0
   VRNDON
                               ; VSTATUS[RND] = 1
   VSETSHR #1
                               ; VSTATUS[SHIFTR] = 1
   VSETSHL #0
                              ; VSTATUS[SHIFTL] = 0
   VCLEARALL
                              ; VR0, VR1...VR8 == 0
   VMOVXI VR3, #13
                              ; VR3 = Re(Y) = 13
   VMOVXI VR2, #12
                               ; VR2 = Im(Y) = 12
   IXVOMV
            VR4, #3
   VMOVIX
            VR4. #4
                                ; VR4 = X = 0x00040003 = 4 + 3j
   VCDADD16 VR5, VR4, VR3, VR2 ; VR5 = Z = 0x00090008 = 9 + 8j
```

The next example illustrates the operation with both a right and left shift value defined along with rounding.



```
VR5H = temp1[15:0] 0xFFFF = -1;
; Imaginary:
   temp2 = 0x00000003 << 2 + 0xFFFFFFF7
   temp2 = 0x0000000C + 0xFFFFFFF7 = 0x00000003
   temp2 = 0x00000003 >> 1 = 0x00000001.8
   temp1 = round(0x00000001.8 = 0x000000002
   VR5L = temp2[15:0] 0x0002 = 2
   VSATOFF
                               ; VSTATUS[SAT] = 0
   VRNDON
                               ; VSTATUS[RND] = 1
   VSETSHR #1
                               ; VSTATUS[SHIFTR] = 1
   VSETSHL
            #2
                               ; VSTATUS[SHIFTL] = 2
                              ; VR0, VR1...VR8 == 0
   VCLEARALL
   VMOVXI VR3, #13
VMOVXI VR2, #-9
VMOVIX VR2, #0xFFFF
                              ; VR3 = Re(Y) = 13 = 0 \times 0000000D
                              ; VR2 = Im(Y) = -9
                              ; sign extend VR2 = 0xFFFFFFF7
   VMOVXI VR4, #3
                              ; VR4 = X = 0xFFFC0003 = -4 + 3j
   VMOVIX VR4, #-4
   VCDADD16 VR5, VR4, VR3, VR2 ; VR5 = Z = 0xffff0002 = -1 + 2j
```

See also

```
VCADD VR5, VR4, VR3, VR2 || VMOV32 VRa, mem32 VCADD VR7, VR6, VR5, VR4 VCDADD16 VR5, VR4, VR3, VR2 || VMOV32 VRa, mem32 VRNDOFF VRNDON VSATON VSATOFF VSETSHL #5-bit VSETSHR #5-bit
```



VCDADD16 VR5, VR4, VR3, VR2 | VMOV32 VRa, mem32 Complex Double Add with Parallel Load

Operands

Before the operation, the inputs should be loaded into registers as shown below. The first operand is a complex number with a 16-bit real and 16-bit imaginary part. The second operand has a 32-bit real and a 32-bit imaginary part.

Input Register	Value
VR4H	16-bit integer:
	<pre>if (VSTATUS[CPACK]==0) Re(X) else Im(X)</pre>
VR4L	16-bit integer:
	<pre>if (VSTATUS[CPACK]==0) Im(X) else Re(X)</pre>
VR3	32-bit integer representing the real part of the 2nd input: Re(Y)
VR2	32-bit integer representing the imaginary part of the 2nd input: Im(Y)
mem32	pointer to a 32-bit memory location.

The result is a complex number with a 16-bit real and a 16-bit imaginary part. The result is stored in VR5 as shown below:

Output Register	Value
VR5H	16-bit integer:
	if (VSTATUS[CPACK]==0){
	<pre>Re(Z) = (Re(X) << SHIFTL) + (Re(Y)) >> SHIFTR } else {</pre>
	$Im(Z) = (Im(X) \iff SHIFTL) + (Im(Y)) >> SHIFTR$
VR5L	16-bit integer:
	if (VSTATUS[CPACK]==0){
	$Im(Z) = (Im(X) \iff SHIFTL) + (Im(Y)) >> SHIFTR$ } else {
	$Re(Z) = (Re(X) \iff SHIFTL) + (Re(Y)) >> SHIFTR$
VRa	Contents of the memory pointed to by [mem32]. VRa can not be VR5 or VR8.

Opcode

```
LSW: 1110 0011 1111 1010 MSW: 0000 aaaa mem32
```

Description

Complex 16 + 32 = 16-bit operation with parallel register load. This operation is useful for algorithms similar to a complex FFT.

The first operand is a complex number with a 16-bit real and 16-bit imaginary part. The second operand has a 32-bit real and a 32-bit imaginary part.

Before the addition, the first input is sign extended to 32-bits and shifted left by VSTATUS[VSHIFTL] bits. The result of the addition is left shifted by VSTATUS[VSHIFTR] before it is stored in VR5H and VR5L. If VSTATUS[RND] is set, then bits shifted out to the right are rounded, otherwise these bits are truncated. The rounding operation is described in Section 2.3.2. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of a 16-bit overflow or underflow.

```
// RND is VSTATUS[RND]
```



```
// SAT
         is VSTATUS[SAT]
// SHIFTR is VSTATUS[SHIFTR]
// SHIFTL is VSTATUS[SHIFTL]
// VSTATUS[CPACK] = 0
// VR4H = Re(X) 16-bit
                 16-bit
// VR4L = Im(X)
// VR3 = Re(Y)
// VR2 = Im(Y) 32-bit
                              // 32-bit extended Re(X)
   temp1 = sign_extend(VR4H);
   temp2 = sign_extend(VR4L);
                                     // 32-bit extended Im(X)
   temp1 = (temp1 << SHIFTL) + VR3; // Re(Z) intermediate</pre>
   temp2 = (temp2 << SHIFTL) + VR2; // Im(Z) intermediate</pre>
   if (RND == 1)
   {
      temp1 = round(temp1 >> SHIFTR);
      temp2 = round(temp2 >> SHIFTR);
   else
   {
      temp1 = truncate(temp1 >> SHIFTR);
      temp2 = truncate(temp2 >> SHIFTR);
   }
   if (SAT == 1)
   {
     VR5H = sat16(temp1);
     VR5L = sat16(temp2);
   }
   else
      VR5H = temp1[15:0];
      VR5L = temp2[15:0];
   VRa = [mem32];
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the real-part (VR5H) computation overflows or underflows.
- OVFI is set if the imaginary-part (VR5L) computation overflows or underflows.

Pipeline

Both operations complete in a single cycle.

Example

For more information regarding the addition operation, see the examples for the VCDADD16 VR5, VR4, VR3, VR2 instruction.

```
; Example: Right Shift, Left Shift and Rounding
X = -4 + 3j
              (16-bit real + 16-bit imaginary)
Y = 13 - 9j
             (32-bit real + 32-bit imaginary)
; Real:
   temp1 = 0xFFFFFFFC << 2 + 0x0000000D
   temp1 = 0xFFFFFFFF + 0x0000000D = 0xFFFFFFFD
   temp1 = 0xFFFFFFFD >> 1 = 0xFFFFFFFE.8
   VR5H = temp1[15:0] 0xFFFF = -1;
; Imaginary:
   temp2 = 0x00000003 << 2 + 0xFFFFFFF7
   temp2 = 0 \times 00000000 + 0 \times FFFFFFFF = 0 \times 000000003
   temp2 = 0x00000003 >> 1 = 0x00000001.8
   temp1 = round(0x00000001.8 = 0x000000002
   VR5L = temp2[15:0] 0x0002 = 2
```

www.ti.com VCDADD16 VR5, VR4, VR3, VR2 || VMOV32 VRa, mem32 — Complex Double Add with Parallel Load

```
; VSTATUS[SAT] = 0
   VSATOFF
   VRNDON
                               ; VSTATUS[RND] = 1
   VSETSHR
                               ; VSTATUS[SHIFTR] = 1
   VSETSHL #2
                              ; VSTATUS[SHIFTL] = 2
                              ; VR0, VR1...VR8 == 0
   VCLEARALL
   VMOVXI VR3, #13
VMOVXI VR2, #-9
                              ; VR3 = Re(Y) = 13 = 0x0000000D
                              ; VR2 = Im(Y) = -9
   VMOVIX VR2, #0xFFFF
                              ; sign extend VR2 = 0xFFFFFFF7
   IXVOMV
            VR4, #3
   XIVOMV
            VR4, #-4
                               ; VR4 = X = 0xFFFC0003 = -4 + 3j
   VCDADD16 VR5, VR4, VR3, VR2 ; VR5 = Z = 0xFFFF0002 = -1 +
VCMOV32 VR2, *XAR7
                               ; VR2 = value pointed to by XAR7
```

See also

VCADD VR5, VR4, VR3, VR2 || VMOV32 VRa, mem32 VCADD VR7, VR6, VR5, VR4 VRNDOFF VRNDON

VRNDON VSATON VSATOFF VSETSHL #5-bit VSETSHR #5-bit



VCDSUB16 VR6, VR4, VR3, VR2 Complex 16-32 = 16 Subtract

Operands

Before the operation, the inputs should be loaded into registers as shown below. The first operand is a complex number with a 16-bit real and 16-bit imaginary part. The second operand has a 32-bit real and a 32-bit imaginary part.

Input Register	Value
VR4H	16-bit integer:
	if(VSTATUS[CPACK]==0)
	Re(X)
	else
	Im(X)
VR4L	16-bit integer:
	<pre>if VSTATUS[CPACK]==0)</pre>
	Im(X)
	else
	Re(X)
VR3	32-bit integer representing the real part of the 2nd input: Re(Y)
VR2	32-bit integer representing the imaginary part of the 2nd input: Im(Y)

The result is a complex number with a 16-bit real and a 16-bit imaginary part. The result is stored in VR6 as shown below:

Output Register	Value
VR6H	16-bit integer:
	<pre>if (VSTATUS[CPACK]==0){ Re(Z) = (Re(X) << SHIFTL) -(Re(Y)) >> SHIFTR } else {</pre>
	$Im(Z) = (Im(X) \ll SHIFTL) - (Im(Y)) >> SHIFTR$
VR6L	16-bit integer:
	<pre>if(VSTATUS[CPACK]==0){ Im(Z) = (Im(X) << SHIFTL) -(Im(Y)) >> SHIFTR</pre>
	}

Opcode

LSW: 1110 0101 0000 0101

Description

Complex 16 - 32 = 16-bit operation. This operation is useful for algorithms similar to a complex FFT.

The first operand is a complex number with a 16-bit real and 16-bit imaginary part. The second operand has a 32-bit real and a 32-bit imaginary part.

Before the addition, the first input is sign extended to 32-bits and shifted left by VSTATUS[VSHIFTL] bits. The result of the subtraction is left shifted by VSTATUS[VSHIFTR] before it is stored in VR5H and VR5L. If VSTATUS[RND] is set, then bits shifted out to the right are rounded, otherwise these bits are truncated. The rounding operation is described in Section 2.3.2. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of a 16-bit overflow or underflow.

```
// RND is VSTATUS[RND]
// SAT is VSTATUS[SAT]
// SHIFTR is VSTATUS[SHIFTR]
// SHIFTL is VSTATUS[SHIFTL]
//
// VSTATUS[CPACK] = 0
// VR4H = Re(X) 16-bit
// VR4L = Im(X) 16-bit
// VR3 = Re(Y) 32-bit
```



```
// VR2 = Im(Y)
                   32-bit
   temp1 = sign_extend(VR4H);
                                      // 32-bit extended Re(X)
   temp2 = sign_extend(VR4L);
                                      // 32-bit extended Im(X)
   temp1 = (temp1 << SHIFTL) - VR3; // Re(Z) intermediate</pre>
   temp2 = (temp2 << SHIFTL) - VR2; // Im(Z) intermediate</pre>
   if (RND == 1)
      temp1 = round(temp1 >> SHIFTR);
      temp2 = round(temp2 >> SHIFTR);
   else
      temp1 = truncate(temp1 >> SHIFTR);
      temp2 = truncate(temp2 >> SHIFTR);
   if (SAT == 1)
   {
      VR5H = sat16(temp1);
      VR5L = sat16(temp2);
   }
   else
      VR5H = temp1[15:0];
      VR5L = temp2[15:0];
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the real-part (VR6H) computation overflows or underflows.
- OVFI is set if the imaginary-part (VR6L) computation overflows or underflows.

Pipeline

This is a single-cycle instruction.

Example

```
; Example: Z = X - Y
X = 4 + 6j
               (16-bit real + 16-bit imaginary)
               (32-bit real + 32-bit imaginary)
; Y = 13 + 22j
; Z = (4 - 13) + (6 - 22)j = -9 - 16j
   VSATOFF
                                 ; VSTATUS[SAT] = 0
   VRNDOFF
                                 ; VSTATUS[RND] = 0
   VSETSHR #0
                                 ; VSTATUS[SHIFTR] = 0
   VSETSHL
            #0
                                ; VSTATUS[SHIFTL] = 0
   VCLEARALL
                                ; VR0, VR1...VR8 = 0
                                ; VR3 = Re(Y) = 13 = 0 \times 00000000D
   VMOVXI VR3, #13
                                ; VR2 = Im(Y) = 22j = 0x00000016
   IXVOMV
            VR2, #22
            VR4, #6
   VMOVXI
   XIVOMV
             VR4, #4
                                 ; VR4 = X = 0x00040006 = 4 + 6j
   VCDSUB16 VR6, VR4, VR3, VR2 ; VR5 = Z = 0xFFF7FFF0 = -9 + -16j
```

The next example illustrates the operation with a right shift value defined.

```
;
; Example: Z = X - Y with Right Shift
; Y = 4 + 6j   (16-bit real + 16-bit imaginary);
; X = 13 + 22j   (32-bit real + 32-bit imaginary);
; Real:
; temp1 = (0x00000004 - 0x0000000D) >> 1
; temp1 = (0xFFFFFFFF7) >> 1
```



```
temp1 = 0xFFFFFFFB
    VR5H = temp1[15:0] = 0xFFFB = -5
;
; Imaginary:
   temp2 = (0x00000006 - 0x00000016) >> 1
    temp2 = (0xFFFFFFF0) >> 1
   temp2 = 0xFFFFFFF8
    VR5L = temp2[15:0] = 0xFFF8 = -8
   VSATOFF
                              ; VSTATUS[SAT] = 0
   VRNDOFF
                              ; VSTATUS[RND] = 0
   VSETSHR #1
                              ; VSTATUS[SHIFTR] = 1
   VSETSHL
            #0
                              ; VSTATUS[SHIFTL] = 0
   VCLEARALL
                              ; VR0, VR1...VR8 == 0
                              ; VR3 = Re(Y) = 13 = 0x0000000D
   VMOVXI VR3, #13
   VMOVXI VR2, #22
                              ; VR2 = Im(Y) = 22j = 0x00000016
            VR4, #6
   VMOVXI
   VMOVIX VR4, #4
                              ; VR4 = X = 0x00040006 = 4 + 6j
   VCDSUB16 VR6, VR4, VR3, VR2; VR5 = Z = 0xFFFBFFF8 = -5 + -8j
```

The next example illustrates rounding with a right shift value defined.

```
; Example: Z = X-Y with Rounding and Right Shift
X = 4 + 6j
                        (16-bit real + 16-bit imaginary)
; Y = -13 + 22j
                        (32-bit real + 32-bit imaginary)
; Real:
    temp1 = round((0x00000004 - 0xFFFFFFF3) >> 1)
    temp1 = round(0x00000011) >> 1)
    temp1 = round(0x000000008.8) = 0x000000009
    VR5H = temp1[15:0] = 0x0009 = 9
; Imaginary:
    temp2 = round((0x00000006 - 0x00000016) >> 1)
    temp2 = round(0xFFFFFFF0) >> 1)
    temp2 = round(0xffffffff8.0) = 0xfffffff8
    VR5L = temp2[15:0] = 0xFFF8 = -8
   VSATOFF
                                ; VSTATUS[SAT] = 0
   VRNDON
                                ; VSTATUS[RND] = 1
   VSETSHR #1
VSETSHL #0
                                ; VSTATUS[SHIFTR] = 1
                                ; VSTATUS[SHIFTL] = 0
   VCLEARALL
                                ; VR0, VR1...VR8 == 0
                               ; VR3 = Re(Y)
   VMOVIX VR3, #0xFFFF
   VMOVXI VR3, #-13
                               ; sign extend VR3 = -13 = 0xFFFFFFFF3
   VMOVXI VR2, #22
                               ; VR2 = Im(Y) = 22j = 0x00000016
            VR4, #6
   IXVOMV
                                ; VR4 = X = 0x00040006 = 4 + 6j
   VMOVIX
             VR4, #4
   VCDSUB16 VR6, VR4, VR3, VR2 ; VR5 = Z = 0x0009FFF8 = 9 + -8j
```

The next example illustrates rounding with both a left and a right shift value defined.



```
temp2 = round((0x00000018)
                                  - 0 \times 00000016) >> 1)
;
    temp2 = round( 0x00000002 >> 1)
    temp1 = round( 0x00000001.0) = 0x00000001
    VR5L = temp2[15:0] = 0x0001 = 1
   VSATOFF
                                 ; VSTATUS[SAT] = 0
   VRNDON
                                ; VSTATUS[RND] = 1
   VSETSHR #1
                                ; VSTATUS[SHIFTR] = 1
   VSETSHL #2
                                ; VSTATUS[SHIFTL] = 2
   VCLEARALL
                                ; VR0, VR1...VR8 == 0
   VMOVXI VR3, #-13
                                ; VR3 = Re(Y)
   XIVOMV
            VR3, #0xFFFF
                                ; sign extend VR3 = -13 = 0xFFFFFFFF3
   IXVOMV
             VR2, #22
                                ; VR2 = Im(Y) = 22j = 0x00000016
   IXVOMV
            VR4, #6
                                ; VR4 = X = 0x00040006 = 4 + 6j
            VR4, #4
   XIVOMV
   VCDSUB16 VR6, VR4, VR3, VR2 ; VR5 = Z = 0x000F0001 = 15 + 1j
```

See also

VCADD VR5, VR4, VR3, VR2 || VMOV32 VRa, mem32 VCADD VR7, VR6, VR5, VR4 VRNDOFF

VRNDON VSATON VSATOFF VSETSHL #5-bit VSETSHR #5-bit



VCDSUB16 VR6, VR4, VR3, VR2 || VMOV32 VRa, mem32 Complex 16-32 = 16 Subtract with Parallel Load

Operands

Before the operation, the inputs should be loaded into registers as shown below. The first operand is a complex number with a 16-bit real and 16-bit imaginary part. The second operand has a 32-bit real and a 32-bit imaginary part.

Input Register	Value
VR4H	16-bit integer:
	<pre>if(VSTATUS[CPACK]==0)</pre>
	Re(X)
	else
	Im(X)
VR4L	16-bit integer:
	<pre>if(VSTATUS[CPACK]==0)</pre>
	Im(X)
	else
	Re(X)
VR3	32-bit integer representing the real part of the 2nd input: Re(Y)
VR2	32-bit integer representing the imaginary part of the 2nd input: Im(Y)
mem32	pointer to a 32-bit memory location.

The result is a complex number with a 16-bit real and a 16-bit imaginary part. The result is stored in VR6 as shown below:

Output Register	Value
VR6H	16-bit integer:
	<pre>if (VSTATUS[CPACK]==0) { Re(Z) = (Re(X) << SHIFTL) - (Re(Y)) >> SHIFTR } else { Im(Z) = (Im(X) << SHIFTL) - (Im(Y)) >> SHIFTR }</pre>
VR6L	16-bit integer:
	<pre>if(VSTATUS[CPACK] == 0) { Im(Z) = (Im(X) << SHIFTL) - (Im(Y)) >> SHIFTR } else { Re(Z) = (Re(X) << SHIFTL) - (Re(Y)) >> SHIFTR }</pre>
VRa	Contents of the memory pointed to by [mem32]. VRa cannot be VR6 or VR8.

Opcode

```
LSW: 1110 0011 1111 1011 MSW: 0000 aaaa mem32
```

Description

Complex 16 - 32 = 16-bit operation with parallel load. This operation is useful for algorithms similar to a complex FFT.

The first operand is a complex number with a 16-bit real and 16-bit imaginary part. The second operand has a 32-bit real and a 32-bit imaginary part.

Before the addition, the first input is sign extended to 32-bits and shifted left by VSTATUS[VSHIFTL] bits. The result of the subtraction is left shifted by VSTATUS[VSHIFTR] before it is stored in VR5H and VR5L. If VSTATUS[RND] is set, then bits shifted out to the right are rounded, otherwise these bits are truncated. The rounding operation is described in Section 2.3.2. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of a 16-bit overflow or underflow.

```
// RND is VSTATUS[RND]
// SAT is VSTATUS[SAT]
// SHIFTR is VSTATUS[SHIFTR]
```

www.ti.com VCDSUB16 VR6, VR4, VR3, VR2 | VMOV32 VRa, mem32 — Complex 16-32 = 16 Subtract with Parallel Load

```
// SHIFTL is VSTATUS[SHIFTL]
//
// VSTATUS[CPACK] = 0
// VR4H = Re(X) 16-bit
// VR4L = Im(X)
                16-bit
// VR3 = Re(Y)
              32-bit
// VR2 = Im(Y) 32-bit
  if (RND == 1)
  {
     temp1 = round(temp1 >> SHIFTR);
     temp2 = round(temp2 >> SHIFTR);
  }
  else
  {
     temp1 = truncate(temp1 >> SHIFTR);
     temp2 = truncate(temp2 >> SHIFTR);
  if (SAT == 1)
  {
     VR5H = sat16(temp1);
     VR5L = sat16(temp2);
  }
  else
  {
     VR5H = temp1[15:0];
     VR5L = temp2[15:0];
  VRa = [mem32];
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the real-part (VR6H) computation overflows or underflows.
- OVFI is set if the imaginary-part (VR6I) computation overflows or underflows.

Pipeline

Both operations complete in a single cycle.

Example

For more information regarding the subtraction operation, please refer to VCDSUB16 VR6, VR4, VR3, VR2.

```
; Example: Z = X-Y with Rounding and both Left and Right Shift
                 (16-bit real + 16-bit imaginary)
X = 4 + 6j
Y = -13 + 22j
                   (32-bit real + 32-bit imaginary)
; Real:
    temp1 = round((0x00000004 << 2 - 0xFFFFFFF3) >> 1)
    temp1 = round((0x00000010 - 0xFFFFFFF3) >> 1)
    temp1 = round( 0x0000001D >> 1)
    temp1 = round( 0x0000000E.8) = 0x0000000F
    VR5H = temp1[15:0] = 0x000F = 15
; Imaginary:
    temp2 = round((0x00000006 << 2 - 0x00000016) >> 1)
    temp2 = round((0x00000018 - 0x00000016) >> 1)
    temp2 = round( 0x00000002 >> 1)
    temp1 = round( 0x00000001.0) = 0x00000001
    VR5L = temp2[15:0] = 0x0001 = 1
   VSATOFF
                                ; VSTATUS[SAT] = 0
   VRNDON
                                ; VSTATUS[RND] = 1
                                ; VSTATUS[SHIFTR] = 1
   VSETSHR
             #1
   VSETSHL
                                 ; VSTATUS[SHIFTL] = 2
```



VCDSUB16 VR6, VR4, VR3, VR2 | VMOV32 VRa, mem32 — Complex 16-32 = 16 Subtract with Parallel Load www.ti.com

```
VCLEARALL ; VR0, VR1...VR8 == 0

VMOVXI VR3, #-13 ; VR3 = Re(Y)

VMOVIX VR3, #0xFFFF ; sign extend VR3 = -13 = 0xFFFFFFF3

VMOVXI VR2, #22 ; VR2 = Im(Y) = 22j = 0x00000016

VMOVXI VR4, #6

VMOVIX VR4, #4 ; VR4 = X = 0x00040006 = 4 + 6j

VCDSUB16 VR6, VR4, VR3, VR2 ; VR5 = Z = 0x000F0001 = 15 + 1j

| VCMOV32 VR2, *XAR7 ; VR2 = contents pointed to by XAR7
```

See also

VCADD VR5, VR4, VR3, VR2 || VMOV32 VRa, mem32

VCADD VR7, VR6, VR5, VR4

VRNDOFF VRNDON VSATON VSATOFF VSETSHL #5-bit VSETSHR #5-bit



VCFLIP VRa Swap Upper and Lower Half of VCU Register

Operands

VRa General purpose register: VR0, VR1....VR7. Cannot be VR8.

Opcode LSW: 1010 0001 0000 aaaa

Description Swap VRaL and VRaH

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction.

Example VCFLIP VR7 ; VR7H := VR7L | VR7L := VR7H

See also



VCMAC VR5, VR4, VR3, VR2, VR1, VR0 Complex Multiply and Accumulate

Operands

Input Register	Value
VR5	Real part of the accumulation
VR4	Imaginary part of the accumulation
VR3	Real part of the product
VR2	Imaginary part of the product
VR1	Second Complex Operand
VR0	First Complex Operand

NOTE: The user will need to do one final addition to accumulate the final multiplications (Real-VR3 and Imaginary-VR2) into the result registers.

Opcode

LSW: 1110 0101 0000 0001

Description

Complex multiply operation.

```
// VR5 = Accumulation of the real part
// VR4 = Accumulation of the imaginary part
//
                  VR0[31:16] = X,
// VR0 = X + jX:
                                       VR0[15:0] = jX
// VR1 = Y + jY:
                   VR1[31:16] = Y,
                                      VR1[15:0] = jY
//
// Perform add
//
   if (RND == 1)
   {
      VR5 = VR5 + round(VR3 >> SHIFTR);
      VR4 = VR4 + round(VR2 >> SHIFTR);
   }
   else
      VR5 = VR5 + (VR3 >> SHIFTR);
      VR4 = VR4 + (VR2 >> SHIFTR);
   }
//
// Perform multiply (X + jX) * (Y + jY)
//
   if(VSTATUS[CPACK] == 0){
      VR3 = VR0H * VR1H - VR0L * VR1L; // Re(Z) = Re(X)*Re(Y) - Im(X)*Im(Y)
      \label{eq:vr2} VR2 \ = \ VR0H \ * \ VR1L \ + \ VR0L \ * \ VR1H; \ // \ Im(Z) \ = \ Re(X)*Im(Y) \ + \ Im(X)*Re(Y)
   }else{
      VR3 = VR0L * VR1L - VR0H * VR1H; // Re(Z) = Re(X)*Re(Y) - Im(X)*Im(Y)
      VR2 = VR0L * VR1H + VR0H * VR1L; // Im(Z) = Re(X)*Im(Y) + Im(X)*Re(Y)
   if(SAT == 1)
   {
      sat32(VR3);
      sat32(VR2);
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the VR3 computation (real part) overflows or underflows.
- OVFI is set if the VR2 computation (imaginary part) overflows or underflows.

Pipeline

This is a 2p-cycle instruction.

Example



See also VCLROVFI

VCLROVFR

VCMAC VR5, VR4, VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32

VSATON VSATOFF



VCMAC VR7, VR6, VR5, VR4, mem32, *XAR7++ Complex Multiply and Accumulate

Operands

The VMAC alternates which registers are used between each cycle. For odd cycles (1, 3, 5, and so on) the following registers are used:

Odd Cycle Input	Value
VR5	Previous real-part total accumulation: Re(odd_sum)
VR4	Previous imaginary-part total accumulation: Im(odd-sum)
VR1	Previous real result from the multiply: Re(odd-mpy)
VR0	Previous imaginary result from the multiply Im(odd-mpy)
[mem32]	Pointer to a 32-bit memory location representing the first input to the multiply
	If(VSTATUS[CPACK] == 0)
	[mem32][32:16] = Re(X)
	[mem32][15:0] = Im(X)
	If(VSTATUS[CPACK] == 1)
	[mem32][32:16] = Im(X)
	mem32][15:0] = Re(X)
XAR7	Pointer to a 32-bit memory location representing the second input to the multiply
	If(VSTATUS[CPACK] == 0)
	*XAR7[32:16] = Re(X)
	*XAR7[15:0] = Im(X)
	If(VSTATUS[CPACK] == 1)
	*XAR7[32:16] = Im(X)
	*XAR7 [15:0] = $Re(X)$

The result from odd cycle is stored as shown below:

Odd Cycle Output	Value
VR5	32-bit real part of the total accumulation Re(odd_sum) = Re(odd_sum) + Re(odd_mpy)
VR4	32-bit imaginary part of the total accumulation Im(odd_sum) = Im(odd_sum) + Im(odd_mpy)
VR1	32-bit real result from the multiplication: Re(Z) = Re(X)*Re(Y) - Im(X)*Im(Y)
VR0	32-bit imaginary result from the multiplication: $Im(Z) = Re(X)*Im(Y) + Re(Y)*Im(X)$

For even cycles (2, 4, 6, and so on) the following registers are used:

Even Cycle Input	Value
VR7	Previous real-part total accumulation: Re(even_sum)
VR6	Previous imaginary-part total accumulation: Im(even-sum)
VR3	Previous real result from the multiply: Re(even-mpy)
VR2	Previous imaginary result from the multiply Im(even-mpy)
[mem32]	Pointer to a 32-bit memory location representing the first input to the multiply
	If(VSTATUS[CPACK] == 0)
	[mem32][32:16] = Re(X)
	[mem32][15:0] = Im(X)
	If(VSTATUS[CPACK] == 1)
	[mem32][32:16] = Im(X)



Even Cycle Input Value

mem32][15:0] = Re(X)

XAR7

Pointer to a 32-bit memory location representing the second input to the multiply If(VSTATUS[CPACK] == 0)

```
*XAR7[32:16] = Re(X)
  *XAR7[15:0] = Im(X)
If(VSTATUS[CPACK] == 1)
  *XAR7[32:16] = Im(X)
  *XAR7 [15:0] = Re(X)
```

The result from even cycles is stored as shown below:

Even Cycle Output	Value
VR7	32-bit real part of the total accumulation Re(even_sum) = Re(even_sum) + Re(even_mpy)
VR6	32-bit imaginary part of the total accumulation Im(even_sum) = Im(even_sum) + Im(even_mpy)
VR3	32-bit real result from the multiplication: Re(Z) = Re(X)*Re(Y) - Im(X)*Im(Y)
VR2	32-bit imaginary result from the multiplication: Im(Z) = Re(X)*Im(Y) + Re(Y)*Im(X)

Opcode

```
LSW: 1110 0010 0101 0001
MSW: 0000 0000 mem32
```

Description

Perform a repeated multiply and accumulate operation. This instruction must be used with the repeat instruction (RPT||). The destination of the accumulate will alternate between VR7/VR6 and VR5/VR4 on each cycle.

```
// Cycle 1:
//
// Perform accumulate
//
   if(RND == 1)
      VR5 = VR5 + round(VR1 >> SHIFTR)
      VR4 = VR4 + round(VR0 >> SHIFTR)
    }
    else
      VR5 = VR5 + (VR1 >> SHIFTR)
      VR4 = VR4 + (VR0 >> SHIFTR)
    // X and Y array element 0
   VR1 = Re(X)*Re(Y) - Im(X)*Im(Y)
    VR0 = Re(X)*Im(Y) + Re(Y)*Im(X)
// Cycle 2:
//
// Perform accumulate
//
   if(RND == 1)
      VR7 = VR7 + round(VR3 >> SHIFTR)
      VR6 = VR6 + round(VR2 >> SHIFTR)
    }
    else
    {
```



```
VR7 = VR7 + (VR3 >> SHIFTR)
      VR6 = VR6 + (VR2 >> SHIFTR)
    }
    //
    // X and Y array element 1
    11
    VR3 = Re(X)*Re(Y) - Im(X)*Im(Y)
    VR2 = Re(X)*Im(Y) + Re(Y)*Im(X)
// Cycle 3:
11
// Perform accumulate
//
   if(RND == 1)
   {
      VR5 = VR5 + round(VR1 >> SHIFTR)
      VR4 = VR4 + round(VR0 >> SHIFTR)
    }
    else
    {
      VR5 = VR5 + (VR1 >> SHIFTR)
      VR4 = VR4 + (VR0 >> SHIFTR)
    //
    \ensuremath{//} X and Y array element 2
    //
    VR1 = Re(X)*Re(Y) - Im(X)*Im(Y)
    VR0 = Re(X)*Im(Y) + Re(Y)*Im(X)
  etc...
```

Restrictions

VR0, VR1, VR2, and VR3 will be used as temporary storage by this instruction.

Flags

The VSTATUS register flags are modified as follows:

- OVFR is set in the case of an overflow or underflow of the addition or subtraction operations.
- OVFI is set in the case an overflow or underflow of the imaginary part of the addition or subtraction operations.

Pipeline

The VCCMAC takes 2p + N cycles where N is the number of times the instruction is repeated. This instruction has the following pipeline restrictions:

```
<<instruction1>> ; No restrictions
<<instruction2>> ; Cannot be a 2p instruction that writes
; to VR0, VR1...VR7 registers
RPT #(N-1) ; Execute N times, where N is even
|| VCMAC VR7, VR6, VR5, VR4, *XAR6++, *XAR7++
<<instruction3>> ; No restrictions
; Can read VR0, VR1...VR8
```

Example

Cascading of RPT || VCMAC is allowed as long as the first and subsequent counts are even. Cascading is useful for creating interruptible windows so that interrupts are not delayed too long by the RPT instruction. For example:

```
; Example of cascaded VMAC instructions;

VCLEARALL ; Zero the accumulation registers;

; Execute MACF32 N+1 (4) times;

RPT #3

| VCMAC VR7, VR6, VR5, VR4, *XAR6++, *XAR7++

; Execute MACF32 N+1 (6) times;
```



```
RPT #5
|| VCMAC VR7, VR6, VR5, VR4, *XAR6++, *XAR7++
;
; Repeat MACF32 N+1 times where N+1 is even
;
    RPT #N
|| MACF32 R7H, R3H, *XAR6++, *XAR7++
    ADDF32 VR7, VR6, VR5, VR4
```

See also

VCCMAC VR7, VR6, VR5, VR4, mem32, *XAR7++



VCMAC VR5, VR4, VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32 — Complex Multiply and Accumulate with Parallel Load www.ti.com

VCMAC VR5, VR4, VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32 Complex Multiply and Accumulate with Parallel Load

Operands

Input Register	Value
VR0	First Complex Operand
VR1	Second Complex Operand
VR2	Imaginary part of the product
VR3	Real part of the product
VR4	Imaginary part of the accumulation
VR5	Real part of the accumulation
VRa	Contents of the memory pointed to by mem32. VRa cannot be VR5, VR4, or VR8
mem32	Pointer to 32-bit memory location

NOTE: The user will need to do one final addition to accumulate the final multiplications (Real-VR3 and Imaginary-VR2) into the result registers.

Opcode

```
LSW: 1110 0011 1111 0111 MSW: 0000 aaaa mem32
```

Description

Complex multiply operation.

```
// VR5 = Accumulation of the real part
// VR4 = Accumulation of the imaginary part
11
// VR0 = X + Xj:
                    VR0[31:16] = Re(X),
                                               VR0[15:0] = Im(X)
// VR1 = Y + Yj:
                    VR1[31:16] = Re(Y),
                                               VR1[15:0] = Im(Y)
11
// Perform add
//
   if (RND == 1)
   {
      VR5 = VR5 + round(VR3 >> SHIFTR);
      VR4 = VR4 + round(VR2 >> SHIFTR);
   }
   else
   {
      VR5 = VR5 + (VR3 >> SHIFTR);
      VR4 = VR4 + (VR2 >> SHIFTR);
   }
//
// Perform multiply Z = (X + Xj) * (Y + Yj)
//
   if(VSTATUS[CPACK] == 0){
      VR3 = VR0H * VR1H - VR0L * VR1L; // Re(Z) = Re(X)*Re(Y) - Im(X)*Im(Y)
      VR2 = VR0H * VR1L + VR0L * VR1H; // Im(Z) = Re(X)*Im(Y) + Im(X)*Re(Y)
   }else{
     \label{eq:vr1} \textit{VR3} \ = \ \textit{VR0L} \ * \ \textit{VR1L} \ - \ \textit{VR0H} \ * \ \textit{VR1H}; \ \ // \ \textit{Re(Z)} \ = \ \textit{Re(X)*Re(Y)} \ - \ \textit{Im(X)*Im(Y)}
     VR2 = VR0L * VR1H + VR0H * VR1L; // Im(Z) = Re(X)*Im(Y) + Im(X)*Re(Y)
   })
   if(SAT == 1)
   {
      sat32(VR3);
      sat32(VR2);
   VRa = [mem32];
```

Flags

This instruction modifies the following bits in the VSTATUS register:

OVFR is set if the VR3 computation (real part) overflows or underflows.



www.ti.com VCMAC VR5, VR4, VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32 — Complex Multiply and Accumulate with Parallel Load

OVFI is set if the VR2 computation (imaginary part) overflows or underflows.

Pipeline This is a 2p/1-cycle instruction. The multiply and accumulate is a 2p-cycle operation and

the VMOV32 is a single-cycle operation.

Example

See also VCLROVFI

VCLROVFR

VCMAC VR5, VR4, VR3, VR2, VR1, VR0

VSATON VSATOFF



VCMAG VRb, VRa Magnitude of a Complex Number

Operands VRb General purpose register VR0...VR8

VRa General purpose register VR0...VR8

Opcode LSW: 1110 0110 1111 0010 MSW: 0000 0100 bbbb aaaa

Description Compute the magnitude of the Complex value in VRa

If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of a 32-bit overflow or underflow.

```
If(VSTATUS[SAT] == 1) {
        If(VSTATUS[RND] == 1) {
            VRb = rnd(sat(VRaH*VRaH + VRaL*VRaL)>>VSTATUS[SHIFTR])
}else {
            VRb = sat(VRaH*VRaH + VRaL*VRaL)>>VSTATUS[SHIFTR]
      }
}else { //VSTATUS[SAT] = 0
            If(VSTATUS[RND] == 1) {
                 VRb = rnd((VRaH*VRaH + VRaL*VRaL)>>VSTATUS[SHIFTR])
}else {
            VRb = (VRaH*VRaH + VRaL*VRaL)>>VSTATUS[SHIFTR]
      }
}
```

Sign-Extension is automatically done for the shift right operations

Flags

This instruction modifies the following bits in the VSTATUS register:

 OVFR is set if overflow is detected in the complex magnitude operation of the real 32-bit result

Pipeline

This is a 2 cycle instruction

Example

See also



VCMPY VR3, VR2, VR1, VR0 Complex Multiply

Operands

Both inputs are complex numbers with a 16-bit real and 16-bit imaginary part. The result is a complex number with a 32-bit real and a 32-bit imaginary part. The result is stored in VR2 and VR3 as shown below:

Input Register	Value
VR3	Real part of the Result
VR2	Imaginary part of the Result
VR1	Second Complex Operand
VR0	First Complex Operand

Opcode

LSW: 1110 0101 0000 0000

Description

Complex $16 \times 16 = 32$ -bit multiply operation.

If the VSTATUS[CPACK] bit is set, the low word of the input is treated as the real part while the upper word is treated as imaginary. If the VSTATUS[SAT] bit is set, the result will be saturated in the event of a 32-bit overflow or underflow.

```
// Calculate: Z = (X + jX) * (Y + jY)
//
   if(VSTATUS[CPACK] == 0){
     VR3 = VR0H * VR1H - VR0L * VR1L; // Re(Z) = Re(X)*Re(Y) - Im(X)*Im(Y)
     VR2 = VR0H * VR1L + VR0L * VR1H; // Im(Z) = Re(X)*Im(Y) + Im(X)*Re(Y)
   }else{
     VR3 = VR0L * VR1L - VR0H * VR1H; // Re(Z) = Re(X)*Re(Y) - Im(X)*Im(Y)
     VR2 = VR0L * VR1H + VR0H * VR1L; // Im(Z) = Re(X)*Im(Y) + Im(X)*Re(Y)
   if(SAT == 1)
   {
      sat32(VR3);
      sat32(VR2);
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the VR3 computation (real part) overflows or underflows.
- OVFI is set if the VR2 computation (imaginary part) overflows or underflows.

Pipeline

This is a 2p-cycle instruction. The instruction following this one should not use VR3 or VR2.

Example

```
; Example 1
; X = 4 + 6j
; Y = 12 + 9j
Z = X * Y
; Re(Z) = 4*12 - 6*9 = -6
; Im(Z) = 4*9 + 6*12 = 108
   VSATOFF
                                 ; VSTATUS[SAT] = 0
   VCLEARALL
                                 ; VR0, VR1...VR8 == 0
   IXVOMV
             VR0, #6
             VR0, #4
                                 ; VR0 = X = 0x00040006 = 4 + 6j
   XIVOMV
   IXVOMV
             VR1, #9
             VR1, #12
                                 ; VR1 = Y = 0x000C0009 = 12 + 9j
   VIVOMV
   VCMPY
             VR3, VR2, VR1, VR0 ; VR3 = Re(Z) = 0xFFFFFFFA = -6
                                 ; VR2 = Im(Z) = 0x0000006C = 108
    <instruction 1>
                                  ; <- Must not use VR2, VR3
                                 ; <- VCMPY completes, VR2, VR3 valid
    <instruction 2>
                                 ; Can use VR2, VR3
```



See also VCLROVFI

VCLROVFR

VCMAC VR5, VR4, VR3, VR2, VR1, VR0

VCMAC VR5, VR4, VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32

VSATON VSATOFF



VCMPY VR3, VR2, VR1, VR0 | VMOV32 mem32, VRa Complex Multiply with Parallel Store

Operands

Both inputs are complex numbers with a 16-bit real and 16-bit imaginary part. The result is a complex number with a 32-bit real and a 32-bit imaginary part. The result is stored in VR2 and VR3 as shown below:

Input Register	Value
VR3	Real part of the Result
VR2	Imaginary part of the Result
VR1	Second Complex Operand
VR0	First Complex Operand
VRa	Value to be stored
mem32	Pointer to 32-bit memory location

Opcode

```
LSW: 1110 0010 1100 1010 MSW: 0000 aaaa mem16
```

Description

Complex $16 \times 16 = 32$ -bit multiply operation with parallel register load.

If the VSTATUS[CPACK] bit is set, the low word of the input is treated as the real part while the upper word is treated as imaginary. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of a 32-bit overflow or underflow.

```
// Calculate: Z = (X + jX) * (Y + jY)
//
if(VSTATUS[CPACK] == 0) {
    VR3 = VR0H * VR1H - VR0L * VR1L; // Re(Z) = Re(X)*Re(Y) - Im(X)*Im(Y)
    VR2 = VR0H * VR1L + VR0L * VR1H; // Im(Z) = Re(X)*Im(Y) + Im(X)*Re(Y)
}else{
    VR3 = VR0L * VR1L - VR0H * VR1H; // Re(Z) = Re(X)*Re(Y) - Im(X)*Im(Y)
    VR2 = VR0L * VR1H + VR0H * VR1L; // Im(Z) = Re(X)*Im(Y) + Im(X)*Re(Y)
}
if(SAT == 1)
{
    sat32(VR3);
    sat32(VR2);
}
VRa = [mem32];
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the VR3 computation (real part) overflows or underflows.
- OVFI is set if the VR2 computation (imaginary part) overflows or underflows.

Pipeline

This is a 2p/1-cycle instruction. The multiply operation takes 2p cycles and the VMOV operation completes in a single cycle. The instruction following this one must not use VR2 or VR3.

Example

```
; Example 1
; X = 4 + 6j
; Y = 12 + 9j
Z = X * Y
Re(Z) = 4*12 - 6*9 = -6
; Im(Z) = 4*9 + 6*12 = 108
   VSATOFF
                                 ; VSTATUS[SAT] = 0
   VCLEARALL
                                 ; VR0, VR1...VR8 == 0
   VMOVXI
             VR0, #6
                                 ; VR0 = X = 0x00040006 = 4 + 6j
   XIVOMV
             VR0, #4
             VR1, #9
    VMOVXI
   XIVOMV
             VR1, #12
                                 ; VR1 = Y = 0x000C0009 = 12 + 9j
                                 ; VR3 = Re(Z) = 0xFFFFFFFA = -6
```



multiply)

; <- VCMPY completes, VR2, VR3 valid

See also VCLROVFI

VCLROVFR

VCMAC VR5, VR4, VR3, VR2, VR1, VR0

VCMAC VR5, VR4, VR3, VR2, VR1, VR0 | VMOV32 VRa, mem32

VSATON VSATOFF



VCMPY VR3, VR2, VR1, VR0 | VMOV32 VRa, mem32 Complex Multiply with Parallel Load

Operands

Both inputs are complex numbers with a 16-bit real and 16-bit imaginary part. The result is a complex number with a 32-bit real and a 32-bit imaginary part. The result is stored in VR2 and VR3 as shown below:

Input Register	Value
VR3	Real part of the Result
VR2	Imaginary part of the Result
VR1	Second Complex Operand
VR0	First Complex Operand
VRa	32-bit value pointed to by mem32. VRa can not be VR2, VR3 or VR8.
mem32	Pointer to 32-bit memory location

Opcode

```
LSW: 1110 0011 1111 0110 MSW: 0000 aaaa mem32
```

Description

Complex $16 \times 16 = 32$ -bit multiply operation with parallel register load.

If the VSTATUS[CPACK] bit is set, the low word of the input is treated as the real part while the upper word is treated as imaginary. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of a 32-bit overflow or underflow.

```
// Calculate: Z = (X + jX) * (Y + jY)
//
if(VSTATUS[CPACK] == 0) {
    VR3 = VR0H * VR1H - VR0L * VR1L; // Re(Z) = Re(X)*Re(Y) - Im(X)*Im(Y)
    VR2 = VR0H * VR1L + VR0L * VR1H; // Im(Z) = Re(X)*Im(Y) + Im(X)*Re(Y)
}else{
    VR3 = VR0L * VR1L - VR0H * VR1H; // Re(Z) = Re(X)*Re(Y) - Im(X)*Im(Y)
    VR2 = VR0L * VR1H + VR0H * VR1L; // Im(Z) = Re(X)*Im(Y) + Im(X)*Re(Y)
}
if(SAT == 1)
{
    sat32(VR3);
    sat32(VR2);
}
VRa = [mem32];
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the VR3 computation (real part) overflows or underflows.
- OVFI is set if the VR2 computation (imaginary part) overflows or underflows.

Pipeline

This is a 2p/1-cycle instruction. The multiply operation takes 2p cycles and the VMOV operation completes in a single cycle. The instruction following this one must not use VR2 or VR3.

Example

```
; Example 1
; X = 4 + 6j
; Y = 12 + 9j
Z = X * Y
Re(Z) = 4*12 - 6*9 = -6
; Im(Z) = 4*9 + 6*12 = 108
   VSATOFF
                                 ; VSTATUS[SAT] = 0
   VCLEARALL
                                 ; VR0, VR1...VR8 == 0
   VMOVXI
             VR0, #6
                                 ; VR0 = X = 0x00040006 = 4 + 6j
   XIVOMV
             VR0, #4
             VR1, #9
    VMOVXI
   XIVOMV
             VR1, #12
                                 ; VR1 = Y = 0x000C0009 = 12 + 9j
                                 ; VR3 = Re(Z) = 0xFFFFFFFA = -6
```

VCMPY VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32 — Complex Multiply with Parallel Load

www.ti.com

VCMPY VR3, VR2, VR1, VR0 ; VR2 = Im(Z) = 0x0000006C = 108| VMOV32 VR0, *XAR7 ; VR0 = contents of location XAR7 points to

See also VCLROVFI

VCLROVFR

VCMAC VR5, VR4, VR3, VR2, VR1, VR0

VCMAC VR5, VR4, VR3, VR2, VR1, VR0 || VMOV32 VRa, mem32

VSATON VSATOFF



VCSHL16 VRa << #4-bit Complex Shift Left

Operands

VRa	General purpose register VR0VR8
#4-bit	4-bit unsigned immediate value

Opcode

```
LSW: 1110 0110 1111 0010 MSW: 0000 0000 IIII aaaa
```

Description

Left Shift the Real and Imaginary parts of the complex value in VRa.

```
if(VSTATUS[CPACK] == 0){
   if(VSTATUS[SAT] == 1){
     VRaL = sat(VRaL <<#4-bit Immediate) (imaginary result)
     VRaH = sat(VRaH << #4-bit Immediate) (real result)
} else {
    VRaL = VRaL << #4-bit Immediate (imaginary result)
     VRaH = VRaH << #4-bit Immediate (real result)
}
} else {
   If(VSTATUS[SAT] == 1){
   VRaL = sat(VRaL << #4-bit Immediate) (real result)
   VRaH = sat(VRaH << #4-bit Immediate) (imaginary result)
   VRaH = sat(VRaH << #4-bit Immediate) (imaginary result)
} else {
   VRaL = VRaL << #4-bit Immediate (real result)
   VRaH = VRaH << #4-bit Immediate (imaginary result)
}</pre>
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if overflow is detected in the shift left operation of the real signed-16-bit result
- OVFI is set if overflow is detected in the shift left operation of the imaginary signed-16-bit result.

Pipeline

This is a single-cycle instruction.

Example

```
VSATOFF ; turn off saturation VCSHL16 VR5 << \#8 ; VR5L := VR5L << 8 | VR5H := VR5H << 8
```

See also



VCSHR16 VRa >> #4-bit Complex Shift Right

Operands

VRa	General purpose register VR0VR8
#4-bit	4-bit unsigned immediate value

Opcode

```
LSW: 1110 0110 1111 0010 MSW: 0000 0001 IIII aaaa
```

Description

Right Shift the Real and Imaginary parts of the complex value in VRa.

```
if(VSTATUS[CPACK] == 0){
if(VSTATUS[RND] == 1){
   VRaL = rnd(VRaL >> #4-bit Immediate) (imaginary result)
   VRaH = rnd(VRaH >> #4-bit Immediate) (real result)
}else {
   VRaL = VRaL >> #4-bit Immediate (imaginary result)
   VRaH = VRaH >> #4-bit Immediate (real result)
}
}else {
   If(VSTATUS[RND] == 1){
   VRaL = rnd(VRaL >> #4-bit Immediate) (real result)
   VRAH = rnd(VRaH >> #4-bit Immediate) (imaginary result)
   VRAH = rnd(VRaH >> #4-bit Immediate) (imaginary result)
}else {
   VRAL = VRAL >> #4-bit Immediate (real result)
   VRAH = VRAH >> #4-bit Immediate (imaginary result)
}
```

Sign-Extension is automatically done for the shift right operations

Flags

This instruction does not affect any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

```
VSATOFF ; turn off saturation
VCSHR16    VR6 >> #8 ; VR6L := VR6L >> 8 | VR6H := VR6H >> 8
```

See also



VCSUB VR5, VR4, VR3, VR2 Complex 32 - 32 = 32 Subtraction

Operands

Before the operation, the inputs should be loaded into registers as shown below. Each complex number includes a 32-bit real and a 32-bit imaginary part.

Input Register	Value
VR5	32-bit integer representing the real part of the first input: Re(X)
VR4	32-bit integer representing the imaginary part of the first input: Im(X)
VR3	32-bit integer representing the real part of the 2nd input: Re(Y)
VR2	32-bit integer representing the imaginary part of the 2nd input: Im(Y)

The result is also a complex number with a 32-bit real and a 32-bit imaginary part. The result is stored in VR5 and VR4 as shown below:

Output Register	Value
VR5	32-bit integer representing the real part of the result: Re(Z) = Re(X) - (Re(Y) >> SHIFTR)
VR4	32-bit integer representing the imaginary part of the result: $Im(Z) = Im(X) - (Im(Y) >> SHIFTR)$

Opcode

LSW: 1110 0101 0000 0011

Description

Complex 32 - 32 = 32-bit subtraction operation.

The second input operand (stored in VR3 and VR2) is shifted right by VSTATUS[SHIFR] bits before the subtraction. If VSTATUS[RND] is set, then bits shifted out to the right are rounded, otherwise these bits are truncated. The rounding operation is described in Section 2.3.2. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of an overflow or underflow.

```
// RND
          is VSTATUS[RND]
// SAT
          is VSTATUS[SAT]
// SHIFTR is VSTATUS[SHIFTR]
   if (RND == 1)
   {
      VR5 = VR5 - round(VR3 >> SHIFTR);
      VR4 = VR4 - round(VR2 >> SHIFTR);
   else
   {
      VR5 = VR5 - (VR3 >> SHIFTR);
      VR4 = VR4 - (VR2 >> SHIFTR);
   if (SAT == 1)
   {
      sat32(VR5);
      sat32(VR4);
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the VR5 computation (real part) overflows or underflows.
- OVFI is set if the VR6 computation (imaginary part) overflows or underflows.

Pipeline

This is a single-cycle instruction.

Example

See also

VCADD VR5, VR4, VR3, VR2 || VMOV32 VRa, mem32 VCADD VR7, VR6, VR5, VR4 VCSUB VR5, VR4, VR3, VR2 || VMOV32 VRa, mem32 VCLROVFI



VCLROVFR VRNDOFF VRNDON VSATON VSATOFF VSETSHR #5-bit



VCSUB VR5, VR4, VR3, VR2 | VMOV32 VRa, mem32 Complex Subtraction

Operands

Before the operation, the inputs should be loaded into registers as shown below. Each complex number includes a 32-bit real and a 32-bit imaginary part.

Input Register	Value
VR5	32-bit integer representing the real part of the first input: Re(X)
VR4	32-bit integer representing the imaginary part of the first input: Im(X)
VR3	32-bit integer representing the real part of the 2nd input: Re(Y)
VR2	32-bit integer representing the imaginary part of the 2nd input: Im(Y)
mem32	pointer to a 32-bit memory location

The result is also a complex number with a 32-bit real and a 32-bit imaginary part. The result is stored in VR5 and VR4 as shown below:

Output Register	Value
VR5	32-bit integer representing the real part of the result: Re(Z) = Re(X) - (Re(Y) >> SHIFTR)
VR4	32-bit integer representing the imaginary part of the result: $Im(Z) = Im(X) - (Im(Y) >> SHIFTR)$
VRa	contents of the memory pointed to by [mem32]. VRa can not be VR5, VR4 or VR8.

Opcode

```
LSW: 1110 0011 1111 1001 MSW: 0000 aaaa mem32
```

Description

Complex 32 - 32 = 32-bit subtraction operation with parallel load.

The second input operand (stored in VR3 and VR2) is shifted right by VSTATUS[SHIFR] bits before the subtraction. If VSTATUS[RND] is set, then bits shifted out to the right are rounded, otherwise these bits are truncated. The rounding operation is described in Section 2.3.2. If the VSTATUS[SAT] bit is set, then the result will be saturated in the event of an overflow or underflow.

```
// RND
          is VSTATUS[RND]
// SAT
         is VSTATUS[SAT]
// SHIFTR is VSTATUS[SHIFTR]
//
  if (RND == 1)
   {
      VR5 = VR5 - round(VR3 >> SHIFTR);
      VR4 = VR4 - round(VR2 >> SHIFTR);
   }
   else
      VR5 = VR5 - (VR3 >> SHIFTR);
      VR4 = VR4 - (VR2 >> SHIFTR);
   if (SAT == 1)
   {
      sat32(VR5);
      sat32(VR4);
   VRa = [mem32];
```

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if the VR5 computation (real part) overflows or underflows.
- OVFI is set if the VR6 computation (imaginary part) overflows or underflows.

Pipeline

This is a single-cycle instruction.

Example



VCADD VR5, VR4, VR3, VR2 || VMOV32 VRa, mem32 See also

VCADD VR7, VR6, VR5, VR4 VCSUB VR5, VR4, VR3, VR2

VCLROVFI

VCLROVFR VRNDOFF VRNDON VSATON VSATOFF VSETSHR #5-bit



www.ti.com Instruction Set

2.5.5 Cyclic Redundancy Check (CRC) Instructions

The instructions are listed alphabetically, preceded by a summary.

Table 2-14. CRC Instructions

Title I	Page
VCRC8H_1 mem16 — CRC8, High Byte	272
VCRC8L_1 mem16 — CRC8 , Low Byte	273
VCRC16P1H_1 mem16 — CRC16, Polynomial 1, High Byte	274
VCRC16P1L_1 mem16 — CRC16, Polynomial 1, Low Byte	275
VCRC16P2H_1 mem16 — CRC16, Polynomial 2, High Byte	276
VCRC16P2L_1 mem16 — CRC16, Polynomial 2, Low Byte	277
VCRC24H_1 mem16 — CRC24, High Byte	278
VCRC24L_1 mem16 — CRC24, Low Byte	279
VCRC32H_1 mem16 — CRC32, High Byte	
VCRC32L_1 mem16 — CRC32, Low Byte	281
VCRC32P2H_1 mem16 — CRC32, Polynomial 2, High Byte	
VCRC32P2L_1 mem16 — CRC32, Low Byte	
VCRCCLR —Clear CRC Result Register	
VMOV32 mem32, VCRC —Store the CRC Result Register	285
VMOV32 VCRC, mem32 — Load the CRC Result Register	



VCRC8H_1 mem16 CRC8, High Byte

Operands

mem16 16-bit memory location

Opcode

LSW: 1110 0010 1100 1100 MSW: 0000 0000 mem16

Description

This instruction uses CRC8 polynomial == 0x07.

Calculate the CRC8 of the most significant byte pointed to by mem16 and accumulate it with the value in the VCRC register. Store the result in VCRC.

```
if (VSTATUS[CRCMSGFLIP == 0) {
   temp[7:0] = [mem16][15:8];
}else {
   temp[7:0] = [mem16][8:15];
}
```

VCRC[7:0] = CRC8 (VCRC[7:0], temp[7:0])

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example Refer to the example for VCRC8L_1 mem16

See also VCRC8L_1 mem16



VCRC8L_1 mem16 CRC8, Low Byte

Operands

mem16 16-bit memory location

Opcode

```
LSW: 1110 0010 1100 1011 MSW: 0000 0000 mem16
```

Description

This instruction uses CRC8 polynomial == 0x07.

Calculate the CRC8 of the least significant byte pointed to by mem16 and accumulate it with the value in the VCRC register. Store the result in VCRC.

```
if (VSTATUS[CRCMSGFLIP] == 0){
   temp[7:0] = [mem16][7:0];
}else{
   temp[7:0] = [mem16][0:7];
}
VCRC[7:0] = CRC8 (VCRC[7:0], temp[7:0])
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

```
typedef struct {
     uint32_t *CRCResult;
                             // Address where result should be stored
     uint16_t *CRCData;
                             // Start of data
     uint16_t CRCLen;
                             // Length of data in bytes
  }CRC_CALC;
  CRC_CALC mycrc;
  CRC8(&mycrc);
   . . .
; Calculate the CRC of a block of data
; This function assumes the block is a multiple of 2 16-bit words
   .global _CRC8
_CRC8
   VCRCCLR
                            ; Clear the result register
   MOV AL,
                 *+XAR4[4] ; AL = CRCLen
               2
#1
   ASR
         AL,
                           ; AL = CRCLen/4
   SUBB AL,
                            ; AL = CRCLen/4 - 1
   MOVL XAR7, *+XAR4[2] ; XAR7 = &CRCData
   .align 2
   NOP
                            ; Align RPTB to an odd address
                         ; Execute block of code AL + 1 times
   RPTB _CRC8_done, AL
   VCRC8L_1 *XAR7
                            ; Calculate CRC for 4 bytes
   VCRC8H_1 *XAR7++
                            ; ...
   VCRC8L_1 *XAR7
                            ; ...
   VCRC8H_1 *XAR7++
CRC8 done
   MOVL XAR7, *_+XAR4[0] ; XAR7 = &CRCResult
   MOV32 *+XAR7[0], VCRC ; Store the
   LRETR
                            ; return to caller
```

See also

VCRC8H_1 mem16



VCRC16P1H_1 mem16 CRC16, Polynomial 1, High Byte

Operands

mem16 16-bit memory location

Opcode

LSW: 1110 0010 1100 1111 MSW: 0000 0000 mem16

Description

This instruction uses CRC16 polynomial 1 == 0x8005.

Calculate the CRC16 of the most significant byte pointed to by mem16 and accumulate it with the value in the VCRC register. Store the result in VCRC.

```
if (VSTATUS[CRCMSGFLIP] == 0){
  temp[7:0] = [mem16][15:8];
}else {
  temp[7:0] = [mem16][8:15];
}
```

VCRC[15:0] = CRC16(VCRC[15:0], temp[7:0])

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example Refer to the example for VCRC16P1L_1 mem16.

See also VCRC16P1L_1 mem16

VCRC16P2H_1 mem16 VCRC16P2L_1 mem16



VCRC16P1L_1 mem16 CRC16, Polynomial 1, Low Byte

Operands

mem16 16-bit memory location

Opcode

LSW: 1110 0010 1100 1110 MSW: 0000 0000 mem16

Description

This instruction uses CRC16 polynomial 1 == 0x8005.

Calculate the CRC16 of the least significant byte pointed to by mem16 and accumulate it with the value in the VCRC register. Store the result in VCRC.

```
if (VSTATUS[CRCMSGFLIP] == 0){
   temp[7:0] = [mem16][7:0];
}else {
   temp[7:0] = [mem16][0:7];
}

VCRC[15:0] = CRC16 (VCRC[15:0], temp[7:0]))
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

```
typedef struct {
     uint32_t *CRCResult;
                             // Address where result should be stored
     uint16_t *CRCData;
                            // Start of data
     uint16_t CRCLen;
                             // Length of data in bytes
  }CRC_CALC;
  CRC_CALC mycrc;
  CRC16P1(&mycrc);
; Calculate the CRC of a block of data
; This function assumes the block is a multiple of 2 16-bit words
   .global _CRC16P1
_CRC16P1
   VCRCCLR
                           ; Clear the result register
   MOV AL,
               *+XAR4[4] ; AL = CRCLen
   ASR
         AL, 2 ; AL = CRCLen/4
   SUBB AL,
                           ; AL = CRCLen/4 - 1
   MOVL XAR7, *+XAR4[2] ; XAR7 = &CRCData
   .aliqn 2
   NOP
                           ; Align RPTB to an odd address
   RPTB _CRC16P1_done, AL ; Execute block of code AL + 1 times
   VCRC16P1L_1 *XAR7
                           ; Calculate CRC for 4 bytes
   VCRC16P1H_1 *XAR7++
                           ; ...
   VCRC16P1L_1 *XAR7
                          ; ...
   VCRC16P1H_1 *XAR7++
_CRC16P1_done
   MOVL XAR7, *_+XAR4[0] ; XAR7 = &CRCResult
   MOV32 *+XAR7[0], VCRC ; Store the result
   LRETR
                           ; return to caller
```

See also

VCRC16P1H_1 mem16 VCRC16P2H_1 mem16 VCRC16P2L_1 mem16



VCRC16P2H_1 mem16 CRC16, Polynomial 2, High Byte

Operands

mem16 16-bit memory location

Opcode

LSW: 1110 0010 1100 1111 MSW: 0001 0000 mem16

Description

This instruction uses CRC16 polynomial 2== 0x1021.

Calculate the CRC16 of the most significant byte pointed to by mem16 and accumulate it with the value in the VCRC register. Store the result in VCRC.

```
if (VSTATUS[CRCMSGFLIP] == 0){
   temp[7:0] = [mem16][15:8];
}else {
   temp[7:0] = [mem16][8:15];
}
```

VCRC[15:0] = CRC16(VCRC[15:0], temp[7:0])

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example Refer to the example for VCRC16P2L_1 mem16.

See also VCRC16P2L_1 mem16

VCRC16P1H_1 mem16 VCRC16P1L_1 mem16



VCRC16P2L_1 mem16 CRC16, Polynomial 2, Low Byte

Operands

mem16 16-bit memory location

Opcode

LSW: 1110 0010 1100 1110 MSW: 0001 0000 mem16

Description

This instruction uses CRC16 polynomial 2== 0x1021.

Calculate the CRC16 of the least significant byte pointed to by mem16 and accumulate it with the value in the VCRC register. Store the result in VCRC.

```
if (VSTATUS[CRCMSGFLIP] == 0){
   temp[7:0] = [mem16][7:0];
}else {
   temp[7:0] = [mem16][0:7];
}

VCRC[15:0] = CRC16 (VCRC[15:0], temp[7:0]
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

```
typedef struct {
    uint32_t *CRCResult;
                           // Address where result should be stored
     uint16_t *CRCData;
                          // Start of data
     uint16_t CRCLen;
                           // Length of data in bytes
  }CRC_CALC;
  CRC_CALC mycrc;
  CRC16P2(&mycrc);
; Calculate the CRC of a block of data
; This function assumes the block is a multiple of 2 16-bit words
   .global _CRC16P2
_CRC16P2
   VCRCCLR
                         ; Clear the result register
   MOV AL,
              *+XAR4[4] ; AL = CRCLen
   ASR
        AL, 2 ; AL = CRCLen/4
   SUBB AL,
                         ; AL = CRCLen/4 - 1
   MOVL XAR7, *+XAR4[2] ; XAR7 = &CRCData
   .aliqn 2
   NOP
                         ; Align RPTB to an odd address
   VCRC16P2L_1 *XAR7
                         ; Calculate CRC for 4 bytes
   VCRC16P2H_1 *XAR7++
                         ; ...
   VCRC16P2L_1 *XAR7
                        ; ...
   VCRC16P2H_1 *XAR7++
_CRC16P2_done
   MOVL XAR7, *_+XAR4[0] ; XAR7 = &CRCResult
   MOV32 *+XAR7[0], VCRC ; Store the result
   LRETR
                         ; return to caller
```

See also

VCRC16P2H_1 mem16 VCRC16P1H_1 mem16 VCRC16P1L_1 mem16



VCRC24H_1 mem16 CRC24, High Byte

Operands

mem16 16-bit memory location

Opcode

LSW: 1110 0010 1100 1011 MSW: 0000 0010 mem16

Description

This instruction uses CRC24 polynomial == 0x5D6DCB

Calculate the CRC24 of the most significant byte pointed to by mem16 and accumulate it with the value in the VCRC register. Store the result in VCRC.

```
if (VSTATUS[CRCMSGFLIP] == 0){
  temp[7:0] = [mem16][15:8];
}else {
  temp[7:0] = [mem16][8:15];
}
VCRC[23:0] = CRC24 (VCRC[23:0], temp[7:0])
```

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example Refer to the example for VCRC24L_1 mem16.

See also VCRC24L_1 mem16



VCRC24L_1 mem16 CRC24, Low Byte

Operands

mem16 16-bit memory location

Opcode

```
LSW: 1110 0010 1100 1011 MSW: 0000 0001 mem16
```

Description

This instruction uses CRC24 polynomial == 0x5D6DCB

Calculate the CRC24 of the most significant byte pointed to by mem16 and accumulate it with the value in the VCRC register. Store the result in VCRC.

```
if (VSTATUS[CRCMSGFLIP] == 0){
   temp[7:0] = [mem16][7:0];
}else {
   temp[7:0] = [mem16][0:7];
}
VCRC[23:0] = CRC24 (VCRC[23:0], temp[7:0])
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

```
typedef struct {
 uint32_t *CRCResult; // Address where result should be stored
 uint16_t *CRCData; // Start of data
 uint16_t CRCLen;
                   // Length of data in bytes
}CRC_CALC;
CRC_CALC mycrc;
CRC24(&mycrc);
; Calculate the CRC of a block of data
; This function assumes the block is a multiple of 2 16-bit words
 .global _CRC24
CRC24
 VCRCCLR
                       ; Clear the result register
 MOV AL, *+XAR4[4]
                       ; AL = CRCLen
 ASR AL, 2
                       ; AL = CRCLen/4
 SUBB AL. #1
                      ; AL = CRCLen/4 - 1
 MOVL XAR7, *+XAR4[2] ; XAR7 = &CRCData
 .align 2
 NOP
                      ; Align RPTB to an odd address
 VCRC24L_1 *XAR7
                      ; Calculate CRC for 4 bytes
 VCRC24H_1 *XAR7++
 VCRC24L_1 *XAR7
 VCRC24H_1 *XAR7++
CRC24 done
 MOVL XAR7, *_+XAR4[0] ; XAR7 = &CRCResult
 VMOV32 *+XAR7[0], VCRC ; Store the result
 LRETR
                       ; return to caller
```

See also

VCRC24H_1 mem16



VCRC32H_1 mem16 CRC32, High Byte

Operands

mem16 16-bit memory location

Opcode

LSW: 1110 0010 1100 0010 MSW: 0000 0000 mem16

Description

This instruction uses CRC32 polynomial 1 == 0x04C11DB7

Calculate the CRC32 of the most significant byte pointed to by mem16 and accumulate it with the value in the VCRC register. Store the result in VCRC.

```
if (VSTATUS[CRCMSGFLIP] == 0){
   temp[7:0] = [mem16][15:8];
}else {
   temp[7:0] = [mem16][8:15];
}
```

VCRC[31:0] = CRC32 (VCRC[31:0], temp[7:0])

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example Refer to the example for VCRC32L_1 mem16.

See also VCRC32L_1 mem16



VCRC32L_1 mem16 CRC32, Low Byte

Operands

mem16 16-bit memory location

Opcode

```
LSW: 1110 0010 1100 0001 MSW: 0000 0000 mem16
```

Description

This instruction uses CRC32 polynomial 1 == 0x04C11DB7

Calculate the CRC32 of the least significant byte pointed to by mem16 and accumulate it with the value in the VCRC register. Store the result in VCRC.

```
if (VSTATUS[CRCMSGFLIP] == 0){
   temp[7:0] = [mem16][7:0];
}else {
   temp[7:0] = [mem16][0:7];
}

VCRC[31:0] = CRC32 (VCRC[31:0], temp[7:0])
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

```
typedef struct {
     uint32_t *CRCResult;
                          // Address where result should be stored
     uint16_t *CRCData;
                          // Start of data
     uint16_t CRCLen;
                          // Length of data in bytes
  }CRC_CALC;
  CRC_CALC mycrc;
  CRC32(&mycrc);
; Calculate the CRC of a block of data
; This function assumes the block is a multiple of 2 16-bit words
   .global _CRC32
_CRC32
   VCRCCLR
                         ; Clear the result register
   MOV AL,
              *+XAR4[4] ; AL = CRCLen
   ASR
       AL, 2 ; AL = CRCLen/4
   SUBB AL,
                         ; AL = CRCLen/4 - 1
   MOVL XAR7, *+XAR4[2] ; XAR7 = &CRCData
   .aliqn 2
   NOP
                         ; Align RPTB to an odd address
   VCRC32L_1 *XAR7
                         ; Calculate CRC for 4 bytes
   VCRC32H_1 *XAR7++
                         ; ...
   VCRC32L_1 *XAR7
                        ; ...
   VCRC32H_1 *XAR7++
                         ; ...
   _CRC32_done
   MOVL XAR7, *_+XAR4[0] ; XAR7 = &CRCResult
   WMOV32 *+XAR7[0], VCRC ; Store the result
   LRETR
                          ; return to caller
```

See also

VCRC32H_1 mem16



VCRC32P2H_1 mem16 CRC32, Polynomial 2, High Byte

Operands

mem16 16-bit memory location

Opcode

LSW: 1110 0010 1100 1011 MSW: 0000 0100 mem16

Description

This instruction uses CRC32 polynomial == 0x1EDC6F41

Calculate the CRC32 of the most significant byte pointed to by mem16 and accumulate it with the value in the VCRC register. Store the result in VCRC.

```
if (VSTATUS[CRCMSGFLIP] == 0){
   temp[7:0] = [mem16][15:8];
}else {
   temp[7:0] = [mem16][8:15];
}

VCRC[31:0] = CRC32 (VCRC[31:0], temp[7:0])
```

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example Refer to the example for VCRC32P2L_1 mem16.

See also VCRC32L_1 mem16



VCRC32P2L_1 mem16 CRC32, Low Byte

Operands

mem16 16-bit memory location

Opcode

```
LSW: 1110 0010 1100 1011 MSW: 0000 0011 mem16
```

Description

This instruction uses CRC32 polynomial == 0x04C11DB7

Calculate the CRC32 of the least significant byte pointed to by mem16 and accumulate it with the value in the VCRC register. Store the result in VCRC.

```
if (VSTATUS[CRCMSGFLIP] == 0){
   temp[7:0] = [mem16][7:0];
}else {
   temp[7:0] = [mem16][0:7];
}

VCRC[31:0] = CRC32 (VCRC[31:0], temp[7:0])
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

```
typedef struct {
   uint32_t *CRCResult; // Address where result should be stored
   uint16_t *CRCData; // Start of data
   uint16_t CRCLen;
                      // Length of data in bytes
 }CRC_CALC;
 CRC_CALC mycrc;
 CRC32P2(&mycrc);
 ; -----
 ; Calculate the CRC of a block of data
 ; This function assumes the block is a multiple of 2 16-bit words
   .global _CRC32P2
 _CRC32P2
   VCRCCLR
                          ; Clear the result register
   MOV AL, *+XAR4[4]
                         ; AL = CRCLen
   ASR AL, 2
                         ; AL = CRCLen/4
   SUBB AL, #1
                         ; AL = CRCLen/4 - 1
   MOVL XAR7, *+XAR4[2] ; XAR7 = &CRCData
   .aliqn 2
   NOP
                          ; Align RPTB to an odd address
   RPTB _CRC32P2_done, AL ; Execute block of code AL + 1 times
   VCRC32P2L_1 *XAR7
                          ; Calculate CRC for 4 bytes
                         ; ...
   VCRC32P2H_1 *XAR7++
                        ; ...
   VCRC32P2L_1 *XAR7
   VCRC32P2H_1 *XAR7++
  _CRC32P2_done
   MOVL XAR7, *_+XAR4[0] ; XAR7 = &CRCResult
   VMOV32 *+XAR7[0], VCRC ; Store the result
   LRETR
                          ; return to caller
```

See also

VCRC32P2H_1 mem16



VCRCCLR Clear CRC Result Register

Operands

mem16 16-bit memory location

Opcode LSW: 1110 0101 0010 0100

Description Clear the VCRC register.

VCRC = 0x0000

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example Refer to the example for VCRC32L_1 mem16.

See also VMOV32 mem32, VCRC

VMOV32 VCRC, mem32



VMOV32 mem32, VCRC Store the CRC Result Register

Operands

mem32 32-bit memory destination

VCRC CRC result register

Opcode LSW: 1110 0010 0000 0110

MSW: 0000 0000 mem32

Description Store the VCRC register.

[mem32] = VCRC

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VCRCCLR

VMOV32 VCRC, mem32



VMOV32 VCRC, mem32 Load the CRC Result Register

Operands

mem32 32-bit memory source VCRC CRC result register

Opcode LSW: 1110 0011 1111 0110

MSW: 0000 0000 mem32

Description Load the VCRC register.

VCRC = [mem32]

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VCRCCLR

VMOV32 mem32, VCRC



www.ti.com Instruction Set

2.5.6 Deinterleaver Instructions

The instructions are listed alphabetically, preceded by a summary.

Table 2-15. Deinterleaver Instructions

Title	Page
VCLRDIVE —Clear DIVE bit in the VSTATUS Register	288
VDEC VRaL —16-bit Decrement	289
VDEC VRaL VMOV32 VRb, mem32 —16-bit Decrement with Parallel Load	290
VINC VRaL —16-bit Increment	291
VINC VRaL VMOV32 VRb, mem32 — 16-bit Increment with Parallel Load	292
VMOD32 VRaH, VRb, VRcH — Modulo Operation	293
VMOD32 VRaH, VRb, VRcH VMOV32 VRd, VRe — Modulo Operation with Parallel Move	294
VMOD32 VRaH, VRb, VRcL — Modulo Operation	295
VMOD32 VRaH, VRb, VRcL VMOV32 VRd, VRe — Modulo Operation with Parallel Move	296
VMOV16 VRaL, VRbH —16-bit Register Move	297
VMOV16 VRaH, VRbL —16-Bit Register Move	298
VMOV16 VRaH, VRbH —16-Bit Register Move	299
VMOV16 VRaL, VRbL —16-Bit Register Move	
VMPYADD VRa, VRaL, VRaH, VRbH — Multiply Add 16-Bit	301
VMPYADD VRa, VRaL, VRaH, VRbL — Multiply Add 16-bit	



VCLRDIVE Clear DIVE bit in the VSTATUS Register

Operands none

Opcode LSW: 1110 0101 0010 0000

Description Clear the DIVE (Divide by zero error) bit in the VSTATUS register.

Flags This instruction clears the DIVE bit in the VSTATUS register

Pipeline This is a single-cycle operation

Example See also



VDEC VRaL 16-bit Decrement

Operands

VRaL Low word of a general purpose register: VR0L, VR1L....VR7L. Cannot be VR8L

Opcode LSW: 1110 0110 1111 0010

MSW: 0000 1011 0000 laaa

Description 16-bit Increment

VRaL = VRaL - 1

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example VDEC VROL ; VROL = VROL - 1

See also VINC VRaL || VMOV32 VRb, mem32

VINC VRaL

VDEC VRaL || VMOV32 VRb, mem32



VDEC VRaL | VMOV32 VRb, mem32 16-bit Decrement with Parallel Load

Operands

VRaL Low word of a general purpose register: VR0L, VR1L....VR7L. Cannot be VR8L

VRb General purpose register: VR0, VR1....VR7. Cannot be VR8

mem32 Pointer to 32-bit memory location

Opcode LSW: 1110 0010 1000 0001

MSW: 01bb baaa mem32

Description 16-bit Decrement with Parallel Load

VRaL = VRaL - 1
VRb = [mem32]

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example VDEC VROL || VMOV32 VR1, *+XAR3[4]

See also VINC VRaL

VDEC VRaL

VINC VRaL || VMOV32 VRb, mem32



VINC VRaL 16-bit Increment

Operands

VRaL Low word of a general purpose register: VR0L, VR1L....VR7L. Cannot be VR8L

Opcode LSW: 1110 0110 1111 0010

MSW: 0000 1011 0000 0aaa

Description 16-bit Increment

VRaL = VRaL + 1

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example VINC VROL ; VROL = VROL + 1

See also VINC VRaL || VMOV32 VRb, mem32

VDEC VRaL

VDEC VRaL || VMOV32 VRb, mem32



VINC VRaL | VMOV32 VRb, mem32 16-bit Increment with Parallel Load

Operands

VRaL Low word of a general purpose register: VR0L, VR1L....VR7L. Cannot be VR8L

VRb General purpose register: VR0, VR1....VR7. Cannot be VR8

mem32 Pointer to 32-bit memory location

Opcode LSW: 1110 0010 1000 0001

MSW: 00bb baaa mem32

Description 16-bit Increment with parallel load

VRaL = VRaL +1
VRb = [mem32]

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example VINC VROL || VMOV32 VR1, *+XAR3[4]

See also VINC VRaL

VDEC VRaL

VDEC VRaL || VMOV32 VRb, mem32



VMOD32 VRaH, VRb, VRcH Modulo Operation

Operands

VRaH	High word of a general purpose register: VR0H, VR1HVR7H. Cannot be VR8H
VRb	General purpose register: VR0, VR1VR7. Cannot be VR8
VRcH	High word of a general purpose register: VR0H, VR1HVR7H. Cannot be VR8H

Opcode

```
LSW: 1110 0110 1000 0000 MSW: 0010 100a aabb bccc
```

Description

Modulo operation: 32-bit signed %16 bit unsigned

```
if(VRcH == 0x0){
  VSTATUS[DIVE] = 1
}else{
  VRaH = VRb % VRcH
}
```

Flags

This instruction modifies the following bits in the VSTATUS register:

DIVE is set if VRcH is 0 i.e. a divide by zero error.

Pipeline

This is a 9p cycle instruction. No VMOD32 related instruction can be present in the delay slot of this instruction.

Example

```
VMOD32 VR5H, VR3, VR4H
                            ; VR5H = VR3%VR4H = j
                             ; compute j = (b * J - v * i) % n;
NOP
                              ; D1
MOV *+XAR1[AR0], AL
                              ; D2
                                      Save previous Y(i+j*m)
                              ; D3
NOP
                              ; D4
NOP
MOV AL, *XAR4++
                              ; D5
                                      AL = X(I)
                                                   load X(I)
NOP
NOP
                               ; D7
NOP
                               ; D8
VMPYADD VR5, VR5L, VR5H, VR4H
                              ; VR5 = VR5L + VR5H*VR4H
                                   = i + j*m
                                                compute i + j*m
```

See also

VMOD32 VRaH, VRb, VRcL VMOD32 VRaH, VRb, VRcL || VMOV32 VRd, VRe VMOD32 VRaH, VRb, VRcH || VMOV32 VRd, Vre VCLRDIVE



VMOD32 VRaH, VRb, VRcH | VMOV32 VRd, VRe Modulo Operation with Parallel Move

Operands

VRaH	High word of a general purpose register: VR0H, VR1HVR7H. Cannot be VR8H
VRb	General purpose register: VR0, VR1VR7. Cannot be VR8
VRcH	Low word of a general purpose register: VR0H, VR1HVR7H. Cannot be VR8H
VRd	General purpose register: VR0, VR1VR7. Cannot be VR8
VRe	General purpose register: VR0, VR1VR7. Cannot be VR8

Opcode

```
LSW: 1110 0110 1111 0011 MSW: 1eee dddc ccbb baaa
```

Description

Modulo operation: 32-bit signed %16 bit unsigned

```
if(VRcL == 0x0){
   VSTATUS[DIVE] = 1
}else{
   VRaH = VRb % VRcH
}
VRd = VRe
```

Flags

This instruction modifies the following bits in the VSTATUS register:

DIVE is set if VRcH is 0, that is, a divide by zero error.

Pipeline

This is a 9p/1 cycle instruction. The VMOD32 instruction takes 9p cycles while the VMOV32 operation completes in a single cycle. No VMOD32 related instruction can be present in the delay slot of this instruction.

Example

```
VMOD32 VR5H, VR3, VR4H ; VR5H = VR3%VR4H = j; VR0 = {J,I}
; load back saved J,I
  VINC VROL
                         ; D1 VR1H = u, VR1L = a
\label{eq:continuous} \begin{tabular}{ll} $\mid \mid $ VMOV32 $VR1, *+XAR3[4] $ & ; increment $I$; load $u, a. \\ \end{tabular}
  \label{eq:mov_problem} \mbox{MOV *+XAR1[AR0], AL} \qquad \qquad \mbox{; D2 Save previous } \mbox{Y(i+j*m)}
  VCMPY VR3, VR2, VR1, VR0 ; D3 VR3 = a*I - u*J
                          ; compute a * I - u * J
  ; D5 AL = X(I) load X(I)
  MOV AL, *XAR4++
  NOP
                         ; D6
  VMOV32 VR6, VR0
                         ; D7 VR6 = \{J,I\} save current \{J,I\}
  VMOV16 VROL, *+XAR5[0] ; D8 VROL = J load J
  VMOD32 VR0H, VR3, VR4H ; VR0H = (VR3 % VR4H) = i
                          ; compute i = (a * I - u * J) % m;
```

See also

VMOD32 VRaH, VRb, VRcH VMOD32 VRaH, VRb, VRcL

VMOD32 VRaH, VRb, VRcL || VMOV32 VRd, VRe

VCLRDIVE



VMOD32 VRaH, VRb, VRcL Modulo Operation

Operands

VRaH	High word of a general purpose register: VR0H, VR1HVR7H. Cannot be VR8H
VRb	General purpose register: VR0, VR1VR7. Cannot be VR8
VRcL	Low word of a general purpose register: VR0L, VR1LVR7L. Cannot be VR8L

Opcode

```
LSW: 1110 0110 1000 0000 MSW: 0010 011a aabb bccc
```

Description

Modulo operation: 32-bit signed %16 bit unsigned

```
if(VRcL == 0x0){
  VSTATUS[DIVE] = 1
}else{
  VRaH = VRb % VRcL
}
```

Flags

This instruction modifies the following bits in the VSTATUS register:

DIVE is set if VRcL is 0, that is, a divide by zero error.

Pipeline

This is a 9p cycle instruction. No VMOD32 related instruction can be present in the delay slot of this instruction.

Example

```
VMOD32 VR5H, VR3, VR4L
                            ; VR5H = VR3%VR4L = j
                             ; compute j = (b * J - v * i) % n;
NOP
                             ; D1
MOV *+XAR1[AR0], AL
                            ; D2 Save previous Y(i+j*m)
NOP
                             ; D3
NOP
                             ; D4
MOV AL, *XAR4++
                             ; D5 AL = X(I)
                                                load X(I)
NOP
NOP
                             ; D7
NOP
                              ; D8
VMPYADD VR5, VR5L, VR5H, VR4H
                             ; VR5 = VR5L + VR5H*VR4H
                                   = i + j*m compute i + j*m
```

See also

VMOD32 VRaH, VRb, VRcH VMOD32 VRaH, VRb, VRcL || VMOV32 VRd, VRe VMOD32 VRaH, VRb, VRcH || VMOV32 VRd, Vre VCLRDIVE



VMOD32 VRaH, VRb, VRcL | VMOV32 VRd, VRe Modulo Operation with Parallel Move

Operands

VRaH	High word of a general purpose register: VR0H, VR1HVR7H. Cannot be VR8H
VRb	General purpose register: VR0, VR1VR7. Cannot be VR8
VRcL	Low word of a general purpose register: VR0L, VR1LVR7L. Cannot be VR8L
VRd	General purpose register: VR0, VR1VR7. Cannot be VR8
VRe	General purpose register: VR0, VR1VR7. Cannot be VR8

Opcode

```
LSW: 1110 0110 1111 0011 MSW: 0eee dddc ccbb baaa
```

Description

Modulo operation: 32-bit signed %16 bit unsigned

```
if(VRcL == 0x0){
   VSTATUS[DIVE] = 1
}else{
   VRaH = VRb % VRcL
}
VRd = VRe
```

Flags

This instruction modifies the following bits in the VSTATUS register:

DIVE is set if VRcH is 0, that is, a divide by zero error.

Pipeline

This is a 9p/1 cycle instruction. The VMOD32 instruction takes 9p cycles while the VMOV32 operation completes in a single cycle. No VMOD32 related instruction can be present in the delay slot of this instruction.

Example

```
VMOD32 VR5H, VR3, VR4L ; VR5H = VR3^{\circ}VR4L = ^{\circ}; VR0 = ^{\circ}J,I^{\circ}
VINC VROL
                           ; D1 VR1H = u, VR1L = a
\label{eq:continuous} \begin{tabular}{ll} $\mid \mid $ VMOV32 $VR1, *+XAR3[4] $ & ; increment $I$; load $u, a. \\ \end{tabular}
  \label{eq:mov_problem} \mbox{MOV *+XAR1[AR0], AL} \qquad \qquad \mbox{; D2 Save previous } \mbox{Y(i+j*m)}
   VCMPY VR3, VR2, VR1, VR0 ; D3 VR3 = a*I - u*J
                            ; compute a * I - u * J
   ; D5 AL = X(I) load X(I)
  MOV AL, *XAR4++
  NOP
                           ; D6
  VMOV32 VR6, VR0
                          ; D7 VR6 = \{J,I\} save current \{J,I\}
   VMOV16 VROL, *+XAR5[0] ; D8 VROL = J load J
   VMOD32 VR0H, VR3, VR4H ; VR0H = (VR3 % VR4H) = i
                            ; compute i = (a * I - u * J) % m;
```

See also

VMOD32 VRaH, VRb, VRcH VMOD32 VRaH, VRb, VRcL

VMOD32 VRaH, VRb, VRcH | VMOV32 VRd, Vre

VCLRDIVE



VMOV16 VRaL, VRbH 16-bit Register Move

Operands

VRbH High word of a general purpose register: VR0H, VR1H....VR7H. Cannot be VR8H
VRaL Low word of a general purpose register: VR0L, VR1L....VR7L. Cannot be VR8L

Opcode LSW: 1110 0110 1111 0010

MSW: 0000 1010 00bb baaa

Description 16-bit Register Move

VRaL = VRbH

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example VMOV16 VR5L, VR0H ; VR5L = VR0H

See also VMOV16 VRaH, VRbL

VMOV16 VRaH, VRbH VMOV16 VRaL, VRbL



VMOV16 VRaH, VRbL 16-Bit Register Move

Operands

VRbL Low word of a general purpose register: VR0L, VR1L....VR7L. Cannot be VR8L
VRaH High word of a general purpose register: VR0H, VR1H....VR7H. Cannot be VR8H

Opcode LSW: 1110 0110 1111 0010

MSW: 0000 1010 01bb baaa

Description 16-bit Register Move

VRaH = VRbL

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example VMOV16 VR5H, VR0L ; VR5H = VR0L

See also VMOV16 VRaL, VRbH

VMOV16 VRaH, VRbH VMOV16 VRaL, VRbL



VMOV16 VRaH, VRbH 16-Bit Register Move

Operands

VRbH High word of a general purpose register: VR0H, VR1H....VR7H. Cannot be VR8H VRaH High word of a general purpose register: VR0H, VR1H....VR7H. Cannot be VR8H

Opcode LSW: 1110 0110 1111 0010

MSW: 0000 1010 10bb baaa

Description 16-bit Register Move

VRaH = VRbH

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example VMOV16 VR5H, VR0H ; VR5H = VR0H

See also VMOV16 VRaL, VRbH

VMOV16 VRaH, VRbL VMOV16 VRaL, VRbL



VMOV16 VRaL, VRbL 16-Bit Register Move

Operands

VRbL Low word of a general purpose register: VR0L, VR1L....VR7L. Cannot be VR8L
VRaL Low word of a general purpose register: VR0L, VR1L....VR7L. Cannot be VR8L

Opcode LSW: 1110 0110 1111 0010

MSW: 0000 1010 11bb baaa

Description 16-bit Register Move

VRaL = VRbL

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example VMOV16 VR5L, VR0L ; VR5L = VR0L

See also VMOV16 VRaL, VRbH

VMOV16 VRaH, VRbL VMOV16 VRaH, VRbH



VMPYADD VRa, VRaL, VRaH, VRbH Multiply Add 16-Bit

Operands

VRbH	High word of a general purpose register: VR0H, VR1HVR7H. Cannot be VR8H
VRaH	Low word of a general purpose register: VR0H, VR1HVR7H. Cannot be VR8H
VRaL	Low word of a general purpose register: VR0L, VR1LVR7L. Cannot be VR8L
VRa	General purpose register: VR0, VR1VR7. Cannot be VR8

Opcode

```
LSW: 1110 0110 1111 0010 MSW: 0000 1100 00bb baaa
```

Description

Performs p + q*r, where p,q, and r are 16-bit values

```
If(VSTATUS[SAT] == 1) {
    If(VSTATUS[RND] == 1) {
        VRa = rnd(sat(VRaL + VRaH * VRbH)>>VSTATUS[SHIFTR]);
    }else {
        VRa = sat(VRaL + VRaH * VRbH)>>VSTATUS[SHIFTR];
    }
}else { //VSTATUS[SAT] = 0
    If(VSTATUS[RND] == 1) {
        VRa = rnd((VRaL + VRaH * VRbH)>>VSTATUS[SHIFTR]);
    }else {
        VRa = (VRaL + VRaH * VRbH)>>VSTATUS[SHIFTR];
    }
}
```

It should be noted that:

- VRaH*VRbH is represented as 32-bit temp value
- VRaL should be sign extended to 32-bit before performing add
- The add operation is a 32-bit operation

Flags

This instruction modifies the following bits in the VSTATUS register:

 OVFR is set if signed overflow if 32-bit signed overflow is detected in the add operation.

Pipeline

This is a 2p cycle operation

Example

See also

VMPYADD VRa, VRaL, VRaH, VRbL



VMPYADD VRa, VRaL, VRaH, VRbL Multiply Add 16-bit

Operands

VRbL	High word of a general purpose register: VR0H, VR1HVR7H. Cannot be VR8H
VRaH	Low word of a general purpose register: VR0H, VR1HVR7H. Cannot be VR8H
VRaL	Low word of a general purpose register: VR0L, VR1LVR7L. Cannot be VR8L
VRa	General purpose register: VR0, VR1VR7. Cannot be VR8

Opcode

```
LSW: 1110 0110 1111 0010 MSW: 0000 1100 01bb baaa
```

Description

Performs p + q*r, where p,q, and r are 16-bit values

```
If(VSTATUS[SAT] == 1) {
    If(VSTATUS[RND] == 1) {
        VRa = rnd(sat(VRaL + VRaH * VRbL)>>VSTATUS[SHIFTR]);
    }else {
        VRa = sat(VRaL + VRaH * VRbL)>>VSTATUS[SHIFTR];
    }
}else { //VSTATUS[SAT] = 0
    If(VSTATUS[RND] == 1) {
        VRa = rnd((VRaL + VRaH * VRbL)>>VSTATUS[SHIFTR]);
    }else {
        VRa = (VRaL + VRaH * VRbL)>>VSTATUS[SHIFTR];
    }
}
```

It should be noted that:

- VRaH* VRbL is represented as 32-bit temp value
- VRaL should be sign extended to 32-bit before performing add
- The add operation is a 32-bit operation

Flags

This instruction modifies the following bits in the VSTATUS register:

 OVFR is set if signed overflow if 32-bit signed overflow is detected in the add operation.

Pipeline

This is a 2p cycle operation

Example

See also

VMPYADD VRa, VRaL, VRaH, VRbH



www.ti.com Instruction Set

2.5.7 FFT Instructions

The instructions are listed alphabetically, preceded by a summary.

Table 2-16. FFT Instructions

Title I	Page
VCFFT1 VR2, VR5, VR4 — Complex FFT calculation instruction	304
VCFFT2 VR7, VR6, VR4, VR2, VR1, VR0, #1-bit —Complex FFT calculation instruction	305
VCFFT2 VR7, VR6, VR4, VR2, VR1, VR0, #1-bit VMOV32 mem32, VR1 — Complex FFT calculation instruction with Parallel Store	307
VCFFT3 VR5, VR4, VR3, VR2, VR0, #1-bit —Complex FFT calculation instruction	309
VCFFT3 VR5, VR4, VR3, VR2, VR0, #1-bit VMOV32 VR5, mem32 — Complex FFT calculation instruction with Parallel Load	311
VCFFT4 VR4, VR2, VR1, VR0, #1-bit —Complex FFT calculation instruction	313
VCFFT4 VR4, VR2, VR1, VR0, #1-bit VMOV32 VR7, mem32 — Complex FFT calculation instruction with Parallel Load	315
VCFFT5 VR5, VR4, VR3, VR2, VR1, VR0, #1-bit VMOV32 mem32, VR1 — Complex FFT calculation instruction with Parallel Load	317
VCFFT6 VR3, VR2, VR1, VR0, #1-bit VMOV32 mem32, VR1 — Complex FFT calculation instruction with Parallel Load	319
VCFFT7 VR1, VR0, #1-bit VMOV32 VR2, mem32 — Complex FFT calculation instruction with Parallel Load	320
VCFFT8 VR3, VR2, #1-bit — Complex FFT calculation instruction	321
VCFFT8 VR3, VR2, #1-bit VOMV32 mem32, VR4 — Complex FFT calculation instruction with Parallel Store	322
VCFFT9 VR5, VR4, VR3, VR2, VR1, VR0 #1-bit —Complex FFT calculation instruction	323
VCFFT9 VR5, VR4, VR3, VR2, VR1, VR0 #1-bit VMOVE32 mem32, VR5 — Complex FFT calculation instruction with Parallel Store	324
VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0 #1-bit —Complex FFT calculation instruction	326
VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0 #1-bit VMOV32 VR0, mem32 — Complex FFT calculation instruction with Parallel Load	330



VCFFT1 VR2, VR5, VR4 Complex FFT calculation instruction

Operands

This operation assumes the following complex packing order for complex operands: VRa[31:16] = Imaginary Part VRa[15:0] = Real Part It ignores the VSTATUS[CPACK] bit.

VR4	First Complex Input
VR5	Second Complex Input
VR2	Complex Output

Opcode

LSW: 1110 0101 0010 1011

Description

This operation is used in the butterfly operation of the FFT:

```
If(VSTATUS[SAT] == 1){
   If(VSTATUS[RND] == 1){
        VR2H = rnd(sat(VR5H*VR4L - VR5L*VR4H)>>VSTATUS[SHIFTR])
        VR2L = rnd(sat(VR5L*VR4L + VR5H*VR4H)>>VSTATUS[SHIFTR])
}else {
        VR2H = sat(VR5H*VR4L - VR5L*VR4H)>>VSTATUS[SHIFTR]
        VR2H = sat(VR5L*VR4L + VR5H*VR4H)>>VSTATUS[SHIFTR]
        VR2H = sat(VR5L*VR4L + VR5H*VR4H)>>VSTATUS[SHIFTR]
}else { //VSTATUS[SAT] = 0
   If(VSTATUS[RND] == 1){
        VR2H = rnd((VR5H*VR4L - VR5L*VR4H)>>VSTATUS[SHIFTR])
        VR2H = rnd((VR5L*VR4L + VR5H*VR4H)>>VSTATUS[SHIFTR])
}else {
        VR2H = (VR5H*VR4L - VR5L*VR4H)>>VSTATUS[SHIFTR]
        VR2L = (VR5L*VR4L + VR5H*VR4H)>>VSTATUS[SHIFTR]
}
```

Sign-Extension is automatically done for the shift right operations

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH
- The OVFR and OVFI flags are also set if, after shift right operation, the 32-bit temporary result can't fit in 16-bit destination

Pipeline

This is a two cycle instruction

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit



VCFFT2 VR7, VR6, VR4, VR2, VR1, VR0, #1-bit Complex FFT calculation instruction

Operands

This operation assumes the following complex packing order for complex operands: VRa[31:16] = Imaginary Part VRa[15:0] = Real Part

It ignores the VSTATUS[CPACK] bit.

VR7	Complex Input	
VR6	Complex Input	
VR4	Complex Input	
VR2	Complex Output	
VR1	Complex Output	
VR0	Complex Output	
#1-bit	1-bit immediate value	

Opcode

LSW: 1010 0001 0011 000I

Description

This operation is used in the butterfly operation of the FFT:

```
If(VSTATUS[SAT] == 1){
  if(VSTATUS[RND] == 1){
   VROH = rnd(sat(VR7H + VR2H)>>#1-bit);
    VROL = rnd(sat(VR7L + VR2L)>>#1-bit);
    VR1L = rnd(sat(VR7L - VR2L)>>#1-bit);
    VR1H = rnd(sat(VR7H - VR2H)>>#1-bit);
    VR2H = rnd(sat(VR6H * VR4L - VR6L * VR4H)>> VSTATUS[SHIFTR]);
   VR2L = rnd(sat(VR6L * VR4L + VR6H * VR4H)>> VSTATUS[SHIFTR]);
  }else {
    VROH = sat(VR7H + VR2H)>>#1-bit;
    VR0L = sat(VR7L + VR2L) >> #1-bit;
    VR1L = sat(VR7L - VR2L)>>#1-bit;
    VR1H = sat(VR7H - VR2H)>>#1-bit;
    VR2H = sat(VR6H * VR4L - VR6L * VR4H)>> VSTATUS[SHIFTR];
    VR2L = sat(VR6L * VR4L + VR6H * VR4H)>> VSTATUS[SHIFTR];
else { //VSTATUS[SAT] = 0}
  If(VSTATUS[RND] == 1){
    VROH = rnd((VR7H + VR2H) >> #1-bit);
    VROL = rnd((VR7L + VR2L) >> #1-bit);
   VR1L = rnd((VR7L - VR2L) >> #1-bit);
    VR1H = rnd((VR7H - VR2H)>> #1-bit);
    VR2H = rnd((VR6H * VR4L - VR6L * VR4H)>> VSTATUS[SHIFTR]);
    VR2L = rnd((VR6L * VR4L + VR6H * VR4H)>> VSTATUS[SHIFTR]);
 }else {
    VROH = (VR7H + VR2H) >> #1-bit;
    VR0L = (VR7L + VR2L) >> #1-bit;
    VR1L = (VR7L - VR2L) >> #1-bit;
    VR1H = (VR7H - VR2H) >> #1-bit;
    VR2H = (VR6H * VR4L - VR6L * VR4H)>> VSTATUS[SHIFTR];
    VR2L = (VR6L * VR4L + VR6H * VR4H)>> VSTATUS[SHIFTR];
}
```

Sign-Extension is automatically done for the shift right operations

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH
- The OVFR and OVFI flags are also set if, after shift right operation, the 32-bit



temporary result can't fit in 16-bit destination

Pipeline This is a two cycle instruction

Example See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit

www.ti.com

VCFFT2 VR7, VR6, VR4, VR2, VR1, VR0, #1-bit | VMOV32 mem32, VR1 — Complex FFT calculation instruction with Parallel Store

VCFFT2 VR7, VR6, VR4, VR2, VR1, VR0, #1-bit || VMOV32 mem32, VR1 Complex FFT calculation instruction with Parallel Store

Operands

This operation assumes the following complex packing order for complex operands: VRa[31:16] = Imaginary Part VRa[15:0] = Real Part It ignores the VSTATUS[CPACK] bit.

VR7	Complex Input
VR6	Complex Input
VR4	Complex Input
VR2	Complex Output
VR1	Complex Output
VR0	Complex Output
#1-bit	1-bit immediate value
mem32	Pointer to 32-bit memory location

Opcode

```
LSW: 1110 0010 0000 0111 MSW: 0010 0001 mem32
```

Description

This operation is used in the butterfly operation of the FFT:

```
if(VSTATUS[SAT] == 1){
  if(VSTATUS[RND] == 1){
   VROH = rnd(sat(VR7H + VR2H)>>#1-bit);
    VROL = rnd(sat(VR7L + VR2L)>>#1-bit);
   VR1L = rnd(sat(VR7L - VR2L)>>#1-bit);
   VR1H = rnd(sat(VR7H - VR2H) >> #1-bit);
   VR2H = rnd(sat(VR6H * VR4L - VR6L * VR4H)>> VSTATUS[SHIFTR]);
    VR2L = rnd(sat(VR6L * VR4L + VR6H * VR4H)>> VSTATUS[SHIFTR]);
  }else {
    VROH = sat(VR7H + VR2H) >> #1-bit;
   VR0L = sat(VR7L + VR2L) >> #1-bit;
   VR1L = sat(VR7L - VR2L)>>#1-bit;
   VR1H = sat(VR7H - VR2H)>>#1-bit;
    VR2H = sat(VR6H * VR4L - VR6L * VR4H)>> VSTATUS[SHIFTR];
    VR2L = sat(VR6L * VR4L + VR6H * VR4H)>> VSTATUS[SHIFTR];
else { //VSTATUS[SAT] = 0}
  if(VSTATUS[RND] == 1){
    VROH = rnd((VR7H + VR2H)>> #1-bit);
   VROL = rnd((VR7L + VR2L) >> #1-bit);
   VR1L = rnd((VR7L - VR2L)>>#1-bit);
   VR1H = rnd((VR7H - VR2H) >> #1-bit);
    VR2H = rnd((VR6H * VR4L - VR6L * VR4H)>> VSTATUS[SHIFTR]);
   VR2L = rnd((VR6L * VR4L + VR6H * VR4H)>> VSTATUS[SHIFTR]);
   VR0H = (VR7H + VR2H)>>#1-bit;
    VR0L = (VR7L + VR2L) >> #1-bit;
    VR1L = (VR7L - VR2L) >> #1-bit;
    VR1H = (VR7H - VR2H) >> #1-bit;
    VR2H = (VR6H * VR4L - VR6L * VR4H)>> VSTATUS[SHIFTR];
    VR2L = (VR6L * VR4L + VR6H * VR4H)>> VSTATUS[SHIFTR];
 }
[mem32] = VR1;
```

Sign-Extension is automatically done for the shift right operations

VCFFT2 VR7, VR6, VR4, VR2, VR1, VR0, #1-bit || VMOV32 mem32, VR1 — Complex FFT calculation instruction with Parallel Store

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH
- The OVFR and OVFI flags are also set if, after shift right operation, the 32-bit temporary result can't fit in 16-bit destination

Pipeline

This is a 2p/1-cycle instruction. The VCFFT operation takes 2p cycles and the VMOV operation completes in a single cycle.

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit



VCFFT3 VR5, VR4, VR3, VR2, VR0, #1-bit Complex FFT calculation instruction

Operands

This operation assumes the following complex packing order for complex operands: VRa[31:16] = Imaginary Part VRa[15:0] = Real Part It ignores the VSTATUS[CPACK] bit.

VR5	Complex Input
VR4	Complex Input
VR3	Complex Output
VR2	Complex Output/Complex Input from previous operation
VR0	Complex Output/Complex Input from previous operation
#1-bit	1-bit immediate value

Opcode

LSW: 1010 0001 0011 001I

Description

This operation is used in the butterfly operation of the FFT:

```
If(VSTATUS[SAT] == 1){
  If(VSTATUS[RND] == 1){
   VROH = rnd(sat(VR5H + VR2H)>>#1-bit);
    VROL = rnd(sat(VR5L + VR2L)>>#1-bit);
   VR3H = rnd(sat(VR5H - VR2H)>>#1-bit);
   VR3L = rnd(sat(VR5L - VR2L)>>#1-bit);
   VR2H = rnd(sat(VR0H * VR4L - VR0L * VR4H)>>VSTATUS[SHIFTR]);
   VR2L = rnd(sat(VR0L * VR4L + VR0H * VR4H)>>VSTATUS[SHIFTR]);
  }else {
    VROH = sat(VR5H + VR2H) >> #1-bit;
    VROL = sat(VR5L + VR2L)>>#1-bit;
   VR3H = sat(VR5H - VR2H) >> #1-bit;
   VR3L = sat(VR5L - VR2L)>>#1-bit;
    VR2H = sat(VR0H * VR4L - VR0L * VR4H)>>VSTATUS[SHIFTR];
   VR2L = sat(VR0L * VR4L + VR0H * VR4H)>>VSTATUS[SHIFTR];
}else { //VSTATUS[SAT] = 0
  If(VSTATUS[RND] == 1){
    VROH = rnd((VR5H + VR2H)>> #1-bit);
    VR0L = rnd((VR5L + VR2L) >> #1-bit);
   VR3H = rnd((VR5H - VR2H)>> #1-bit);
   VR3L = rnd((VR5L - VR2L) >> #1-bit);
   VR2H = rnd((VR0H * VR4L - VR0L * VR4H)>>VSTATUS[SHIFTR]);
   VR2L = rnd((VR0L * VR4L + VR0H * VR4H)>>VSTATUS[SHIFTR]);
  }else {
    VR0H = (VR5H + VR2H) >> #1-bit;
    VR0L = (VR5L + VR2L) >> #1-bit;
    VR3H = (VR5H - VR2H) >> #1-bit;
    VR3L = (VR5L - VR2L) >> #1-bit;
   VR2H = (VR0H * VR4L - VR0L * VR4H)>>VSTATUS[SHIFTR];
   VR2L = (VR0L * VR4L + VR0H * VR4H)>>VSTATUS[SHIFTR];
```

Sign-Extension is automatically done for the shift right operations



Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH
- The OVFR and OVFI flags are also set if, after shift right operation, the 32-bit temporary result can't fit in 16-bit destination

Pipeline

This is a 2p/1-cycle instruction. The VCFFT operation takes 2p cycles and the VMOV operation completes in a single cycle.

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit

www.ti.com

VCFFT3 VR5, VR4, VR3, VR2, VR0, #1-bit || VMOV32 VR5, mem32 — Complex FFT calculation instruction with Parallel Load

VCFFT3 VR5, VR4, VR3, VR2, VR0, #1-bit || VMOV32 VR5, mem32 Complex FFT calculation instruction with Parallel Load

Operands

This operation assumes the following complex packing order for complex operands:

VRa[31:16] = Imaginary Part VRa[15:0] = Real Part

It ignores the VSTATUS[CPACK] bit.

VR5	Complex Input
VR4	Complex Input
VR3	Complex Output
VR2	Complex Output/Complex Input from previous operation
VR0	Complex Output/Complex Input from previous operation
#1-bit	1-bit immediate value
mem32	Pointer to 32-bit memory location

Opcode

```
LSW: 1110 0010 1011 0000 MSW: 0000 001I mem32
```

Description

This operation is used in the butterfly operation of the FFT:

```
If(VSTATUS[SAT] == 1){
  if(VSTATUS[RND] == 1){
   VR0H = rnd(sat(VR5H + VR2H) >> #1-bit);
    VROL = rnd(sat(VR5L + VR2L)>>#1-bit);
    VR3H = rnd(sat(VR5H - VR2H) >> #1-bit);
   VR3L = rnd(sat(VR5L - VR2L)>>#1-bit);
   VR2H = rnd(sat(VR0H * VR4L - VR0L * VR4H)>>VSTATUS[SHIFTR]);
   VR2L = rnd(sat(VR0L * VR4L + VR0H * VR4H)>>VSTATUS[SHIFTR]);
  }else {
    VROH = sat(VR5H + VR2H)>>#1-bit;
    VR0L = sat(VR5L + VR2L) >> #1-bit;
   VR3H = sat(VR5H - VR2H) >> #1-bit;
    VR3L = sat(VR5L - VR2L)>>#1-bit;
    VR2H = sat(VR0H * VR4L - VR0L * VR4H)>>VSTATUS[SHIFTR];
    VR2L = sat(VR0L * VR4L + VR0H * VR4H)>>VSTATUS[SHIFTR];
}else { //VSTATUS[SAT] = 0
  If(VSTATUS[RND] == 1){
    VROH = rnd((VR5H + VR2H)>> #1-bit);
   VR0L = rnd((VR5L + VR2L) >> #1-bit);
   VR3H = rnd((VR5H - VR2H) >> \#1-bit);
    VR3L = rnd((VR5L - VR2L) >> #1-bit);
    VR2H = rnd((VR0H * VR4L - VR0L * VR4H)>>VSTATUS[SHIFTR]);
    VR2L = rnd((VR0L * VR4L + VR0H * VR4H)>>VSTATUS[SHIFTR]);
  }else {
    VROH = (VR5H + VR2H) >> #1-bit;
   VR0L = (VR5L + VR2L)>>#1-bit;
    VR3H = (VR5H - VR2H)>>#1-bit;
   VR3L = (VR5L - VR2L) >> #1-bit;
   VR2H = (VR0H * VR4L - VR0L * VR4H)>>VSTATUS[SHIFTR];
    VR2L = (VR0L * VR4L + VR0H * VR4H)>>VSTATUS[SHIFTR];
VR5 = [mem32];
```

Sign-Extension is automatically done for the shift right operations



VCFFT3 VR5, VR4, VR3, VR2, VR0, #1-bit || VMOV32 VR5, mem32 — Complex FFT calculation instruction with Parallel Load www.ti.com

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH
- The OVFR and OVFI flags are also set if, after shift right operation, the 32-bit temporary result can't fit in 16-bit destination

Pipeline

This is a 2p cycle instruction.

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit



VCFFT4 VR4, VR2, VR1, VR0, #1-bit Complex FFT calculation instruction

Operands

This operation assumes the following complex packing order for complex operands: VRa[31:16] = Imaginary Part

VRa[15:0] = Real Part

It ignores the VSTATUS[CPACK] bit.

VR4	Complex Input
VR2	Complex Output/Complex Input from previous operation
VR1	Complex Output/Complex Input from previous operation
VR0	Complex Output/Complex Input from previous operation
#1-bit	1-bit immediate value

Opcode

LSW: 1010 0001 0011 010I

Description

This operation is used in the butterfly operation of the FFT:

```
If(VSTATUS[SAT] == 1){
  If(VSTATUS[RND] == 1){
   VROH = rnd(sat(VROH + VR2H)>>#1-bit);
    VROL = rnd(sat(VROL + VR2L)>>#1-bit);
    VR1H = rnd(sat(VR0H - VR2H)>>#1-bit);
    VR1L = rnd(sat(VR0L - VR2L)>>#1-bit);
   VR2H = rnd(sat(VR1L * VR4L + VR1H * VR4H)>>VSTATUS[SHIFTR]);
   VR2L = rnd(sat(VR1H * VR4L - VR1L * VR4H)>>VSTATUS[SHIFTR]);
  }else {
    VROH = sat(VROH + VR2H) >> #1-bit;
    VROL = sat(VROL + VR2L)>>#1-bit;
   VR1H = sat(VR0H - VR2H)>>#1-bit;
    VR1L = sat(VR0L - VR2L)>>#1-bit;
    VR2H = sat(VR1L * VR4L + VR1H * VR4H)>>VSTATUS[SHIFTR];
    VR2L = sat(VR1H * VR4L - VR1L * VR4H)>>VSTATUS[SHIFTR];
}else { //VSTATUS[SAT] = 0
  If(VSTATUS[RND] == 1){
   VROH = rnd((VROH + VR2H)>> #1-bit);
   VR0L = rnd((VR0L + VR2L)>> #1-bit);
   \label{eq:vr1H} \textit{VR1H} = \textit{rnd((VR0H - VR2H)>>\#1-bit);}
   VR1L = rnd((VR0L - VR2L)>>#1-bit);
    VR2H = rnd((VR1L * VR4L + VR1H * VR4H)>>VSTATUS[SHIFTR]);
    VR2L = rnd((VR1H * VR4L - VR1L * VR4H)>>VSTATUS[SHIFTR]);
    VR0H = (VR0H + VR2H) >> #1-bit;
   VROL = (VROL + VR2L) >> #1-bit;
   VR1H = (VR0H - VR2H)>>#1-bit;
   VR1L = (VR0L - VR2L) >> #1-bit;
   VR2H = (VR1L * VR4L + VR1H * VR4H)>>VSTATUS[SHIFTR];
    VR2L = (VR1H * VR4L - VR1L * VR4H)>>VSTATUS[SHIFTR];
```

Sign-Extension is automatically done for the shift right operations



Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH
- The OVFR and OVFI flags are also set if, after shift right operation, the 32-bit temporary result can't fit in 16-bit destination

Pipeline

This is a 2p cycle instruction.

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit

www.ti.com

VCFFT4 VR4, VR2, VR1, VR0, #1-bit || VMOV32 VR7, mem32 — Complex FFT calculation instruction with Parallel Load

VCFFT4 VR4, VR2, VR1, VR0, #1-bit || VMOV32 VR7, mem32 Complex FFT calculation instruction with Parallel Load

Operands

This operation assumes the following complex packing order for complex operands:

VRa[31:16] = Imaginary Part

VRa[15:0] = Real Part

It ignores the VSTATUS[CPACK] bit.

VR4	Complex Input
VR2	Complex Output/Complex Input from previous operation
VR1	Complex Output/Complex Input from previous operation
VR0	Complex Output/Complex Input from previous operation
#1-bit	1-bit immediate value
mem32	Pointer to 32-bit memory location

Opcode

```
LSW: 1110 0010 1011 0000 MSW: 0000 010I mem32
```

Description

This operation is used in the butterfly operation of the FFT:

```
If(VSTATUS[SAT] == 1){
  If(VSTATUS[RND] == 1){
   VROH = rnd(sat(VROH + VR2H)>>#1-bit);
    VR0L = rnd(sat(VR0L + VR2L)>>#1-bit);
   VR1H = rnd(sat(VR0H - VR2H)>>#1-bit);
   VR1L = rnd(sat(VR0L - VR2L)>>#1-bit);
   VR2H = rnd(sat(VR1L * VR4L + VR1H * VR4H)>>VSTATUS[SHIFTR]);
   VR2L = rnd(sat(VR1H * VR4L - VR1L * VR4H)>>VSTATUS[SHIFTR]);
  }else {
    VROH = sat(VROH + VR2H)>>#1-bit;
   VROL = sat(VROL + VR2L)>>#1-bit;
   VR1H = sat(VR0H - VR2H)>>#1-bit;
   VR1L = sat(VR0L - VR2L)>>#1-bit;
    VR2H = sat(VR1L * VR4L + VR1H * VR4H)>>VSTATUS[SHIFTR];
   VR2L = sat(VR1H * VR4L - VR1L * VR4H)>>VSTATUS[SHIFTR];
}else { //VSTATUS[SAT] = 0
  If(VSTATUS[RND] == 1){
    VROH = rnd((VROH + VR2H)>> #1-bit);
   VROL = rnd((VROL + VR2L) >> #1-bit);
   VR1H = rnd((VR0H - VR2H)>>#1-bit);
   VR1L = rnd((VR0L - VR2L)>>#1-bit);
   VR2H = rnd((VR1L * VR4L + VR1H * VR4H)>>VSTATUS[SHIFTR]);
   VR2L = rnd((VR1H * VR4L - VR1L * VR4H)>>VSTATUS[SHIFTR]);
  }else {
    VROH = (VROH + VR2H) >> #1-bit;
    VR0L = (VR0L + VR2L) >> #1-bit;
    VR1H = (VR0H - VR2H)>>#1-bit;
   VR1L = (VR0L - VR2L) >> #1-bit;
    VR2H = (VR1L * VR4L + VR1H * VR4H)>>VSTATUS[SHIFTR];
    VR2L = (VR1H * VR4L - VR1L * VR4H)>>VSTATUS[SHIFTR];
  }
VR7 = [mem32];
```

Sign-Extension is automatically done for the shift right operations



VCFFT4 VR4, VR2, VR1, VR0, #1-bit || VMOV32 VR7, mem32 — Complex FFT calculation instruction with Parallel Load www.ti.com

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH
- The OVFR and OVFI flags are also set if, after shift right operation, the 32-bit temporary result can't fit in 16-bit destination

Pipeline

This is a 2p cycle instruction.

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit

www.ti.com

VCFFT5 VR5, VR4, VR3, VR2, VR1, VR0, #1-bit | VMOV32 mem32, VR1 — Complex FFT calculation instruction with Parallel Load

VCFFT5 VR5, VR4, VR3, VR2, VR1, VR0, #1-bit | VMOV32 mem32, VR1 Complex FFT calculation instruction with Parallel Load

Operands

This operation assumes the following complex packing order for complex operands: VRa[31:16] = Imaginary Part VRa[15:0] = Real Part

It ignores the VSTATUS[CPACK] bit.

VR5	Complex Input
VR4	Complex Input
VR3	Complex Input
VR2	Complex Output/Complex Input from previous operation
VR1	Complex Output/Complex Input from previous operation
VR0	Complex Output/Complex Input from previous operation
#1-bit	1-bit immediate value
mem32	Pointer to 32-bit memory location

Opcode

```
LSW: 1110 0010 0000 0111 MSW: 0010 001I mem32
```

Description

This operation is used in the butterfly operation of the FFT:

```
if(VSTATUS[SAT] == 1){
  if(VSTATUS[RND] == 1){
   VROH = rnd(sat(VR3H - VR2H)>>#1-bit);
    VROL = rnd(sat(VR3L + VR2L)>>#1-bit);
   VR1H = rnd(sat(VR3H + VR2H)>>#1-bit);
   VR1L = rnd(sat(VR3L - VR2L)>>#1-bit);
   VR2H = rnd(sat(VR5H * VR4L - VR5L * VR4H)>>VSTATUS[SHIFTR]);
    VR2L = rnd(sat(VR5L * VR4L + VR5H * VR4H)>>VSTATUS[SHIFTR]);
  }else {
    VROH = sat(VR3H - VR2H)>>#1-bit;
   VROL = sat(VR3L + VR2L)>>#1-bit;
   VR1H = sat(VR3H + VR2H)>>#1-bit;
   VR1L = sat(VR3L - VR2L)>>#1-bit;
    VR2H = sat(VR5H * VR4L - VR5L * VR4H)>>VSTATUS[SHIFTR];
    VR2L = sat(VR5L * VR4L + VR5H * VR4H)>>VSTATUS[SHIFTR];
else { //VSTATUS[SAT] = 0}
  if(VSTATUS[RND] == 1){
    VROH = rnd((VR3H - VR2H)>>#1-bit);
   VROL = rnd((VR3L + VR2L) >> #1-bit);
   VR1H = rnd((VR3H + VR2H)>> #1-bit);
   VR1L = rnd((VR3L - VR2L) >> #1-bit);
    VR2H = rnd((VR5H * VR4L - VR5L * VR4H)>>VSTATUS[SHIFTR]);
   VR2L = rnd((VR5L * VR4L + VR5H * VR4H)>>VSTATUS[SHIFTR]);
    VROH = (VR3H - VR2H)>>#1-bit;
    VR0L = (VR3L + VR2L) >> #1-bit;
    VR1H = (VR3H + VR2H) >> #1-bit;
    VR1L = (VR3L - VR2L) >> #1-bit;
   VR2H = (VR5H * VR4L - VR5L * VR4H)>>VSTATUS[SHIFTR];
    VR2L = (VR5L * VR4L + VR5H * VR4H)>>VSTATUS[SHIFTR];
[mem32] = VR1;
```

Sign-Extension is automatically done for the shift right operations



VCFFT5 VR5, VR4, VR3, VR2, VR1, VR0, #1-bit || VMOV32 mem32, VR1 — Complex FFT calculation instruction with Parallel Load www.ti.com

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH
- The OVFR and OVFI flags are also set if, after shift right operation, the 32-bit temporary result can't fit in 16-bit destination

Pipeline

This is a 2p cycle instruction.

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit

www.ti.com

VCFFT6 VR3, VR2, VR1, VR0, #1-bit || VMOV32 mem32, VR1 — Complex FFT calculation instruction with Parallel Load

VCFFT6 VR3, VR2, VR1, VR0, #1-bit || VMOV32 mem32, VR1 Complex FFT calculation instruction with Parallel Load

Operands

This operation assumes the following complex packing order for complex operands:

VRa[31:16] = Imaginary Part

VRa[15:0] = Real Part

It ignores the VSTATUS[CPACK] bit.

VR3	Complex Input
VR2	Complex Output/Complex Input from previous operation
VR1	Complex Output/Complex Input from previous operation
VR0	Complex Output/Complex Input from previous operation
#1-bit	1-bit immediate value
mem32	Pointer to 32-bit memory location

Opcode

```
LSW: 1110 0010 0000 0111 MSW: 0010 0101 mem32
```

Description

This operation is used in the butterfly operation of the FFT:

```
If(VSTATUS[SAT] == 1){
  If(VSTATUS[RND] == 1){
   VROH = rnd(sat(VR3H - VR2H)>>#1-bit);
    VR0L = rnd(sat(VR3L + VR2L)>>#1-bit);
   VR1H = rnd(sat(VR3H + VR2H)>>#1-bit);
   VR1L = rnd(sat(VR3L - VR2L)>>#1-bit);
  }else {
    VR0H = sat(VR3H - VR2H)>>#1-bit;
    VROL = sat(VR3L + VR2L)>>#1-bit;
    VR1H = sat(VR3H + VR2H)>>#1-bit;
   VR1L = sat(VR3L - VR2L)>>#1-bit;
}else { //VSTATUS[SAT] = 0
  If(VSTATUS[RND] == 1){
   VROH = rnd((VR3H - VR2H)>> #1-bit);
   VR0L = rnd((VR3L + VR2L)>> #1-bit);
   VR1H = rnd((VR3H + VR2H)>> #1-bit);
    VR1L = rnd((VR3L - VR2L)>> #1-bit);
  }else {
    VROH = (VR3H - VR2H) >> #1-bit;
    VR0L = (VR3L + VR2L) >> #1-bit;
   VR1H = (VR3H + VR2H) >> #1-bit;
    VR1L = (VR3L - VR2L)>>#1-bit;
[mem32] = VR1;
```

Sign-Extension is automatically done for the shift right operations

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH

Pipeline

This is a 1/1-cycle instruction. The VCFFT and VMOV operations are completed in one cycle.

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit



VCFFT7 VR1, VR0, #1-bit || VMOV32 VR2, mem32 Complex FFT calculation instruction with Parallel Load

Operands

This operation assumes the following complex packing order for complex operands:

VRa[31:16] = Imaginary Part VRa[15:0] = Real Part

It ignores the VSTATUS[CPACK] bit.

VR3	Complex Input
VR2	Complex Output/Complex Input from previous operation
VR1	Complex Output/Complex Input from previous operation
VR0	Complex Output/Complex Input from previous operation
#1-bit	1-bit immediate value
mem32	Pointer to 32-bit memory location

Opcode

```
LSW: 1110 0010 1011 0000 MSW: 0000 011I mem32
```

Description

This operation is used in the butterfly operation of the FFT:

```
If(VSTATUS[SAT] == 1){
  If(VSTATUS[RND] == 1){
   VR0L = rnd(sat(VR0L + VR1L)>>#1-bit);
   VROH = rnd(sat(VROL - VR1L)>>#1-bit);
   VR1L = rnd(sat(VR0H + VR1H)>>#1-bit);
   VR1H = rnd(sat(VR0H - VR1H)>>#1-bit);
  }else {
   VROL = sat(VROL + VR1L)>>#1-bit;
    VROH = sat(VROL - VR1L)>>#1-bit;
   VR1L = sat(VR0H + VR1H)>>#1-bit;
   VR1H = sat(VR0H - VR1H)>>#1-bit;
}else { //VSTATUS[SAT] = 0
  If(VSTATUS[RND] == 1){
   VROL = rnd((VROL + VR1L)>>#1-bit);
   VROH = rnd((VROL - VR1L)>>#1-bit);
   VR1L = rnd((VR0H + VR1H) >> #1-bit);
   VR1H = rnd((VR0H - VR1H) >> #1-bit);
  }else {
   VR0L = (VR0L + VR1L) >> #1-bit;
   VROH = (VROL - VR1L)>>#1-bit;
   VR1L = (VR0H + VR1H) >> #1-bit;
   VR1H = (VR0H - VR1H) >> #1-bit;
VR2 = [mem32];
```

Sign-Extension is automatically done for the shift right operations

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH

Pipeline

This is a 1/1-cycle instruction. The VCFFT and VMOV operations are completed in one cycle.

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit



VCFFT8 VR3, VR2, #1-bit Complex FFT calculation instruction

Operands

This operation assumes the following complex packing order for complex operands: VRa[31:16] = Imaginary Part

VRa[15:0] = Real Part

It ignores the VSTATUS[CPACK] bit.

VR2	Complex Output/Complex Input from previous operation
VR3	Complex Output/Complex Input from previous operation
#1-bit	1-bit immediate value

Opcode

LSW: 1010 0001 0011 011I

Description

This operation is used in the butterfly operation of the FFT:

```
if(VSTATUS[SAT] == 1){
  If(VSTATUS[RND] == 1){
   VR2L = rnd(sat(VR2L + VR3L) >> #1-bit);
    VR2H = rnd(sat(VR2L - VR3L)>>#1-bit);
    VR3L = rnd(sat(VR2H + VR3H)>>#1-bit);
   VR3H = rnd(sat(VR2H - VR3H) >> #1-bit);
  }else {
    VR2L = sat(VR2L + VR3L)>>#1-bit;
    VR2H = sat(VR2L - VR3L)>>#1-bit;
   VR3L = sat(VR2H + VR3H)>>#1-bit;
   VR3H = sat(VR2H - VR3H)>>#1-bit;
else { //VSTATUS[SAT] = 0}
  if(VSTATUS[RND] == 1){
    VR2L = rnd((VR2L + VR3L) >> #1-bit);
   VR2H = rnd((VR2L - VR3L)>> #1-bit);
   VR3L = rnd((VR2H + VR3H) >> #1-bit);
   VR3H = rnd((VR2H - VR3H) >> #1-bit);
    VR2L = (VR2L + VR3L) >> #1-bit;
   VR2H = (VR2L - VR3L) >> #1-bit;
   VR3L = (VR2H + VR3H) >> #1-bit;
    VR3H = (VR2H - VR3H)>>#1-bit;
```

Sign-Extension is automatically done for the shift right operations

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH

Pipeline

This is a single cycle instruction.

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit



VCFFT8 VR3, VR2, #1-bit || VOMV32 mem32, VR4 Complex FFT calculation instruction with Parallel Store

Operands

This operation assumes the following complex packing order for complex operands:

VRa[31:16] = Imaginary Part

VRa[15:0] = Real Part

It ignores the VSTATUS[CPACK] bit.

VR4	Complex Input from previous operation
VR2	Complex Output/Complex Input from previous operation
VR3	Complex Output/Complex Input from previous operation
#1-bit	1-bit immediate value
mem32	Pointer to 32-bit memory location

Opcode

```
LSW: 1110 0010 0000 0111 MSW: 0010 0111 mem32
```

Description

This operation is used in the butterfly operation of the FFT:

```
if(VSTATUS[SAT] == 1){
  if(VSTATUS[RND] == 1){
   VR2L = rnd(sat(VR2L + VR3L) >> #1-bit);
    VR2H = rnd(sat(VR2L - VR3L)>>#1-bit);
    VR3L = rnd(sat(VR2H + VR3H)>>#1-bit);
    VR3H = rnd(sat(VR2H - VR3H)>>#1-bit);
  }else {
    VR2L = sat(VR2L + VR3L)>>#1-bit;
    VR2H = sat(VR2L - VR3L)>>#1-bit;
   VR3L = sat(VR2H + VR3H) >> #1-bit;
   VR3H = sat(VR2H - VR3H)>>#1-bit;
}else { //VSTATUS[SAT] = 0
  if(VSTATUS[RND] == 1){
    VR2L = rnd((VR2L + VR3L) >> #1-bit);
   VR2H = rnd((VR2L - VR3L)>>#1-bit);
   VR3L = rnd((VR2H + VR3H) >> #1-bit);
    VR3H = rnd((VR2H - VR3H) >> #1-bit);
  }else {
    VR2L = (VR2L + VR3L) >> #1-bit;
   VR2H = (VR2L - VR3L) >> #1-bit;
   VR3L = (VR2H + VR3H) >> #1-bit;
    VR3H = (VR2H - VR3H)>>#1-bit;
[mem32] = VR4;
```

Sign-Extension is automatically done for the shift right operations

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH

Pipeline

This is a single cycle instruction.

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit



VCFFT9 VR5, VR4, VR3, VR2, VR1, VR0 #1-bit Complex FFT calculation instruction

Operands

This operation assumes the following complex packing order for complex operands: VRa[31:16] = Imaginary Part

VRa[15:0] = Real Part

It ignores the VSTATUS[CPACK] bit.

VR0	Complex Input
VR1	Complex Input
VR2	Complex Input
VR3	Complex Input
VR4	Complex Output
VR5	Complex Output
#1-bit	1-bit immediate value

Opcode

LSW: 1010 0001 0011 100I

Description

This operation is used in the butterfly operation of the FFT:

```
If(VSTATUS[SAT] == 1){
  if(VSTATUS[RND] == 1){
   VR4L = rnd(sat(VR0L + VR2L)>>#1-bit);
    VR4H = rnd(sat(VR1L + VR3L)>>#1-bit);
    VR5L = rnd(sat(VR0L - VR2L)>>#1-bit);
   VR5H = rnd(sat(VR1L - VR3L)>>#1-bit);
  }else {
    VR4L = sat(VR0L + VR2L)>>#1-bit;
    VR4H = sat(VR1L + VR3L)>>#1-bit;
    VR5L = sat(VR0L - VR2L)>>#1-bit;
    VR5H = sat(VR1L - VR3L)>>#1-bit;
}else { //VSTATUS[SAT] = 0
  if(VSTATUS[RND] == 1){
    VR4L = rnd((VR0L + VR2L) >> #1-bit);
    VR4H = rnd((VR1L + VR3L)>> #1-bit);
   VR5L = rnd((VR0L - VR2L)>>#1-bit);
   VR5H = rnd((VR1L - VR3L) >> #1-bit);
  }else {
    VR4L = (VR0L + VR2L) >> #1-bit;
   VR4H = (VR1L + VR3L) >> #1-bit;
   VR5L = (VR0L - VR2L) >> #1-bit;
    VR5H = (VR1L - VR3L)>>#1-bit;
```

Sign-Extension is automatically done for the shift right operations

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH

Pipeline

This is a single cycle instruction.

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit

VCFFT9 VR5, VR4, VR3, VR2, VR1, VR0 #1-bit || VMOVE32 mem32, VR5 — Complex FFT calculation instruction with Parallel Store

VCFFT9 VR5, VR4, VR3, VR2, VR1, VR0 #1-bit || VMOVE32 mem32, VR5 Complex FFT calculation instruction with Parallel Store

Operands

This operation assumes the following complex packing order for complex operands: VRa[31:16] = Imaginary Part VRa[15:0] = Real Part

It ignores the VSTATUS[CPACK] bit.

VR0	Complex Input
VR1	Complex Input
VR2	Complex Input
VR3	Complex Input
VR4	Complex Output
VR5	Complex Output
#1-bit	1-bit immediate value
mem32	Pointer to 32-bit memory location

Opcode

```
LSW: 1110 0010 0000 0111 MSW: 0010 1001 mem32
```

Description

This operation is used in the butterfly operation of the FFT:

```
If(VSTATUS[SAT] == 1){
  If(VSTATUS[RND] == 1){
   VR4L = rnd(sat(VR0L + VR2L)>>#1-bit);
   VR4H = rnd(sat(VR1L + VR3L)>>#1-bit);
   VR5L = rnd(sat(VR0L - VR2L)>>#1-bit);
   VR5H = rnd(sat(VR1L - VR3L)>>#1-bit);
  }else {
    VR4L = sat(VR0L + VR2L)>>#1-bit;
    VR4H = sat(VR1L + VR3L)>>#1-bit;
   VR5L = sat(VR0L - VR2L)>>#1-bit;
   VR5H = sat(VR1L - VR3L)>>#1-bit;
}else { //VSTATUS[SAT] = 0
  If(VSTATUS[RND] == 1){
   VR4L = rnd((VR0L + VR2L) >> #1-bit);
   VR4H = rnd((VR1L + VR3L) >> #1-bit);
    VR5L = rnd((VR0L - VR2L)>> #1-bit);
    VR5H = rnd((VR1L - VR3L)>>#1-bit);
  }else {
   VR4L = (VR0L + VR2L) >> #1-bit;
   VR4H = (VR1L + VR3L) >> #1-bit;
   VR5L = (VR0L - VR2L)>>#1-bit;
   VR5H = (VR1L - VR3L) >> #1-bit;
  }
[mem32] = VR5;
```

Sign-Extension is automatically done for the shift right operations



Www.ti.com

VCFFT9 VR5, VR4, VR3, VR2, VR1, VR0 #1-bit || VMOVE32 mem32, VR5 — Complex FFT calculation instruction with Parallel Store

This instruction modifies the following bits in the VSTATUS register:

OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL

OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH

This is a 1/1-cycle instruction. The VCFFT and VMOV operations are completed in one cycle.

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit

See also



VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0 #1-bit Complex FFT calculation instruction

Operands

This operation assumes the following complex packing order for complex operands: VRa[31:16] = Imaginary Part VRa[15:0] = Real Part It ignores the VSTATUS[CPACK] bit.

VR0	Complex Input
VR1	Complex Input
VR2	Complex Input
VR3	Complex Input
VR6	Complex Output
VR7	Complex Output
#1-bit	1-bit immediate value

Opcode

LSW: 1010 0001 0011 101I

Description

This operation is used in the butterfly operation of the FFT:

```
If(VSTATUS[SAT] == 1){
  if(VSTATUS[RND] == 1){
   VR6L = rnd(sat(VR0H + VR3H)>>#1-bit);
    VR6H = rnd(sat(VR1H - VR2H)>>#1-bit);
    VR7L = rnd(sat(VR0H - VR3H)>>#1-bit);
   VR7H = rnd(sat(VR1H + VR2H)>>#1-bit);
  }else {
    VR6L = sat(VR0H + VR3H)>>#1-bit;
    VR6H = sat(VR1H - VR2H)>>#1-bit;
    VR7L = sat(VR0H - VR3H)>>#1-bit;
    VR7H = sat(VR1H + VR2H) >> #1-bit;
}else { //VSTATUS[SAT] = 0
  if(VSTATUS[RND] == 1){
    VR6L = rnd((VR0H + VR3H)>> #1-bit);
    VR6H = rnd((VR1H - VR2H)>>#1-bit);
   VR7L = rnd((VR0H - VR3H) >> #1-bit);
   VR7H = rnd((VR1H + VR2H) >> #1-bit);
  }else {
    VR6L = (VR0H + VR3H)>>#1-bit;
   VR6H = (VR1H - VR2H) >> #1-bit;
   VR7L = (VR0H - VR3H) >> #1-bit;
    VR7H = (VR1H + VR2H)>>#1-bit;
```

Sign-Extension is automatically done for the shift right operations

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH

Pipeline

This is a single cycle instruction.

Example


```
_CFFT_run1024Pt:
    ...
    etc ...
    ...
    MOVL *-SP[ARG_OFFSET], XAR4
    VSATON
```



```
_CFFT_run1024Pt_stages1and2Combined:
   MOVZ
             AR0, *+XAR4[NSAMPLES_OFFSET]
   MOVL
             XAR2, *+XAR4[INBUFFER_OFFSET]
   MOVL
             XAR1, *+XAR4[OUTBUFFER_OFFSET]
    .lp_amode
   SETC
             AMODE
   NOP
             *,ARP2
             VR0, *BR0++
   VMOV32
   VMOV32
             VR1, *BR0++
   VCFFT7
             VR1, VR0, #1
 | VMOV32
             VR2, *BR0++
             VR3, *BR0++
   VMOV32
   VCFFT8
             VR3, VR2, #1
   VCFFT9
             VR5, VR4, VR3, VR2, VR1, VR0, #1
    .aliqn
              _CFFT_run1024Pt_stages1and2CombinedLoop, #S12_LOOP_COUNT
   RPTB
   VCFFT10
             VR7, VR6, VR3, VR2, VR1, VR0, #1
 || VMOV32
             VR0, *BR0++
   VMOV32
             VR1, *BR0++
   VCFFT7
             VR1, VR0, #1
 | VMOV32
             VR2, *BR0++
   VMOV32
             VR3, *BR0++
    VCFFT8
             VR3, VR2, #1
 | VMOV32
              *XAR1++, VR4
   VMOV32
             *XAR1++, VR6
   VCFFT9
             VR5, VR4, VR3, VR2, VR1, VR0, #1
 || VMOV32
             *XAR1++, VR5
             *++, VR7, ARP2
   VMOV32
_CFFT_run1024Pt_stages1and2CombinedLoop:
   VCFFT10
            VR7, VR6, VR3, VR2, VR1, VR0, #1
   VMOV32
             *XAR1++, VR4
   VMOV32
             *XAR1++, VR6
   VMOV32
             *XAR1++, VR5
   VMOV32
             *XAR1++, VR7
_CFFT_run1024Pt_stages1and2CombinedEnd:
   .c28_amode
    CLRC
             AMODE
_CFFT_run1024Pt_stages3and4Combined:
   etc ...
              #15
   VSETSHR
   VRNDON
             XAR2, *+XAR4[S34_INPUT_OFFSET]
   MOVL
   MOVL
             XAR1, #S34_INSEP
   MOVL
             XAR0, #S34_OUTSEP
             XAR6, *+XAR4[S34_OUTPUT_OFFSET]
   MOVL
   MOVL
             XAR7, XAR6
    ADDB
             XAR7, #S34_GROUPSEP
   MOVL
             XAR3, #_vcu2_twiddleFactors
```



```
MOVL
              *-SP[TFPTR_OFFSET], XAR3
   MOVL
             XAR4, XAR2
   ADDB
             XAR4, #S34_GROUPSEP
   MOVL XAR5, #S34_OUTER_LOOP_COUNT
_CFFT_run1024Pt_stages3and4OuterLoop:
   MOVL
             XAR3, *-SP[TFPTR_OFFSET]
    ; Inner Butterfly Loop
             VR5, *+XAR4[AR1]
   VMOV32
   VMOV32
             VR6, *+XAR2[AR1]
   VMOV32
             VR7, *XAR4++
             VR4, *XAR3++
   VMOV32
             VR2, VR5, VR4
   VCFFT1
   VMOV32
             VR5, *XAR2++
   VCFFT2
             VR7, VR6, VR4, VR2, VR1, VR0, #1
    .align
              _CFFT_run1024Pt_stages3and4InnerLoop, #S34_INNER_LOOP_COUNT
   RPTB
   VMOV32
             VR4, *XAR3++
   VCFFT3
             VR5, VR4, VR3, VR2, VR0, #1
 | VMOV32
             VR5, *+XAR4[AR1]
   VMOV32
             VR6, *+XAR2[AR1]
   VCFFT4
             VR4, VR2, VR1, VR0, #1
 | VMOV32
             VR7, *XAR4++
   VMOV32
             VR4, *XAR3++
   VMOV32
             *XAR6++, VR0
   VCFFT5
             VR5, VR4, VR3, VR2, VR1, VR0, #1
 || VMOV32
             *XAR7++, VR1
   VMOV32
             VR5, *XAR2++
   VMOV32
             *+XAR6[AR0], VR0
   VCFFT2
             VR7, VR6, VR4, VR2, VR1, VR0, #1
 || VMOV32
             *+XAR7[AR0], VR1
_CFFT_run1024Pt_stages3and4InnerLoop:
   VMOV32
             VR4, *XAR3++
   VCFFT3
             VR5, VR4, VR3, VR2, VR0, #1
   NOP
   VCFFT4
             VR4, VR2, VR1, VR0, #1
   NOP
   VMOV32
             *XAR6++, VR0
              VR3, VR2, VR1, VR0, #1
   VCFFT6
              *XAR7++, VR1
 || VMOV32
   NOP
   VMOV32
             *+XAR6[AR0], VR0
   VMOV32
             *+XAR7[AR0], VR1
   ADDB
              XAR2, #S34_POST_INCREMENT
   ADDB
              XAR4, #S34_POST_INCREMENT
   ADDB
              XAR6, #S34_POST_INCREMENT
              XAR7, #S34_POST_INCREMENT
   ADDB
   BANZ
              _CFFT_run1024Pt_stages3and4OuterLoop, AR5--
_CFFT_run1024Pt_stages3and4CombinedEnd:
```



www.ti.com

TEXAS INSTRUMENTS

See also

The entire FFT implementation, with accompanying code comments, can be found in the VCU Library in controlSUITE.

VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0 #1-bit || VMOV32 VR0, mem32 — Complex FFT calculation instruction with Parallel Load www.ti.com

VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0 #1-bit || VMOV32 VR0, mem32 Complex FFT calculation instruction with Parallel Load

Operands

This operation assumes the following complex packing order for complex operands: VRa[31:16] = Imaginary Part

VRa[15:0] = Real Part

It ignores the VSTATUS[CPACK] bit.

VR0	Complex Input
VR1	Complex Input
VR2	Complex Input
VR3	Complex Input
VR6	Complex Output
VR7	Complex Output
#1-bit	1-bit immediate value
mem32	pointer to 32-bit memory location

Opcode

```
LSW: 1110 0010 1011 0000 MSW: 0000 1001 mem32
```

Description

This operation is used in the butterfly operation of the FFT:

```
If(VSTATUS[SAT] == 1){
  If(VSTATUS[RND] == 1){
   VR6L = rnd(sat(VR0H + VR3H) >> #1-bit);
   VR6H = rnd(sat(VR1H - VR2H)>>#1-bit);
    VR7L = rnd(sat(VR0H - VR3H)>>#1-bit);
    VR7H = rnd(sat(VR1H + VR2H)>>#1-bit);
  }else {
    VR6L = sat(VR0H + VR3H)>>#1-bit;
   VR6H = sat(VR1H - VR2H)>>#1-bit;
   VR7L = sat(VR0H - VR3H)>>#1-bit;
   VR7H = sat(VR1H + VR2H)>>#1-bit;
else { //VSTATUS[SAT] = 0}
 if(VSTATUS[RND] == 1){
   VR6L = rnd((VR0H + VR3H)>>#1-bit);
    VR6H = rnd((VR1H - VR2H)>>#1-bit);
   VR7L = rnd((VR0H - VR3H)>> #1-bit);
   VR7H = rnd((VR1H + VR2H)>> #1-bit);
  }else {
    VR6L = (VR0H + VR3H) >> #1-bit;
    VR6H = (VR1H - VR2H)>>#1-bit;
   VR7L = (VR0H - VR3H) >> #1-bit;
    VR7H = (VR1H + VR2H) >> #1-bit;
VR0 = [mem32];
```

Sign-Extension is automatically done for the shift right operations

Flags

This instruction modifies the following bits in the VSTATUS register:

- OVFR is set if signed overflow is detected for add/sub calculation in which destination is VRxL
- OVFI is set if signed overflow is detected for add/sub calculation in which destination is VRxH

Pipeline

This is a 1/1-cycle instruction. The VCFFT and VMOV operations are completed in one cycle.

Example

See the example for VCFFT10 VR7, VR6, VR3, VR2, VR1, VR0, #1-bit



www.ti.com Instruction Set

2.5.8 Galois Instructions

The instructions are listed alphabetically, preceded by a summary.

Table 2-17. Galois Field Instructions

Title	Page
VGFACC VRa, VRb, #4-bit —Galois Field Instruction	332
VGFACC VRa, VRb, VR7 — Galois Field Instruction	333
VGFACC VRa, VRb, VR7 VMOV32 VRc, mem32 — Galois Field Instruction with Parallel Load	334
VGFADD4 VRa, VRb, VRc, #4-bit — Galois Field Four Parallel Byte X Byte Add	335
VGFINIT mem16 — Initialize Galois Field Polynomial and Order	336
VGFMAC4 VRa, VRb, VRc — Galois Field Four Parallel Byte X Byte Multiply and Accumulate	337
VGFMPY4 VRa, VRb, VRc — Galois Field Four Parallel Byte X Byte Multiply	338
VGFMPY4 VRa, VRb, VRc VMOV32 VR0, mem32 — Galois Field Four Parallel Byte X Byte Multiply with Parallel Load	339
VGFMAC4 VRa, VRb, VRc PACK4 VR0, mem32, #2-bit —Galois Field Four Parallel Byte X Byte Multiply and Accumulate with Parallel Byte Packing	340
VPACK4 VRa, mem32, #2-bit —Byte Packing	341
VREVB VRa — Byte Reversal	342
VSHLMB VRa, VRb — Shift Left and Merge Right Bytes	343



VGFACC VRa, VRb, #4-bit Galois Field Instruction

Operands

VRb	General purpose register: VR0, VR1VR7. Cannot be VR8
VRa	General purpose register: VR0, VR1VR7. Cannot be VR8
#4-bit	4-bit Immediate Value

Opcode

```
LSW: 1110 0110 1000 0001 MSW: 0000 000a abbb IIII
```

Description

Performs the following sequence of operations

```
If (I[0:0] == 1 )
    VRa[7:0] = VRa[7:0] ^ VRb[7:0]

If (I[1:1] == 1 )
    VRa[7:0] = VRa[7:0] ^ VRb[15:8]

If (I[2:2] == 1 )
    VRa[7:0] = VRa[7:0] ^ VRb[23:16]

If (I[3:3] == 1 )
    VRa[7:0] = VRa[7:0] ^ VRb[31:24]
```

Flags

This instruction does not affect any flags in the VSTATUS register

Pipeline

This is a single-cycle instruction

Example

See the Reed-Solomon algorithm implementation in the VCU library in controlSUITE

See also

VGFACC VRa, VRb, VR7

VGFACC VRa, VRb, VR7 || VMOV32 VRc, mem32



VGFACC VRa, VRb, VR7 Galois Field Instruction

Operands

VRb	General purpose register: VR0, VR1VR7. Cannot be VR8
VRa	General purpose register: VR0, VR1VR7. Cannot be VR8
VR7	General purpose register: VR7

Opcode LSW: 1110 0110 1000 0001 MSW: 0000 0100 00aa abbb

Description Performs the following sequence of operations

```
If (VR7[0:0] == 1 )
   VRa[7:0] = VRa[7:0] ^ VRb[7:0]

If (VR7[1:1] == 1 )
   VRa[7:0] = VRa[7:0] ^ VRb[15:8]

If (VR7[2:2] == 1 )
   VRa[7:0] = VRa[7:0] ^ VRb[23:16]

If (VR7[3:3] == 1 )
   VRa[7:0] = VRa[7:0] ^ VRb[31:24]
```

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example See the Reed-Solomon algorithm implementation in the VCU library in controlSUITE

See also VGFACC VRa, VRb, #4-bit

VGFACC VRa, VRb, VR7 || VMOV32 VRc, mem32



VGFACC VRa, VRb, VR7 || VMOV32 VRc, mem32 Galois Field Instruction with Parallel Load

Operands

VRb	General purpose register: VR0, VR1VR7. Cannot be VR8
VRa	General purpose register: VR0, VR1VR7. Cannot be VR8
VRc	General purpose register: VR0, VR1VR7. Cannot be VR8
VR7	General purpose register: VR7
mem32	Pointer to a 32-bit memory location

Opcode LSW: 1110 0010 1011 011a MSW: aabb bccc mem32

Description Performs the following sequence of operations

```
If (VR7[0:0] == 1 )
   VRa[7:0] = VRa[7:0] ^ VRb[7:0]

If (VR7[1:1] == 1 )
   VRa[7:0] = VRa[7:0] ^ VRb[15:8]

If (VR7[2:2] == 1 )
   VRa[7:0] = VRa[7:0] ^ VRb[23:16]

If (VR7[3:3] == 1 )
   VRa[7:0] = VRa[7:0] ^ VRb[31:24]

VRc = [mem32]
```

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a 1/1-cycle instruction. Both the VGFACC and VMOV32 operation complete in a

single cycle.

Example See the Reed-Solomon algorithm implementation in the VCU library in controlSUITE

See also VGFACC VRa, VRb, #4-bit

VGFACC VRa, VRb, VR7



VGFADD4 VRa, VRb, VRc, #4-bit Galois Field Four Parallel Byte X Byte Add

Operands

VRb	General purpose register: VR0, VR1VR7. Cannot be VR8	
VRa	General purpose register: VR0, VR1VR7. Cannot be VR8	
VRc	General purpose register: VR0, VR1VR7. Cannot be VR8	
#4-bit	4-bit Immediate Value	

Opcode

LSW: 1110 0110 1000 0000 MSW: 000a aabb bccc IIII

Description

Performs the following sequence of operations

```
If (I[0:0] == 1 )
   VRa[7:0] = VRb[7:0] ^ VRc[7:0]
else
   VRa[7:0] = VRb[7:0]

If (I[1:1] == 1 )
   VRa[15:8] = VRb[15:8] ^ VRc[15:8]
else
   VRa[15:8] = VRb[15:8]

If (I[2:2] == 1 )
   VRa[23:16] = VRb[23:16] ^ VRc[23:16]
else
   VRa[23:16] = VRb[23:16]

If (I[3:3] == 1 )
   VRa[31:24] = VRb[31:24] ^ VRc[31:24]
else
   VRa[31:24] = VRb[31:24]
```

Flags

This instruction does not affect any flags in the VSTATUS register

Pipeline

This is a single cycle instruction

Example

See the Reed-Solomon algorithm implementation in the VCU library in controlSUITE



VGFINIT mem16	Initialize Galois Field Polynomial and Order
---------------	--

Operands

mem16 Pointer to 16-bit memory location

Opcode LSW: 1110 0010 1100 0101

MSW: 0000 0000 mem16

Description Initialize GF Polynomial and Order

VSTATUS[GFPOLY] = [mem16][7:0]
VSTATUS[GFORDER] = [mem16][10:8]

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example See the Reed-Solomon algorithm implementation in the VCU library in controlSUITE



VGFMAC4 VRa, VRb, VRc Galois Field Four Parallel Byte X Byte Multiply and Accumulate

Operands

VRb	General purpose register: VR0, VR1VR7. Cannot be VR8
VRa	General purpose register: VR0, VR1VR7. Cannot be VR8
VRc	General purpose register: VR0, VR1VR7. Cannot be VR8

Opcode LSW: 1110 0110 1000 0000

MSW: 0010 001a aabb bccc

Description Performs the follow sequence of operations:

VRa[7:0] = (VRa[7:0] * VRb[7:0]) ^ VRc[7:0] VRa[15:8] = (VRa[15:8] * VRb[15:8]) ^ VRc[15:8] VRa[23:16] = (VRa[23:16] * VRb[23:16]) ^ VRc[23:16] VRa[31:24] = (VRa[31:24] * VRb[31:24]) ^ VRc[31:24]

The GF multiply operation is defined by VSTATUS[GFPOLY] and VSTATUS[GFORDER]

bits.

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example See the Reed-Solomon algorithm implementation in the VCU library in controlSUITE

See also VGFMPY4 VRa, VRb, VRc || VMOV32 VR0, mem32



VGFMPY4 VRa, VRb, VRc Galois Field Four Parallel Byte X Byte Multiply

Operands

VRb	General purpose register: VR0, VR1VR7. Cannot be VR8	
VRa	General purpose register: VR0, VR1VR7. Cannot be VR8	
VRc	General purpose register: VR0, VR1VR7. Cannot be VR8	

Opcode LSW: 1110 0110 1000 0000

MSW: 0010 000a aabb bccc

Description Performs the following sequence of operations

VRa[7:0] = VRb[7:0] * VRc[7:0] VRa[15:8] = VRb[15:8] * VRc[15:8] VRa[23:16] = VRb[23:16] * VRc[23:16] VRa[31:24] = VRb[31:24] * VRc[31:24]

The GF multiply operation is defined by VSTATUS[GFPOLY] and VSTATUS[GFORDER]

bits.

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single cycle instruction

Example See the Reed-Solomon algorithm implementation in the VCU library in controlSUITE

See also VGFMPY4 VRa, VRb, VRc || VMOV32 VR0, mem32



www.ti.com

VGFMPY4 VRa, VRb, VRc || VMOV32 VR0, mem32 — Galois Field Four Parallel Byte X Byte Multiply with Parallel Load

VGFMPY4 VRa, VRb, VRc | VMOV32 VR0, mem32 Galois Field Four Parallel Byte X Byte Multiply with Parallel Load

Operands

VRb	General purpose register: VR0, VR1VR7. Cannot be VR8
VRa	General purpose register: VR0, VR1VR7. Cannot be VR8
VRc	General purpose register: VR0, VR1VR7. Cannot be VR8
VR0	General purpose register: VR0
mem32	Pointer to a 32-bit memory location

Opcode LSW: 1110 0010 1011 010a MSW: aabb bccc mem32

Description Performs the following sequence of operations

VRa[7:0] = VRb[7:0] * VRc[7:0] VRa[15:8] = VRb[15:8] * VRc[15:8] VRa[23:16] = VRb[23:16] * VRc[23:16] VRa[31:24] = VRb[31:24] * VRc[31:24]

VR0 = [mem32]

The GF multiply operation is defined by VSTATUS[GFPOLY] and VSTATUS[GFORDER]

bits.

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a 1/1-cycle instruction. Both the VGFMPY4 and VMOV32 operation complete in a

single cycle.

Example See the Reed-Solomon algorithm implementation in the VCU library in controlSUITE

See also VGFMPY4 VRa, VRb, VRc

VGFMAC4 VRa, VRb, VRc || PACK4 VR0, mem32, #2-bit — Galois Field Four Parallel Byte X Byte Multiply and Accumulate with Parallel Byte Packing www.ti.com

VGFMAC4 VRa, VRb, VRc | PACK4 VR0, mem32, #2-bit Galois Field Four Parallel Byte X Byte Multiply and Accumulate with Parallel Byte Packing

Operands

VRb	General purpose register: VR0, VR1VR7. Cannot be VR8
VRa	General purpose register: VR0, VR1VR7. Cannot be VR8
VRc	General purpose register: VR0, VR1VR7. Cannot be VR8
VR0	General purpose register: VR0
mem32	Pointer to 32-bit memory location
#2-bit	2-bit Immediate Value

Opcode LSW: 1110 0010 1011 1IIa MSW: aabb bccc mem32

Description

Performs the follow sequence of operations:

```
VRa[7:0] = (VRa[7:0] * VRb[7:0]) ^ VRc[7:0]
VRa[15:8] = (VRa[15:8] * VRb[15:8]) ^ VRc[15:8]
VRa[23:16] = (VRa[23:16] * VRb[23:16]) ^ VRc[23:16]
VRa[31:24] = (VRa[31:24] * VRb[31:24]) ^ VRc[31:24]
If (I == 0)
 VR0[7:0]
           = [mem32][7:0]
 VR0[15:8] = [mem32][7:0]
 VR0[23:16] = [mem32][7:0]
 VR0[31:24] = [mem32][7:0]
Else If (I == 1)
 VR0[7:0] = [mem32][15:8]
 VR0[15:8] = [mem32][15:8]
 VR0[23:16] = [mem32][15:8]
 VR0[31:24] = [mem32][15:8]
Else If (I == 2)
 VR0[7:0] = [mem32][23:16]
 VR0[15:8] = [mem32][23:16]
 VR0[23:16] = [mem32][23:16]
 VR0[31:24] = [mem32][23:16]
Else If (I == 3)
  VR0[7:0] = [mem32][31:24]
 VR0[15:8] = [mem32][31:24]
 VR0[23:16] = [mem32][31:24]
 VR0[31:24] = [mem32][31:24]
```

The GF multiply operation is defined by VSTATUS[GFPOLY] and VSTATUS[GFORDER]

Flags

This instruction does not affect any flags in the VSTATUS register

Pipeline

This is a 1/1-cycle instruction. Both the VGFMAC4 and PACK4 operations complete in a

single cycle.

Example

See the Reed-Solomon algorithm implementation in the VCU library in controlSUITE



VPACK4 VRa, mem32, #2-bit Byte Packing

Operands

VRa	General purpose register: VR0, VR1VR7. Cannot be VR8
mem32	Pointer to a 32-bit memory location
#2-bit	2-bit Immediate Value

Opcode LSW: 1110 0010 1011 0001 MSW: 000a aaII mem32

Description

Pack Ith byte from a memory location 4 times in VRa

```
If (I == 0)
  VRa[7:0]
            = [mem32][7:0]
 VRa[15:8] = [mem32][7:0]
 VRa[23:16] = [mem32][7:0]
 VRa[31:24] = [mem32][7:0]
Else If (I == 1)
 VRa[7:0] = [mem32][15:8]
 VRa[15:8] = [mem32][15:8]
 VRa[23:16] = [mem32][15:8]
 VRa[31:24] = [mem32][15:8]
Else If (I == 2)
  VRa[7:0] = [mem32][23:16]
 VRa[15:8] = [mem32][23:16]
 VRa[23:16] = [mem32][23:16]
 VRa[31:24] = [mem32][23:16]
Else If (I == 3)
 VRa[7:0] = [mem32][31:24]
 VRa[15:8] = [mem32][31:24]
 VRa[23:16] = [mem32][31:24]
 VRa[31:24] = [mem32][31:24]
```

The GF multiply operation is defined by VSTATUS[GFPOLY] and VSTATUS[GFORDER] hits

Flags

This instruction does not affect any flags in the VSTATUS register

Pipeline

This is a single-cycle instruction

Example

See the Reed-Solomon algorithm implementation in the VCU library in controlSUITE



Operands

VRa General purpose register: VR0, VR1....VR7. Cannot be VR8

Opcode LSW: 1110 0110 1000 0000

MSW: 0010 0100 0000 0aaa

Description Reverse Bytes

Input: $VRa = \{B3, B2, B1, B0\}$ Output: $VRa = \{B0, B1, B2, B3\}$

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example See the Reed-Solomon algorithm implementation in the VCU library in controlSUITE



VSHLMB VRa, VRb Shift Left and Merge Right Bytes

Operands

VRa General purpose register: VR0, VR1....VR7. Cannot be VR8
VRb General purpose register: VR0, VR1....VR7. Cannot be VR8

Opcode LSW: 1110 0110 1000 0000

MSW: 0010 0100 01aa abbb

Description Shift Left and Merge Bytes

Input: VRa = {B7,B6,B5,B4}
Input: VRb = {B3,B2,B1,B0}
Output: VRa = {B6,B5,B4,B3}
Output: VRb = {B2,B1,B0,8'b0}

Restrictions VRa != VRb. The source and destination registers must be different

Flags This instruction does not affect any flags in the VSTATUS register

Pipeline This is a single-cycle instruction

Example See the Reed-Solomon algorithm implementation in the VCU library in controlSUITE



Instruction Set www.ti.com

2.5.9 Viterbi Instructions

The instructions are listed alphabetically, preceded by a summary.

Table 2-18. Viterbi Instructions

Title	Page
VITBM2 VR0 — Code Rate 1:2 Branch Metric Calculation	345
VITBM2 VR0, mem32 — Branch Metric Calculation CR=1/2	346
VITBM2 VR0 VMOV32 VR2, mem32 — Code Rate 1:2 Branch Metric Calculation with Parallel Load	347
VITBM3 VR0, VR1, VR2 — Code Rate 1:3 Branch Metric Calculation	348
VITBM3 VR0, VR1, VR2 VMOV32 VR2, mem32 —Code Rate 1:3 Branch Metric Calculation with Parallel Load	349
VITBM3 VR0L, VR1L, mem16 — Branch Metric Calculation CR=1/3	350
VITDHADDSUB VR4, VR3, VR2, VRa — Viterbi Double Add and Subtract, High	351
$\textbf{VITDHADDSUB VR4, VR3, VR2, VRa VMOV32 mem32, VRb} \\ - \\ \textbf{Viterbi Add and Subtract High with Parallel Store .} \\$	353
VITDHSUBADD VR4, VR3, VR2, VRa — Viterbi Add and Subtract Low	354
VITDHSUBADD VR4, VR3, VR2, VRa VMOV32 mem32, VRb — Viterbi Subtract and Add, High with Parallel Store	
VITDLADDSUB VR4, VR3, VR2, VRa — Viterbi Add and Subtract Low	
VITDLADDSUB VR4, VR3, VR2, VRa VMOV32 mem32, VRb — Viterbi Add and Subtract Low with Parallel Load	357
VITDLSUBADD VR4, VR3, VR2, VRa — Viterbi Subtract and Add Low	
VITDLSUBADD VR4, VR3, VR2, VRa VMOV32 mem32, VRb — Viterbi Subtract and Add, Low with Parallel Store .	359
VITHSEL VRa, VRb, VR4, VR3 — Viterbi Select High	
VITHSEL VRa, VRb, VR4, VR3 VMOV32 VR2, mem32 — Viterbi Select High with Parallel Load	
VITLSEL VRa, VRb, VR4, VR3 — Viterbi Select, Low Word	
VITLSEL VRa, VRb, VR4, VR3 VMOV32 VR2, mem32 — Viterbi Select Low with Parallel Load	363
VITSTAGE — Parallel Butterfly Computation	365
VITSTAGE VITBM2 VR0, mem32 — Parallel Butterfly Computation with Parallel Branch Metric Calculation CR=1/2	
VITSTAGE VMOV16 VR0L, mem16 — Parallel Butterfly Computation with Parallel Load	
VMOV32 VSM (k+1):VSM(k), mem32 — Load Consecutive State Metrics	
VMOV32 mem32, VSM (k+1):VSM(k) —Store Consecutive State Metrics	
VSETK #3-bit — Set Constraint Length for Viterbi Operation	
VSMINIT mem16 — State Metrics Register initialization	
VTCLEAR —Clear Transition Bit Registers	
VTRACE mem32, VR0, VT0, VT1 — Viterbi Traceback, Store to Memory	
VTRACE VR1, VR0, VT0, VT1 — Viterbi Traceback, Store to Register	
VTRACE VR1, VR0, VT0, VT1 VMOV32 VT0, mem32 — Trace-back with Parallel Load	378



VITBM2 VR0

Code Rate 1:2 Branch Metric Calculation

Operands

Before the operation, the inputs are loaded into the registers as shown below. Each operand for the branch metric calculation is 16-bits.

Input Register	Value
VR0L	16-bit decoder input 0
VR0H	16-bit decoder input 1

The result of the operation is also stored in VR0 as shown below:

Output Register	Value
VR0L	16-bit branch metric 0 = VR0L + VR0H
VR0H	16-bit branch metric 1 = VR0L - VR0L

Opcode

LSW: 1110 0101 0000 1100

Description

Branch metric calculation for code rate = 1/2.

Flags

This instruction sets the real overflow flag, VSTATUS[OVFR] in the event of an overflow or underflow.

Pipeline

This is a single-cycle instruction.

Example

See also

VITBM2 VR0 || VMOV32 VR2, mem32 VITBM3 VR0, VR1, VR2



VITBM2 VR0, mem32 Branch Metric Calculation CR=1/2

Operands

Before the operation, the inputs are loaded into the registers as shown below.

Opcode

```
LSW: 1110 0010 1000 0000 MSW: 0000 0001 mem16
```

Description

Calculates two Branch-Metrics (BMs) for CR = 1/2

```
If(VSTATUS[SAT] == 1){
   VROL = sat([mem32][15:0] + [mem32][31:16]);
   VROH = sat([mem32][15:0] - [mem32][31:16]);
}else {
   VROL = [mem32][15:0] + [mem32][31:16];
   VROH = [mem32][15:0] - [mem32][31:16];
}
```

Flags

This instruction modifies the following bits in the VSTATUS register:

OVFR is set if overflow is detected in the computation of 16-bit signed result

Pipeline

This is a single-cycle instruction.

Example

```
; Viterbi K=4 CR = 1/2
;
;etc ...
 VSETK
          #CONSTRAINT_LENGTH ; Set constraint length
          AR1, #SMETRICINIT_OFFSET
 MOV
 VSMINIT *+XAR4[AR1]
                                ; Initialize the state metrics
          AR1, #NBITS_OFFSET
 VOM
          AL, *+XAR4[AR1]
 MOV
          AL, 2
 LSR
 SUBB
          AL, #2
 VOM
           AR3, AL
                                ; Initialize the BMSEL register
                                 ; for butterfly 0 to K-1
 MOVL
          XAR6, *+XAR4[BMSELINIT_OFFSET]
 VMOV32
          VR2, *XAR6 ; Initialize BMSEL for
                                 ; butterfly 0 to 7
 VITBM2
         VR0, *XAR0++
                                 ; Calculate and store BMs in
                                 ; VROL and VROH
;etc ...
```

See also

VITBM2 VR0

VITBM2 VR0 || VMOV32 VR2, mem32 VITSTAGE_VITBM2_VR0_mem32



VITBM2 VR0 || VMOV32 VR2, mem32 Code Rate 1:2 Branch Metric Calculation with Parallel Load

Operands

Before the operation, the inputs are loaded into the registers as shown below. Each operand for the branch metric calculation is 16-bits.

Input Register	Value
VR0L	16-bit decoder input 0
VR0H	16-bit decoder input 1
[mem32]	pointer to 32-bit memory location.

The result of the operation is stored in VR0 as shown below:

Output Register	Value
VR0L	16-bit branch metric 0 = VR0L + VR0H
VR0H	16-bit branch metric 1 = VR0L - VR0L
VR2	contents of memory pointed to by [mem32]

Opcode

```
LSW: 1110 0011 1111 1100
MSW: 0000 0000 mem32
```

Description

Branch metric calculation for a code rate of 1/2 with parallel register load.

```
// SAT is VSTATUS[SAT]
// VROL is decoder input 0
// VROH is decoder input 1
// Calculate the branch metrics by performing 16-bit signed
// addition and subtraction
                          // VROL = branch metric 0
  VR0L = VR0L + VR0H;
  VROH = VROL - VROL;
                          // VROH = branch metric 1
  if (SAT == 1)
  {
     sat16(VROL);
     sat16(VROH);
  VR2 = [mem32]
                           // Load VR2L and VR2H with the next state metrics
```

Flags

This instruction sets the real overflow flag, VSTATUS[OVFR] in the event of an overflow or underflow.

Pipeline

Both operations complete in a single cycle.

Example

See also

VITBM2 VR0

VITBM3 VR0, VR1, VR2

VITBM3 VR0, VR1, VR2 || VMOV32 VR2, mem32



VITBM3 VR0, VR1, VR2 Code Rate 1:3 Branch Metric Calculation

Operands

Before the operation, the inputs are loaded into the registers as shown below. Each operand for the branch metric calculation is 16-bits.

Input Register	Value
VR0L	16-bit decoder input 0
VR1L	16-bit decoder input 1
VR2L	16-bit decoder input 2

The result of the operation is stored in VR0 and VR1 as shown below:

Output Register	Value
VR0L	16-bit branch metric 0 = VR0L + VR1L + VR2L
VR0H	16-bit branch metric 1 = VR0L + VR1L - VR2L
VR1L	16-bit branch metric 2 = VR0L - VR1L + VR2L
VR1H	16-bit branch metric 3 = VR0L - VR1L - VR2L

Opcode

LSW: 1110 0101 0000 1101

Description

Calculate the four branch metrics for a code rate of 1/3.

```
// SAT is VSTATUS[SAT]
// VROL is decoder input 0
// VR1L is decoder input 1
// VR2L is decoder input 2
// Calculate the branch metrics by performing 16-bit signed
// addition and subtraction
//
   VROL = VROL + VR1L + VR2L; // VROL = branch Metric 0
   \label{eq:vr0h} {\tt VR0H = VR0L + VR1L - VR2L;} \qquad // \ {\tt VR0H = branch \ Metric \ 1}
   VR1L = VR0L - VR1L + VR2L;  // VR1L = branch Metric 2
   VR1H = VR0L - VR1L - VR2L;
                                 // VR1H = branch Metric 3
   if(SAT == 1)
      sat16(VROL);
      sat16(VROH);
      sat16(VR1L);
      sat16(VR1H);
   }
```

Flags

This instruction sets the real overflow flag, VSTATUS[OVFR] in the event of an overflow or underflow.

Pipeline

This is a 2p-cycle instruction. The instruction following VITBM3 must not use VR0 or VR1.

Example

Refer to the example for VITDHADDSUB VR4, VR3, VR2, VRa.

See also

VITBM2 VR0

VITBM3 VR0, VR1, VR2 || VMOV32 VR2, mem32

VITBM2 VR0 || VMOV32 VR2, mem32

www.ti.com

VITBM3 VR0, VR1, VR2 || VMOV32 VR2, mem32 — Code Rate 1:3 Branch Metric Calculation with Parallel Load

VITBM3 VR0, VR1, VR2 || VMOV32 VR2, mem32 Code Rate 1:3 Branch Metric Calculation with Parallel Load

Operands

Before the operation, the inputs are loaded into the registers as shown below. Each operand for the branch metric calculation is 16-bits.

Input Register	Value
VR0L	16-bit decoder input 0
VR1L	16-bit decoder input 1
[mem32]	pointer to a 32-bit memory location

The result of the operation is stored in VR0 and VR1 and VR2 as shown below:

Output Register	Value
VR0L	16-bit branch metric 0 = VR0L + VR1L + VR2L
VR0H	16-bit branch metric 1 = VR0L + VR1L - VR2L
VR1L	16-bit branch metric 2 = VR0L - VR1L + VR2
VR1H	16-bit branch metric 3 = VR0L - VR1L - VR2L
VR2	Contents of the memory pointed to by [mem32]

Opcode

```
LSW: 1110 0011 1111 1101 MSW: 0000 0000 mem32
```

Description

Calculate the four branch metrics for a code rate of 1/3 with parallel register load.

```
// SAT is VSTATUS[SAT]
// VROL is decoder input 0
// VR1L is decoder input 1
// VR2L is decoder input 2
//
// Calculate the branch metrics by performing 16-bit signed
// addition and subtraction
//
  VROL = VROL + VR1L + VR2L;  // VROL = branch Metric 0
  VROH = VROL + VR1L - VR2L; // VROH = branch Metric 1
  VR1L = VR0L - VR1L + VR2L; // VR1L = branch Metric 2
  VR1H = VR0L - VR1L - VR2L; // VR1H = branch Metric 3
  if(SAT == 1)
     sat16(VR0L);
     sat16(VROH);
     sat16(VR1L);
     sat16(VR1H);
  VR2 = [mem32];
```

Flags

This instruction sets the real overflow flag, VSTATUS[OVFR] in the event of an overflow or underflow.

Pipeline

This is a 2p/1-cycle instruction. The VBITM3 operation takes 2p cycles and the VMOV32 completes in a single cycle. The next instruction must not use VR0 or VR1.

Example

Refer to the example for VITDHADDSUB VR4, VR3, VR2, VRa.

See also

VITBM2 VR0

VITBM2 VR0 || VMOV32 VR2, mem32



VITBM3 VR0L, VR1L, mem16 Branch Metric Calculation CR=1/3

Operands

Input	Output
VR0L	Low word of the general purpose register VR0
VR1L	Low word of the general purpose register VR1
mem16	Pointer to 16-bit memory location

Opcode

```
LSW: 1110 0010 1100 0101 MSW: 0000 0010 mem16
```

Description

Calculates four Branch-Metrics (BMs) for CR = 1/3

```
If(VSTATUS[SAT] == 1){
   VR0L = sat(VR0L + VR1L + [mem16]);
   VR0H = sat(VR0L + VR1L - [mem16]);
   VR1L = sat(VR0L - VR1L + [mem16]);
   VR1H = sat(VR0L - VR1L - [mem16]);
}else {
   VR0L = VR0L + VR1L + [mem16];
   VR0H = VR0L + VR1L - [mem16];
   VR1L = VR0L - VR1L + [mem16];
   VR1L = VR0L - VR1L - [mem16];
   VR1H = VR0L - VR1L - [mem16];
}
```

Flags

This instruction modifies the following bits in the VSTATUS register.

OVFR is set if overflow is detected in the computation of a 16-bit signed result

Pipeline

This is a single-cycle instruction.

Example

See the example for VITSTAGE || VMOV16 VROL, mem16

See also

VITBM3

VITBM3 VR0, VR1, VR2 || VMOV32 VR2, mem32



VITDHADDSUB VR4, VR3, VR2, VRa Viterbi Double Add and Subtract, High

Operands

Before the operation, the inputs are loaded into the registers as shown below. This operation uses the branch metric stored in VRaH.

Input Register	Value
VR2L	16-bit state metric 0
VR2H	16-bit state metric 1
VRaH	Branch metric 1. VRa must be VR0 or VR1.

The result of the operation is stored in VR3 and VR4 as shown below:

Output Register	Value
VR3L	16-bit path metric 0 = VR2L + VRaH
VR3H	16-bit path metric 1 = VR2H - VRaH
VR4L	16-bit path metric 2 = VR2L - VRaH
VR4H	16-bit path metric 3 = VR2H +VRaH

Opcode

LSW: 1110 0101 0111 aaaa

Description

Viterbi high add and subtract. This instruction is used to calculate four path metrics.

```
// Calculate the four path metrics by performing 16-bit signed
// addition and subtraction
//
\ensuremath{//} Before this operation VR2L and VR2H are loaded with the state
// metrics and VRaH with the branch metric.
11
   VR3H = VR2H - VRaH // Path metric 1
   VR4L = VR2L - VRaH // Path metric 2
   VR4H = VR2H + VRaH
                       // Path metric 3
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

```
; Example Viterbi decoder code fragment
; Viterbi butterfly calculations
; Loop once for each decoder input pair
; Branch metrics = BMO and BM1
; XAR5 points to the input stream to the decoder
 . . .
loop:
  VMOV32 VR0, *XAR5++
                               ; Load two inputs into VROL, VROH
  VITBM2 VR0
                                ; VR0L = BM0 VR0H = BM1
| VMOV32 VR2, *XAR1++
                                ; Load previous state metrics
; 2 cycle Viterbi butterfly
  VITDLADDSUB VR4, VR3, VR2, VR0 ; Perform add/sub
  VITLSEL VR6, VR5, VR4, VR3 ; Perform compare/select
| VMOV32 VR2, *XAR1++
                             ; Load previous state metrics
; 2 cycle Viterbi butterfly, next stage
  VITDHADDSUB VR4, VR3, VR2, VR0
```



```
VITHSEL VR6,VR5,VR4,VR3
|| VMOV32 VR2, *XAR1++

;
; 2 cycle Viterbi butterfly, next stage;
  VITDLADDSUB VR4,VR3,VR2,VR0
|| VMOV32 *XAR2++, VR5
    ...
    ...
    ...
```

See also

VITDHSUBADD VR4, VR3, VR2, VRa VITDLADDSUB VR4, VR3, VR2, VRa VITDLSUBADD VR4, VR3, VR2, VRa



www.ti.com VITDHADDSUB VR4, VR3, VR2, VRa || VMOV32 mem32, VRb — Viterbi Add and Subtract High with Parallel

VITDHADDSUB VR4, VR3, VR2, VRa || VMOV32 mem32, VRb Viterbi Add and Subtract High with Parallel Store

Operands

Before the operation, the inputs are loaded into the registers as shown below. This operation uses the branch metric stored in VRaH.

Input Register	Value
VR2L	16-bit state metric 0
VR2H	16-bit state metric 1
VRaH	Branch metric 1. VRa must be VR0 or VR1.
VRb	Value to be stored. VRb can be VR5, VR6, VR7 or VR8.

The result of the operation is stored in VR3 and VR4 as shown below:

Output Register	Value
VR3L	16-bit path metric 0 = VR2L + VRaH
VR3H	16-bit path metric 1 = VR2H - VRaH
VR4L	16-bit path metric 2 = VR2L - VRaH
VR4H	16-bit path metric 3 = VR2H +VRaH
[mem32]	Contents of VRb. VRb can be VR5, VR6, VR7 or VR8.

Opcode

LSW: 1110 0010 0000 1001 MSW: bbbb aaaa mem32

Description

Viterbi high add and subtract. This instruction is used to calculate four path metrics.

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

See also

VITDHSUBADD VR4, VR3, VR2, VRa VITDLADDSUB VR4, VR3, VR2, VRa VITDLSUBADD VR4, VR3, VR2, VRa



VITDHSUBADD VR4, VR3, VR2, VRa Viterbi Add and Subtract Low

Operands

Before the operation, the inputs are loaded into the registers as shown below. This operation uses the branch metric stored in VRaL.

Input Register	Value
VR2L	16-bit state metric 0
VR2H	16-bit state metric 1
VRaL	Branch metric 0. VRa must be VR0 or VR1.

The result of the operation is 4 path metrics stored in VR3 and VR4 as shown below:

Output Register	Value
VR3L	16-bit path metric 0 = VR2L - VRaH
VR3H	16-bit path metric 1 = VR2H + VRaH
VR4L	16-bit path metric 2 = VR2L + VRaH
VR4H	16-bit path metric 3 = VR2H - VRaL

Opcode

LSW: 1110 0101 1111 aaaa

Description

This instruction is used to calculate four path metrics in the Viterbi butterfly. This operation uses the branch metric stored in VRaL.

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

Refer to the example for VITDHADDSUB VR4, VR3, VR2, VRa.

See also

VITDHADDSUB VR4, VR3, VR2, VRa VITDHSUBADD VR4, VR3, VR2, VRa VITDLSUBADD VR4, VR3, VR2, VRa



www.ti.com VITDHSUBADD VR4, VR3, VR2, VRa || VMOV32 mem32, VRb — Viterbi Subtract and Add, High with Parallel

VITDHSUBADD VR4, VR3, VR2, VRa || VMOV32 mem32, VRb Viterbi Subtract and Add, High with Parallel Store

Operands

Before the operation, the inputs are loaded into the registers as shown below. This operation uses the branch metric stored in VRaH.

Input Register	Value
VR2L	16-bit state metric 0
VR2H	16-bit state metric 1
VRaH	Branch metric 1. VRa must be VR0 or VR1.
VRb	Contents to be stored. VRb can be VR5, VR6, VR7 or VR8.

The result of the operation is stored in VR3 and VR4 as shown below:

Output Register	Value
VR3L	16-bit path metric 0 = VR2L -VRaH
VR3H	16-bit path metric 1 = VR2H + VRaH
VR4L	16-bit path metric 2 = VR2L + VRaH
VR4H	16-bit path metric 3 = VR2H - VRaH
[mem32]	Contents of VRb. VRb can be VR5, VR6, VR7 or VR8.

Opcode

```
LSW: 1110 0010 0000 1011 MSW: bbbb aaaa mem32
```

Description

Viterbi high subtract and add. This instruction is used to calculate four path metrics.

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

See also

VITDHADDSUB VR4, VR3, VR2, VRa VITDLADDSUB VR4, VR3, VR2, VRa VITDLSUBADD VR4, VR3, VR2, VRa



VITDLADDSUB VR4, VR3, VR2, VRa Viterbi Add and Subtract Low

Operands

Before the operation, the inputs are loaded into the registers as shown below. This operation uses the branch metric stored in VRaL.

Input Register	Value
VR2L	16-bit state metric 0
VR2H	16-bit state metric 1
VRaL	Branch metric 0. VRa must be VR0 or VR1.

The result of the operation is 4 path metrics stored in VR3 and VR4 as shown below:

Output Register	Value
VR3L	16-bit path metric 0 = VR2L + VRaH
VR3H	16-bit path metric 1 = VR2H - VRaH
VR4L	16-bit path metric 2 = VR2L - VRaH
VR4H	16-bit path metric 3 = VR2H + VRaL

Opcode

LSW: 1110 0101 0011 aaaa

Description

This instruction is used to calculate four path metrics in the Viterbi butterfly. This operation uses the branch metric stored in VRaL.

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

Refer to the example for VITDHADDSUB VR4, VR3, VR2, VRa.

See also

VITDHADDSUB VR4, VR3, VR2, VRa VITDHSUBADD VR4, VR3, VR2, VRa VITDLSUBADD VR4, VR3, VR2, VRa



www.ti.com VITDLADDSUB VR4, VR3, VR2, VRa | VMOV32 mem32, VRb — Viterbi Add and Subtract Low with Parallel

VITDLADDSUB VR4, VR3, VR2, VRa || VMOV32 mem32, VRb Viterbi Add and Subtract Low with Parallel Load

Operands

Before the operation, the inputs are loaded into the registers as shown below. This operation uses the branch metric stored in VRaL.

Input Register	Value
VR2L	16-bit state metric 0
VR2H	16-bit state metric 1
VRaL	Branch metric 0. VRa can be VR0 or VR1.
VRb	Contents to be stored to memory

The result of the operation is four path metrics stored in VR3 and VR4 as shown below:

Output Register	Value
VR3L	16-bit path metric 0 = VR2L + VRaH
VR3H	16-bit path metric 1 = VR2H - VRaH
VR4L	16-bit path metric 2 = VR2L - VRaH
VR4H	16-bit path metric 3 = VR2H + VRaL
[mem32]	Contents of VRb. VRb can be VR5, VR6, VR7 or VR8.

Opcode

```
LSW: 1110 0010 0000 1000 MSW: bbbb aaaa mem32
```

Description

This instruction is used to calculate four path metrics in the Viterbi butterfly. This operation uses the branch metric stored in VRaL.

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

Refer to the example for VITDHADDSUB VR4, VR3, VR2, VRa.

See also

VITDHADDSUB VR4, VR3, VR2, VRa VITDHSUBADD VR4, VR3, VR2, VRa VITDLSUBADD VR4, VR3, VR2, VRa



VITDLSUBADD VR4, VR3, VR2, VRa Viterbi Subtract and Add Low

Operands

Before the operation, the inputs are loaded into the registers as shown below. This operation uses the branch metric stored in VRaL.

Input Register	Value
VR2L	16-bit state metric 0
VR2H	16-bit state metric 1
VRaL	Branch metric 0. VRa must be VR0 or VR1.

The result of the operation is four path metrics stored in VR3 and VR4 as shown below:

Output Register	Value
VR3L	16-bit path metric 0= VR2L - VRaH
VR3H	16-bit path metric 1 = VR2H + VRaH
VR4L	16-bit path metric 2 = VR2L + VRaH
VR4H	16-bit path metric 3 = VR2H - VRaL

Opcode

LSW: 1110 0101 1110 aaaa

Description

This instruction is used to calculate four path metrics in the Viterbi butterfly. This operation uses the branch metric stored in VRaL.

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

Refer to the example for VITDHADDSUB VR4, VR3, VR2, VRa.

See also

VITDHADDSUB VR4, VR3, VR2, VRa VITDHSUBADD VR4, VR3, VR2, VRa VITDLADDSUB VR4, VR3, VR2, VRa



www.ti.com VITDLSUBADD VR4, VR3, VR2, VRa || VMOV32 mem32, VRb — Viterbi Subtract and Add, Low with Parallel

VITDLSUBADD VR4, VR3, VR2, VRa || VMOV32 mem32, VRb Viterbi Subtract and Add, Low with Parallel Store

Operands

Before the operation, the inputs are loaded into the registers as shown below. This operation uses the branch metric stored in VRaL.

Input Register	Value
VR2L	16-bit state metric 0
VR2H	16-bit state metric 1
VRaL	Branch metric 0. VRa must be VR0 or VR1.
VRb	Value to be stored. VRb can be VR5, VR6, VR7 or VR8.

The result of the operation is 4 path metrics stored in VR3 and VR4 as shown below:

Output Register	Value
VR3L	16-bit path metric 0= VR2L - VRaH
VR3H	16-bit path metric 1 = VR2H + VRaH
VR4L	16-bit path metric 2 = VR2L + VRaH
VR4H	16-bit path metric 3 = VR2H - VRaL
[mem32]	Contents of VRb. VRb can be VR5, VR6, VR7 or VR8.

Opcode

```
LSW: 1110 0010 0000 1010 MSW: bbbb aaaa mem32
```

Description

This instruction is used to calculate four path metrics in the Viterbi butterfly. This operation uses the branch metric stored in VRaL.

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

Refer to the example for VITDHADDSUB VR4, VR3, VR2, VRa.

See also

VITDHADDSUB VR4, VR3, VR2, VRa VITDHSUBADD VR4, VR3, VR2, VRa VITDLADDSUB VR4, VR3, VR2, VRa



VITHSEL VRa, VRb, VR4, VR3 Viterbi Select High

Operands

Before the operation, the path metrics are loaded into the registers as shown below. Typically this will have been done using a Viterbi AddSub or SubAdd instruction.

Input Register	Value
VR3L	16-bit path metric 0
VR3H	16-bit path metric 1
VR4L	16-bit path metric 2
VR4H	16-bit path metric 3

The result of the operation is the new state metrics stored in VRa and VRb as shown below:

Output Register	Value
VRaH	16-bit state metric 0. VRa can be VR6 or VR8.
VRbH	16-bit state metric 1. VRb can be VR5 or VR7.
VT0	The transition bit is appended to the end of the register.
VT1	The transition bit is appended to the end of the register.

Opcode

```
LSW: 1110 0110 1111 0111 MSW: 0000 0000 bbbb aaaa
```

Description

This instruction computes the new state metrics of a Viterbi butterfly operation and stores them in the higher 16 bits of the VRa and VRb registers. To instead load the state metrics into the low 16-bits use the VITLSEL instruction.

```
T0 = T0 << 1
                // Shift previous transition bits left
if (VR3L > VR3H)
{
  VRbH = VR3L; // New state metric 0
  T0[0:0] = 0; // Store the transition bit
else
{
  VRbH = VR3H; // New state metric 0
  T0[0:0] = 1; // Store the transition bit
}
T1 = T1 << 1
                // Shift previous transition bits left
if (VR4L > VR4H)
  VRaH = VR4L; // New state metric 1
  T1[0:0] = 0; // Store the transition bit
else
  VRaH = VR4H; // New state metric 1
  T1[0:0] = 1; // Store the transition bit
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

Refer to the example for VITDHADDSUB VR4, VR3, VR2, VRa.

See also

VITLSEL VRa, VRb, VR4, VR3



VITHSEL VRa, VRb, VR4, VR3 | VMOV32 VR2, mem32 Viterbi Select High with Parallel Load

Operands

Before the operation, the path metrics are loaded into the registers as shown below. Typically this will have been done using a Viterbi AddSub or SubAdd instruction.

Input Register	Value
VR3L	16-bit path metric 0
VR3H	16-bit path metric 1
VR4L	16-bit path metric 2
VR4H	16-bit path metric 3
[mem32]	pointer to 32-bit memory location.

The result of the operation is the new state metrics stored in VRa and VRb as shown below:

Output Register	Value
VRaH	16-bit state metric 0. VRa can be VR6 or VR8.
VRbH	16-bit state metric 1. VRb can be VR5 or VR7.
VT0	The transition bit is appended to the end of the register.
VT1	The transition bit is appended to the end of the register.
VR2	Contents of the memory pointed to by [mem32].

Opcode

```
LSW: 1110 0011 1111 1111 MSW: bbbb aaaa mem32
```

Description

This instruction computes the new state metrics of a Viterbi butterfly operation and stores them in the higher 16-bits of the VRa and VRb registers. To instead load the state metrics into the low 16-bits use the VITLSEL instruction.

```
T0 = T0 << 1
                 // Shift previous transition bits left
if (VR3L > VR3H)
   VRbH = VR3L; // New state metric 0
   T0[0:0] = 0; // Store the transition bit
}
else
   VRbH = VR3H; // New state metric 0
   T0[0:0] = 1; // Store the transition bit
T1 = T1 << 1
                // Shift previous transition bits left
if (VR4L > VR4H)
   VRaH = VR4L; // New state metric 1
   T1[0:0] = 0; // Store the transition bit
else
   VRaH = VR4H; // New state metric 1
   T1[0:0] = 1; // Store the transition bit
VR2 = [mem32]; // Load VR2
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

Refer to the example for VITDHADDSUB VR4, VR3, VR2, VRa.

See also

VITLSEL VRa, VRb, VR4, VR3



VITLSEL VRa, VRb, VR4, VR3 Viterbi Select, Low Word

Operands

Before the operation, the path metrics are loaded into the registers as shown below. Typically this will have been done using a Viterbi AddSub or SubAdd instruction.

Input Register	Value
VR3L	16-bit path metric 0
VR3H	16-bit path metric 1
VR4L	16-bit path metric 2
VR4H	16-bit path metric 3

The result of the operation is the new state metrics stored in VRa and VRb as shown below:

Output Register	Value
VRaL	16-bit state metric 0. VRa can be VR6 or VR8.
VRbL	16-bit state metric 1. VRb can be VR5 or VR7.
VT0	The transition bit is appended to the end of the register.
VT1	The transition bit is appended to the end of the register.

Opcode

```
LSW: 1110 0110 1111 0110 MSW: 0000 0000 bbbb aaaa
```

Description

This instruction computes the new state metrics of a Viterbi butterfly operation and stores them in the higher 16-bits of the VRa and VRb registers. To instead load the state metrics into the low 16-bits use the VITHSEL instruction.

```
T0 = T0 << 1
                 // Shift previous transition bits left
if (VR3L > VR3H)
{
  VRbL = VR3L; // New state metric 0
  T0[0:0] = 0; // Store the transition bit
}
else
{
  VRbL = VR3H; // New state metric 0
  T0[0:0] = 1; // Store the transition bit
T1 = T1 << 1
                 // Shift previous transition bits left
if (VR4L > VR4H)
  VRaL = VR4L; // New state metric 1
  T1[0:0] = 0; // Store the transition bit
}
else
  VRaL = VR4H; // New state metric 1
  T1[0:0] = 1; // Store the transition bit
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

Refer to the example for VITDHADDSUB VR4, VR3, VR2, VRa.

See also

VITHSEL VRa, VRb, VR4, VR3



VITLSEL VRa, VRb, VR4, VR3 | VMOV32 VR2, mem32 Viterbi Select Low with Parallel Load

Operands

Before the operation, the path metrics are loaded into the registers as shown below. Typically this will have been done using a Viterbi AddSub or SubAdd instruction.

Input Register	Value
VR3L	16-bit path metric 0
VR3H	16-bit path metric 1
VR4L	16-bit path metric 2
VR4H	16-bit path metric 3
mem32	Pointer to 32-bit memory location.

The result of the operation is the new state metrics stored in VRa and VRb as shown below:

Output Register	Value
VRaL	16-bit state metric 0. VRa can be VR6 or VR8.
VRbL	16-bit state metric 1. VRb can be VR5 or VR7.
VT0	The transition bit is appended to the end of the register.
VT1	The transition bit is appended to the end of the register.
VR2	Contents of 32-bit memory pointed to by mem32.

Opcode

```
LSW: 1110 0011 1111 1110
MSW: bbbb aaaa mem32
```

Description

This instruction computes the new state metrics of a Viterbi butterfly operation and stores them in the higher 16-bits of the VRa and VRb registers. To instead load the state metrics into the low 16-bits use the VITHSEL instruction. In parallel the VR2 register is loaded with the contents of memory pointed to by [mem32].

```
T0 = T0 << 1
                 // Shift previous transition bits left
if (VR3L > VR3H)
  VRbL = VR3L; // New state metric 0
  T0[0:0] = 0; // Store the transition bit
}
else
  VRbL = VR3H; // New state metric 0
  T0[0:0] = 1; // Store the transition bit
T1 = T1 << 1
                // Shift previous transition bits left
if (VR4L > VR4H)
{
  VRaL = VR4L; // New state metric 1
  T1[0:0] = 0; // Store the transition bit
else
{
  VRaL = VR4H; // New state metric 1
  T1[0:0] = 1; // Store the transition bit
VR2 = [mem32]
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

Refer to the example for VITDHADDSUB VR4, VR3, VR2, VRa.



See also

VITHSEL VRa, VRb, VR4, VR3



VITSTAGE

Parallel Butterfly Computation

Operands

None

Opcode

LSW: 1110 0101 0010 0110

Description

VITSTAGE instruction performs 32 viterbi butterflies in a single cycle. This instructions does the following:

- Depends on the Initial 64 State Metrics of the current stage stored in registers VSM0 to VSM63
- Depends on the Branch Metrics Select configuration stored in registers VR2 to VR5
- Depends on the Computed Branch Metrics of the current stage stored in registers VR0 and VR1
- Computes the State Metrics for the next stage and updates registers VSM0 to VSM63. The 16-bit signed result of the computation is saturated if VSTATUS[SAT]
 == 1
- Computes transition bits for all 64 states and updates registers VT0 and VT1

Flags

This instruction modifies the following bits in the VSTATUS register.

OVFR is set if overflow is detected in the computation of a 16-bit signed result

Pipeline

This is a single-cycle instruction.

Example

```
; Viterbi K=4 CR = 1/2
;etc ...
 VSETK
         #CONSTRAINT_LENGTH ; Set constraint length
 MOV
          AR1, #SMETRICINIT_OFFSET
 VSMINIT *+XAR4[AR1]
                             ; Initialize the state metrics
          AR1, #NBITS_OFFSET
 MOV
 MOV
          AL, *+XAR4[AR1]
          AL, 2
 LSR
 SUBB
          AL, #2
          AR3, AL
                                ; Initialize the BMSEL register
 MOV
                                ; for butterfly 0 to K-1
         XAR6, *+XAR4[BMSELINIT_OFFSET]
 MOVL
 VMOV32 VR2, *XAR6
                               ; Initialize BMSEL for
                               ; butterfly 0 to 7
          VR0, *XAR0++
 VITBM2
                               ; Calculate and store BMs in
                                ; VROL and VROH
 .aliqn 2
        _VITERBI_runK4CR12_stageAandB, AR3
_VITERBI_runK4CR12_stageA:
 VITSTAGE
                                ; Compute NSTATES/2 butterflies
                               ; in parallel,
 VITBM2 VR0, *XAR0++
                               ; compute branch metrics for
                               ; next butterfly
          *XAR2++, VT1
 VMOV32
                               ; Store VT1
 VMOV32
          *XAR2++, VT0
                                ; Store VT0
;etc ...
```

See also

VITSTAGE || VITBM2 VR0, mem32 VITSTAGE || VMOV16 VROL, mem16 VITSTAGE || VITBM2 VR0, mem32 — Parallel Butterfly Computation with Parallel Branch Metric Calculation CR=1/2 www.ti.com

VITSTAGE || VITBM2 VR0, mem32 Parallel Butterfly Computation with Parallel Branch Metric Calculation CR=1/2

Operands

Input	Output
VR0	Destination register
mem32	Pointer to 32-bit memory location

Opcode

```
LSW: 1110 0010 1000 0000 MSW: 0000 0010 mem32
```

Description

VITSTAGE instruction performs 32 viterbi butterflies in a single cycle. This instructions does the following:

- Depends on the Initial 64 State Metrics of the current stage stored in registers VSM0 to VSM63
- Depends on the Branch Metrics Select configuration stored in registers VR2 to VR5
- Depends on the Computed Branch Metrics of the current stage stored in registers VR0 and VR1
- Computes the State Metrics for the next stage and updates registers VSM0 to VSM63. The 16-bit signed result of the computation is saturated if VSTATUS[SAT]
- Computes transition bits for all 64 states and updates registers VT0 and VT1

```
VROL = [mem32][15:0] + [mem32][31:16]
VROH = [mem32][15:0] - [mem32][31:16]
```

Flags

This instruction modifies the following bits in the VSTATUS register.

OVFR is set if overflow is detected in the computation of a 16-bit signed result

Pipeline

This is a single-cycle instruction.

Example

```
; Viterbi K=4 CR = 1/2
;etc ...
 VSETK #CONSTRAINT_LENGTH ; Set constraint length
          AR1, #SMETRICINIT_OFFSET
 VOM
                            ; Initialize the state metrics
 VSMINIT *+XAR4[AR1]
 MOV
          AR1, #NBITS_OFFSET
 VOM
          AL, *+XAR4[AR1]
          AL, 2
 LSR
 SUBB
          AL, #2
          AR3, AL
                                 ; Initialize the BMSEL register
 VOM
                                 ; for butterfly 0 to K-1
 MOVL
         XAR6, *+XAR4[BMSELINIT_OFFSET]
 VMOV32 VR2, *XAR6 ; Initialize BMSEL for
                                 ; butterfly 0 to 7
 VITBM2
          VR0, *XAR0++
                                 ; Calculate and store BMs in
                                 ; VROL and VROH
  .align 2
 RPTB
         _VITERBI_runK4CR12_stageAandB, AR3
_VITERBI_runK4CR12_stageA:
 VITSTAGE
                                 ; Compute NSTATES/2 butterflies
                                ; in parallel,
VITBM2 VR0, *XAR0++
                                ; compute branch metrics for
                                ; next butterfly
 VMOV32
          *XAR2++, VT1
                                 ; Store VT1
          *XAR2++, VT0
 VMOV32
                                 ; Store VTO
```



www.ti.com VITSTAGE || VITBM2 VR0, mem32 — Parallel Butterfly Computation with Parallel Branch Metric Calculation

;etc ...;

See also VITSTAGE

VITSTAGE || VMOV16 VROL, mem16



VITSTAGE | VMOV16 VR0L, mem16 Parallel Butterfly Computation with Parallel Load

Operands

Input	Output
VR0L	Low word of the destination register
mem16	Pointer to 16-bit memory location

Opcode

```
LSW: 1110 0010 1100 0101 MSW: 0000 0011 mem16
```

Description

VITSTAGE instruction performs 32 viterbi butterflies in a single cycle. This instructions does the following:

- Depends on the Initial 64 State Metrics of the current stage stored in registers VSM0 to VSM63
- Depends on the Branch Metrics Select configuration stored in registers VR2 to VR5
- Depends on the Computed Branch Metrics of the current stage stored in registers VR0 and VR1
- Computes the State Metrics for the next stage and updates registers VSM0 to VSM63. The 16-bit signed result of the computation is saturated if VSTATUS[SAT]
- Computes transition bits for all 64 states and updates registers VT0 and VT1

```
VR0L = [mem16]
```

Flags

This instruction modifies the following bits in the VSTATUS register.

OVFR is set if overflow is detected in the computation of a 16-bit signed result

Pipeline

This is a single-cycle instruction.

Example

```
; Viterbi K=7 CR = 1/3
;etc ...
_VITERBI_runK7CR13_stageA:
 VITSTAGE
                                ; Compute NSTATES/2 butterflies in
            VROL, *XARO++ ; Load LLR(A) for next butterfly
VR1L, *XARO++ ; Load LLR(B) for next butterfly
||VMOV16
  VMOV16
            VROL, VR1L, *XARO++; Load LLR(C) and compute branch
  VITBM3
                                 ; metric for next butterfly
 VMOV32 *XAR2++, VT1
                                ; Store VT1
          *XAR2++, VT0
 VMOV32
                                ; Store VT0
;etc ...
```

See also

VITSTAGE

VITSTAGE || VITBM2 VR0, mem32



VMOV32 VSM (k+1):VSM(k), mem32 Load Consecutive State Metrics

Operands

Input	Output
VSM(k+1):VSM(k)	Consecutive State Metric Registers (VSM1:VSM0 VSM63:VSM62)
mem32	Pointer to 32-bit memory location

Opcode LSW: 1110 0010 1000 0000

MSW: 001n nnnn mem32

Description Load a pair of Consecutive State Metrics from memory:

VSM(k+1) = [mem32][31:16];VSM(k) = [mem32][15:0];

Note:

n-k/2, used in opcode assignment

· k is always even

Flags This instruction does not affect any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example VMOV32 VSM63: VSM62, *XAR7++

See also VMOV32 mem32, VSM (k+1):VSM(k)



VMOV32 mem32, VSM (k+1):VSM(k) Store Consecutive State Metrics

Operands

 Input
 Output

 VSM(k+1):VSM(k)
 Consecutive State Metric Registers (VSM1:VSM0 VSM63:VSM62)

 mem32
 Pointer to 32-bit memory location

Opcode LSW: 1110 0010 0000 1110

MSW: 000n nnnn mem32

Description Store a pair of Consecutive State Metrics from memory:

[mem32] [31:16] = VSM(k+1); [mem32] [15:0] = VSM(k);

NOTE:

• n-k/2, used in opcode assignment

k is always even

Flags This instruction does not affect any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example VMOV32 *XAR7++ VSM63: VSM62

See also VMOV32 VSM (k+1):VSM(k), mem32



VSETK #3-bit Set Constraint Length for Viterbi Operation

Operands

InputOutput#3-bit3-bit immediate value

Opcode

LSW: 1110 0110 1111 0010 MSW: 0000 1001 0000 0III

Description VSTATUS[K] = #3-bit Immediate

Flags This instruction does not affect any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also



VSMINIT mem16 State Metrics Register initialization

Operands

Input Output
mem16 Pointer to 16-bit memory location

Opcode

LSW: 1111 0010 1100 0101 MSW: 0000 0001 mem16

Description Initializes the state metric registers.

VSM0 = 0

VSM1 to VSM63 = [mem16]

Flags This instruction does not affect any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example VSMINIT *+XAR4[AR1] ; Initialize the state metrics

See also



VTCLEAR Clear Transition Bit Registers

Operands

none

Opcode LSW: 1110 0101 0010 1001

Description Clear the VT0 and VT1 registers.

VT0 = 0; VT1 = 0;

Flags This instruction does not modify any flags in the VSTATUS register.

Pipeline This is a single-cycle instruction.

Example

See also VCLEARALL

VCLEAR VRa



VTRACE mem32, VR0, VT0, VT1 Viterbi Traceback, Store to Memory

Operands

Before the operation, the path metrics are loaded into the registers as shown below using a Viterbi AddSub or SubAdd instruction.

Input Register	Value
VT0	transition bit register 0
VT1	transition bit register 1
VR0	Initial value is zero. After the first VTRACE, this contains information from the previous trace-back.

The result of the operation is the new state metrics stored in VRa and VRb as shown below:

Output Register	Value
[mem32]	Traceback result from the transition bits.

Opcode

```
LSW: 1110 0010 0000 1100 MSW: 0000 0000 mem32
```

Description

Trace-back from the transition bits stored in VT0 and VT1 registers. Write the result to memory. The transition bits in the VT0 and VT1 registers are stored in the following format by the VITLSEL and VITHSEL instructions:

VT0[31]	Transition bit [State 0]
VT0[30]	Transition bit [State 1]
VT0[29]	Transition bit [State 2]
VT0[0]	Transition bit [State 31]
VT1[31]	Transition bit [State 32]
VT1[30]	Transition bit [State 33]
VT1[29]	Transition bit [State 34]
VT1[0]	Transition bit [State 63]

```
//
// Calculate the decoder output bit by performing a
// traceback from the transition bits stored in the VTO and VT1 registers
//

K = VSTATUS[K];
S = VR0[K-2:0];
VR0[31:K-1] = 0;
if (S < (1<<(K-2))){
   temp[0] = VT0[(1 << (K-2)) - 1 -S];
}else{
   temp[0] = VT1[(1 << (K-1)) - 1 -S];
}
[mem32][0] = temp;
[mem32][31:1] = 0;

VR0[K-2:0] = 2*VR0[K-2:0] + temp[0];</pre>
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.

Example

```
//
// Example traceback code fragment
```



```
//
// XAR5 points to the beginning of Decoder Output array
//
  VCLEAR VR0
  MOVL XAR5,*+XAR4[0]
// To retrieve each original message:
// Load VT0/VT1 with the stored transition values \,
// and use VTRACE instruction
//
  VMOV32 VT0, *--XAR3
  VMOV32 VT1, *--XAR3
  VTRACE *XAR5++, VR0, VT0, VT1
  VMOV32 VT0, *--XAR3
  VMOV32 VT1, *--XAR3
  VTRACE *XAR5++, VR0, VT0, VT1
   ...etc for each VTO/VT1 pair
```

See also

VTRACE VR1, VR0, VT0, VT1



VTRACE VR1, VR0, VT0, VT1 Viterbi Traceback, Store to Register

Operands

Before the operation, the path metrics are loaded into the registers as shown below using a Viterbi AddSub or SubAdd instruction.

Input Register	Value
VT0	transition bit register 0
VT1	transiton bit register 1
VR0	Initial value is zero. After the first VTRACE, this contains information from the previous trace-back.

The result of the operation is the output of the decoder stored in VR1:

Output Register	Value
VR1	Traceback result from the transition bits.

Opcode

LSW: 1110 0101 0010 1000

Description

Trace-back from the transition bits stored in VT0 and VT1 registers. Write the result to VR1. The transition bits in the VT0 and VT1 registers are stored in the following format by the VITLSEL and VITHSEL instructions:

VT0[31]	Transition bit [State 0]	
VT0[30]	Transition bit [State 1]	
VT0[29]	Transition bit [State 2]	
VT0[0]	Transition bit [State 31]	
VT1[31]	Transition bit [State 32]	
VT1[30]	Transition bit [State 33]	
VT1[29]	Transition bit [State 34]	
VT1[0]	Transition bit [State 63]	

```
// Calculate the decoder output bit by performing a
// traceback from the transition bits stored in the VTO and VT1 registers
//
   K = VSTATUS[K];
    S = VR0[K-2:0];
   VR0[31:K-1] = 0;
    if (S < (1 << (K-2))) {
        temp[0] = VT0[(1 << (K-2)) - 1 -S];
    }else{
        temp[0] = VT1[(1 << (K-1)) - 1 -S];
    }
    if(VSTATUS[OPACK]==0){
      VR1 = VR1<<1;
      VR1[0:0] = temp[0];
      VR0[K-2:0] = 2*VR0[K-2:0] + temp[0];
    }else{
      VR1 = VR1 >> 1
      VR1[31:31] = temp[0];
      VR0[K-2:0] = 2*VR0[K-2:0] + temp[0];
```

Flags

This instruction does not modify any flags in the VSTATUS register.

Pipeline

This is a single-cycle instruction.





Example

See also VTRACE mem32, VR0, VT0, VT1



VTRACE VR1, VR0, VT0, VT1 || VMOV32 VT0, mem32 Trace-back with Parallel Load

Operands

Input Register	Value
VT0	Traceback register
VT1	Traceback register
VR0	Decoded output bits register
VR1	Decoded output bits register
mem32	Pointer to 32-bit memory location

Opcode

```
LSW: 1110 0010 1011 0000 MSW: 0000 0001 mem32
```

Description

Trace-back with Parallel Load

```
K = VSTATUS[K];
S = VR0[K-2:0]; VR0[31:K-1] = 0;

if (S < (1 << (K-2)))
    temp[0] = VT0[(1<<(K-2))- 1 -S];

else
    temp[0] = VT1[(1<<(K-1))- 1 -S];

if(VSTATUS[OPACK]==0){
    VR1 = VR1<<1;
    VR1[0:0] = temp[0];
    VR0[K-2:0] = 2*VR0[K-2:0] + temp[0];
}else{
    VR1 = VR1>>1;
    VR1[31:31] = temp[0];
    VR0[K-2:0] = 2*VR0[K-2:0] + temp[0];
}

VT0 = [mem32]
```

Flags

This instruction does not affect any flags in the VSTATUS register.

Pipeline

This is a 1/1 cycle instruction. The VTRACE and VMOV32 instruction complete in a single cycle.

Example

```
; etc ...
  .align
 RPTB
               _tb_loop_ovlp2, #12
               VT0, *--XAR3
VT1, *--XAR3
 VMOV32
 VMOV32
  VTRACE
                VR1, VR0, VT0, VT1
VMOV32
               VT0, *--XAR3
           VT1, *--XAR3
VR1,VR0,VT0,VT1
  VMOV32
  VTRACE
_tb_loop_ovlp2
; etc ...
```

See also

VTRACE mem32, VR0, VT0, VT1



www.ti.com Rounding Mode

2.6 Rounding Mode

This section details the rounding operation as applied to a right shift. When the rounding mode is enabled in the VSTATUS register, .5 will be added to the right shifted intermediate value before truncation. If rounding is disabled the right shifted value is only truncated. Table 2-19 shows the bit representation of two values, 11.0 and 13.0. The columns marked Bit-1, Bit-2 and Bit-3 hold temporary bits resulting from the right shift operation.

Table 2-19. Example: Values Before Shift Right

	Bit5	Bit4	Bit3	Bit2	Bit1	Bit0	Bit-1	Bit-2	Bit -3	Value
Val A	0	0	1	0	1	1	0	0	0	11.000
Val B	0	0	0	0	0	1	0	0	0	13.000

Table 2-19 shows the intermediate values after the right shift has been applied to Val B. The columns marked Bit-1, Bit-2 and Bit-3 hold temporary bits resulting from the right shift operation.

Table 2-20. Example: Values after Shift Right

	Bit5	Bit4	Bit3	Bit2	Bit1	Bit0	Bit-1	Bit-2	Bit -3	Value
Val A	0	0	1	0	1	1	0	0	0	11.000
Val B >> 3	0	0	0	0	0	1	1	0	1	1.625

When the rounding mode is enabled, .5 will be added to the intermediate result before truncation. Table 2-21 shows the bit representation of Val A + Val (B >> 3) operation with rounding. Notice .5 is added to the intermediate shifted right value. After the addition, the bits in Bit-1, Bit-2 and Bit-3 are removed. In this case the result of the operation will be 13 which is the truncated value after rounding.

Table 2-21. Example: Addition with Right Shift and Rounding

	Bit5	Bit4	Bit3	Bit2	Bit1	Bit0	Bit-1	Bit-2	Bit -3	Value
Val A	0	0	1	0	1	1	0	0	0	11.000
Val B >> 3	0	0	0	0	0	1	1	0	1	1.625
.5	0	0	0	0	0	0	1	0	0	0 .500
Val A + Val B >> 3 + .5	0	0	1	1	0	1	0	0	1	13.125

When the rounding mode is disabled, the value is simply truncated. Table 2-22 shows the bit representation of the operation Val A + (Val B >> 3) without rounding. After the addition, the bits in Bit-1, Bit-2 and Bit-3 are removed. In this case the result of the operation will be 12 which is the truncated value without rounding.

Table 2-22. Example: Addition with Rounding After Shift Right

	Bit5	Bit4	Bit3	Bit2	Bit1	Bit0	Bit-1	Bit-2	Bit -3	Value
Val A	0	0	1	0	1	1	0	0	0	11.000
Val B >> 3	0	0	0	0	0	1	1	0	1	1.625
Val A + Val B >> 3	0	0	1	1	0	0	1	0	1	12.625

Table 2-23 shows more examples of the intermediate shifted value along with the result if rounding is enabled or disabled. In each case, the truncated value is without .5 added and the rounded value is with .5 added.



Rounding Mode www.ti.com

Table 2-23. Shift Right Operation With and Without Rounding

Bit2	Bit1	Bit0	Bit -1	Bit -2	Value	Result with RND = 0	Result with RND = 1
0	1	0	0	0	2.00	2	2
0	0	1	1	1	1.75	1	2
0	0	1	1	0	1.50	1	2
0	0	1	0	1	1.25	1	1
0	0	0	1	1	0.75	0	1
0	0	0	1	0	0.50	0	1
0	0	0	0	1	0.25	0	0
0	0	0	0	0	0.00	0	0
1	1	1	1	1	-0.25	0	0
1	1	1	1	0	-0.50	0	0
1	1	1	0	1	-0.75	0	-1
1	1	1	0	0	-1.00	-1	-1
1	1	0	1	1	-1.25	-1	-1
1	1	0	1	0	-1.50	-1	-1
1	1	0	0	1	-1.75	-1	-2
1	1	0	0	0	-2.00	-2	-2



Trigonometric Math Unit (TMU)

The Trigonometric Math Unit (TMU) is a fully programmable block that enhances the instruction set of the C28-FPU to more efficiently execute common trigonometric and arithmetic operations.

The TMU module described in this reference guide is a Type 0 TMU. For a list of all devices with a TMU module of the same type and to determine differences between the types, see the *TMS320x28xx*, *28xxx DSP Peripheral Reference Guide* (SPRU566). This document describes the architecture and instruction set of the C28x+FPU+TMU.

Topic Page

3.1	Overview	382
3.2	Components of the C28x+FPU Plus TMU	382
3.3	Data Format	382
3.4	Pipeline	383
3.5	TMU Instruction Set	388



Overview www.ti.com

3.1 Overview

The TMU extends the capabilities of a C28x+FPU enabled processor by adding instructions to speed up the execution of common trigonometric and arithmetic operations listed in Table 3-1.

Table 3-1. TMU Supported Instructions

Instructions	C Equivalent Operation
MPY2PIF32 RaH,RbH	a = b * 2pi
DIV2PIF32 RaH,RbH	a = b / 2pi
DIVF32 RaH,RbH,RcH	a = b/c
SQRTF32 RaH,RbH	a = sqrt(b)
SINPUF32 RaH,RbH	$a = \sin(b^*2pi)$
COSPUF32 RaH,RbH	$a = \cos(b^*2pi)$
ATANPUF32 RaH,RbH	a = atan(b)/2pi
QUADF32 RaH,RbH,RcH,RdH	Operation to assist in calculating ATANPU2

3.2 Components of the C28x+FPU Plus TMU

The TMU extends the capabilities of the C28x+FPU processors by adding new instructions and, in some cases, leveraging existing FPU instructions to carry out common arithmetic operations used in control applications.

No changes have been made to existing instructions, pipeline or memory bus architecture. All TMU instructions use the existing FPU register set (R0H to R7H) to carry out their operations. A detailed explanation of the workings of the FPU can be found in the *TMS320C28x Floating Point Unit and Instruction Set Reference Guide* (SPRUEO2).

3.2.1 Interrupt Context Save and Restore

Since the TMU uses the same register set and flags as the FPU, there are no special considerations with regards to interrupt context save and restore.

If a TMU operation is executing when an interrupt occurs, the C28 can initiate an interrupt context switch without affecting the TMU operation. The TMU will continue to process the operation to completion. Even though most TMU operations are multi-cycle, the TMU operation will have completed by the time register context save operations for the FPU are commenced. When restoring FPU registers, you must make sure that all TMU operations are completed before restoring any register used by another TMU operation.

3.3 Data Format

The encoding of the floating-point formats is given in Table 3-2.

Table 3-2. IEEE 32-Bit Single Precision Floating-Point Format

S32	E32 (7:0)	M32 (22:0)	Value (V)
0	0	0	Zero (V = 0)
1	0	0	Negative Zero (V = -0)
0 +ve	0	non zero	De-normalized (V=(-1) ^{S*} 2 ^{(-126)*} (0.M))
1 -ve			
0 +ve	1 to 254	0 to 0x7FFFFF	Normal Range (V=(-1) ^S * 2 ^(E-127) * (1.M))
1 -ve			
0	254	0x7FFFF	Positive Max (V = +Max)
1	254	0x7FFFF	Negative Max (V = -Max)
0	max=255	0	Positive Infinity (V = +Infinity)
1	max=255	0	Negative Infinity (V = -Infinity)
х	max=255	non zero	Not A Number (V = NaN)



www.ti.com Pipeline

The treatment of the various IEEE floating-point numerical formats for this TMU is the same as the FPU implementation given below:

Negative Zero: All TMU operations generate a positive (S==0, E==0, M==0) zero, never a negative zero if the result of the operation is zero. All TMU operations treat negative zero operations as zero.

De-Normalized Numbers: A de-normalized operand (E==0, M!=0) input is treated as zero (E==0, M==0) by all TMU operations. TMU operations never generate a de-normalized value.

Underflow: Underflow occurs when an operation generates a value that is too small to represent in the given floating-point format. Under such cases, a zero value is returned. If a TMU operation generates an underflow condition, then the latched underflow flag (LUF) is set to 1. The LUF flag will remain latched until cleared by the user executing an instruction that clears the flag.

Overflow: Overflow occurs when an operation generates a value that is too large to represent in the given floating-point format. Under such cases, a \pm Infinity value is returned. If a TMU operation generates an overflow condition, then the latched overflow flag (LVF) is set to 1. The LVF flag will remain latched until cleared by the user executing an instruction that clears the flag.

Rounding: There are various rounding formats supported by the IEEE standard. Rounding has no meaning for TMU operations (rounding is inherent in the implementation). Hence rounding mode is ignored by TMU operations.

Infinity and Not a Number (NaN): An NaN operand (E==max, M!=0) input is treated as Infinity (E==max, M==0) for all operations. TMU operations will never generate a NaN value but Infinity instead.

3.4 Pipeline

The TMU enhances the instruction set of the C28-FPU and, therefore, operates the C28x pipeline in the same fashion as the FPU. For a detailed explanation on the working of the pipeline, see the TMS320C28x Floating Point Unit and Instruction Set Reference Guide (SPRUEO2).

3.4.1 Pipeline and Register Conflicts

In addition to the restrictions mentioned in the *TMS320C28x Floating Point Unit and Instruction Set Reference Guide* (SPRUEO2), the TMU places the following restrictions on its instructions:

Example 3-1. SINPUF32 Operation (4p cycles)

```
SINPUF32 RaH,RbH; Value in registers RbH read in this cycle.

Instruction1; Instructions 1-3 cannot operate on register RaH.

Instruction2; Instructions 1-3 can operate on register RbH.

Instruction3; Instructions 1-3 can be any TMU/FPU/VCU/CPU operation.

Instruction4; Result in RaH usable by Instruction 4.
```

Example 3-2. COSPUF32 Operation (4p cycles)

```
COSPUF32 RaH,RbH; Value in registers RbH read in this cycle.

Instruction1; Instructions 1-3 cannot operate on register RaH.

Instruction2; Instructions 1-3 can operate on register RbH.

Instruction3; Instructions 1-3 can be any TMU/FPU/VCU/CPU operation.

Instruction4; Result in RaH usable by Instruction4.
```

Example 3-3. ATANPUF32 Operation (4p cycles)

```
ATANPUF32 RaH,RbH; Value in registers RbH read in this cycle.

Instruction1; Instructions 1-3 cannot operate on register RaH.

Instruction2; Instructions 1-3 can operate on register RbH.

Instruction3; Instructions 1-3 can be any TMU/FPU/VCU/CPU operation.

; Result, LVF flag updated on Instruction3 (4th cycle).

Instruction4; Result in RaH usable by Instruction4.
```



Pipeline www.ti.com

Example 3-4. DIVF32 Operation (5p cycles)

```
DIVF32 RaH,RbH,RcH; Value in registers RbH & RcH read in this cycle.

Instruction1; Instructions 1-4 cannot operate on register RaH.

Instruction2; Instructions 1-4 can operate on register RbH & RcH.

Instruction3; Instructions 1-4 can be any TMU/FPU/VCU/CPU operation.

Instruction4; Result, LVF and LUF flags updated on Instruction4 (5th cycle).

Instruction5; Result in RaH usable by Instruction5.
```

Example 3-5. SQRTF32 Operation (5p cycles)

```
SQRTF32 RaH,RbH ; Value in register RbH read in this cycle.

Instruction1 ; Instructions 1-4 cannot operate on register RaH.

Instruction2 ; Instructions 1-4 can operate on register RbH.

Instruction3 ; Instructions 1-4 can be any TMU/FPU/VCU/CPU operation.

Instruction4 ; Result, LVF flag updated on Instruction4 (5th cycle).

Instruction5 ; Result in register RaH usable by Instruction5.
```

Example 3-6. QUADF32 Operations (5p cycles)

```
QUADF32 RaH,RbH,RcH,RdH

; Value in registers RcH & RdH read in this cycle.

Instruction1 ; Instructions 1-4 cannot operate on registers RaH & RbH.

Instruction2 ; Instructions 1-4 can operate on register RbH.

Instruction3 ; Instructions 1-4 can be any TMU/FPU/VCU/CPU operation.

Instruction4 ; Result, LVF and LUF flags updated on Instruction4 (5th cycle).

Instruction5 ; Result in registers RaH & RbH usable by Instruction5.
```



www.ti.com Pipeline

3.4.2 Delay Slot Requirements

The Delay slot requirements for the TMU instructions are presented in Table 3-3.

Table 3-3. Delay Slot Requirements for TMU Instructions

Case	Description
1	Any Single Cycle FPU operation (including any memory load/store operation) SINPUF32/COSPUF32/ATANPUF32/QUADF32/MPY2PIF32/DIV2PIF32/DIVF32/SQRTF32
2	All FPU 2p-cycle operations MPY/ADD/SUB/ NOP NOP SINPUF32/COSPUF32/ATANPUF32/QUADF32/MPY2PIF32/DIV2PIF32/DIVF32/SQRTF32
3	SINPUF32/COSPUF32/ATANPUF32 NOP NOP NOP All TMU or FPU operations
4	QUADF32/DIVF32/SQRTF32 NOP NOP NOP NOP All TMU or FPU operations
Special C	ases Involving MPY2PIF32/DIV2PIF32
5	MPY2PIF32/DIV2PIF32 NOP SINPUF32/COSPUF32
6	MPY2PIF32/DIV2PIF32 NOP NOP ATANPUF32/QUADF32/DIVF32/SQRTF32
7	MPY2PIF32/DIV2PIF32 NOP NOP All FPU operations
8	MPY2PIF32/DIV2PIF32 NOP MOV32 mem,RxH; Special case: Store result of MPY2PIF32/DIV2PIF32 to memory (but does not include MOV32 operation between CPU and FPU registers).

Notes:

The "NOPs" can be any other FPU, TMU, VCU or CPU operation that does not conflict with the current active TMU operation (does not use same destination register). For example,

Example 3-7. Use of Non-Conflicting Instructions in Delay Slots

SINPUF32	ROH,R1H						
COSPUF32	R2H,R1H						
MOV32	R4H,@VarA						
MOV32	R5H,@VarB						
ADDF32	R3H,R4H,R0H	;	SINPUF32 v	<i>r</i> alue	(R0H)	used	here
ADDF32	R7H,R5H,R2H	;	COSPUF32 v	alue	(R2H)	used	here

The delay FPU slot requirements apply to the operation whereby the destination register value is subsequently used by the TMU operation. For example, in the following case, a parallel MPY and MOV operation precedes the TMU operation and the result from MPY operation is used, then two delay slots are required (Case 2 of Table 3-3):



Pipeline www.ti.com

Example 3-8. Delay Slot Requirement for TMU Instructions That Use Results of Prior FPU Instructions

MPYF32 R3H,R2H,R1H ||MOV32 R4H,@varA NOP NOP

If however the result of the parallel MOV operation is used, then no delay slots are required since the MOV will complete in a single cycle. (Case 1 of Table 3-3):

Example 3-9. FPU Instruction Followed by a Non-Dependent TMU Instruction

MPYF32 R3H,R2H,R1H ||MOV32 R4H,@varA SINPUF32 R6H,R4H

3.4.3 Effect of Delay Slot Operations on the Flags

SINPUF32

R6H,R3H

The LVF and LUF flags can only be set. If multiple operations (from FPU or TMU) try to set the flags, the operations on the flags are ORed together. Operations that set the LVF or LUF flags (either FPU or TMU) are allowed in delay slots. For example, the following sequence of operations is valid:

Example 3-10. Valid Back-to-Back Instructions That may Set the LVF, LUF Flag

MPY2PIF32 R0H,R0H MPY2PIF32 R1H,R1H

If the SETFLG, SAVE, RESTORE, MOVST0, or loading and storing of the STF register, operations try to modify the state of the LVF, LUF flags while a TMU or any other FPU operation is trying to set the flags, the LUV, LVF flags are undefined. This can only occur if the SAVE, SETFLG, RESTORE, MOVST0, or loading and storing of the STF register, operations are placed in the delay slots of the pipeline operations; this should be avoided. This also applies to ZF and NF flags, which are not affected by TMU operations.

3.4.4 Multi-Cycle Operations in Delay Slots

A multi-cycle operation like RET, BRANCH, CALL is equivalent to a minimum four NOPs. For example, the code shown in Example 3-11 returns the correct value because LRETR takes a minimum of four cycles to execute (equivalent to four NOPs):

Example 3-11. Multi-Cycle Operation in the Delay Slot of a TMU Instruction

DIVF32 R0H,R2H,R1H LRETR

3.4.5 Moves From FPU Registers to C28x Registers

When transferring from floating-point unit registers (result of an FPU or TMU operation) to the C28x CPU register, additional pipeline alignment is required as shown in Example 3-12.



www.ti.com Pipeline

Example 3-12. Floating-Point to C28x Register Software Pipeline Alignment

```
; SINPUF32: Per unit sine: 4 pipeline cycle operation
; An alignment cycle is required before copying ROH to ACC
SINPUF32 ROH,R1H
NOP ; Delay Slot 1
NOP ; Delay Slot 2
NOP ; Delay Slot 3
NOP ; Alignment cycle
```



TMU Instruction Set www.ti.com

3.5 TMU Instruction Set

This section describes the assembly language instructions of the TMU.

3.5.1 Instruction Descriptions

This section provides detailed information on the instruction set. Each instruction may present the following information:

- Operands
- Opcode
- Description
- Exceptions
- Pipeline
- Examples
- See also

The example INSTRUCTION is shown to familiarize you with the way each instruction is described. The example describes the kind of information you will find in each part of the individual instruction description and where to obtain more information. TMU instructions follow the same format as the C28x and the C28x+FPU; the source operand(s) are always on the right and the destination operand(s) are on the left.

The explanations for the syntax of the operands used in the instruction descriptions for the C28x TMU are given in Table 3-4. For information on the operands of standard C28x instructions, see the *TMS320C28x CPU and Instruction Set Reference Guide* (SPRU430).

Table 3-4. Operand Nomenclature

Symbol	Description
#16FHi	16-bit immediate (hex or float) value that represents the upper 16-bits of an IEEE 32-bit floating-point value. Lower 16-bits of the mantissa are assumed to be zero.
#16FHiHex	16-bit immediate hex value that represents the upper 16-bits of an IEEE 32-bit floating-point value. Lower 16-bits of the mantissa are assumed to be zero.
#16FLoHex	A 16-bit immediate hex value that represents the lower 16-bits of an IEEE 32-bit floating-point value
#32Fhex	32-bit immediate value that represents an IEEE 32-bit floating-point value
#32F	Immediate float value represented in floating-point representation
#0.0	Immediate zero
#RC	16-bit immediate value for the repeat count
*(0:16bitAddr)	16-bit immediate address, zero extended
CNDF	Condition to test the flags in the STF register
FLAG	Selected flags from STF register (OR) 11 bit mask indicating which floating-point status flags to change
label	Label representing the end of the repeat block
mem16	Pointer (using any of the direct or indirect addressing modes) to a 16-bit memory location
mem32	Pointer (using any of the direct or indirect addressing modes) to a 32-bit memory location
RaH	R0H to R7H registers
RbH	R0H to R7H registers
RcH	R0H to R7H registers
RdH	R0H to R7H registers
ReH	R0H to R7H registers
RfH	R0H to R7H registers
RB	Repeat Block Register
STF	FPU Status Register
VALUE	Flag value of 0 or 1 for selected flag (OR) 11 bit mask indicating the flag value; 0 or 1



INSTRUCTION dest1, source1, source2 Short Description

Operands

dest1 Description for the 1st operand for the instruction source1 Description for the 2nd operand for the instruction source2 Description for the 3rd operand for the instruction

Each instruction has a table that gives a list of the operands and a short description. Instructions always have their destination operand(s) first followed by the source

operand(s).

Opcode This section shows the opcode for the instruction.

Description Detailed description of the instruction execution is described. Any constraints on the

operands imposed by the processor or the assembler are discussed.

Restrictions Any constraints on the operands or use of the instruction imposed by the processor are

discussed.

Pipeline This section describes the instruction in terms of pipeline cycles.

Example Examples of instruction execution. If applicable, register and memory values are given

before and after instruction execution. All examples assume the device is running with the OBJMODE set to 1. Normally the boot ROM or the c-code initialization will set this

bit.

See Also Lists related instructions.

3.5.2 Common Restrictions

For all the TMU instructions, the inputs are conditioned as follows (LVF, LUF are not affected):

- Negative zero is treated as positive zero
- Positive or negative denormalized numbers are treated as positive zero
- · Positive and negative NaN are treated as positve and negative infinity respectively

3.5.3 Instructions

The instructions are listed alphabetically.

Table 3-5. Summary of Instructions

Title	Page
MPY2PIF32 RaH, RbH — 32-Bit Floating-Point Multiply by Two Pi	391



TMU Instruction Set www.ti.com

Table 3-5. Summary of Instructions (continued)

DIV2PIF32 RaH, RbH —32-Bit Floating-Point Divide by Two Pi	392
DIVF32 RaH, RbH, RcH —32-Bit Floating-Point Division	393
SQRTF32 RaH, RbH — 32-Bit Floating-Point Square Root	395
SINPUF32 RaH, RbH —32-Bit Floating-Point Sine (per unit)	
COSPUF32 RaH, RbH — 32-Bit Floating-Point Cosine (per unit)	
ATANPUF32 RaH, RbH —32-Bit Floating-Point ArcTangent (per unit)	
QUADF32 RaH, RbH, RcH — Quadrant Determination Used in Conjunction With ATANPUF32()	



MPY2PIF32 RaH, RbH 32-Bit Floating-Point Multiply by Two Pi

Operands

RaH Floating-point destination register (R0H to R7H) RbH Floating-point source register (R0H to R7H)

Opcode

LSW 1110 0010 0111 0000 0000 0000 00bb baaa **MSW**

Description

This operation is similar to the MPYF32 operation except that the second operand is the constant value 2pi:

RaH = RbH * 2pi

This operation is used in converting Per Unit values to Radians. Per Unit values are used in control applications to represent normalized radians:

Per Unit	Radians
1.0	2pi
0.0	0
1.0	2pi

2pi = 6.28318530718 = 1.570796326795 * 2^2

In IEEE 32-bit Floating point format:

M = (1.570796326795 * 2^23) & 0x007FFFFF= 0x00490FDB

2pi = S+E+M = 0x40C90FDB

Flags

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	Yes

Restrictions

If(RaH result is too big for floating-point number, Ea > 255){

RaH = ±Infinity LVF = 1;

Pipeline

Instruction takes 2 pipeline cycles to execute if followed by either SINPUF32,

COSPUF32 or MOV32 mem, Rx operations and 3 pipeline cycles for all other operations

(FPU or TMU).

Example

;; Convert Per Unit value to Radians: MOV32 ROH,@PerUnit ; ROH = Per Unit value MPY2PIF32 ROH,ROH ; R0H = R0H * 2pi ; pipeline delay NOP MOV32 @Radians, ROH ; store Radian result

; 4 cycles



DIV2PIF32 RaH, RbH 32-Bit Floating-Point Divide by Two Pi

Operands

RaH Floating-point destination register (R0H to R7H)
RbH Floating-point source register (R0H to R7H)

Opcode

LSW 1110 0010 0111 0001 MSW 0000 0000 00bb baaa

Description

This operation is similar to the MPYF32 operation except that the second operand is the constant value 1/2pi:

$$RaH = RbH * 1/2pi$$

This operation is used in converting Radians to Per unit values. Per unit values are used in control representing normalized Radians:

Per Unit	Radians
1.0	2pi
0.0	0
-1.0	-2pi

In IEEE 32-bit Floating point format:

 $M = (1.273239544735 * 2^23) & 0x007FFFFF = 0x0022F983$

$$1/2pi = S+E+M = 0x3E22F983$$

Flags

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	Yes	No

Restrictions

If (RaH result is too small for floating-point number, Ea < 0) {

$$RaH = 0.0$$

$$LUF = 1;$$

}

Pipeline

Instruction takes 2 pipeline cycles to execute if followed by either SINPUF32, COSPUF32 or MOV32 mem, Rx operations and 3 pipeline cycles for all other operations

(FPU or TMU).

Example



DIVF32 RaH, RbH, RcH 32-Bit Floating-Point Division

Operands

RaH Floating-point destination register (R0H to R7H)
RbH Floating-point source register (R0H to R7H)
RcH Floating-point source register (R0H to R7H)

Opcode

LSW 1110 0010 0111 0100 MSW 0000 000c ccbb baaa

Description

RaH = RbH/RcH

The sequence of operations are as follows:

```
Sa = Sb ^ Sc;
                                   // Set sign of result
Ea = (Eb - Ec) + 127;
                                  // Calculate Exponent
Ma = Mb / Mc;
                                  // 0.5 < Ma < 2.0
if(Ma < 1.0){)}
                                  // Re-normalize mantissa range
   Ea = Ea - 1;
   Ma = Ma * 2.0;
if(Ea >= 255){
                                   // Chek if result too big:
   Ea = 255;
                                   // Return Inf
   Ma = 0;
   LVF = 1;
                                   // Set overflow flag
if((Ea == 0) & (Ma != 0)){
                                   // Check if result Denorm value:
   Sa = 0;
   Ea = 0;
                                   // Return zero
   Ma = 0;
   LUF = 1;
                                   // Set underflow flag
if(Ea < 0){
                                   // Check if result too small:
   Sa = 0;
   Ea = 0;
                                   // Return zero
   Ma = 0;
   LUF = 1;
                                   // Set underflow flag
```

Flags

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	Yes	Yes



Restrictions

The following boundary conditions apply:

Division	Result	LVF	LUF
0/0	0	1	-
0/Inf	0	-	1
Inf/Normal	Inf	1	-
Inf/0	Inf	1	-
Inf/Inf	Inf	-	1
Normal/0	Inf	1	-
Normal/Inf	0	-	1

Pipeline Instruction takes 5 pipeline cycles to execute.

Example

```
;; Calculate Z = Y/X
                  ; R0H = X
; R1H = Y
 MOV32 ROH,@X
 MOV32 R1H,@Y
 DIVF32 R2H,R1H,R0H ; R2H = R1H/R0H = Y/X = Z
 NOP
                      ; pipeline delay
 NOP
                      ; pipeline delay
 NOP
                      ; pipeline delay
 NOP
                      ; pipeline delay
 MOV32 @Z,R2H
                     Z = Y/X
                      ; 8 cycles
```



SQRTF32 RaH, RbH 32-Bit Floating-Point Square Root

Operands

RaH Floating-point destination register (R0H to R7H)
RbH Floating-point source register (R0H to R7H)

Opcode

LSW 1110 0010 0111 0111 MSW 0000 0000 00bb baaa

Description

Rah = \sqrt{RbH}

Flags


Flag	TF	ZI	NI	ZF	NF	LUF	LVF	
Modified	No	No	No	No	No	No	Yes	

Restrictions

Pipeline

Instruction takes 5 pipeline cycles to execute.

Example



SINPUF32 RaH, RbH 32-Bit Floating-Point Sine (per unit)

Operands

RaH Floating-point destination register (R0H to R7H)
RbH Floating-point source register (R0H to R7H)

Opcode

LSW 1110 0010 0111 1000 MSW 0000 0000 00bb baaa

Description

This instruction performs the following equivalent operation:

PerUnit = fraction(RbH)
RaH = sin(PerUnit*2pi)

In control applications radians are usually normalized to the range of -1.0 to 1.0.

Per Unit	Radians
1.0	2pi
0.0	0
-1.0	-2pi

The operation takes the fraction of the input value RbH. This equates to the cosine waveform repeating itself every 2pi radians

RbH	Per Unit	Radians	Sine Value
2.0	0.0	0	0.0
1.75	0.75	3pi/2	-1.0
1.5	0.5	pi	0.0
1.25	0.25	pi/2	1.0
1.0	0.0	0	0.0
0.75	0.75	3pi/2	-1.0
0.5	0.5	pi	0.0
0.25	0.25	pi/2	1.0
0.0	0.0	0	0.0
-0.25	-0.25	-pi/2	-1.0
-0.5	-0.5	-pi	0.0
-0.75	-0.75	-3pi/2	1.0
-1.0	0.0	0	0.0
-1.25	-0.25	-pi/2	-1.0
-1.5	-0.5	-pi	0.0
-1.75	-0.75	-3pi/2	1.0
-2.0	0.0	0	0.0

Flags

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No



Restrictions If the input value is too small ($\leq 2^{-33}$) or too big ($\geq 2^{22}$), then the output will be

returned as 0.0 (no flags affected).

Pipeline Instruction takes 4 pipeline cycles to execute.

Example ;; Convert Radian value to PerUnit value and

;; calculate Sin value:

MOV32 ROH,@RadianValue ; ROH = Radian value

DIV2PIF32 R1H,R0H

; R1H=R0H/2pi= Per Unit Value

NOP ; pipeline delay

SINPUF32 R2H,R1H ; R2H = SINPU(fraction(R1H))

NOP ; pipeline delay
NOP ; pipeline delay
NOP ; pipeline delay

MOV32 @SinValue,R2H ; Sin Value=sin(Radian Value)

; 8 cycles



COSPUF32 RaH, RbH 32-Bit Floating-Point Cosine (per unit)

Operands

RaH Floating-point destination register (R0H to R7H)
RbH Floating-point source register (R0H to R7H)

Opcode

LSW 1110 0010 0111 1001 MSW 0000 0000 00bb baaa

Description

This instruction performs the following equivalent operation:

PerUnit = fraction(RbH) RaH = cos(PerUnit*2pi)

In control applications radians are usually normalized to the range of -1.0 to 1.0.

Per Unit	Radians
1.0	2pi
0.0	0
-1.0	-2pi

The operation takes the fraction of the input value RbH. This equates to the cosine waveform repeating itself every 2pi radians

RbH	Per Unit	Radians	Cosine Value
2.0	0.0	0	1.0
1.75	0.75	3pi/2	0.0
1.5	0.5	pi	-1.0
1.25	0.25	pi/2	0.0
1.0	0.0	0	1.0
0.75	0.75	3pi/2	0.0
0.5	0.5	pi	-1.0
0.25	0.25	pi/2	0.0
0.0	0.0	0	1.0
-0.25	-0.25	-pi/2	0.0
-0.5	-0.5	-pi	-1.0
-0.75	-0.75	-3pi/2	0.0
-1.0	0.0	0	1.0
-1.25	-0.25	-pi/2	0.0
-1.5	-0.5	-pi	-1.0
-1.75	-0.75	-3pi/2	0.0
-2.0	0.0	0	1.0

Flags

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	No



Restrictions

STRUMENTS

www.ti.com

returned as 1.0 (no flags affected).

Instruction takes 4 pipeline cycles to execute. **Pipeline**

Example ;; Convert Radian value to PerUnit value and

;; calculate Sin value:

MOV32 ROH,@RadianValue ; ROH = Radian value

DIV2PIF32 R1H,R0H

; R1H=R0H/2pi= Per Unit Value

; pipeline delay

COSPUF32 R2H,R1H ; R2H = COSPU(fraction(R1H))

; pipeline delay NOP NOP ; pipeline delay NOP ; pipeline delay

MOV32 @CosValue,R2H ; Cos Value=cos(Radian Value)

; 8 cycles

If the input value is too small ($<= 2^-33$) or too big ($>= 2^22$), then the output will be



ATANPUF32 RaH, RbH 32-Bit Floating-Point ArcTangent (per unit)

Operands

RaH Floating-point destination register (R0H to R7H)
RbH Floating-point source register (R0H to R7H)

Opcode

LSW 1110 0010 0111 1010 MSW 0000 0000 00bb baaa

Description

This instruction computes the arc tangent of a given value and returns the result as a

per-unit value:

PerUnit = atan(RbH)/2pi

The operation limits the input ranget of the input value RbH to:

-1.0 < = RbH < = 1.0

Values outside this range return 0.125 as follows:

RbH	Per Unit	Radians	ATANPU Value	LVF Flag
>1.0	0.125	pi/4	0.125	1
1.0	0.125	pi/4	0.125	
0.0	0.0	0	0.0	
-1.0	-0.125	-pi/4	-0.125	
<-1.0	-0.125	-pi/4	-0.125	1

Flags

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	No	Yes

Pipeline Instruction takes 4 pipeline cycles to execute.

;; convert to Radians:

MOV32 ROH,@AtanValue ; ROH = Atan Value ATANPUF32 R1H,R0H ; R1H = ATANPU(R0H) NOP ; pipeline delay ; pipeline delay NOP NOP ; pipeline delay MPY2PIF32 R2H,R1H ; R2H = R1H * 2pi = Radian value ; pipeline delay NOP MOV @RadianValue,R2H ; Store result

; 8 cycles



QUADF32 RaH, RbH, RcH Quadrant Determination Used in Conjunction With ATANPUF32()

Operands

RaH Floating-point destination register (R0H to R7H)
RbH Floating-point destination register (R0H to R7H)
RcH Floating-point source register (R0H to R7H)
RdH Floating-point source register (R0H to R7H)

Opcode

LSW 1110 0010 0111 1100 MSW 0000 dddc ccbb baaa

Description

This operation, in conjunction with atanpu(), is used in calculating atanpu2() for a full circle:

RdH = X value

RcH = Y value

RbH = Ratio of X & Y

RaH = Quadrant value $(0.0, \pm 0.25, \pm 0.5)$

Calculation of RaH (Quadrant) and RbH (Ratio) Based on RcH (Y) and RdH (X) Values shows how the values RaH and RbH are generated based on the contents of RbH and RcH.

The algorithm for this instruction is as follows:

```
if((fabs(RcH(Y)) == 0.0) & (fabs(RdH(X)) == 0.0)) 
  RaH(Quadrant) = 0.0;
                = 0.0;
  RbH(Ratio)
 else if(fabs(RcH(Y)) < = fabs(RdH(X))) 
  RbH(Ratio) = RcH(Y) / RdH(X);
  if(RdH(X) >= 0.0)
      RaH(Quadrant) = 0.0;
  else {
      if(RcH(Y) >= 0.0)
         RaH(Quadrant) = 0.5;
         RaH(Quadrant) = -0.5;
    }
}else {
    if(RcH(Y) >= 0.0)
       RaH(Quadrant) = 0.25;
       RaH(Quadrant) = -0.25;
   RbH(Ratio) = - RdH(X) / RcH(Y);
 }
```

Flags

Flag	TF	ZI	NI	ZF	NF	LUF	LVF
Modified	No	No	No	No	No	Yes	Yes



Restrictions

Division	Result	LVF	LUF
0/0	0	1	-
0/Inf	0	-	1
Inf/Normal	Inf	1	-
Inf/0	Inf	1	-
Inf/Inf	Inf	-	1
Normal/0	Inf	1	-
Normal/Inf	0	-	1


Pipeline

Instruction takes 5 pipeline cycles to execute.

Example

```
;; Calculate Z = atan2(Y,X), where Z is in
;; radians:
 MOV32
             ROH,@X
                              ; ROH = X
 MOV32
             R1H,@Y
                              ; R1H = Y
;; if(Y <= X) R2H= R1H/R0H
;; else
             R2H = -R0H/R1H
;; R3H= 0.0, +/-0.25, +/-0.5
  OUADF32
             R3H,R2H,R1H,R0H
 NOP
                              ; pipeline delay
 NOP
                              ; pipeline delay
 NOP
                              ; pipeline delay
                              ; pipeline delay
 NOP
;; R4H = ATANPU(R2H)(Per Unit result)
 ATANPUF32 R4H,R2H
  NOP
                              ; pipeline delay
 NOP
                              ; pipeline delay
                              ; pipeline delay
 NOP
;; R5H = R3H + ATANPU(R4H) = ATANPU2 value
             R5H,R3H,R4H
 ADDF32
 NOP
                              ; pipeline delay
;; R6H = ATANPU2 * 2pi = atan2 value(radians)
 MPY2PIF32 R6H,R5H
 NOP
                              ; pipeline delay
  MOV32
              @Z,R6H
                              ; store result
                              ; 16 cycles
```

Calculation of RaH (Quadrant) and RbH (Ratio) Based on RcH (Y) and RdH (X) Values





www.ti.com Revision History

Revision History

Cr	nanges from March 15, 2014 to November 7, 2015	Page
•	Section 2.4.2: Added the last paragraph to this section	20
•	Section 1.4.4: Revised this paragraph.	21
•	Chapter 2: C28 Viterbi, Complex Math and CRC Unit-II (VCU-II): Made changes to the majority of the LSW and opcodes.	

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, enhancements, improvements and other changes to its semiconductor products and services per JESD46, latest issue, and to discontinue any product or service per JESD48, latest issue. Buyers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All semiconductor products (also referred to herein as "components") are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its components to the specifications applicable at the time of sale, in accordance with the warranty in TI's terms and conditions of sale of semiconductor products. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by applicable law, testing of all parameters of each component is not necessarily performed.

TI assumes no liability for applications assistance or the design of Buyers' products. Buyers are responsible for their products and applications using TI components. To minimize the risks associated with Buyers' products and applications, Buyers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any patent right, copyright, mask work right, or other intellectual property right relating to any combination, machine, or process in which TI components or services are used. Information published by TI regarding third-party products or services does not constitute a license to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of significant portions of TI information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. TI is not responsible or liable for such altered documentation. Information of third parties may be subject to additional restrictions.

Resale of TI components or services with statements different from or beyond the parameters stated by TI for that component or service voids all express and any implied warranties for the associated TI component or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

Buyer acknowledges and agrees that it is solely responsible for compliance with all legal, regulatory and safety-related requirements concerning its products, and any use of TI components in its applications, notwithstanding any applications-related information or support that may be provided by TI. Buyer represents and agrees that it has all the necessary expertise to create and implement safeguards which anticipate dangerous consequences of failures, monitor failures and their consequences, lessen the likelihood of failures that might cause harm and take appropriate remedial actions. Buyer will fully indemnify TI and its representatives against any damages arising out of the use of any TI components in safety-critical applications.

In some cases, TI components may be promoted specifically to facilitate safety-related applications. With such components, TI's goal is to help enable customers to design and create their own end-product solutions that meet applicable functional safety standards and requirements. Nonetheless, such components are subject to these terms.

No TI components are authorized for use in FDA Class III (or similar life-critical medical equipment) unless authorized officers of the parties have executed a special agreement specifically governing such use.

Only those TI components which TI has specifically designated as military grade or "enhanced plastic" are designed and intended for use in military/aerospace applications or environments. Buyer acknowledges and agrees that any military or aerospace use of TI components which have *not* been so designated is solely at the Buyer's risk, and that Buyer is solely responsible for compliance with all legal and regulatory requirements in connection with such use.

TI has specifically designated certain components as meeting ISO/TS16949 requirements, mainly for automotive use. In any case of use of non-designated products, TI will not be responsible for any failure to meet ISO/TS16949.

Products		Applications	
Audio	www.ti.com/audio	Automotive and Transportation	www.ti.com/automotive
Amplifiers	amplifier.ti.com	Communications and Telecom	www.ti.com/communications
Data Converters	dataconverter.ti.com	Computers and Peripherals	www.ti.com/computers
DLP® Products	www.dlp.com	Consumer Electronics	www.ti.com/consumer-apps
DSP	dsp.ti.com	Energy and Lighting	www.ti.com/energy
Clocks and Timers	www.ti.com/clocks	Industrial	www.ti.com/industrial
Interface	interface.ti.com	Medical	www.ti.com/medical
Logic	logic.ti.com	Security	www.ti.com/security
Power Mgmt	power.ti.com	Space, Avionics and Defense	www.ti.com/space-avionics-defense
Microcontrollers	microcontroller.ti.com	Video and Imaging	www.ti.com/video
RFID	www.ti-rfid.com		
OMAP Applications Processors	www.ti.com/omap	TI E2E Community	e2e.ti.com
Wireless Connectivity	www.ti.com/wirelesscon	nectivity	