
# How to order SMT with single PCB board?

## Files needed:


- 1) Gerber file for PCB;
- 2) BOM& CPL files for SMT/THT assembly.

Note: The following are samples for data required in both BOM and CPL, and please note that better use the same names on the first row.




#### **Ordering steps:**

## 1. Upload Gerber file




2. Select suitable parameter for PCB.




3. Click "SMT assembly" service, and select following options, like


### assembly side.



## 4. Click "Next" on right bottom to continue.




### 5. Upload BOM& CPL files.



#### 6. Select parts


(Note: Pls double check the system matched parts whether they are the ones you want)




#### Then click NEXT to continue



### 7. Check preview and price



#### 8. Save to cart



9. Checkout and fulfil following steps.

